# BEE BEE ARCHITE Architects & Eng

APURBA BI

Annexure A

		Architect	's Certificate <sup>*</sup>			
ort	for qua	rter ending	30 MAR 2021			
ubject			Certificate of progress of construction work			
	I/We have undertaken assignment as architect for certifying progress of construction work below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 8093.7 sq mtr , Commercial Cum Residential Colony			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	11.49375 acres			
	4.	Area for registration in acres	1.99 acres			
	5.	HARERA registration no.	111 of 2017			
	6.	Name of licensee	Robust Buildwell Private Limited			
	7.	Name of collaborator				
	8.	Name of developer	Robust Buildwell Private Limited			
	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection				
	2.	Name of Architect/ Architect's firm	BEE BEE Architects			
	3.	Date of site inspection				



#### **Architects & Engineers**

#### APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. Consultants		Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
	3.	Proof consultant			
	4.	MEP consultant	Mr, Digambar Singh		
	5.	Site incharge	Mr. D.C Pant		
4.	Haryan constru envisag	a Building Code, 2017/ National Buction, infrastructure works and in	ed as per approved drawings, statutory/ mandatory approvals, Building Code (wherever applicable) and the material used in the ternal development works are as per the projected standard as are, publication material and other documents shared with the		
5.	of the below.	real estate project/phase of the pro	ntage of work done in the project for each of the building/ tower ject under HARERA is as per table A and table B given herein cuted with respect to each of the activity of the entire project/		

Date : Yours faithfully,

Signature & name (in block letters) with Place : stamp of architect

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date) Jaros Alchitect Reg. 13/61616

Architects & Engineers

# APURBA BORAH

			Table – A				
(to be	prepar	ower no. ed separately for each building/ tower // phase of the project)					
A1	Cumulative progress of the project/phase at the end of the quarter.						
Sr. No.	Project components  Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.			0.4 CR	11.78 CR	100%		
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		1.5 CR	1.5 Cr	20%		
3.	MEP				0		
	3.1	Mechanical (lifts, ventilation, etc.)	-	-			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-			
4.	Finishing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	- 			
	4.2	External (plaster, painting, facade, etc.)	-	-			



#### **Architects & Engineers**

#### APURBA BORAH

Sr.		Tasks/ Activity	Description of work		Percentage of total		
No.	i	Sub-Structure Status		done		proposed work	
1.	Excav	vation	Completed		100	)%	
2.	Laying of foundation						
	(i)	Raft	Comp	leted	100	)%	
	(ii)	Pile	N/A		N/A		
3.	Number of basement(s)						
	(i) Basement Level 1		Comp	Completed		)%	
	(ii)	Basement level 2*	Completed		100%		
	(iii)	Basement Level 3	Completed		100%		
	(iv)	Basement Level 4	Comp	leted	100	)%	
4.		rproofing of the above sub-structure rever applicable)					
		Super-Structure Status					
5.	Total	floors in the tower/ building	4		-		
6.	Total	area on each floor	120	000	-		
7.	Stilt f	loor/ ground floor	63600		-		
8.	Status of laying of slabs floor wise		-		-		
	Cumulative number of slabs in the building/ towerlaid by end of quarter						
9.	Status of construction						
	(i)	Walls on floors	-		-		
	(ii)	Staircase	-		-	-	
	(iii)	Lift wells along with water proofing	-		-		
	(iv)	Lift lobbies/ common areas floor wise	-		-		
10.	Fixin units	g of door and window frames in flats/					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works					
	(ii)	Electrical works including wiring	-				
	(iii)	Plumbing works		-			
12.	Status of wall plastering						
	(i)	External plaster	-				
	(ii)	Internal plaster	-				
13.	Status of wall tiling						
	(i)	In bathroom	-				
	(ii)	In kitchen	-				
14.	Statu	s of flooring					
	(i)	Common areas		-			
	(ii)	Units/ flats	-			_	

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Juma 209

# BEE BEE ARCHITEC Architects & Engin

APURBA BOI

Sr. No.	Tasks/ Activity Sub-Structure Status Status of white washing		Description of work	Percentage of total
			done	proposed work
15.				
	(i)	Internal walls	•	
	(ii)	External walls	-	
16.	Status of finishing			
	(i)	Staircase with railing	-	
	(ii)	Lift wells	-	
	(iii)	Lift lobbies/ common areas floor wise	-	
17.	Status	of installation		
	(within flat/unit)			
	(i)	Doors and windows panels	-	
	(ii)	Sanitary fixtures	-	
	(iii)	Modular kitchen	-	
	(iv)	Electrical fittings/ lighting	-	
	(v)	Gas piping (if any)	-	
	(other than flat/units)			
	(vi)	Lifts installation	-	
	(vii)	Overhead tanks	-	
	(viii)	Underground water tank	-	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	
	(x)	Electrical fittings in common areas	-	
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	
18.	Water	rproofing of terraces		
19.	Entrai	nce lobby finishing	-	
20.	Status	s of construction of compound wall	-	

Note: (\*) extend rows as per requirement.

#### **Architects & Engineers**

#### APURBA BORAH

Table – B

r. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements		0%	
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	-		
	Fixing of children play equipment's	-		
	Benches	-		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	-		
12.	Water conservation, rain water, harvesting, percolating well/ pit	-		
13.	Energy management (solar)	-		
14.	Fire protection and fire safety requirements	-		
15.	Electrical meter room, sub-station, receiving station	-		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community center	-		
18.	Others	-		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	-	·	
20.	Dispensary	-		
21.	Club	-		
22.	Others	-		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

