Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect's	s Certificate¹
Repo	Report for quarter ended		30 <sup>th</sup> September 2025
Subje	Subject		Certificate of progress of construction work
1.	. I/We have undertaken assignmen construction work in the below ment		ent as architect for certifying progress of ntioned project as per the approved plans
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Elevate Phase – I
	2.	Location	Village Behrampur, Sector-59, Gurugram
	3.	Licensed area in acres	8.91875
	4.	Area for registration in acres	5.95
	5.	HARERA registration no.	19 of 2019
	6.	Name of licensee	License no. 16 of 2008 :

6) Bulls Realtors Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. 11) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd. Heritage Max Realtech Pvt. Ltd.  8. Name of developer Heritage Max Realtech Pvt. Ltd.	
6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011:  1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd.	
6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011:  1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd.	
6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011:  1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd.	
1) BTVS Buildwell Pvt. Ltd. 2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008:  1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd.	

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	30 <sup>th</sup> September 2025

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Sunil Chauhan		
	2.	Structural consultant	Vintech Consultant (Mr. Vinod Jain)		
	3.	Proof consultant	Mehro Consultants		
	4.	MEP consultant	Sanelac Consultants Pvt Ltd		
	5.	Site supervisor/incharge	Sunil Chauhan		
4.	mand applic develo	atory approvals, Haryana Buildinable) and the material used in the properties of the properties are as per the proposition material and the properties are as per the properties the properties are as a per the properties are a per the prop	Recuted as per approved drawings, statutory/ ng Code, 2017/National Building Code (wherever e construction, infrastructure works and internal ojected standard as envisaged in the registration d other documents shared with the buyers in this		
5.	the bu	ilding/ tower of the real estate	ercentage of work done in the project for each of project/phase of the project under HARERA is as elow. The percentage of the work executed with		

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

Place

:

Yours faithfully

Labib Alam, Architect

Registration No.: CA/2001/27447

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : CA/200/27444

registration no.

Council of architects (CoA) : 31-12-2027

registration valid till (date)

	Table – A						
Building/ Tower no.  (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower-A				
<b>A1</b>	Cun	nulative progress of the projec	t/phase at the e	nd of the quarte	r.		
Sr. No.	Proj	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.	(incl	structure usive of excavation, dation, basements, water ofing, etc.)	0	35.00	100%		
2.	(slat	er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.)	0	56.00	100%		
3.	МЕР	)					
	3.1	Mechanical (lifts, ventilation, etc.)	1.20	18.80	100 %		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.91	11.75	100 %		

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.40	12.69	100%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.10	19.02	100%
	4.2	External (plaster, painting, facade, etc.)	1.40	15.26	100%

Sr. No.	i	Tasks/ Activity Description of work done Sub-Structure Status		Percentage of total proposed work	
1.	Exca	vation	Complete	100 %	
2.	Layi	ng of foundation			
	(i)	Raft	Complete	100 %	
	(ii)	Pile	NA	NA	
3.	Num	lber of basement(s)			
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%	
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%	
4.		erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%	

		Super-Structure Status		
5.	Tota	l floors in the tower/building	1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Tota	l area on each floor	785 Sqm	100%
7.	Stilt	floor/ground floor	Structure Tower Entrance	100%
8.	Statı	ıs of laying of slabs floor wise	Upto terrace Level Completed	100%
		ulative number of slabs in the	Total Slabs	100%
		ling/ tower laid by of quarter	1Stilt+1Service Floor+31 Apt Floor	
9.	Statı	us of construction		
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		ng of door and window frames in units		
11.	Statu	us of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statu	ns of wall plastering		Los

(ii)         Gypsum Plaster         100% (31 of 31 Floor completed)         100%           13.         Status of wall tiling         100% Completed         100%           (i)         Bathroom Tiles         100% Completed         100%           (ii)         Kitchen Wall Tile         100% Completed         100%           14.         Status of flooring         100% Completed         100%           (ii)         Apt Stone Flooring         100% Completed         100%           15.         Status of white washing         100% Completed         100%           (ii)         Apartment Prefinal Paint         100% Completed         100%           (iii)         Putty+1stCoat+2nd Coat         100% Completed         100%           16.         Status of finishing         100% Completed         100% Completed           (i)         MS Railing         100% Completed         100% Completed	
(i)       Bathroom Tiles       100% Completed       100%         (ii)       Kitchen Wall Tile       100% Completed       100%         14.       Status of flooring       100% Completed       100%         (ii)       Apt Stone Flooring       100% Completed       100%         15.       Status of white washing       100% Completed       100%         (i)       Apartment Prefinal Paint       100% Completed       100%         (ii)       Putty+1stCoat+2nd Coat       100% Completed       100%         16.       Status of finishing       100% Completed       100% Completed	_
(i)       Kitchen Wall Tile       100% Completed       100%         14.       Status of flooring       100% Completed       100%         (i)       Lift Lobby Flooring       100% Completed       100%         (ii)       Apt Stone Flooring       100% Completed       100%         15.       Status of white washing       100% Completed       100%         (i)       Apartment Prefinal Paint       100% Completed       100%         (ii)       Putty+1stCoat+2nd Coat       100% Completed       100%         16.       Status of finishing       100% Completed       100% Completed	
14. Status of flooring  (i) Lift Lobby Flooring 100% Completed 100%  (ii) Apt Stone Flooring 100% Completed 100%  15. Status of white washing  (i) Apartment Prefinal Paint 100% Completed 100%  (ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing 100% Completed 100%	
(i) Lift Lobby Flooring 100% Completed 100%  (ii) Apt Stone Flooring 100% Completed 100%  15. Status of white washing  (i) Apartment Prefinal Paint 100% Completed 100%  (ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing  (i) MS Railing 100% Completed 100% Completed 100%	44
(ii) Apt Stone Flooring 100% Completed 100%  15. Status of white washing  (i) Apartment Prefinal Paint 100% Completed 100%  (ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing 100% Completed 100%	
15. Status of white washing  (i) Apartment Prefinal Paint 100% Completed 100%  (ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing 100% Completed 100%	83
(i) Apartment Prefinal Paint 100% Completed 100%  (ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing 100% Completed 100%	
(ii) Putty+1stCoat+2nd Coat 100% Completed 100%  16. Status of finishing  (i) MS Railing 100% Completed 100%	
16. Status of finishing  (i) MS Railing 100% Com	
(i) MS Railing 100% Com	
(1)   Mo (tailing	
	pleted in
(ii) Lift Well HO for Lift Installation 100% Completed 100%	
(iii) Lobby Wall Tiling 100% Completed 100%	
17. Status of installation	
(within flat/unit)	91
(i) UPVC Windows 100% Completed 100%	
(ii) Bathroom Chinaware 100% Completed 100%	
(iii) Modular Kitchen Cabinet 100% Completed 100% Installation (Without Panels)	60.

	(iv)	Switch & Sockets	100% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)	× 1	
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	100% Completed
	(vii)	RCC Work	100% Completed	100% Completed
1	(viii)	RCC Work	100% Completed	100% Completed
	(ix)	Fire Pump Installation	100% Completed	100% Completed
	(x)	Staircase & Lobby Wiring	100% Completed	100% Completed
	(xi)	Six Monthly Compliance	100% Compliance	100% Completed
18.	Wate	erproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services		J	
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes		_
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	-
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	Jb

16.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA	<b>I</b>	
17.	Community centre	Yes	100%	
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	100%	
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
23.	*		-	

Note: (\*) extend as per requirement

		•	Table - A		
(to build	be p	Tower no.  repared separately for each tower in the project/ phase of	Tower-B		
<b>A1</b>	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	35.00	100%
6.	(slab	er structure os, brick work, block work, case, lift wells, machine os, water tank, etc.)	0	60.05	100%
7.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	1.72	18.93	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.01	12.73	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.31	13.23	100%
8.	Fini	shing	-		
	4.1	Internal  (plaster, tilling, flooring, painting, etc. within units and common areas)	2.02	19.90	100%
	4.2	External (plaster, painting, facade, etc.)	1.01	14.23	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status	_		
21.	Exca	vation	Complete	100 %	
22.	Layir	ng of foundation			
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Num	ber of basement(s)			
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	1	erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
		Super-Structure Status		Labib Alam, Architec	

25.	Total	floors in the tower/building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt floor/ ground floor		Structure Tower Entrance	100% Completed
28.	Status of laying of slabs floor wise  Cumulative number of slabs in the building/tower laid by end of quarter		Upto terrace Level Completed	100%
			Total Slabs  1Stilt+1Service Floor+31 Apt Floor	100%
29.	Statu	s of construction	1	
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(vii)	Lift Well including Machine room	100% Completed	100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
30.		g of door and window frames in / units	Door Frame	100% Completed
31.	Statu	as of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	100% Completed	100% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	100% Completed
32.	Stati	s of wall plastering		
	(iii)	RCC External Wall	NA	anily Atlant Aredited

	(iv)	Gypsum Plaster	100%	100% Completed
33.	Statu	s of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	100% Completed
	(iv)	Kitchen Wall Tile	100% Completed	100% Completed
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	100% Completed	100% Completed
	(iv)	Apt Stone Flooring	100% Completed	100% Completed
35.	Statu	as of white washing		
	(iii)	Apartment Prefinal Paint	100% Completed	100% Completed
	(iv)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed
36.	Status of finishing			
	(iv)	MS Railing	100% Completed	100% Completed
	(v)	Lift Well HO for Lift Installation	100% Completed	100% Completed
	(vi)	Lobby Wall Tiling	100% Completed	100% Completed
37.	Statı	us of installation		
	(witl	hin flat/unit)		
	(xii)	UPVC Windows	100% Completed	100% Completed
	(xiii)	Bathroom Chinaware	100% Completed	100% Completed
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	100% Completed
	(xv)	Switch & Sockets	100% Completed	100% Completed
	(xvi)	NA	NA ·	
	(oth	er than flat/units)		Colon Colon

	Guide Rail+ Floor Door+ Car Installation	100 % Complete	100% Completed
(xvii	RCC Work	100% Completed	100% Completed
(xix)	RCC Work	100% Completed	100% Completed
(xx)	Fire Pump Installation	100% Completed	100% Completed
(xxi)	Staircase & Lobby Wiring	100% Completed	100% Completed
(xxii	Six Monthly Compliance	100% Compliance	100% Completed
Wate	erproofing of terraces	PU Waterproofing	100% Completed
Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed
	(xix) (xxi) (xxii) Wate	(xvii RCC Work  (xix) RCC Work  (xx) Fire Pump Installation  (xxi) Staircase & Lobby Wiring  (xxii Six Monthly Compliance  Waterproofing of terraces  Entrance lobby finishing  Status of construction of compound	(xvii)RCC Work100% Completed(xix)RCC Work100% Completed(xx)Fire Pump Installation100% Completed(xxi)Staircase & Lobby Wiring100% Completed(xxii)Six Monthly Compliance100% ComplianceWaterproofing of terracesPU WaterproofingEntrance lobby finishingGypsum False ceilingStatus of construction of compoundBoundary Wall RCC and

Note: (\*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
24.	Internal roads & pavements	Yes	100%	
25.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	100%	
30.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
31.	Shopping area	Yes	0%	
32.	Street lighting/ electrification	Yes	100%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	100%   ahib A	am, Archite

39.	Other (option to add more)	NA			
B-2	Community building to be transferred to RWA				
40.	Community centre	Yes	100%		
41.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
42.	Schools	NA			
43.	Dispensary	NA			
44.	Club	Yes	100%		
45.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
46.	*				

Note: (\*) extend as per requirement

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page **18** of **25** 

		1	Table – A		
(to build	be pr	Tower no.  repared separately for each ower in the project/ phase of	Tower-C		
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.			Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	24.96	100%
10.	(slab	er structure es, brick work, block work, case, lift wells, machine es, water tank, etc.)	0	40.02	100%
11.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0.40	9.71	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.79	7.98	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.40	7.94	100%
12.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.30	16.24	100%
	4.2	External (plaster, painting, facade, etc.)	0.11	5.62	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
41.	Exca	vation	Complete	100 %	
42.	Layii	ng of foundation		107	
	(v)	Complete	100% Completed	100%	
	(vi)	NA	NA	0	
43.	Num	ber of basement(s)			
	(v)	Structure under Tower Footprint Complete	100% Completed	100%	
	(vi)	Structure under Tower Footprint Complete	100% Completed	100%	
44.	4	erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
		Super-Structure Status		Labib Alam, Arch	

45.	Total floors in the tower/ building		1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt floor/ ground floor		Structure Tower Entrance	100% Completed
48.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	100% Completed
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	100% Completed
	(xi)	Lift Well including Machine room	100% Completed	100% Completed
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	100% Completed
50.		ng of door and window frames in / units	Door Frame	100% Completed
51.	Statı	us of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	100% Completed
52.	Statı	us of wall plastering		
	(v)	RCC External Wall	NA	College .

	(vi)	Gypsum Plaster	100%	100% Completed	
53.	Status of wall tiling				
	(v)	Bathroom Tiles	100% Completed	100% Completed	
	(vi)	Kitchen Wall Tile	100% Completed	100% Completed	
54.	Status of flooring				
	(v)	Lift Lobby Flooring	100% Completed	100% Completed	
	(vi)	Apt Stone Flooring	100% Completed	100% Completed	
55.	Status of white washing				
	(v)	Apartment Prefinal Paint	100% Completed	100% Completed	
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed	
56.	Status of finishing				
	(vii)	MS Railing	100% Completed	100% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	100% Completed	
	(ix)	Lobby Wall Tiling	100% Completed	100% Completed	
57.	Statu	s of installation			
	(with	nin flat/unit)			
	(xxiii	UPVC Windows	100% Completed	100% Completed	
	(xxiv	Bathroom Chinaware	100%	100% Completed	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	100%	100% Completed	
	(xxvi	Switch & Sockets	100% Completed	100% Completed	
	(xxvi	NA	NA	1 00	
	(othe	er than flat/units)		Labib Alam, Archit	

	(xxvi Guide Rail+ Floor Door+ Cal Installation	100% Complete	100% Completed	
	(xxix RCC Work	100% Completed	100% Completed	
	(xxx) RCC Work	100% Completed	100% Completed	
	(xxxi Fire Pump Installation	100% Completed	100% Completed	
	(xxxi Staircase & Lobby Wiring	100% Completed	100% Completed	
	(xxxi Six Monthly Compliance	100% Compliance	100% Completed	
58.	Waterproofing of terraces	PU Waterproofing	100% Completed	
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed	
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed	

Note: (\*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
47.	Internal roads & pavements	Yes	100%	
48.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
49.	Water supply	Yes	100%	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
51.	Storm water drains	Yes	100%	
52.	Landscaping & tree plantation	Yes	100%	
53.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
54.	Shopping area	Yes	0%	
55.	Street lighting/ electrification	Yes	100%	
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
57.	Solid waste management & disposal	Yes	100%	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
59.	Energy management (solar)	Yes	100%	
60.	Fire protection and fire safety requirements	Yes	100%	
61.	Electrical meter room, sub-station, receiving station	Yes	100%	ih Alam, Ar

62.	Other (option to add more)	NA			
B-2	Community building to be transferred to RWA				
63.	Community centre	Yes	100%		
64.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
65.	Schools	NA			
66.	Dispensary	NA			
67.	Club	Yes	100%		
68.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
69.	*			2	

Note: (\*) extend as per requirement