



ANNEXURE 6-A
ARCHITECT'S CERTIFICATE
On the letter head of the architect firm
To whom so ever it may concern

Report for quarter ending 31.12.2021

Subject: Certificate of progress of construction work:

Sr. No.	Particulars	Information
1.	Project/Phase of the project	Habitat_78
2.	Location	Village Faridpur, Sector-78, Faridabad, Haryana
3.	Area in acres	7.394 Acre
4.	HARERA Registration No.	78 of 2017 dated – 22/08/2017
5.	Name of Licensee	Conscient Infrastructure Pvt. Ltd.
6.	Name of Collaborator	N/A
7.	Name of Developer	Conscient Infrastructure Pvt. Ltd.

Sir,

I/ We have undertaken assignment as architect for certifying progress of construction work in the above mentioned project as per the approved plans.

1.	Date of certifying of percentage of construction work/ site inspection	30/12/2021
2.	Name of Architect/Architect's firm	R.K. & ASSOCIATES
3.	Date of site inspection	29/12/2021



Aditya

E-31, GREEN PARK MAIN, NEW DELHI-110016, INDIA, TEL 2696-3158, 2651-6751, FAX-2686-2540

E-MAIL: rka01@vsnl.net , rka.architects@gmail.com & contact@rkaindia.net
www.rkaindia.net

Following technical professionals are appointed by Promoter: - (as applicable)

Sr.No.	Consultants	Name
1.	Site Engineer	Mr. Sharad Chandra
2.	Structural Consultant	NNC DESIGN INTERNATIONAL
3.	Proof Consultant	Chordia Engineering Consultancy Services
4.	MEP Consultant	V CONSULTING
5.	Site Supervisor/in charge	Mr. Manoj Kumar

I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B

Table - A

Building/Tower no. **Tower-A-1** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	
3.	Number of basement(s) <u>Nil</u>		
	i. Basement level 1	NA	
	ii. Basement level 2*	NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	G+14	
6.	Total area on each floor	584.38 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise	G+14	
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15	100%
9.	Status of construction		
	i. Walls on floors	Completed	100%
	ii. Staircase	Completed	100%



Adhik

	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	
	ii. In Kitchen	Completed		100%	
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				
	i. Staircase with railing	Completed		100%	
	ii. Lift wells	Completed		100%	
	iii. Lift lobbies / common area floor wise	Completed		100%	
16.	Status of Installation				
	(Within flat/unit)				
	i. Doors and windows panels	Completed		100%	
	ii. Sanitary Fixtures	Completed		100%	
	iii. Modular Kitchen	NA		NA	
	iv. Electrical fittings/Lighting	Completed		100%	
	v. Gas piping (if any)	NA		NA	
	(Other than flat/units)				
	vi. Lifts installation	Completed		100%	
	vii. Overhead tanks	Completed		100%	
	viii. Underground water tank	Completed		100%	
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed		100%	
	x. Electrical fittings in common areas				
	xi. Compliance to conditions of environment /CRZ NOC	Completed		100%	
17.	Waterproofing of terraces	Completed		100%	
18.	Entrance lobby finishing	Completed		100%	



Adhik

19.	Status of construction of Compound wall	Completed	100%
-----	---	-----------	------

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-A-2** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done		Percentage of total proposed work	
A1	SUB- STRUCTURE STATUS				
1.	Excavation	Completed		100%	
2.	Laying of foundation				
	i. Raft	Completed		100%	
	ii. Pile	NA			
3.	Number of basement(s) <u>Nil</u>				
	i. Basement level 1	NA			
	ii. Basement level 2*	NA			
4.	Waterproofing of the above sub- structure (wherever applicable)				
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	G+14			
6.	Total area on each floor	584.38 Sqm			
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise	G+14			
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15		100%	
9.	Status of construction				
	i. Walls on floors	Completed		100%	
	ii. Staircase	Completed		100%	
	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%



Adarsh

12.	Status of wall Finishing (Plaster/Paint/White washing Coating)		
	i. External	Completed	100%
	ii. Internal	Completed	100%
13.	Status of wall tiling		
	i. In bathroom	Completed	100%
	ii. In Kitchen	Completed	100%
14.	Status of flooring		
	i. Common areas	Completed	100%
	ii. Units/flats	Completed	100%
15.	Status of finishing		
	i. Staircase with railing	Completed	100%
	ii. Lift wells	Completed	100%
	iii. Lift lobbies / common area floor wise	Completed	100%
16.	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	NA	NA
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	NA	NA
	(Other than flat/units)		
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-A-3** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
---------	------------------	--------------------------	-----------------------------------



Adhik

A1	SUB- STRUCTURE STATUS			
1.	Excavation	Completed	100%	
2.	Laying of foundation			
	i. Raft	Completed	100%	
	ii. Pile	NA		
3.	Number of basement(s) Nil			
	i. Basement level 1	NA		
	ii. Basement level 2*	NA		
4.	Waterproofing of the above sub- structure (wherever applicable)			
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building	G+14		
6.	Total area on each floor	584.38 Sqm		
7.	Stilt Floor/ Ground Floor			
8.	Status of laying of slabs floor wise	G+14		
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15	100%	
9.	Status of construction			
	i. Walls on floors	Completed	100%	
	ii. Staircase	Completed	100%	
	iii. Lift wells	Completed	100%	
	iv. Lift lobbies /common areas floor wise	Completed	100%	
10.	Fixing of door and window frames in flats/units			
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)
	i. Mechanical works			
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%
	iii. Plumbing works	120	Completed	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)			
	i. External	Completed	100%	
	ii. Internal	Completed	100%	
13.	Status of wall tiling			
	i. In bathroom	Completed	100%	
	ii. In Kitchen	Completed	100%	
14.	Status of flooring			
	i. Common areas	Completed	100%	
	ii. Units/flats	Completed	100%	
15.	Status of finishing			
	i. Staircase with railing	Completed	100%	



Adhik

	ii. Lift wells	Completed	100%
	iii. Lift lobbies / common area floor wise	Completed	100%
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	NA	NA
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	NA	NA
	(Other than flat/units)		
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-A-4** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	
3.	Number of basement(s) <u>Nil</u>		
	i. Basement level 1	NA	
	ii. Basement level 2*	NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		
A2	SUPER- STRUCTURE STATUS		



Adhik

5.	Total floors in the tower/building	G+14			
6.	Total area on each floor	584.38 Sqm			
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise	G+14			
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15		100%	
9.	Status of construction				
	i. Walls on floors	Completed		100%	
	ii. Staircase	Completed		100%	
	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	
	ii. In Kitchen	Completed		100%	
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				
	i. Staircase with railing	Completed		100%	
	ii. Lift wells	Completed		100%	
	iii. Lift lobbies / common area floor wise	Completed		100%	
16.	Status of Installation (Within flat/unit)				
	i. Doors and windows panels	Completed		100%	
	ii. Sanitary Fixtures	Completed		100%	
	iii. Modular Kitchen	NA		NA	
	iv. Electrical fittings/Lighting	Completed		100%	
	v. Gas piping (if any)	NA		NA	
	(Other than flat/units)				



Adhik

	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-A-5** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	
3.	Number of basement(s) <u>Nil</u>		
	i. Basement level 1	NA	
	ii. Basement level 2*	NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	G+14	
6.	Total area on each floor	584.38 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise	G+14	
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15	100%
9.	Status of construction		
	i. Walls on floors	Completed	100%
	ii. Staircase	Completed	100%
	iii. Lift wells	Completed	100%
	iv. Lift lobbies /common areas floor wise	Completed	100%



Adhik

10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	
	ii. In Kitchen	Completed		100%	
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				
	i. Staircase with railing	Completed		100%	
	ii. Lift wells	Completed		100%	
	iii. Lift lobbies / common area floor wise	Completed		100%	
16.	Status of Installation (Within flat/unit)				
	i. Doors and windows panels	Completed		100%	
	ii. Sanitary Fixtures	Completed		100%	
	iii. Modular Kitchen	NA		NA	
	iv. Electrical fittings/Lighting	Completed		100%	
	v. Gas piping (if any)	NA		NA	
	(Other than flat/units)				
	vi. Lifts installation	Completed		100%	
	vii. Overhead tanks	Completed		100%	
	viii. Underground water tank	Completed		100%	
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed		100%	
	x. Electrical fittings in common areas				
	xi. Compliance to conditions of environment /CRZ NOC	Completed		100%	
17.	Waterproofing of terraces	Completed		100%	
18.	Entrance lobby finishing	Completed		100%	
19.	Status of construction of Compound wall	Completed		100%	

Note: (*) Extend rows as per requirement



Adhik

Building/Tower no. **Tower-A-6** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done		Percentage of total proposed work	
A1	SUB- STRUCTURE STATUS				
1.	Excavation	Completed		100%	
2.	Laying of foundation				
	i. Raft	Completed		100%	
	ii. Pile	NA			
3.	Number of basement(s) <u>Nil</u>				
	i. Basement level 1	NA			
	ii. Basement level 2*	NA			
4.	Waterproofing of the above sub- structure (wherever applicable)				
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	G+14			
6.	Total area on each floor	584.38 Sqm			
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise	G+14			
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15		100%	
9.	Status of construction				
	i. Walls on floors	Completed		100%	
	ii. Staircase	Completed		100%	
	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	



Adhik

	ii. In Kitchen	Completed	100%
14.	Status of flooring		
	i. Common areas	Completed	100%
	ii. Units/flats	Completed	100%
15.	Status of finishing		
	i. Staircase with railing	Completed	100%
	ii. Lift wells	Completed	100%
	iii. Lift lobbies / common area floor wise	Completed	100%
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	NA	NA
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	NA	NA
	(Other than flat/units)		
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-A-7** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	
2.	Laying of foundation		
	i. Raft	Completed	
	ii. Pile	NA	
3.	Number of basement(s) <u>Nil</u>		
	i. Basement level 1	NA	



Adhik

	ii. Basement level 2*	NA			
4.	Waterproofing of the above sub- structure (wherever applicable)				
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	G+12/13			
6.	Total area on each floor	584.38			
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise	G+9			
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	10			
9.	Status of construction				
	i. Walls on floors	Completed up to 9th floor			
	ii. Staircase	Completed up to 9th floor			
	iii. Lift wells	Completed up to 9th floor			
	iv. Lift lobbies /common areas floor wise	Completed up to 9th floor			
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	107	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	
	ii. In Kitchen	Completed		100%	
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				
	i. Staircase with railing	Completed		100%	
	ii. Lift wells	Completed		100%	
	iii. Lift lobbies / common area floor wise	Completed		100%	
16.	Status of Installation				
	(Within flat/unit)				
	i. Doors and windows panels	Completed		100%	
	ii. Sanitary Fixtures	Completed		100%	
	iii. Modular Kitchen	NA		NA	



Adhik

	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any) (Other than flat/units)	NA	NA
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-B-1** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	
3.	Number of basement(s) <u>Nil</u>		
	i. Basement level 1	NA	
	ii. Basement level 2*	NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	G+14	
6.	Total area on each floor	533.67	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise	G+14	
	Cumulative number of slabs in the building/tower <u>13</u> laid by end of quarter	15	100%
9.	Status of construction		
	i. Walls on floors	Completed	100%



Adarsh

	ii. Staircase	Completed		100%	
	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
11.	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)				
	i. External	Completed		100%	
	ii. Internal	Completed		100%	
13.	Status of wall tiling				
	i. In bathroom	Completed		100%	
	ii. In Kitchen	Completed		100%	
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				
	i. Staircase with railing	Completed		100%	
	ii. Lift wells	Completed		100%	
	iii. Lift lobbies / common area floor wise	Completed		100%	
16.	Status of Installation (Within flat/unit)				
	i. Doors and windows panels	Completed		100%	
	ii. Sanitary Fixtures	Completed		100%	
	iii. Modular Kitchen	NA		NA	
	iv. Electrical fittings/Lighting	Completed		100%	
	v. Gas piping (if any)	NA		NA	
	(Other than flat/units)				
	vi. Lifts installation	Completed		100%	
	vii. Overhead tanks	Completed		100%	
	viii. Underground water tank	Completed		100%	
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed		100%	
	x. Electrical fittings in common areas				
	xi. Compliance to conditions of environment /CRZ NOC	Completed		100%	
17.	Waterproofing of terraces	Completed		100%	



Adhik

18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-B-2** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done		Percentage of total proposed work	
A1	SUB- STRUCTURE STATUS				
1.	Excavation	Completed		100%	
2.	Laying of foundation				
	i. Raft	Completed		100%	
	ii. Pile	NA			
3.	Number of basement(s) Nil				
	i. Basement level 1	NA			
	ii. Basement level 2*	NA			
4.	Waterproofing of the above sub- structure (wherever applicable)				
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	G+14			
6.	Total area on each floor	533.67			
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise	G+14			
	Cumulative number of slabs in the building/tower 13 laid by end of quarter	15		100%	
9.	Status of construction				
	i. Walls on floors	Completed		100%	
	ii. Staircase	Completed		100%	
	iii. Lift wells	Completed		100%	
	iv. Lift lobbies /common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works				
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%	100%
	iii. Plumbing works	120	Completed	100%	100%



Adhik

12.	Status of wall Finishing (Plaster/Paint/White washing Coating)		
	i. External	Completed	100%
	ii. Internal	Completed	100%
13.	Status of wall tiling		
	i. In bathroom	Completed	100%
	ii. In Kitchen	Completed	100%
14.	Status of flooring		
	i. Common areas	Completed	100%
	ii. Units/flats	Completed	100%
15.	Status of finishing		
	i. Staircase with railing	Completed	100%
	ii. Lift wells	Completed	100%
	iii. Lift lobbies / common area floor wise	Completed	100%
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	NA	NA
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	NA	NA
	(Other than flat/units)		
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Tower-C** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
---------	------------------	--------------------------	-----------------------------------



Adhik

A1	SUB- STRUCTURE STATUS			
1.	Excavation	Completed		
2.	Laying of foundation			
	i. Raft	Completed		
	ii. Pile	NA		
3.	Number of basement(s) Nil			
	i. Basement level 1	NA		
	ii. Basement level 2*	NA		
4.	Waterproofing of the above sub- structure (wherever applicable)			
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building	G+12/13		
6.	Total area on each floor	332.6		
7.	Stilt Floor/ Ground Floor			
8.	Status of laying of slabs floor wise	G+12/13		
	Cumulative number of slabs in the building/tower 13 laid by end of quarter	G+12/13		
9.	Status of construction			
	i. Walls on floors	Completed	100%	
	ii. Staircase	Completed	100%	
	iii. Lift wells	Completed	100%	
	iv. Lift lobbies /common areas floor wise	Completed	100%	
10.	Fixing of door and window frames in flats/units			
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)
	i. Mechanical works			
	ii. Electrical works conduiting and Box Fixing	120	Completed	100%
	iii. Plumbing works	120	Completed	100%
12.	Status of wall Finishing (Plaster/Paint/White washing Coating)			
	i. External	Completed	100%	
	ii. Internal	Completed	100%	
13.	Status of wall tiling			
	i. In bathroom	Completed	100%	
	ii. In Kitchen	Completed	100%	
14.	Status of flooring			
	i. Common areas	Completed	100%	
	ii. Units/flats	Completed	100%	
15.	Status of finishing			
	i. Staircase with railing	Completed	100%	



Adhik

	ii. Lift wells	Completed	100%
	iii. Lift lobbies / common area floor wise	Completed	100%
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	NA	NA
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	NA	NA
	(Other than flat/units)		
	vi. Lifts installation	Completed	100%
	vii. Overhead tanks	Completed	100%
	viii. Underground water tank	Completed	100%
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas		
	xi. Compliance to conditions of environment /CRZ NOC	Completed	100%
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	Completed	100%
19.	Status of construction of Compound wall	Completed	100%

Note: (*) Extend rows as per requirement

Building/Tower no. **Commercial** (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work
	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation	Completed	100%
	i. Raft	N/A	
	ii. Pile	N/A	
	iii. Isolate footing	Completed	100%
3.	Number of basement(s)	N/A	
	i. Basement level 1	N/A	



Adhik

	ii. Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)	N/A			
	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	8 Blocks		100%	
6.	Total area on each floor	2290.197 Sqm (Covered Area).			
7.	Stilt Floor/ Ground Floor	8 Blocks		100%	
8.	Status of laying of slabs floor wise	8 Blocks		100%	
	Cumulative number of slabs in the building/tower <u>1</u> laid by end of quarter	8 Blocks		100%	
9.	Status of construction				
	i. Walls on floors	Completed		100%	
	ii. Staircase	N/A			
	iii. Lift wells along with water proofing	N/A			
	iv. Lift lobbies /common areas floor wise	N/A			
10.	Fixing of door and window frames in flats/units	Work in Progress			
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanical works	N/A	N/A		
	ii. Electrical works including wiring	Completed	Completed		
	iii. Plumbing works	Completed	Completed		
12.	Status of wall Finishing (Plaster/Paint/White Coating) washing				
	i. External	8 Blocks		100%	
	ii. Internal	8 Blocks		100%	
13.	Status of wall tiling	To be starts			
	i. In bathroom	Completed			
	ii. In Kitchen	N/A			
14.	Status of flooring				
	i. Common areas	Completed		100%	
	ii. Units/flats	Completed		100%	
15.	Status of finishing				



Adhik

	i. Staircase with railing	N/A	
	ii. Lift wells	N/A	
	iii. Lift lobbies /common areas floor wise	N/A	
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Completed	100%
	ii. Sanitary Fixtures	Completed	100%
	iii. Modular Kitchen	N/A	
	iv. Electrical fittings/Lighting	Completed	100%
	v. Gas piping (if any)	N/A	
	(Other than flat/units)		
	vi. Lifts installation	N/A	
	vii. Overhead tanks	N/A	
	viii. Underground water tank	N/A.	
	ix. Firefighting fittings and equipment's as per CFO NOC	Completed	100%
	x. Electrical fittings in common areas	Completed	100%
	xi. Compliance to conditions of environment /CRZ NOC		
17.	Waterproofing of terraces	Completed	100%
18.	Entrance lobby finishing	N/A	
19.	Status of construction of Compound wall	Completed	100%

Note : (*) Extend rows as per requirement.

Table - B

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of Work Done	Remarks
	B-1 Services			
1.	Internal roads & pavements	Yes	Completed	100%
2.	Parking		Completed	100%
	Covered no			Scooter Parking.
	Open no (1121)	Yes		Scooter Parking.



Adarsh

3.	Water supply	Yes	Completed	100%
4.	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	Completed	100%
5.	Storm water drains	Yes	Completed	100%
6.	Landscaping & tree plantation	Yes	Completed	100%
7.	Parks and playgrounds	Yes	Completed	100%
	Fixing of children play equipment's	Yes	Completed	100%
	Benches		Completed	100%
8.	Shopping Area	Yes	Completed	100%
9.	Street Lighting/Electrification	Yes	Completed	100%
10.	Treatment and disposal of sewage and sullage water/STP	Yes	Completed	100%
11.	Solid Waste Management & disposal	Yes	Completed	100%
12.	Water Conservation, Rainwater Harvesting, Percolating Well/Pit	Yes	Completed	100%
13.	Energy management (Solar)	Yes	Completed	100%
14.	Fire Protection and Fire Safety Requirements	Yes	Completed	100%
15.	Electrical meter room, Sub-Station, Receiving station	Yes	Completed	100%
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre	Yes	Completed	100%
18.	Creche.	Yes	Completed	100%
B-3	Community buildings not to be transferred to RWA/Competent Authority			
19.	Schools	No		N/A
20.	Dispensary	No		N/A
21.	Club	No		N/A
22.	Commercial	Yes	Completed	100%
B-4	Services /facilities to be transferred to Competent Authority			
23.	*	N/A		

Note : (*)Extend as per requirement



Adhik