SOBHA

Annexure - A

		Architec	ct's Certificate*
Report for quarter ending 30th Sep.2025			30th Sep.2025
Subject Certificate of progress of construction w			Certificate of progress of construction work
1.			as architect for certifying progress of entioned project as per the approved plans
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Sobha City, Phase-4
	2.	Location	Sector-108, Babupur Village, Gurugram, Haryana
	3.	Licensed area in acres	39.375 acres
	4.	Area for registration in acres	2.6778 acres
	5.	HARERA registration no.	34 of 2019
	6.	Name of licensee	M/s Chintels India Limited
			M/s Vidu Properties Private Limited
			M/s Chintels Credit Corporation Limited
			M/s Madhyanchal Leasing Limited
			Mr. Prashant Solomon
			Mr. Rohan Solomon
			Mr. Ramesh Solomon
			Mrs. Chanderlekha Solomon and
		4	M/s Sobha Limited (as Developer)
	7.	Name of collaborator	NA
	8.	Name of developer	M/s Sobha Limited
2.	Details	related to inspection are as	under

	1.	Date of certifying of percentage of construction work /site inspection	30th Sep.2025			
	2.	Name of Architect/ Architect's firm	Mr. Venkatesh Gudi/Sobha Limited			
	3.	Date of site inspection	30th Sep.2025			
3.	Follow	ing technical professionals ar	re appointed by promoter: - (as applicable)			
	Sr. No.	Consultants	Name			
	1.	Site engineer	Mr. Prem Mohan			
	2.	Structural consultant	Mr. Srinivas Sathyanarayan			
	3.	Proof consultant	Mr. Srinivas Sathyanarayan			
	4.	MEP consultant	Mr. Prasanna Venkatesh G			
	5.	Site supervisor/incharge	Mr. Prabhuraj/Mr. Suleman/ Mr. Prakash Bhishtt			
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.					
5.	with the buyers in this regard. I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.					

Date:

Place:

Council of architects registration no.: CA/2005/36913

Council of architects registration valid till (date): 31.12.2026

(to b	e prep	ower no. pared separately for each building/ the project/ phase of the project)	Tower No. A3		
A1	Cur	nulative progress of the project/	phase at the er	nd of the quarte	er.
Sr. No.	Pro	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	60,414,532	100%
2.	(sla	er structure bs, brick work, block work, stair e, liftwells, machine rooms, water k, etc.)	NIL	116,761,564	100%
3.	MEI	P			
	3.1	Mechanical (lifts, ventilation, etc.)	NIL	9,196,088	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	2,473,732	30,921,655	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1,335,583	26,711,659	100%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common	19,206,821	64,022,735	100%
	4.2	External (plaster, painting, facade, etc.)	44,94,234	15,843,786	100%

		Та	ble -A		
Building/Tower no. (to be prepared separately for each building/tower in the project/phase of the project)			Tower No. A4	881	
A1	Cur	nulative progress of the project/	phase at the e	nd of the quart	er.
Sr. No.	Pro	eject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		inclusive of excavation, foundation,	60,414,532	100%
2.	Super structure (slabs, brick work, block work, stair case, liftwells, machine rooms, water tank, etc.)		NIL	116,761,564	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	NIL	9,196,088	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	NIL	30,921,655	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	NIL	30,591,701	100%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common	NIL	64,022,737	100%
	4.2	External (plaster, painting, facade, etc.)	NIL	15,843,786	100%

		Та	ble –A			
(to be	e prep	ower no. pared separately for each building/ ne project/ phase of the project)	Tower No. B3			
A1	Cur	nulative progress of the project/	phase at the e	nd of the quart	er.	
Sr. No.	Pro	ject components	Work done value work done during the quarter date		Percentage of work done to the total proposed	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		inclusive of excavation, foundation,	72,609,908	100%	
2.	Super structure (slabs, brick work, block work, stair case, liftwells, machine rooms, water tank, etc.)		NIL	140,331,243	100%	
3.	MEP					
	3.1	Mechanical (lifts, ventilation, etc.)	NIL	11,042,909	100%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	NIL	37,163,551	100%	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	NIL	32,103,717	100%	
4.	Fini	shing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common	NIL	76,946,471	100%	
	4.2	External (plaster, painting, facade, etc.)	NIL	19,042,038	100%	

		Та	ble -A			
Building/Tower no. (to be prepared separately for each building/tower in the project/phase of the project)			Tower No. B4		,	
A1	Cur	nulative progress of the project,	phase at the e	nd of the quart	er.	
Sr. No.	Pro	eject components	Work done value work done during the quarter Cumulative work done value till date		Percentage of work done to the total proposed	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		inclusive of excavation, foundation,		100%	
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		NIL	140,330,195	100%	
3.	МЕР					
	3.1	Mechanical (lifts, ventilation, etc.)	NIL	11,052,343	100%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	NIL	37,163,273	100%	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	NIL	32,103,478	100%	
4.	Fini	shing	3			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common	NIL	76,945,896	100%	
	4.2	External (plaster, painting, facade, etc.)	NIL	19,041,896	100%	

Sr. No.	Tower A3 Tasks/ Activity Description done		tion of work	Percentage of tota		
	Sub-	Structure Status				
1.	Exca	vation	Excavatio	n	100%	
2.	Layii	ng of foundation				
	(i)	Raft	Reinforce Shuttering Concreting	g-	100%	
	(ii)	Pile			100%	
3.	Num	ber of basement(s)				
	(i)	Basement Level 1	01 numbe	rof	100 %	
	(ii)	Basement level 2*	NA		NA	
4.		Waterproofing of the above sub- structure (wherever applicable)				
	Sup	er-Structure Status				
5.	Total	floors in the tower/ building	18			
6.	Total	l area on each floor	473.39 Sqm			
7.	Stilt f	loor/ ground floor	01 number of Stilt		100%	
8.	Statu	is of laying of slabs floor wise				
	build	ulative number of slabs in the ling/tower A3 laid and of quarter	18/18		100%	
9.	Statu	s of construction				
	(i)	Walls on floors	18/18		100%	
	(ii)	Staircase	18/18		100%	
	(iii)	Lift wells along with water proofing	18/18		100%	
	(iv)	Lift lobbies/ common areas floor wise	18/18		100%	
10.		g of door and window frames ats/units	0/18		0 %	
11.	Statu	s of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	(i)	Mechanical works	2 3	-	100%	- (1)

	(ii)	Electrical works including	18/18	18/18	100 %	100 %
	(iii)	Plumbing works	18/18	18/18	100%	100 %
12.	Statu	s of wall finishing (Plaster/				274
	pain	t/whitewashing/coating)				
	(i)	External plaster	18/18		100%	
	(ii)	Internal plaster	18/18		100%	
13.	Statu	s of wall tiling				
	(i)	Inbathroom	18/18		100%	
	(ii)	Inkitchen	18/18		100 %	
14.	Statu	s of flooring				
	(i)	Common areas	17/18		94%	
	(ii)	Units/ flats	12.5/18		69%	
15.	Statu	s of white washing				Very-
	(i)	Internal walls	18/18		100%	
<u> </u>	(ii)	External walls	18/18		100%	
16.	Statu	s of finishing				
	(i)	Staircase with railing	18/18		100%	
	(ii)	Lift wells (Blockwork)	18/18		100 %	
	(iii)	Liftlobbies/ common areas	18/18		100 %	
		floor wise				
17.	Statu	s of installation				
	(with	in flat/unit)				
	(i)	Doors and windows panels	18/18		100 %	
	(ii)	Sanitary fixtures	18/18		100 %	
	(iii)	Modular kitchen	NA			
	(iv)	Electrical fittings/ lighting	NA			
	(v)	Gas piping (if any)	NA			
	(othe	r than flat/units)				
	(vi)	Lifts installation	2/2		100 %	
	(vii)	Overhead tanks	2/2		100 %	
	(viii)	Underground water tank	NA			
	(ix)	Firefighting fitting and equipment's as per CFO NOC	18/18		100 %	
	(x)	Electrical fittings in common	18/18		100 %	
	(xi)	Compliance to conditions of environment/CRZ NOC				CE.

18.	Waterproofing of terraces	0	100 %
19.	Entrance lobby finishing	0	60 %
20.	Status of construction of compound wall	1850/1875	98%
			Park

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-	Structure Status			
1.	Exca	vation	Excavation	100%	
2.	Layir	ng of foundation			
	(i)	Raft	Reinforcement- Shuttering- Concreting-	100%	
	(ii)	Pile		100%	
3.	Num	ber of basement(s)1			
	(i)	Basement Level 1	01 number of	100%	
	(ii)	Basement level 2*	NA	NA	
4.	Waterproofing of the above sub- structure (wherever applicable)			100%	
	Sup	er-Structure Status			
5.	Total floors in the tower/ building 18		18		
6.	Total	area on each floor	473.39 Sqm		
7.	Stilt f	loor/ ground floor	01 number of Stilt	100%	
8.	Statu	s of laying of slabs floor wise			
	build	alative number of slabs in the ing/tower A4 laid and of quarter	18/18	100%	
9.	Statu	s of construction	1		
	(i)	Walls on floors	18/18	100%	
	(ii)	Staircase	18/18	100%	
	(iii)	Lift wells along with water proofing	1/2	100%	
	(iv)	Lift lobbies/ common areas floor wise	18/18	100%	
10.	1	g of door and window frames ats/units	18/18	100%	

11.	Statu	s of MEP	Internal	External	Internal	Externa
		**	(within	works	(within	works
	(i)	Mechanical works	Flat)		Flat) 100%	
	(ii)	Electrical works including	18/18	100%	100%	0 %
	(iii)	Plumbing works	18/18	100%	100%	0 %
12.		s of wall finishing (Plaster/	10/10	10070	10070	0 70
12.		t/whitewashing/coating)				
	(i)	External plaster	18/18		100 %	
	(ii)	Internal plaster	18/18		100 %	
13.	+	s of wall tiling	10/10		100 /0	
	(i)	Inbathroom	18/18		100 %	
	(ii)	Inkitchen	18/18		100 %	
14.		s of flooring	1			
	(i)	Common areas	18/18		100 %	
	(ii)	Units/ flats	18/18		100%	
15.	Statu	s of white washing				
	(i)	Internal walls	18/18		100 %	
	(ii)	External walls	100%		100 %	
16.	Statu	s of finishing				
	(i)	Staircase with railing	18/18)¥	100%	
	(ii)	Lift wells (Blockwork)	18/18		100%	
	(iii)	Lift lobbies/ common areas floor wise	18/18		100 %	
17.	Statu	s of installation				
	(with	in flat/unit)				
	(i)	Doors and windows panels	18/18		100%	
	(ii)	Sanitary fixtures	18/18		100%	
	(iii)	Modular kitchen	NA			
	(iv)	Electrical fittings/ lighting	NA			
	(v)	Gas piping (if any)	NA			
	(othe	r than flat/units)				
	(vi)	Lifts installation	2/2		100 %	LIE III
	(vii)	Overhead tanks	2/2		100 %	
	(viii)	Underground water tank	NA			

	(ix)	Firefighting fitting and equipment's as per CFO NOC	18/18	100 %
	(x)	Electrical fittings in common	18/18	100 %
	(xi)	Compliance to conditions of environment/CRZ NOC		
18.	Wate	rproofing of terraces	100%	100 %
19.	Entrance lobby finishing		100%	100 %
20.	Status of construction of compound wall		1875/1875	100%

8		Tow	ver B3	
Sr. No.	Task	ss/ Activity	Description of work done	Percentage of total proposed work
	Sub-	Structure Status		
1.	Exca	vation	Excavation	100%
2.	Layii	ng of foundation		
	(i)	Raft	Reinforcement- Shuttering- Concreting-	100%
	(ii)	Pile		100%
3.	Num	ber of basement(s)1		
	(i)	Basement Level 1	01 number of Basement(s) and	100 %
	(ii)	Basement level 2*	NA	NA
4.		erproofing of the above sub- eture (wherever applicable)		100%
	Sup	er-Structure Status		
5.	Total	floors in the tower/ building	18/18	100%

6.	Tota	l area on each floor	564.374 Sqm			
7.	Stilt	floor/ ground floor	01 number of Stilt		100%	
8.	Status of laying of slabs floor wise					
	build	ulative number of slabs in the ling/tower B3 laid by of quarter	NIL		NIL	
9.	Status of construction					
	(i)	Walls on floors	18/18		100%	
	(ii)	Staircase	18/18		100%	
	(iii)	Lift wells along with water proofing	100%		100%	-
	(iv)	Lift lobbies/ common areas floor wise	18/18		100%	
10.		g of door and window frames ats/units	18/18		100 %	
11.	Status of MEP		Internal (within Flat)	External works	Internal (within Flat)	External works
	(i)	Mechanical works	-		-	-
	(ii)	Electrical works including	18/18	100 %	100 %	100 %
	(iii)	Plumbing works	18/18	100 %	100 %	100 %
12.	Status of wall finishing (Plaster/paint/whitewashing/coating)					
	(i)	External plaster	18/18		100 %	
	(ii)	Internal plaster	18/18		100 %	
13.	Statu	s of wall tiling				
	(i)	Inbathroom	18/18		100 %	
	(ii)	Inkitchen	18/18		100%	
14.	Status of flooring					
	(i)	Common areas	18/18		100 %	
	(ii)	Units/ flats	18/18		100 %	
15.	Status of white washing					
	(i)	Internal walls	18/18		100 %	
	(ii)	External walls	18/18		100 %	
16.	Statu	s of finishing	-			
	(i)	Staircase with railing	19/19		100 %	(DA)

	(ii)	Lift wells (Blockwork)	18/18	100 %
	(iii)	Lift lobbies/ common areas floor wise	18/18	100 %
17.	Statu	s of installation		
	(with	in flat/unit)		
	(i)	Doors and windows panels	18/18	100 %
	(ii)	Sanitary fixtures	18/18	100 %
	(iii)	Modular kitchen	NA	
	(iv)	Electrical fittings/ lighting	NA	
	(v)	Gas piping (if any)	NA	
	(othe	r than flat/units)		
	(vi)	Lifts installation	2/2	100 %
	(vii)	Overhead tanks	2/2	100 %
	(viii)	Underground water tank	NA	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	18/18	100 %
	(x)	Electrical fittings in common	18/18	100 %
	(xi)	Compliance to conditions of environment/CRZ NOC		
18.	Water	rproofing of terraces	100%	100%
19.	Entra	nce lobby finishing	100 %	100 %
20.	Status	s of construction of compound	1035/1875	56%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
	Sub-	Structure Status			
1.	Exca	vation	Excavation	100%	
2.	Layir	ng of foundation			
	(i)	Raft	Reinforcement- Shuttering- Concreting-	100%	
	(ii)	Pile		100%	
3.	Num	ber of basement(s)1			
	(i)	Basement Level 1	01 number of	100 %	
	(ii)	Basement level 2*	NA	NA	
4.	4.470.04	rproofing of the above sub- ture (wherever applicable)		0%	
	Supe	er-Structure Status			
5.	Total	floors in the tower/ building	18		
6.	Total	area on each floor	564.374 Sqm		
7.	Stilt f	loor/ ground floor	01 number of Stilt	100%	
8.	Statu	s of laying of slabs floor wise			
	build	ulative number of slabs in the ing/tower B4 laid and of quarter	18/18	100%	
9.	Statu	s of construction			
	(i)	Walls on floors	18/18	100%	
	(ii)	Staircase	18/18	100%	
	(iii)	Lift wells along with water proofing	18/18	100%	
	(iv)	Lift lobbies/ common areas floor wise	18/18	100%	
10.		g of door and window frames its/units	18/18	100%	

11.	Statu	s of MEP	Internal (within	External works	Internal (within	External works
		•	Flat)	0.000-0.000	Flat)	
	(i)	Mechanical works	NA	NA	NA	NA
	(ii)	Electrical works including	18/18	18/18	100%	100%
	(iii)	Plumbing works	18/18	18/18	100%	100%
12.	Statu	s of wall finishing (Plaster/				
	paint/whitewashing/coating)					
	(i)	External plaster	18/18		100 %	
	(ii)	Internal plaster	18/18		100%	
13.	Statu	s of wall tiling				
	(i)	Inbathroom	18/18		100 %	
	(ii)	Inkitchen	18/18		100%	
14.	Statu	s of flooring				
	(i)	Common areas	18/18		100 %	
	(ii)	Units/ flats	18/18		100 %	
15.	Status of white washing					
	(i)	Internal walls	18/18		100 %	
	(ii)	External walls	18/18		100 %	
16.	Statu	s of finishing				
	(i)	Staircase with railing	18/18		100 %	
	(ii)	Lift wells (Blockwork)	18/18		100 %	
	(iii)	Lift lobbies/ common areas floor wise	18/18		100%	
17.	Statu	s of installation				
	(with	in flat/unit)				
	(i)	Doors and windows panels	18/18		100 %	
	(ii)	Sanitary fixtures	18/18		100%	
	(iii)	Modular kitchen	NA			
	(iv)	Electrical fittings/ lighting	NA			
	(v)	Gas piping (if any)	NA			
	(othe	r than flat/units)				
	(vi)	Lifts installation	2/2		100 %	
	(vii)	Overhead tanks	2/2		100 %	
	(viii)	Underground water tank	NA		(Vil

	(ix)	Firefighting fitting and equipment's as per CFO NOC	18/18	100%
	(x)	Electrical fittings in common	0/18	0 %
	(xi)	Compliance to conditions of environment/CRZ NOC		
18.	Wate	rproofing of terraces	100%	100 %
19.	Entra	ance lobby finishing	0	0 %
20.	Statu wall	s of construction of compound	1875/1875	100%

Table -B

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of Work Done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	88 %	
2.	Parking			
	Covered no. (2619 Nos)	Yes	0 %	
	Open no. (474 Nos)	Yes	0 %	
3.	Water supply	Yes	65 %	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	70 %	
5.	Storm water drains	Yes	64%	
6.	Landscaping & tree plantation	Yes	72 %	
7.	Parks and playgrounds	Yes	58 %	
	Fixing of children play equipment's	Yes	54 %	
	Benches	Yes	50 %	
8.	Shopping area	Yes	30 %	
9.	Street lighting/ electrification	Yes	65 %	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100 %	STP-01
11.	Solid waste management & disposal	Yes	30 %	
12.	Water conservation, rain water,	Yes	68% (Rain Water	68 % of
	harvesting, percolating well/ pit		Harvesting)	Sump 1 to
13.	Energy management (solar)	Yes	30%	
14.	Fire protection and fire safety	Yes	30%	
15.	Electrical meter room, sub-station, receiving station	Yes	30%	
16.	Other (option to add more)			
B-2	Community building to be transferred t	to RWA		(iii

17.	Community centre	Yes	35 %	
18.	Others			
B-3	Community buildings not to b	e transferred to RV	VA/competent au	thority
19.	Schools			
	Primary School	Yes	33.33 %	
	Nursery School 1	Yes	33.33 %	- 1
	Nursery School 2	Yes	33.33 %	
20.	Dispensary	No		
21.	Club	Yes		
22.	Others			
B-4	Services/facilities to be tran	sferred to the Cor	npetent Authori	ity
23.	*			(N:
				12