#### **ARCHITECT'S CERTIFICATE**

To whom so ever it may concern

REPORT FOR QUARTER ENDING 31-Dec-2021	

**Subject:** Certificate of progress of construction work:

Sr. No.	Particulars	Information
i.	Project/Phase of the project	Phase-1
ii.	Location	GH-01, Sec-41, Surajkund Faridabad, Haryana
iii.	Area in acres	1.62 Acres
vi.	HARERA Registration No.	Regd. 326 of 2017 dated 17.10.2017
v.	Name of Licensee	Arihant Infra Realtors Pvt.Ltd.
vi.	Name of Collaborator	N.A
vii.	Name of Developer	Arihant Infra Realtors Pvt.Ltd.

Sir,

1. I/ We have undertaken assignment as architect for certifying progress of construction work in the above mentioned project as per the approved plans.

i.	Date of certifying of percentage of construction work/ site inspection	11-01-2022
ii.	Name of Architect/Architect's firm	M/s Deepak Mehta & Associates
iii.	Date of site inspection	07-01-2022

2. Following technical professionals are appointed by Promoter: - (as applicable)

Sr.No.	Consultants	Name
i.	Site Engineer	Mr. Puran Singh
ii.	Structural Consultant	Mr. Padam Kumar
iii.	Proof Consultant	Mr. Padam Kumar
vi.	MEP Consultant	Mr. Anand Havelia
v.	Site supervisor/incharge	Mr. Puran Singh

3. I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B.

Yours Faithfully,

Signature & Name (IN BLOCK LETTERS) with stamp of Architect

Council of Architects (CoA) Registration No. CA/87//10840/Council of Architects

(CoA) Registration valid till (Date) Dec'2029



## **DEEPAK MEHTA & ASSOCIATES**

### ARCHITECTS, PLANNERS, VALUERS, LAINDISCAPE & INTERIORS

Building/Tower no. A & B (to be prepared separately for each building/tower in the project/phase of the project) Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description done	of work	Percentage proposed w	
A1	SUB- STRUCTURE STATUS				
1.	Excavation	Achieved		100%	
2.	Laying of foundation	Achieved		100%	
	i. Raft	Achieved		100%	
	ii. Pile	N/A		-	
3.	Number of basement(s)1				
	i. Basement level 1	Achi	ieved	100%	
	ii. Basement level 2*	N/	/A		-
4.	Waterproofing of the above sub- structure (wherever applicable)	Achi	ieved	100%	
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building	Tower-A-12floor, B-12 floor		100%	
6.	Total area on each floor	1 <sup>st</sup> Floor-709.77 Sq.Mtr. 2 <sup>nd</sup> Floor-749.07 Sq.Mtr. 3 <sup>rd</sup> to 12 <sup>th</sup> Floor- 703.64 Sq.Mtr.			
7.	Stilt Floor/ Ground Floor	Achieved		100%	
8.	Status of laying of slabs floor wise	Achi	eved	100%	
	Cumulative number of slabs in the building/tower arihant South Winds, Tower A& B laid by end of quarter	Achieved		100%	
9.	Status of construction				
	i. Walls on floors	Achieved		100%	
	ii. Staircase	Achieved		100%	
	iii. Lift wells along with water proofing	Achieved		100%	
	iv. Lift lobbies /common areas floor wise	Achieved		100%	
10.	Fixing of door and window frames in flats/units (UPVC)	Tower A-100%, B-100%		100%	
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	Externa works
	i. Mechanical works				
	ii. Electrical works moluding wiring o	A-100%, B- 100% A-100%, B-	90%	100%	90%
	iii. Plumbing works Plot No. 16 Plot No. 1	A-100%, B- 80%	90%	100%	100%

1/21 324

# **DEEPAK MEHTA & ASSOCIATES**

12.	Status of wall finishing (plaster/paint/ whitewashing/coating)				
	i. External	A-95%, B-90%	93%		
	ii. Internal	A-90%, B-90%	90%		
13.	Status of wall tiling				
	i. In bathroom	A-100%, B-100%	100%		
	ii. In Kitchen	A-100%, B-100%	100%		
14.	Status of flooring				
	i. Common areas	A-100%, B-100%	100%		
	ii. Units/flats	A-100%, B-100%	100%		
15.	Status of other civil works	27			
	i. Staircase with railing	A-98%, B-90%	100%		
	ii. Lift wells	A-100%, B-100%	100%		
	iii. Lift lobbies /common areas floor wise	A-100%, B-95%	100%		
16.	Status of Installation				
	(Within flat/unit)				
	i. Doors and windows panels	A-90%, B-90%	90%		
	ii. Sanitary Fixtures	A-15%, B-0%	7.5%		
	iii. Modular Kitchen	A-5%, B-0%	2.5%		
	iv. Electrical fittings/Lighting	A-10%, B-0%	5%		
	v. Gas piping (if any)	N/A			
	(Other than flat/units)				
	vi. Lifts installation	In Progress	100%		
	vii. Overhead tanks	Structure Done	100%		
	viii. Underground water tank	Structure Done	100%		
	ix. Firefighting fittings and equipment's as per CFO NOC	Sprinkler System in all flats & down cummer in shaft	100%		
	x. Electrical fittings in common areas	Street Light partly Install	100%		
	xi. Compliance to conditions of environment /CRZ NOC	Rain Water Harvesting & STP	100%		
17.	Waterproofing of terraces	A100% & B100%	100%		
18.	Entrance lobby finishing	Tower A-100%, B-100%	100%		
19.	Status of construction of Compound wall	Three side compound wall almost ready	100%		



#### Table – B

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of Work Done	Remarks
	B-1 Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (Chamber, Lines, Septic Tank, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
8.	Shopping Area	No	N.A	
9.	Street Lighting/Electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	90%	
11.	Solid Waste Management & disposal	Yes	90%	
12.	Water Conservation, Rain Water Harvesting, Percolating Well/Pit	Yes	100%	
13.	Energy management (Solar)	Yes	90%	
14.	Fire Protection and Fire Safety Requirements	Yes	100%	
15.	Electrical meter room, Sub-Station, Receiving station	Yes	100%	
16.	Other (option to add more)			(AS
B-2	Community building to be transferred to RWA			CON87/108 Plot No. 10
17.	Community centre (Civil & POP Done), Flooring In Progress+ Wood work in progress		100%	Abhishea SC Mayur Ph-II, Dethi
10	0.1	1 .		10

Second Floor, Plot No. 16, Abhishek Plaza, Local Shopping Center, Mayur Vihar Phase - II, Delhi - 110 091, India
Telephone: 91 - 11 - 6527 2180, 2277 0180, E-mail: deepakmehta1962@gmail.com

Website: www.indianarchitect.co.in

DEEPAK MEHTA & ASSOCIATES Community buildings not to be transferred to RWA/Competen Authority PRS, LANDSCAPE & INTERIORS N/A N/A N/A 19. Schools N/A N/A N/A 20. Dispensary N/A N/A N/A 21. Club N/A N/A N/A 22. Others N/A N/A N/A B-4 Services /facilities to be transferred to the **Competent Authority** \* 23.

M/s Deepak Mehta & Associates

ishek Plaza Mayur Vihat

Deepal Mohta Delhi-91
(Architect)