Ar. Vinemra Goyal
Architect, Engineer, Interior Designer & Valuers
Office no. 313, 2nd Floor, AKD Tower, Old Delhi Road Gurgaon-122001
Mob: -9654091685 Email: - vinemra.goyal@gmail.com

### Annexure A

			Annexure A		
		Architect	t's Certificate <sup>*</sup>		
Report for quarter ending			30.09.2025		
Subject			Certificate of progress of construction work		
1.		ave undertaken assignment as archimentioned project as per the approve	itect for certifying progress of construction work in the ed plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	SS HIGH POINT		
	2.	Location	Vill- Badha, Sector-86, Tehsil-Manesar, Gurugram		
	3.	Licensed area in acres	2.80625		
	4.	Area for registration in acres	2.80625		
	5.	HARERA registration No.	36 of 2019		
	6. Name of licensee		Shiva Profins Pvt. Ltd., Matrix Buildwell Pvt. Ltd.		
			North Star Towers Pvt. Ltd.		
	7.	Name of collaborator	SS Group Pvt. Ltd.		
	8.	Name of developer	SS Group Pvt. Ltd.		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	04.10.2025		
	2.	Name of Architect/ Architect's firm	Ar. Vinemra Goyal		
	3.	Date of site inspection	03.10.2025		
3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr.	Consultants	Name		
	1.	Site engineer	Saurabh Joshi		
	2.	Structural consultant	DESMAN		
	3. Proof consultant		Arvind Gupta		
	4.	MEP consultant	ASHOK GANGWAR (ARK Consultants)		
85	5.	Site supervisor/in charge	Dev Kumar Dutta		

# Ar. Vinemra Goyal

## Architect, Engineer, Interior Designer & Valuers

Office no. 313, 2nd Floor, AKD Tower, Old Delhi Road Gurgaon-122001 Mob: -9654091685

Email: - vinemra.goyal@gmail.com

- 4. I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
- I also certify that as on the date, the percentage of work done in the project for each of the building/ tower 5. of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Yours Faithfully

Signature & Name (in block letters)

With stamp of Architect

**VINEMRA GOYAL** CA/2019-114662 Off. No. 313, AKD Tower, Sec.-14,

Gurugram, Haryana

Date 04/10/2025

Place Guzugram

Council of Architects (CoA): OA 2019/114662

Registration No.

Council of Architects (CoA): 31, Dec. 2031 Registration valid till (Date)

			TABLE-A				
Buildi	ng No/Tov	ver No.	SS HIGH POINT				
A1		Progress of the Project/Ph		ıarter			
Sr.No	Project Cor		Work done value during the Quarter ( In Lakh)			Percentage done to the proposed w	total
1	Sub Structi	ıre	0.00	68:	1.11	9.9	1%
2	Super Stru	cture	144.33	192	4.44	28.0	00%
3	MEP						
	3.1	Mechanical Work	0.00	386	5.61	5.6	3%
	3.2	Electrical Work	0.00	51!	5.48	7.5	0%
	3.3	Plumbing & Fire Fighting Work	0.00	360	0.83	5.2	5%
4	FINISHING						
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0.00	930.69		13.54%	
	4.2	External ( Plaster, Painting, Façade etc.)	0.00	494	1.86	7.2	0%
Sr.No.		Tasks/ Activity	1	Description of Work Done		Percentage of total proposed work	
	Sub-Structu	ire Status			30000000000000		
1	Excavation			Complete		0.2	0%
2	Laying of Foundation			,			
	(i)	Raft		Complete		5.90%	
3	Number of	Basements		Complete Complete			
	(i)	Basement Level-1				1.20%	
	(ii)	Basement Level-2				1.20%	
	(iii)	Basement Level-3		Com	plete	1.2	0%
4	Water Proo applicable)	fing of the Above Sub-Struc	ture ( wherever	In Progress		0.21%	
	Super-Strue	cture Status					
5	Total Floors	in the Tower/ Building		G+18			
6		on each floor ( Sq.Mtr.)		2760	0.368		
	Stilt / Groun			4964.783			
8		ying of slabs floor wise number of the slabs in the	Building Laid by end of	3		28.0%	
9	Status of Construction						
	(i)	Walls on floors		In Progress		28.00%	
Ī	(ii)	Staircase		In Pro	gress	28.0	00%
	(iii)	Liftwells along with water	oroofing	In Progress		28.00%	
	(iv) Lift Lobbies/Common areas floor wise			In Progress		28.00%	
_		or & window frames in the	Units	In Progress		13.54%	
11	Status of M	EP		Internal ( with in Flat)	External Work	Internal ( with in Flat)	External Work
[	(i)	Mechanical Work			gress 🛕	5.6	
	(ii) Electrical work including wiring			In Progress 7.50%			

AR. VINEMRA GOYAL CA/2019-114662 Off. No. 313, AKD Tower, Sec.-14, Gurugram, Haryana

	(iii)	Plumbing & Fire Fighting Work	In Progress	5.25%
12	. ,	Wall Plastering		5.2570
12	(i) External Plaster		In Progress	7.20%
	(ii)	Internal Plaster	In Progress	13.54%
13	Status of \		1111081033	1010 170
10	(i)	In Toilets	In Progress	13.54%
14	Status of Flooring			
	(i) Common Areas		In Progress	13.54%
	(ii)	Units/Flats	In Progress	13.54%
15	` '	White Washing		
13	(i)	Internal Walls	In Progress	7.20%
	(ii)	External Walls	In Progress	7.20%
16	. ,		III TOGICSS	712070
10	(i) Staircase with Railing		In Progress	13.54%
	(ii)	Lift Wells	In Progress	13.54%
	(iii)	Lift Lobbies/Common areas floor wise	In Progress	13.54%
17	Status of i		mi rogress	13.3 170
1,	( within Flats/ Units)			
	(i)	Doors & Windows Panels	NA	NA
	(ii)	Sanitary Fixtures	NA NA	NA
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA NA	NA
	(v)	Gas Piping ( if any)	NA	NA
		nn Flats/ Units)		
	(vi)	Lift Installations	In Progress	6%
	(vii)	Over Head Tanks	In Progress	28.0%
	(viii)	Under Ground Water Tanks	In Progress	9.91%
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	In Progress	5.25%
	(x)	Electrical Fittings in Common Areas	In Progress	7.50%
	(xi)	Compliance to condition of environment/CRZ NOC	NA	NA
18		ofing of Terraces	In Progress	0%
19		obby Finishing	In Progress	13.54%
20		onstruction of Compound wall	Nil	0%



TABLE-B ( SSH)						
Sr.No	Common Areas and Facilities	Proposed	Percentage of work	Remarks		
	Amenities	( Yes/No)	done			
B-1	Services					
1	Internal Roads & Pavements	Yes	60%			
2	Parkings	Yes				
	Covered	Yes	50%			
	Open NoS	NA	NA	9		
3	Water Supply	Yes	40%			
4	Sewarage( Chambers,Lines,STP,Septic Tanks)	Yes	55%			
5	Storm Water Drains	Yes	60%			
6	Landscaping & Tree Plantations	Yes	30%			
7	Parks & Playgrounds	NA	NA			
8	Shopping Areas	NA	NA			
9	Street Lighting/Electrification	Yes	70%			
10	Treatment & Disposal of Sewage & Sludge water/STP	Yes	90%			
11	Solid waste Management & Disposal	NA	NA			
12	Rain water Harvesting	Yes	70%			
13	Energy Management ( Solar)	Yes	0%			
14	Fire Protection & Fire safety Equipments	Yes	5%			
15	Electrical Meter Room,Sub- Station,Receiving Station	Yes	20%			
16	Under Ground Water Tank	Yes	100%			
B-2	Community Building to be Transferred to RWA					
17	Community Center	NA	NA			
18	Others.	NA	NA			
B-2	Community Building not to be Transferred to RWA/Competent Authority					
19	School	NA	NA			
20	Milk Booth	NA	NA			
21	Club/Community Building	NA	NA			

AR. VINEMRA GOYAL CA/2019-114662 Off. No. 313, AKD Tower, Sec.-14, Gurugram, Haryana