



ANNEXURE 6-A ARCHITECT'S CERTIFICATE
On the letter head of the architect firm
To whom so ever it may concern

REPORT FOR QUARTER ENDING		Jan'25 TO March'25
----------------------------------	--	--------------------

Subject: Certificate of progress of construction work:

Sr. No.	Particulars	Information
i.	Project/Phase of the project	La- Regencia Phase-II
ii.	Location	Sec.-19 Sushant City Panipat
iii.	Area in acres	4.367
vi.	HARERA Registration No.	HRERA-PKL-PNP-46-2018
v.	Name of Licensee	Stanza Developers And Infrastructure Pvt. Ltd.
vi.	Name of Collaborator	
vii.	Name of Developer	M/s Astrum Value homes Pvt. Ltd.

Sir,

1. I/ We have undertaken assignment as architect for certifying progress of construction work in the above mentioned project as per the approved plans.

i.	Date of certifying of percentage of construction work/ site inspection	12.04.2025
ii.	Name of Architect/Architect's firm	Nitin Chauhan/ Urban Atelier
iii.	Date of site inspection	04-04-2025

2. Following technical professionals are appointed by Promoter: - (as applicable)

Sr.No.	Consultants	Name
i.	Site Engineer	Mr. Akhilesh
ii.	Structural Consultant	M/s N.M. Roof Designers Ltd.
iii.	Proof Consultant	M/s. Roark Consulting Engineers
vi.	MEP Consultant	M/s Acrobat Engineers Pvt. Ltd.
v.	Site supervisor/in charge	Mr. Ashwani Kumar Sinha

3. I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B.

Yours Faithfully,

Signature & Name (IN BLOCK LETTERS) with stamp of Architect : NITIN CHAUHAN

Council of Architects (CoA) Registration No. CA/ 2012 / 55425 Council of Architects (CoA) Registration valid till -31/12/2028



Table – A

Building/Tower no. Tower-D2 or called Emerald
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work Upto March'25.	
A1	SUB- STRUCTURE STATUS			
1.	Excavation		100%	
2.	Laying of foundation			
	i. Raft		100%	
	ii. Pile		NA	
3.	Number of basement(s)			
	i. Basement level 1		NA	
	ii. Basement level 2*		NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		100%	
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building		S+9	
6.	Total area on each floor	SQ. Ft.	7244	
7.	Stilt Floor/ Ground Floor		7244	
8.	Status of laying of slabs floor wise			
	Cumulative number of slabs in the building/tower	laid by end of quarter	100%	
9.	Status of construction			
	i. Walls on floors		100%	
	ii. Staircase		100%	
	iii. Lift wells along with water proofing		100%	
	iv. Lift lobbies /common areas floor wise		100%	
10.	Fixing of door and window frames in flats/units		100%	
11.	Status of MEP		Internal (within Flat)	External works
	i. Mechanical works		NA	NA
	ii. Electrical works including wiring		100%	100%
	iii. Plumbing works		100%	100%
12.	Status of wall finishing (plaster/paint/ whitewashing/coating)			
	i. External		NA	100%
	ii. Internal		100%	NA
13.	Status of wall tiling			
	i. In bathroom		100%	NA
	ii. In Kitchen		100%	NA
14.	Status of flooring			
	i. Common areas		NA	100%
	ii. Units/flats		100%	NA
15.	Status of other civil works			
	i. Staircase with railing		NA	100%
	ii. Lift wells		NA	100%
	iii. Lift lobbies /common areas floor wise		NA	100%



16.	Status of Installation (Within flat/unit)			
i.	Doors and windows panels		100%	NA
ii.	Sanitary Fixtures		100%	NA
iii.	Modular Kitchen		NA	NA
iv.	Electrical fittings/Lighting		NA	100%
v.	Gas piping (if any)		NA	NA
(Other than flat/units)				
vi.	Lifts installation		NA	100%
vii.	Overhead tanks		NA	100%
viii.	Underground water tank		NA	99%
ix.	Firefighting fittings and equipment's as per CFO NOC		NA	100%
x.	Electrical fittings in common areas		NA	100%
xi.	Compliance to conditions of environment /CRZ NOC			
17.	Waterproofing of terraces		NA	100%
18.	Entrance lobby finishing		NA	100%
19.	Status of construction of Compound wall		NA	100%

Note.— (*) Extend rows as per requirement



Table – A

Building/Tower no. E or called Florence

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work Upto March'25.	
A1	SUB- STRUCTURE STATUS			
1.	Excavation		100%	
2.	Laying of foundation		100%	
	i. Raft		NA	
	ii. Pile		NA	
3.	Number of basement(s)			
	i. Basement level 1		NA	
	ii. Basement level 2*		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		100%	
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building		S+9	
6.	Total area on each floor	SQ. Ft.	7980	
7.	Stilt Floor/ Ground Floor		7980	
8.	Status of laying of slabs floor wise Cumulative number of slabs in the building/tower laid by end of quarter		100%	
9.	Status of construction i. Walls on floors		100%	
	ii. Staircase		100%	
	iii. Lift wells along with water proofing		100%	
	iv. Lift lobbies /common areas floor wise		100%	
10.	Fixing of door and window frames in flats/units		100%	
11.	Status of MEP	Internal (within Flat)	External works	
	i. Mechanical works	NA	NA	
	ii. Electrical works including wiring	100%	100%	
	iii. Plumbing works	100%	100%	
12.	Status of wall finishing (plaster/paint/ whitewashing/coating)			
	i. External	NA	100%	
	ii. Internal	100%	NA	



13.	Status of wall tiling			
	i. In bathroom		100%	NA
	ii. In Kitchen		100%	NA
14.	Status of flooring			
	i. Common areas		NA	100%
	ii. Units/flats		100%	NA
15.	Status of other civil works			
	i. Staircase with railing		NA	100%
	ii. Lift wells		NA	100%
	iii. Lift lobbies /common areas floor wise		NA	100%
16.	Status of Installation (Within flat/unit)			
	i. Doors and windows panels		100%	NA
	ii. Sanitary Fixtures		NA	100%
	iii. Modular Kitchen		NA	NA
	iv. Electrical fittings/Lighting		NA	100%
	v. Gas piping (if any)		NA	NA
	(Other than flat/units)			
	vi. Lifts installation		NA	100%
	vii. Overhead tanks		NA	100%
	viii. Underground water tank		NA	100%
	ix. Firefighting fittings and equipment's as per CFO NOC		NA	100%
	x. Electrical fittings in common areas		NA	100%
	xi. Compliance to conditions of environment /CRZ NOC			
17.	Waterproofing of terraces		NA	100%
18.	Entrance lobby finishing		NA	100%
19.	Status of construction of Compound wall		NA	100%

Note.—(*) Extend rows as per requirement






Table – A

Building/Tower no. D1 or called Galleon

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work Upto March'25.	
A1	SUB- STRUCTURE STATUS			
1.	Excavation		100%	
2.	Laying of foundation			
	i. Raft		100%	
	ii. Pile		NA	
3.	Number of basement(s)			
	i. Basement level 1		NA	
	ii. Basement level 2*		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		100%	
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building		S+9	
6.	Total area on each floor	SQ. Ft.	7244	
7.	Stilt Floor/ Ground Floor		7244	
8.	Status of laying of slabs floor wise Cumulative number of slabs in the building/tower laid by end of quarter		100%	
9.	Status of construction i. Walls on floors		100%	
	ii. Staircase		100%	
	iii. Lift wells along with water proofing		100%	
	iv. Lift lobbies /common areas floor wise		100%	
10.	Fixing of door and window frames in flats/units		100%	
11.	Status of MEP		Internal (within Flat)	External works
	i. Mechanical works		NA	NA
	ii. Electrical works including wiring		100%	100%
	iii. Plumbing works		100%	100%
12.	Status of wall finishing (plaster/paint/ whitewashing/coating)			
	i. External	NA	92%	
	ii. Internal	100%		Nitin Chauhan CA/2012/55425





13.	Status of wall tiling		100%	NA
14.	Status of flooring		NA	100%
15.	Status of other civil works		100%	NA
16.	Status of Installation (Within flat/unit)		NA	100%
	(Other than flat/units)		NA	100%
17.	Waterproofing of terraces		NA	100%
18.	Entrance lobby finishing		NA	100%
19.	Status of construction of Compound wall		NA	100%

Note.—(*) Extend rows as per requirement





Table – A

Building/Tower no. A1 or called Hamilton

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work Upto March'25.	
A1	SUB- STRUCTURE STATUS			
1.	Excavation		100%	
2.	Laying of foundation			
	i. Raft		100%	
	ii. Pile		NA	
3.	Number of basement(s)			
	i. Basement level 1		NA	
	ii. Basement level 2*		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		100%	
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building		S+9	
6.	Total area on each floor	SQ. Ft.	7244	
7.	Stilt Floor/ Ground Floor		7244	
8.	Status of laying of slabs floor wise Cumulative number of slabs in the building/tower laid by end of quarter		100%	
9.	Status of construction i. Walls on floors ii. Staircase iii. Lift wells along with water proofing iv. Lift lobbies /common areas floor wise		100%	
10.	Fixing of door and window frames in flats/units		100%	
11.	Status of MEP i. Mechanical works ii. Electrical works including wiring iii. Plumbing works		Internal (within Flat)	External works
	i. Mechanical works		NA	NA
	ii. Electrical works including wiring		100%	100%
	iii. Plumbing works		100%	100%
12.	Status of wall finishing (plaster/paint/ whitewashing/coating) i. External ii. Internal		NA	99%
13.	Status of wall tiling i. In bathroom ii. In Kitchen		99%	NA
	i. In bathroom		100%	NA
	ii. In Kitchen		100%	NA





14.	Status of flooring		NA	100%
	i. Common areas			
15.	Status of other civil works		NA	1000%
	i. Staircase with railing			
16.	Status of Installation (Within flat/unit)		NA	100%
	i. Doors and windows panels			
17.	ii. Sanitary Fixtures		NA	99%
	iii. Modular Kitchen			
18.	iv. Electrical fittings/Lighting		NA	100%
	v. Gas piping (if any)			
19.	(Other than flat/units)		NA	NA
	vi. Lifts installation			
17.	vii. Overhead tanks		NA	100%
	viii. Underground water tank			
18.	ix. Firefighting fittings and equipment's as per CFO NOC		NA	99%
	x. Electrical fittings in common areas			
19.	xi. Compliance to conditions of environment /CRZ NOC		NA	100%
	Waterproofing of terraces			
18.	Entrance lobby finishing		NA	100%
19.	Status of construction of Compound wall		NA	100%

Note.— (*) Extend rows as per requirement





Table – A

Building/Tower no. F or called Irvine

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description of work done	Percentage of total proposed work Upto March'25.	
A1	SUB- STRUCTURE STATUS			
1.	Excavation		100%	
2.	Laying of foundation			
	i. Raft		100%	
	ii. Pile		NA	
3.	Number of basement(s)			
	i. Basement level 1		NA	
	ii. Basement level 2*		NA	
4.	Waterproofing of the above sub- structure (wherever applicable)		100%	
A2	SUPER- STRUCTURE STATUS			
5.	Total floors in the tower/building		S+10	
6.	Total area on each floor	SQ. Ft.	9752	
7.	Stilt Floor/ Ground Floor		9752	
8.	Status of laying of slabs floor wise Cumulative number of slabs in the building/tower laid by end of quarter		100%	
9.	Status of construction i. Walls on floors		100%	
	ii. Staircase		100%	
	iii. Lift wells along with water proofing		100%	
	iv. Lift lobbies /common areas floor wise		100%	
10.	Fixing of door and window frames in flats/units		100%	
11.	Status of MEP		Internal (within Flat)	External works
	i. Mechanical works		NA	NA
	ii. Electrical works including wiring		93%	100%
	iii. Plumbing works		100%	100%
12.	Status of wall finishing (plaster/paint/ whitewashing/coating)			
	i. External		NA	65%
	ii. Internal		93%	NA

* Nitin Chauhan
CA/2012/552

13.	Status of wall tiling		100%	NA		
	i. In bathroom					
14.	Status of flooring		NA	100%		
	i. Common areas					
15.	Status of other civil works		100%	NA		
	i. Staircase with railing					
	ii. Lift wells					
16.	iii. Lift lobbies /common areas floor wise		NA	100%		
	Status of Installation (Within flat/unit)					
	i. Doors and windows panels					
	ii. Sanitary Fixtures					
	iii. Modular Kitchen					
	iv. Electrical fittings/Lighting					
	v. Gas piping (if any)					
	(Other than flat/units)					
	vi. Lifts installation					
	vii. Overhead tanks					
	viii. Underground water tank					
	ix. Firefighting fittings and equipment's as per CFO NOC					
17.	x. Electrical fittings in common areas		NA	90%		
	xi. Compliance to conditions of environment /CRZ NOC					
17.	Waterproofing of terraces		NA	100%		
18.	Entrance lobby finishing		NA	99%		
19.	Status of construction of Compound wall		NA	100%		
Note.—(*) Extend rows as per requirement						

