

### ARCHITECTS & ENGINEER'S

Annexure A

		Architect'	s Certificate*			
Report	for quart	ter ending	30 <sup>th</sup> June- 2025			
Subject	t		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 10241.29 sq mtr , Commercial Cum Residential Colony, SCO Phase 3			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	11.49375 acres			
	4.	Area for registration in acres	2.53 acres			
	5.	HARERA registration no.	117 of 2017			
	6.	Name of licensee	Omaxe World Street Pvt. Ltd			
	7.	Name of collaborator				
	8.	Name of developer	Omaxe World Street Pvt. Ltd			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	04.07.2025			
	2.	Name of Architect/ Architect's firm	ABMS Design Associates			
	3.	Date of site inspection	02.07.2025			
		The state of the s	1.19.5 1.19			





#### ARCHITECTS & ENGINEER'S

	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
	3.	Proof consultant			
	4.	MEP consultant	Mr, Digambar Singh		
	5.	Site incharge	Mr. D.C Pant		
4.	Haryar constru envisas	na Building Code, 2017/ National action, infrastructure works and i	ted as per approved drawings, statutory/ mandatory approvals, Building Code (wherever applicable) and the material used in the nternal development works are as per the projected standard as ture, publication material and other documents shared with the		
5.	of the below.	real estate project/phase of the pr	entage of work done in the project for each of the building/ tower oject under HARERA is as per table A and table B given herein ecuted with respect to each of the activity of the entire project/		

Date: 04.07.2025

Yours faithfully,

Place

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date) Read Architect 8



### ARCHITECTS & ENGINEER'S

		161 15	Table – A		
(to be	prepar	ed separately for each building/ tower // phase of the project)			
A1	Cum	ulative progress of the project/phase a	rter.	11	
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)		- , , , , ,	2 Cr	100%
2.	Super structure (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	6.00 CR	100%
3.	MEP			10	
	3.1	Mechanical (lifts, ventilation, etc.)	- ,	70 F 20 F	* * * * * * * * * * * * * * * * * * * *
	3.2	Electrical (conduiting, wiring, fixtures, etc.)		2.90 Cr.	96%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	gentorea es	3.12 Cr.	96%
4.	Finishing				* Hara'
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.10	7.50 Cr.	97%
	4.2	External (plaster, painting, facade, etc.)	0.10	7.20 Cr.	97%

APURBA BORAH Regd. Architect CA/2013/61618



### ARCHITECTS & ENGINEER'S

Sr.	Tasks/ Activity		Description of work done		Percentage of total		
No.		Sub-Structure Status	Sub-Structure Status  Completed		proposed work		
1.	Excav	ration	Completed		100%		
2.	Layin	g of foundation					
	(i) Raft		Comp	Completed		100%	
	(ii)	) Pile N/A		'A	N/A		
3.	Numb	per of basement(s) 1					
	(i) Basement Level 1		Comp	oleted	100	9%	
	(ii) Basement level 2*		-		-	-	
4.		rproofing of the above sub-structure ever applicable)	-		-		
	Super-Structure Status		,				
5.	Total	floors in the tower/ building	3	3	100	)%	
6.	Total	area on each floor	27545	5 SFT			
7.	Stilt f	loor/ ground floor	27545	5 SFT			
8.	Status	s of laying of slabs floor wise	comp	oleted	100	)%	
		llative number of slabs in the building/	3				
9.	Status	s of construction				-	
	(i)	Walls on floors	-		100%		
	(ii)	Staircase	-		100%		
	(iii)	Lift wells along with water proofing	Langer of the selection of		a publicant		
	(iv)	Lift lobbies/ common areas floor wise	and the second s				
10.	Fixin units	g of door and window frames in flats/			guls	atat it in it.	
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works		100000 1000	L. Waren		
	(ii)	Electrical works including wiring	WIP		96	5%	
	(iii)	Plumbing works	-				
12.	Statu	s of wall plastering					
	(i)	External plaster	WIP		100%		
	(ii)	Internal plaster	WIP		10	0%	
13.	Statu	s of wall tiling					
	(i) In bathroom		-			- 6	
	(ii)	In kitchen	- /		1 mis	BORIE	
14.	Statu	is of flooring			D IR	EL MCHON	
	(i) FI	In kitchen as of flooring Common areas AT NO. 3A, HIWIGIRI APARTMENTS, POC Units/ flats	CKET-14, KALKA	AOIZNATXA I	I, NEW DELAT	10017	



### ARCHITECTS & ENGINEER'S

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total	
			done	proposed work	
15.	Status of white washing				
	(i)	Internal walls	-		
	(ii)	External walls	-		
16.	Status of finishing				
	(i)	Staircase with railing	-	*	
	(ii)	Lift wells			
	(iii)	Lift lobbies/ common areas floor wise	-		
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels		-	
	(ii)	Sanitary fixtures	-	-	
	(iii)	Modular kitchen	-	-	
	(iv)	Electrical fittings/ lighting	-	-	
	(v)	Gas piping (if any)	-	-	
	(other	than flat/units)		-	
	(vi)	Lifts installation	- maple just an	and the same of the same	
	(vii)	Overhead tanks	100	100%	
	(viii)	Underground water tank	dangga sa a <del>t</del> y ferogras s	Mara I sanga and I	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	100	100%	
	(x)	Electrical fittings in common areas	I DE LOS DE L'EU ET SE MESE		
	(xi)	Compliance to conditions of environment/ CRZ NOC		and a	
18.	Water	rproofing of terraces	Traksodius tas	signes ARM	
19.	Entra	nce lobby finishing	-	al mir?	
20.	Status	s of construction of compound wall	-	[additional red]	

Note: (\*) extend rows as per requirement.





#### ARCHITECTS & ENGINEER'S

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	YES	100%	
2.	Parking			
	Covered no	NO	0%	
	Open no	YES	100%	
3.	Water supply	YES	95%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	95%	
5.	Storm water drains	YES	95%	
6.	Landscaping & tree plantation	YES	95%	
7.	Parks and playgrounds	N/A		
	Fixing of children play equipment's	N/A		
	Benches	N/A		
8.	Shopping area	YES	95%	
9.	Street lighting/ electrification	YES	95%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	95%	
11.	Solid waste management & disposal	N/A		
12.	Water conservation, rain water, harvesting, percolating well/ pit	-		
13.	Energy management (solar)	-		
14.	Fire protection and fire safety requirements	-	e 10000 - 1	
15.	Electrical meter room, sub-station, receiving station	- 1500		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community centre	-		
18.	Others	-		
В-3	Community buildings not to be transferred to RWA/competent authority		A Charley I. L. Chingson pl	
19.	Schools	-	a pristancia contra con	1907
20.	Dispensary	-		
21.	Club	-		
22.	Others	-	ACTION OF STREET	
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

