

ARCHITECTS & ENGINEER'S

Annexure A

		Architect'	s Certificate*			
Report	for quar	rter ending	30 th June- 2025			
Subject			Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 8093.7 sq mtr , Commercial Cum Residential Colony			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	11.49375 acres			
	4.	Area for registration in acres	1.99 acres			
	5.	HARERA registration no.	111 of 2017			
	6.	Name of licensee	Omaxe World Street Pvt. Ltd			
	7.	Name of collaborator				
	8.	Name of developer	Omaxe World Street Pvt. Ltd			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	04.07.2025			
	2.	Name of Architect/ Architect's firm	ABMS Design Associates			
	3.	Date of site inspection	02.07.2025			





ARCHITECTS & ENGINEER'S

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. Consultants		Name			
	1.	Site engineer	Mr. D.C Pant			
	2.	Structural consultant	Mr. Pankaj Varshney			
	3.	Proof consultant				
	4.	MEP consultant	Mr. Digambar Singh			
	5.	Site incharge	Mr. D.C Pant			
4.	Haryar constru envisa	na Building Code, 2017/ Nationa action, infrastructure works and	euted as per approved drawings, statutory/ mandatory approvals. I Building Code (wherever applicable) and the material used in the internal development works are as per the projected standard as are, publication material and other documents shared with the buyers			
5.	of the below.	real estate project/phase of the p	recentage of work done in the project for each of the building/ tower project under HARERA is as per table A and table B given herein cuted with respect to each of the activity of the entire project/ phase			

Date: 04.07.2025

:

Yours faithfully,

Place

.

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no.

: CA/2013/61618

Council of architects (CoA) registration valid till (date)

APUREA BORAH CA/2013/61618



ARCHITECTS & ENGINEER'S

			Table – A		
(to be	prepar	ed separately for each building/ tower // phase of the project)			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	15.94 CR	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		1.90	35.77 Cr	93%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0	0	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.07	2.07	35%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	1.94	56%
4.	Finishing		23, 1° - m		
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.10	0.50 Cr.	11%
	4.2	External (plaster, painting, facade, etc.)	0.10	0.97 Cr.	60%





Sr. No.	Tasks/ Activity Sub-Structure Status Excavation		Description of work done Completed		Percentage of total		
1							
1.			Comp	leted	100	70	
2.	Laying of foundation		Comp	Completed		100%	
	(i)	Raft					
	(ii)	Pile	N/.	A	N/A	4	
3.	Number of basement(s)						
	(i)	Basement Level 1	Completed		100		
	(ii)	Basement level 2*	Completed		100%		
	(iii)	Basement Level 3	Comp	Completed		100%	
	(iv)	Basement Level 4	Comp	leted	100	%	
4.		rproofing of the above sub-structure rever applicable)					
		Super-Structure Status					
5.	Total	floors in the tower/ building	4		85	0%	
6.	Total	area on each floor	120	000	-		
7.	Stilt f	loor/ ground floor	636	500	-		
8.	Status of laying of slabs floor wise		3.	3.5		85%	
		ulative number of slabs in the building/	Cumulative nu slabs=4/ End o		85%		
9.	Statu	s of construction	6.7			- ,	
	(i)	Walls on floors	- 15,000 - 101,11 p. 11		gamini ang -		
	(ii)	Staircase	-		Structure & Brick Work -859		
	(iii)	Lift wells along with water proofing	Transfer to the contract of		90%		
	(iv)	Lift lobbies/ common areas floor wise		-		Structure Work 85%	
10.	Fixin units	g of door and window frames in flats/		artification of the control of the c		Marin	
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	11/10/2012 12:		0%		
	(ii)	Electrical works including wiring		-	35%	T C	
	(iii)	Plumbing works	1 12	a official com-	56%		
12.	Statu	s of wall plastering					
	(i)	External plaster	-		50%		
	(ii)	Internal plaster		-	10%		
13.	- '	s of wall tiling		V - A1	· ·		
	(i)	In bathroom	June	- A BORK	0%		
	(ii)	In kitchen	RET-14. KALKAJI EXTENSION.		0%		
14.	-	as of flooring	PIR	89120131			
17,		AT NO. 3A, HIMGIRI APARTMENTS, POC	KET-14, KALKA	II EXTENSION	, NEW DELHI-1	10017	
	(ii)	Units/ flats		-	0%		



ARCHITECTS & ENGINEER'S

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total
No.			done	proposed work
15.	Status	of white washing		
	(i)	Internal walls	-	0%
	(ii)	External walls	-	10%
16.	Status of finishing			
	(i)	Staircase with railing	-	0%
	(ii)	Lift wells	-	0%
	(iii)	Lift lobbies/ common areas floor wise		0%
17.	Status	of installation		
	(within	n flat/unit)		
	(i)	Doors and windows panels	-	0%
	(ii)	Sanitary fixtures	- L- 180 - L	0%
	(iii)	Modular kitchen	-	0%
	(iv)	Electrical fittings/ lighting	-	0%
	(v)	Gas piping (if any)	-	0%
	(other	than flat/units)		
	(vi)	Lifts installation	- 1	0%
	(vii)	Overhead tanks	2	0%
	(viii)	Underground water tank	- i chily busine	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	a been least to be realized as griffing tom	10%
	(x)	Electrical fittings in common areas	-	50%
	(xi)	Compliance to conditions of environment/ CRZ NOC	volumen ad a top agniblina genodinas ipa	3.40 (mm.) 3.40 (1.4 (1.7 (m.))
18.	Water	proofing of terraces		0%
19.	Entrai	nce lobby finishing	-	0%
20.	Status	s of construction of compound wall	_	0%

Note: (*) extend rows as per requirement.





ARCHITECTS & ENGINEER'S

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements		0%	
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	85%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	85%	
5.	Storm water drains	YES	85%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	-		
	Fixing of children play equipment's	-		
	Benches	-		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	100%	
11.	Solid waste management & disposal	-		
12.	Water conservation, rain water, harvesting, percolating well/ pit			
13.	Energy management (solar)	-	1771171171	11714
14.	Fire protection and fire safety requirements	-	for Arabin Ba	
15.	Electrical meter room, sub-station, receiving station	-	50%	
16.	Other (option to add more)	- 1.	(LINE TO BOOK DOLLAR)	41111
B-2	Community building to be transferred to RWA	Charles of part of the	caretti şeləfeliə. 1	
17.	Community center	-	70.05 0/17.195	
18.	Others	control and	diagnost last suid-	Tall in
B-3	Community buildings not to be transferred to RWA/competent authority	eretitin u.v.	c Shiralgari'i	1921
19.	Schools	-		
20.	Dispensary	-		
21.	Club	-		761
22.	Others	1 00-00	· · · b. Br [r] · s · r · · · H. ·	1416 0
B-4	Services/ facilities to be transferred to competent authority	N1:		I II I
23.	*			

Note: (*) extend as per requirement

