
Architect's Certificate ¹						
Repor	rt for qı	uarter ending	31/12/2021			
Subje	ct	U	Certificate of progress of construction work			
1.		<u> </u>	nt as architect for certifying progress of ntioned project as per the approved plans			
	Sr. Particulars No.		Information			
	1.	Project/Phase of the project	Conscient One			
	2.	Location	Sector-109, Gurugram, Haryana			
	3.	Licensed area in acres	8.393 Acres			
	4.	Area for registration in acres	3.138 Acres			
	5.	HARERA registration no.	RC/REP/HARERA/GGM/308/40/2019/02 /Dated-16-01-2019			
	6.	Name of licensee	M/S Shrimaya Buildcon Pvt. Ltd. And Others			
	7.	Name of collaborator	M/S Shrimaya Buildcon Pvt. Ltd.			
	8.	Name of developer	Conscient Infrastructure Private Limited			
2. Details related to		ls related to inspection are as	under			
	1.	Date of certifying of percentage of construction work/ site inspection	31/12/2021			
	2.	Name of Architect/ Architect's firm	Ashwin Alva Associates			
	3.	Date of site inspection	30/12/2021			

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in



3.	Follov	wing technical professionals a	re appointed by promoter: - (as applicable)
	Sr. No.	Consultants	Name
	1.	Site engineer	Sharad Chandra
	2.	Structural consultant	Civtech Consultant Pvt. Ltd.
	3.	Proof consultant	Mehro Consultants
	4.	MEP consultant	Plumbing & Fire Fighting- Soni Consultants, Electrical Consultant-Kanwar Krishen Associates Pvt Ltd
	5.	Site supervisor/incharge	Sharad Chandra
4.	mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherev applicable) and the material used in the construction, infrastructure works and intern development works are as per the projected standard as envisaged in the registratic and brochure, publication material and other documents shared with the buyers in the regard.		
5.			

Date : Yours faithfully,

Place Signature & name (in block letters) with stamp of architect

Council of architects (CoA):

registration no.

Council of architects (CoA) : 31-12-2026 registration valid till (date)

SHOBHNA BATRA CA/2005/35496

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

		Ta	able – A						
(to build	be pi	Tower no. repared separately for each tower in the project/ phase of			1 Nos				
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.							
Sr. No.	Project components		Work done value during the quarter (In Lacs)	Cumulative work done value till date (in Lacs)	Percentage of work done to the total proposed work				
1.	(incl	structure usive of excavation, dation, basements, water ofing, etc.)	0.0	1621.8	100%				
2.	(slat	er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	0.0	3300.9	100%				
3.	МЕР								
	3.1	Mechanical (lifts, ventilation, etc.)	0.0	1094.1	100%				
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	180.0	1419.6	97%				
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	120.0	1302.0	97%				
4.	Finishing								
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	166.1	3293.2	94%				
	4.2	External (plaster, painting, facade, etc.)	0.0	1721.8	100%				

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed work	
NO.						
1.	Exca	vation		Completed		100%
2.	Laying of foundation					
	(i)	Raft		Completed		100%
	(ii)	Pile				
3.	Num	ber of basement(s) 3				
	(i)	Basement Level 1		Completed		100%
	(ii)	Basement level 2		Completed		100%
	(iii)	Basement level 3		Completed		100%
4.		erproofing of the above sub- cture (wherever applicable)		Completed		100%
		Super-Structure Status				
5.	Tota	l floors in the tower/ building		G+10		
6.	Tota	l area on each floor	FAR=2 6260 Service FAR=10	79.602 to .212 Sqm. Apartment 41.907 to 2.663 Sqm		
7.	Stilt	floor/ ground floor		Completed	V 20-17	100%
8.	Statu	is of laying of slabs floor wise		Completed		100%
	build	ulative number of slabs in the ling/tower11 laid by of quarter				
9.	Statı	is of construction				
	(i)	Walls on floors		Completed		100%
	(ii)	Staircase		Completed		100%
	(iii)	Lift wells along with water proofing	•		1009	
	(iv)	Lift lobbies/ common areas floor wise			1009	
10.		g of door and window frames in / units	In Progress		97	
11.	Statu	as of MEP	Internal (within flat)	External works	Internal (within flat)	Externa work
	(i)	Mechanical works		Completed	-	100%
	(ii)	Electrical works including wiring	In Progress		97%	

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

	(iii)	Plumbing works	In Progress	97%		
12.	Statu Glazi	, 0, ,				
	(i)	External plaster/Façade Glazing	Completed	100%		
	(ii)	Internal plaster	Completed	100%		
13.	Status of wall tiling					
	(i)	In bathroom	Completed	100%		
	(ii)	In kitchen	NA	He with		
14.	Statu	s of flooring				
	(i)	Common areas	Completed	100%		
	(ii)	Units/ flats	NA			
15.	Statu	s of white washing				
	(i)	Internal walls	Completed	100%		
	(ii)	External walls	NA	V/ 192		
16.	Statu	s of finishing				
	(i)	Staircase with railing	Completed	100%		
	(ii)	Lift wells	Completed	100%		
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%		
17.	Status of installation					
	(with	nin flat/unit)				
	(i)	Doors and windows panels	Completed	100%		
	(ii)	Sanitary fixtures	Completed	100%		
	(iii)	Modular kitchen – Only in Service apartment	In Progress	50%		
	(iv)	Electrical fittings/lighting	In Progress	97%		
	(v)	Gas piping (if any)	In Progress	97%		
	(othe	er than flat/units)				
	(vi)	Lifts installation	Completed	100%		
	(vii)	Overhead tanks	Completed	100%		
	(viii)	Underground water tank	Completed	100%		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%		
	(x)	Electrical fittings in common areas	Completed	100%		
	(xi)	Compliance to conditions of environment/ CRZ NOC				
18.	Wate	erproofing of terraces	Completed	100%		

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in



19.	Entrance lobby finishing	Completed	100%
20.	Status of construction of compound wall	Completed	100%

Note: (*) extend rows as per requirement.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no513	Yes	100%	
	Open no	No		
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	No		
	Fixing of children play equipment's	No		
	Benches	Yes	100%	
8.	Shopping area	No		
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	2000
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)	NA	NA	
B-2	Community building to be transferred to	RWA		
17.	Community centre	NA		
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority ASHWIN ALVA ASSOC		- Ocas	r don

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

19.	Schools	NA	
20.	Dispensary	NA	
21.	Club	NA	
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority		
23.	*		

Note: (*) extend as per requirement

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in