Ashish Sawe

B. Arch., FIV, ISO Internal Audit, IBBI Registered Valuer

Email ashish.sawe@amail.com

Mobile +91-7044091174

Website www.architectashahsawe.com City:Delhi:110092 Email: architectashishsawe@gmail.com Architect

SJARERA4/042022/M3M Prive 73

CAI2001128463

U

		Architec	ct's Certificate		
	R	eport for quarter ending	JAN 2022 - MAR 2022.		
		Subject	Certificate of Percentage of completion construction work of the project at the end of the quarter		
Januth n	the below intellitioned project as per the		rchitect for certifying progress of construction work in approved plans		
	Sr.No. Particulars		Information		
	1.	Project/Phase of the project	M3M Prive 73		
	2.	Location	Sector 73 Gurugram		
	3.	Licensed area in acres	2.75 acres		
	4.	Area for registration in acres	1.625 acres		
	5.	HARERA registration no.	(27 of 2019) RC/REP/HARERA/GGM/333/65/2019/27 dated 24/05/2019		
	6.	Name of licensee	M/S Lavish Buildmart Pvt Ltd.		
	7.	Name of collaborator	N.A.		
	8.	Name of developer	M/S Lavish Buildmart Pvt Ltd.		
2.	Details related to inspection are as under				
	quel .	Date of certifying of percentage of construction work/ site inspection	03.04.2022		
	2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe		
	3.	Date of site inspection	03.04.2022		

l		arms recumical professionals are ap	pointed by promoter: - (as applicable)
	Sr. No.	Consultants	Name
	1.	Site engineer	Akhilesh singh
	2.	Structural consultant	BMSF Design consultant pvt. Ltd
	3.	Proof consultant	Manish Consultant
	4.	MEP consultant	Udyan Chaudhary Tech Consultants
	5.	Site supervisor/incharge	Vikas Garg

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 03.04.2022

Issued without prejudice,

Name :- Ar. ASHISH SAWE

CA/2001/28463

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:_CA/2001/28463

(CoA)

Registration valid till (date) : 31-12-2023

			Table – A		
D. C.	ding/T	ower no.	Project Consist of Re	tail commercial space, Ground +5 Floors.	retail block of Lowe
A1	Cum	oulative progress of the project/phase a	ter.		
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		work done value during the quarter (Sq.mt.)		Percentage of work done to the total proposed work
1.			-	7,975	100%
2.	(slab	er structure s, brick work, block work, stair case, vells, machine rooms, water tank, etc.)		14190	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	22165	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	22165	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	22165	100%
₫.	Finishing				THE STATE SHAPE SH
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	22165	100%
	4.2	External (plaster, painting, facade, etc.)	-	22165	100%

Sr. No.		Tasks/ Activity Sub-Structure Status	Description of work done	Percentage of total proposed work
1.	Excar	vation	Complete	100%
2.	Layin	ng of foundation		
	(i)	Raft	Complete	100%
	(ii)	Pile	N.A.	N.A.
3,	Num	ber of basement(s) (2)		
	(i)	Basement Level 1	Complete	100%
	(îî)	Basement level 2	Complete	100%



4.		erproofing of the above sub-structure erever applicable)	Con	nplete	10	00%
		Super-Structure Status				
5.	Tota	I floors in the tower/ building	Complete		100%	
6.	Tota	l area on each floor	Con	ıplete	100%	
7.	Stilt	floor/ ground floor	Complete		100%	
8.	State	us of laying of slabs floor wise	Con	plete	10	10%
		ulative number of slabs in the building/ er laid by end of quarter	Con	plete	10	10%
9.	State	us of construction				
	(i)	Walls on floors	Com	iplete	10	0%
	(11)	Staircase	Complete		100%	
	(iii)	Lift wells along with water proofing	Com	plete	10	0%
	(iv)	Lift lobbies/ common areas floor wise	Com	plete	10	0%
10.	Fixing	g of door and window frames in flats/	Com	plete	Complete	
11.	Statu	is of MEP	Internal (within flat)	External works	Internal (within flat)	External
	(i)	Mechanical works	Com	plete		0%
	(ii)	Electrical works including wiring	Com	plete	10	0%
	(iii)	Plumbing works	Complete		100%	
12.	Statu	s of wall plastering				
	(i)	External plaster	Complete		100%	
	(ii)	Internal plaster	Com	plete	100	0%
13.	Statu	s of wall tiling				
	(i)	In bathroom	Complete		100	0%
	(ii)	In kitchen	N	A	N	A
14.	Status	s of flooring	-		and the state of t	
	(î)	Common areas	Com	olete	100	0%
	(ii)	Units/ flats	N.	A,	N.	A.

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total proposed work
			done	
15.	Status of white washing			
	(i)	Internal walls	Complete	100%



	(ii)	External walls	NA	NA
16.	Statu	s of finishing		
	(i)	Staircase with railing	Complete	100%
	(ii)	Lift wells	Complete	100%
	(iii)	Lift lobbies/ common areas floor wise	Complete	100%
17.	Statu	s of installation		
	(with	in flat/unit)		
	(i)	Doors and windows panels	Complete	100%
	(ii)	Sanitary fixtures	Complete	100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	Complete	100%
	(v)	Gas piping (if any)	Complete	100%
	(other	r than flat/units)		
	(vi)	Lifts installation	Complete	100%
	(vii)	Overhead tanks	Complete	100%
	(viii)	Underground water tank	Complete	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Complete	100%
	(x)	Electrical fittings in common areas	Complete	100%
	(xi)	Compliance to conditions of environment/ CRZNOC	Complete	100%
18.	Water	proofing of terraces	Complete	100%
19.	Entrar	nce lobby finishing	Complete	100%
20.	Status	of construction of compound wall	Complete	100%

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	Complete	100%
2.	Parking	Yes	Complete	100%
	Covered no. parking are 250 nos.	Yes	Complete	100%
	Open & handicap parking	Yes	Complete	100%
3,	Water supply	Yes	Complete	100%
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	Complete	100%
5.	Storm water drains	Yes	Complete	100%
6.	Landscaping & tree plantation	Yes	Complete	100%
7.	Parks and playgrounds	NO	N.A.	N.A.

CA/2001/28463

	Fixing of children play equipment's	NO	N.A.	N.A.
	Benches	NO	N.A.	N.A.
8.	Shopping area	Yes	Complete	100%
9.	Street lighting/ electrification	Yes	Complete	100%
10.	Treatment and disposal of sewage and selvage water/ STP	Yes	Complete	100%
11.	Solid waste management & disposal	Yes	Complete	100%
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	Complete	100%
13.	Energy management (solar)	Yes	Complete	100%
14.	Fire protection and fire safety requirements	Yes	Complete	100%
15.	Electrical meter room, sub-station, receiving station	Yes	Complete	100%
16.	Other (option to add more)	NO	N.A.	N.A.
8-2	Community building to be transferred to RWA			
17.	Community centre	NO	N.A.	N.A.
18.	Others(HSD Tank,Gas bank)	NO	N.A.	N.A.
B-3	Community buildings not to be transferred to RWA	/competent au	thority	
19.	Schools	NO	N.A.	N.A.
20.	Dispensary	NO	N.A.	N.A.
21.	Club	NO	N.A.	N.A.
22.	Others	NO	N.A.	N.A.
B-4	Services/ facilities to be transferred to competent a	uthority		

CA/2001/28463

-----End Of Report-----



