Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

Annexure A

Architect's Certificate			
Report for quarter ending			**31st December. 2025**
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	PALM COUNTY
	2.	Location	Revenue estate- Shikohpur & Naurangpur Sector – 78, Gurugram, Haryana
	3.	Licensed area in acres	6.3000 Acres
	4.	Area for registration in acres	6.3000 Acres
	5.	HARERA registration no.	55 of 2022
	6.	Name of licensee	CONMIN INFRADEVELOPERS LLP
	7.	Name of collaborator	CONMIN INFRADEVELOPERS LLP
	8.	Name of developer	CONMIN INFRADEVELOPERS LLP
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	31.12.2025
	2.	Name of Architect/ Architect's firm	VIVEK SINGH RAO P/O RAO AND ASSOCIATES
	3.	Date of site inspection	**31st December. 2025**

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

*On the letter head of the architect firm

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Mr. Rahul Singh
	2.	Structural consultant	M/S NNC Design International
	3.	Proof consultant	
	4.	MEP consultant	V Consulting, Delhi.
	5.	Site supervisor/incharge	Mr. Rahul Singh
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 31.12.2025

Yours faithfully,

Place :

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. :

Council of architects (CoA) registration valid till (date) :

VIVEK SINGH RAO
B. Arch, F.I.V., F.I.I.A.
C.O.A. Reg. No. CA/99/25040
RAO AND ASSOCIATE
374, U.V., Ph-4, Gurgaon-15
Ph:- 4569374, 9811130867

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

Table – A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			N/A		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		N/A	N/A	N/A
2.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		N/A	N/A	N/A
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	N/A	N/A	N/A
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	N/A	N/A	N/A
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	N/A	N/A	N/A
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	N/A	N/A	N/A
	4.2	External (plaster, painting, facade, etc.)	N/A	N/A	N/A

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMD), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : +91 9811130867

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
1.	Excavation			
2.	Laying of foundation			
	(i)	Raft	N/A	N/A
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A
4.	Waterproofing of the above sub-structure (wherever applicable)		N/A	N/A
	Super-Structure Status			
5.	Total floors in the tower/ building		N/A	N/A
6.	Total area on each floor		N/A	N/A
7.	Stilt floor/ ground floor		N/A	N/A
8.	Status of laying of slabs floor wise		N/A	N/A
	Cumulative number of slabs in the building/ tower.....laid by end of quarter		N/A	N/A
9.	Status of construction			
	(i)	Walls on floors	N/A	N/A
	(ii)	Staircase	N/A	N/A
	(iii)	Lift wells along with water proofing	N/A	N/A
	(iv)	Lift lobbies/ common areas floor wise	N/A	N/A
10.	Fixing of door and window frames in flats/ units			
11.	Status of MEP		Internal (within flat) / External works	Internal (within flat) / External works
	(i)	Mechanical works	N/A	N/A
	(ii)	Electrical works including wiring	N/A	N/A
	(iii)	Plumbing works	N/A	N/A
12.	Status of wall plastering			
	(i)	External plaster	N/A	N/A
	(ii)	Internal plaster	N/A	N/A
13.	Status of wall tiling			
	(i)	In bathroom	N/A	N/A
	(ii)	In kitchen	N/A	N/A
14.	Status of flooring			
	(i)	Common areas	N/A	N/A
	(ii)	Units/ flats	N/A	N/A

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMD), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : +91 9811130867

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	N/A	N/A
	(ii)	External walls	N/A	N/A
16.	Status of finishing			
	(i)	Staircase with railing	N/A	N/A
	(ii)	Lift wells	N/A	N/A
	(iii)	Lift lobbies/ common areas floor wise	N/A	N/A
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	N/A	N/A
	(ii)	Sanitary fixtures	N/A	N/A
	(iii)	Modular kitchen		
	(iv)	Electrical fittings/ lighting	N/A	N/A
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	N/A	N/A
	(vii)	Overhead tanks	N/A	N/A
	(viii)	Underground water tank		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	N/A
	(x)	Electrical fittings in common areas	N/A	N/A
	(xi)	Compliance to conditions of environment/ CRZ NOC	N/A	N/A
18.	Waterproofing of terraces		N/A	N/A
19.	Entrance lobby finishing		N/A	N/A
20.	Status of construction of compound wall		N/A	N/A

Note: (*) extend rows as per requirement.

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	**Services**			
1.	Internal roads & pavements	YES	100.00%	
2.	Parking	YES	0%	
	Covered no.	YES	0.00%	
	Open no.	YES	0.00%	
3.	Water supply	YES	100.00%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	100.00%	
5.	Storm water drains	YES	100.00%	
6.	Landscaping & tree plantation	YES	100.00%	
7.	Parks and playgrounds	YES	0%	
	Fixing of children play equipment's	YES	0%	
	Benches	YES	0%	
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	100.00%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	100.00%	
11.	Solid waste management & disposal	YES	100.00%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	100.00%	
13.	Energy management (solar)	YES	0%	
14.	Fire protection and fire safety requirements	YES	100.00%	
15.	Electrical meter room, sub-station, receiving station	YES	100.00%	
16.	Other (option to add more)	YES	100.00%	
B-2	**Community building to be transferred to RWA**			
17.	Community centre	NO	0.00%	
18.	others	NO	0.00%	
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools	NO	0.00%	
20.	Dispensary	NO	0.00%	
21.	Club	NO	0.00%	
22.	Others	NO	0.00%	
B-4	**Services/ facilities to be transferred to competent authority**			
23.	*			

Note: (*) extend as per requirement

RAO AND ASSOCIATE Architects, Planners & Regd. Valuers 374, Udyog Vihar, Ph-IV, Gurgaon