``

TATHAGAT ARCHITECT & VALUERS

Architects, Interior Designers & Valuers

Office No. 313, 2nd Floor, AKD Tower, Sector-14, Old Delhi Road Gurgaon-122001

Annexure A

Architect's Certificate			
Report for quarter ending			**30th June 2026**
Subject			Certificate of progress of construction work in percentage
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	4S THE AURRUM
	2.	Location	Sector 59 & 63A, GURUGRAM, HARYANA
	3.	Licensed area in acres	10.071875 Acres
	4.	Area for registration in acres	5.4295 Acres
	5.	HARERA registration no.	76 of 2024 Dated 15.07.2024
	6.	Name of licensee	Sh. Rishi Aggarwal and Others M/s 4S Developers Pvt Ltd
	7.	Name of collaborator	M/s 4S Developers Pvt Ltd
	8.	Name of developer	M/s 4S Developers Pvt Ltd
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	15.07.2026
	2.	Name of Architect/ Architect's firm	Mr. VIKKEY
	3.	Date of site inspection	30.06.2026

TATHAGAT ARCHITECT & VALUERS
CA/2017-86236
M. 7988789153
GURUGRAM

``

TATHAGAT ARCHITECT & VALUERS

Architects, Interior Designers & Valuers

Office No. 313, 2nd Floor, AKD Tower, Sector-14, Old Delhi Road Gurgaon-122001

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Mr. Samay Sehrawat
	2.	Structural consultant	M/S Global Design Engineers (Pankish Goel)
	3.	Proof consultant	Mr. Vijay Pushkarana
	4.	MEP consultant	AEON Integrated Building Design Consultant LLP
	5.	Site supervisor/in charge	Mr. Daljeet Ram Gujar
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 15.07.2026

yours faithfully,

Place :- Gurugram

VIKKEY
Signature & name withstamp of architect

Council of architects (CoA) Registration No.:- CA/2017/86236

Council of architects (CoA):registration valid till (date) :- 31/12/2028

TATHAGAT ARCHITECT & VALUERS CA/2017-86236 M. 7988789153 GURUGRAM

``

TATHAGAT ARCHITECT & VALUERS

Architects, Interior Designers & Valuers

Office No. 313, 2nd Floor, AKD Tower, Sector-14, Old Delhi Road Gurgaon-122001

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower 1 to 3**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		5%	70%	70%
2.	**Super structure** (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)		3%	10%	10%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0%	0%	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	0%	0%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%

TATHAGAT ARCHITECT & VALUERS CA/2017-86236 M. 7988789153 GURUGRAM

``

TATHAGAT ARCHITECT & VALUERS

Architects, Interior Designers & Valuers

Office No. 313, 2nd Floor, AKD Tower, Sector-14, Old Delhi Road Gurgaon-122001

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Excavation in Ordinary Soil		0%	
2.	Laying of foundation					
	(i)	Raft	RCC		0%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	NA		0%	
	(ii)	Basement level 2*	NA		0%	
4.	Waterproofing of the above sub-structure (wherever applicable)					
	Super-Structure Status					
5.	Total floors in the tower/ building		243 Units		0%	
6.	Total area on each floor		Yet to be started		0%	
7.	Stilt floor/ ground floor		Yet to be started		0%	
8.	Status of laying of slabs floor wise		Yet to be started		0%	
	Cumulative number of slabs in the building/ tower..... laid by end of quarter		Yet to be started		0%	
9.	Status of construction					
	(i)	Walls on floors	Yet to be started		0%	
	(ii)	Staircase	Yet to be started		0%	
	(iii)	Lift wells along with water proofing	Yet to be started		0%	
	(iv)	Lift lobbies/ common areas floor wise	Yet to be started		0%	
10.	Fixing of door and window frames in flats/ units		Yet to be started		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Yet to be started		0%	
	(ii)	Electrical works including wiring	Yet to be started		0%	
	(iii)	Plumbing works	Yet to be started		0%	
12.	Status of wall plastering					
	(i)	External plaster	Yet to be started		0%	
	(ii)	Internal plaster	Yet to be started		0%	
13.	Status of wall tiling					
	(i)	In bathroom	Yet to be started		0%	
	(ii)	In kitchen	Yet to be started		0%	
14.	Status of flooring					
	(i)	Common areas	Yet to be started		0%	
	(ii)	Units/ flats	Yet to be started		0%	

TATHAGAT ARCHITECT & VALUERS CA/2017-86236 M. 7988789153 GURUGRAM

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Yet to be started	0%
	(ii)	External walls	Yet to be started	0%
16.	Status of finishing			
	(i)	Staircase with railing	Yet to be started	0%
	(ii)	Lift wells	Yet to be started	0%
	(iii)	Lift lobbies/ common areas floor wise	Yet to be started	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Yet to be started	0%
	(ii)	Sanitary fixtures	Yet to be started	0%
	(iii)	Modular kitchen	Yet to be started	0%
	(iv)	Electrical fittings/ lighting	Yet to be started	0%
	(v)	Gas piping (if any)	Yet to be started	0%
	(other than flat/units)			
	(vi)	Lifts installation	Yet to be started	0%
	(vii)	Overhead tanks	Yet to be started	0%
	(viii)	Underground water tank	Yet to be started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be started	0%
	(x)	Electrical fittings in common areas	Yet to be started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yet to be started	0%
18.	Waterproofing of terraces		Yet to be started	0%
19.	Entrance lobby finishing		Yet to be started	0%
20.	Status of construction of compound wall		Yet to be started	0%

Note: (*) extend rows as per requirement.

