



### ARCHITECTS & ENGINEER'S

Annexure A

		Architec	t's Certificate*		
Repor	t for qua	rter ending	31 MARCH 2022		
Subject			Certificate of progress of construction work		
1.	I/We I below	nave undertaken assignment as archi mentioned project as per the approv	itect for certifying progress of construction work in the /ed plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	San Francisco Street		
	2.	Location	Omaxe World Street, Sector-79, Faridabad		
	3.	Licensed area in acres	2.66 acres		
	4.	Area for registration in acres	2.66 acres		
	5.	HARERA registration no.	HRERA-PKL-FBD-216-2020		
	6.	Name of licensee	FBD REAL GROW PVT LTD		
	7.	Name of collaborator			
	8.	Name of developer	FBD REAL GROW PVT LTD		
2.	Details	related to inspection are as under			
	1.	Date of certifying of percentage of construction work/ site inspection	10.07.2021		
	2.	Name of Architect/ Architect's firm	BEE BEE Architects		
	3.	Date of site inspection	05.07.2021		
			Aptiba Bor Regd. Architect CA/2013/61618		





ARCHITECTS & ENGINEER'S

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer Structural consultant	Mr. D.C Pant			
	2.		Mr. Pankaj Varshney			
	3.	Proof consultant				
	4.	MEP consultant	Mr, Digambar Singh			
	5.	Site incharge	Mr. D.C Pant			
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approved Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in construction, infrastructure works and internal development works are as per the projected standard envisaged in the registration and brochure, publication material and other documents shared with the built in this regard.					
5.	below.	can estude project/pliase of the n	centage of work done in the project for each of the building/ towe roject under HARERA is as per table A and table B given herein uted with respect to each of the activity of the entire project/ phase			

Date

Yours faithfully,

Place

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. : CA Council of architects (CoA) registration valid till (date)

:

: CA/2013/61618

German Bench

Apurba Borah Regd. Architect GA/2013/61618



#### ARCHITECTS & ENGINEER'S

Sr. Pro No. Sul (Ind bas	<ul> <li>b structure</li> <li>clusive of excavation, foundation, sements, water proofing, etc.)</li> <li>per structure</li> <li>abs, brick work, block work, stair case, wells, machine rooms, water tank, etc.)</li> </ul>	at the end of the qua Work done value during the quarter - 1.30 CR	Cumulative work done value till date 6.30 CR	Percentage of work done to the total proposed work 100 %
No. Sul (Ind bas S. Suj (Sla lift	b structure clusive of excavation, foundation, sements, water proofing, etc.) per structure abs, brick work, block work, stair case,	during the quarter -	work done value till date 6.30 CR	work done to the total proposed work
(Indbas 2. Suj (Sla lift	clusive of excavation, foundation, sements, water proofing, etc.) <b>per structure</b> abs, brick work, block work, stair case,	- 1.30 CR		100 %
(Sla lift	abs, brick work, block work, stair case,	1.30 CR	1 (0 0	
. MI			4.60 Cr	22%
	EP			
3.1	Mechanical (lifts, ventilation, etc.)	-	-	
3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	
. Fin	ishing	1 N		
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0 LACS	0 CR	0%
4.2	External (plaster, painting, facade, etc.)	O LACS	0 CR	0%

Apurba Bora Regd. Architect CA/2013/81618



Sr.	Tasks/ Activity     Sub-Structure Status		Description of work done		CHITECTS & ENGINEER Percentage of total proposed work	
No.						
1.	Exca	vation	Completed		10	0%
2.	Layir	ng of foundation				
	(i)	Raft	10	0%		
	(ii)	Pile	N	/A		
3.	Number of basement(s)					
	(i)	Basement Level 1			10	0%
	(ii)	Basement level 2*	N	A		
	(iii)	Basement Level 3				
	(iv)	Basement Level 4				
4.		rproofing of the above sub-structure rever applicable)			0%	
		Super-Structure Status				
5.	Total	floors in the tower/ building	4			
6.	Total	area on each floor	113550 SFT			
7.	Stilt f	floor/ ground floor	11355	50 SFT		
8.	Status of laying of slabs floor wise				25	5%
	Cumulative number of slabs in the building/ towerlaid by end of quarter					
9.	Status	s of construction				
	(i) Walls on floors				10%	
	(ii)	Staircase			10	)%
	(iii)	Lift wells along with water proofing	-		15-	
	(iv)	Lift lobbies/ common areas floor wise	-		-	
10.	Fixin; units	g of door and window frames in flats/			0	%
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works				L.,
	(ii)	Electrical works including wiring		-		
	(iii)	Plumbing works		-		
12.	Status	s of wall plastering				
	(i)	External plaster			0%	1
	(ii)	Internal plaster			0%	1 town
13.	Status	s of wall tiling				robeni
	(i)	In bathroom		-	AN A	- GO- 310
	(ii)	In kitchen		-	C	390-318 Al201316
14.	Status	s of flooring			-	
	(i)	Common areas				
		NOnisA HallMGIRI APARTMENTS, POCK	ET-14, KALKA	I EXTENSIO	DN, NEW DELHI-	110017



ARCHITECTS & ENGINEER'S

Sr. No.	Tasks/ Activity       Sub-Structure Status		Description of work	Percentage of total proposed work	
			done		
15.	Status of white washing				
	(i)	Internal walls		0%	
	(ii)	External walls		0%	
16.	Status of finishing				
	(i)	Staircase with railing			
	(ii)	Lift wells	N/A		
	(iii)	Lift lobbies/ common areas floor wise	N/A		
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels		0%	
	(ii)	Sanitary fixtures	N/A		
	(iii)	Modular kitchen	N/A		
	(iv)	Electrical fittings/ lighting	N/A		
	(v)	Gas piping (if any)	N/A		
	(other	than flat/units)			
	(vi)	Lifts installation	N/A		
	(vii)	Overhead tanks	N/A		
	(viii)	Underground water tank	N/A		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A		
	(x)	Electrical fittings in common areas	N/A		
	(xi)	Compliance to conditions of environment/ CRZ NOC	N/A		
18.	Water	proofing of terraces		0%	
19.	Entrar	nce lobby finishing	N/A		
20.	Status	of construction of compound wall	-		

Note: (\*) extend rows as per requirement.

Apurba Borah Regd. Architect CA/2013/61616 Mario a Boward



### ARCHITECTS & ENGINEER'S

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
<b>B-1</b>	Services			
1.	Internal roads & pavements	YES	0%	1
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	NA		
	Fixing of children play equipment's	NA		
	Benches	NA		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	NA		
12.	Water conservation, rain water, harvesting, percolating well/ pit	NA		
13.	Energy management (solar)	NA		
14.	Fire protection and fire safety requirements	NA		
15.	Electrical meter room, sub-station, receiving station	NA		
16.	Other (option to add more)	NA		
B-2	Community building to be transferred to RWA			
17.	Community center	NA		
18.	Others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

Apurba Borah Regd. Architect CA/2013/61618 Jawo Corros 5