RAHUL BHARGAVA			
Architect's Certificate			
As on Date			**30.09.2026**
Subject			Certificate of percentage of completion of construction work of the project for the period ending 30.06.2026
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	DOWNTOWN 66
	2.	Location	Sector 66-67, Gurugram
	3.	Licensed area in acres	14.518 Acres
	4.	Area for registration in acres	4.235 Acres
	5.	HARERA registration no.	GGM/981/713/2025/84 DATED 19.09.2025
	6.	Name of licensee	Sh. Shyambir, Sh. Sanjay and others
	7.	Name of collaborator	BPTP Limited (Countrywide Promoters Private Limited has been amalgamated with BPTP Limited)
2.	Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection	12.10.2026
	2.	Name of Architect/ Architect's firm	Aedas Pte Ltd
	3.	Date of site inspection	12.10.2026

<table>
<tr><td></td><td colspan="3">Following technical professionals are appointed by promoter: - (as applicable)</td></tr>
<tr><td></td><td>Sr. No.</td><td>Consultants</td><td>Name</td></tr>
<tr><td></td><td>1.</td><td>Site engineer</td><td>Bipin Pratap Singh</td></tr>
<tr><td></td><td>2.</td><td>Structural consultant</td><td>Optimal Consultancy Services</td></tr>
<tr><td></td><td>3.</td><td>Proof consultant</td><td>Manish Consultant</td></tr>
<tr><td></td><td>4.</td><td>MEP consultant</td><td>Senealc</td></tr>
<tr><td></td><td>5.</td><td>Site supervisor/in charge</td><td>Amit Chhillar</td></tr>
<tr><td>4.</td><td colspan="3">I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.</td></tr>
<tr><td>5.</td><td colspan="3">I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.</td></tr>
</table>

Date: 12.10.2026
NOIDA, Uttar Pradeesh

Yours faithfully,



Signature & name (in block letters) with stamp of architect

Physical Progress for Tower 1, 2 3 as on 30.09.2026

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total	
	Sub-Structure Status					
1.	Excavation		1,18,575		56%	
2.	Laying of foundation					
	(i)	D- Wall Works			100%	
	(ii)	Foundation Works			20%	
3.	Number of basement(s) . . . . 3 . . .					
	(i)	Basement 1	-		5%	
	(ii)	Basement 2	-			
	(iii)	Basement 3	-			
4.	Waterproofing of the above sub-structure (wherever applicable)		-		0%	
	Super-Structure Status		-		0%	
5.	Total floors in the tower/ building		-		0%	
6.	Total area on each floor		-		0%	
7.	Stilt floor/ ground floor		-		0%	
8.	Status of laying of slabs floor wise		-		0%	
	Slab Works		-		0%	
9.	Status of construction		-		0%	
	(i)	Walls on floors	-		0%	
	(ii)	Staircase	-		0%	
	(iii)	Lift wells along with water proofing	-		0%	
	(iv)	Lift lobbies/ common areas floor wise	-		0%	
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flats)	External works

	(i)	Mechanical works	-	0%
	(ii)	Electrical works including wiring	-	0%
	(iii)	Plumbing works	-	0%
12.	Status of wall plastering			-
	(i)	External plaster	-	0%
	(ii)	Internal plaster	-	0%
13.	Status of wall tiling			-
	(i)	In bathroom	-	0%
	(ii)	In kitchen	-	0%
14.	Status of flooring			-
	(i)	Common areas	-	0%
	(ii)	Units/ flats	-	0%
15.	Status of white washing			
	(i)	Internal walls	-	0%
	(ii)	External walls	-	0%
16.	Status of finishing			
	(i)	Staircase with railing	-	0%
	(ii)	Lift wells	-	0%
	(iii)	Lift lobbies/ common areas floor wise	-	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	-	0%
	(ii)	Sanitary fixtures	-	0%
	(iii)	Modular kitchen	-	0%
	(iv)	Electrical fittings/ lighting	-	0%
	(v)	Gas piping (if any)	-	0%
	(other than flat/units)			-
	(vi)	Lifts installation	-	0%
	(vii)	Overhead tanks	-	0%
	(viii)	Underground water tank	-	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	0%
	(x)	Electrical fittings in common areas	-	0%

	(xi)	Compliance to conditions of environment/ CRZ NOC	-	0%
18.	Waterproofing of terraces		-	0%
19.	Entrance lobby finishing		-	0%
20.	Status of construction of compound wall		-	0%

Physical Progress for Common areas and facilities amenities as on 30.09.2026

Sr. No.	Common areas and facilities amenities	Proposed (Yes/	Percentage of work done	Remarks
B-1				
1.	Internal roads & pavements	Yes	0%	
2.	Parking	Yes	0%	
	Covered	Yes	0%	
	Open no Parking	Yes	0%	
3.	Water supply	Yes	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation	Yes	0%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Primary School	Yes	0%	
17.	Club	Yes	0%	
19.	Others	Yes	0%	

Note: (*) extend as per requirement

