Arcop Associates Private Limited

Architecture
Planning
Urban Design
Interiors

Annexure A

Architect's Certificate*			
Report for quarter ending			Sep 2026
Subject			Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	La VIDA, Phase-1
	2.	Location	Sector – 112 -113, Gurugram
	3.	Licensed area in acres	10.175 Acre
	4.	Area for registration in acres	5.989 Acre
	5.	HARERA registration no.	148 of 2017
	6.	Name of licensee	C.S.N. ESTATES PRIVATE LIMITED
	7.	Name of collaborator	C.S.N. ESTATES PRIVATE LIMITED
	8.	Name of developer	Sector 113 Gatevida Developers Pvt Ltd
2.	Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection	12th October 2026
	2.	Name of Architect/ Architect's firm	Arcop Associates (P) Ltd
	3.	Date of site inspection	12th October 2026

Plot No 36-B, Sector 32, Institutional Area, Gurgaon, Haryana 122001, India
CIN/LLPIN – U45201DL1985 PT C021337 Tel.: +91-124-4595500, Fax: +91-124-4595550
email: info@arcop.co.in, web: www.arcop.co.in

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Tata Housing Development Company
	2.	Structural consultant	TPC Technical Projects Consultants Pvt Ltd
	3.	Proof consultant	KPM Engineering
	4.	MEP consultant	Paradise Consultants
	5.	Site supervisor/in charge	Mr. Gurmeet Singh Alabadia
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 12.10.2026

Place: Gurgaon

Arcop Associates Pvt. Ltd. Gurgaon

ABHISHEK TIWARI Council of Architecture Registration No. CA/2011/52113 REGISTERED ARCHITECT

yours faithfully,

ABHISHEK TIWARI

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. : CA-2011-52113

Council of architects (CoA) registration valid till (date) : 31-12-2032

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower B1**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter (Lakhs)**	**Cumulative work done value till date (Lakhs)**	**Percentage of work done to the total proposed work (Lakhs)**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	1421.2Lakhs	100%
2.	**Super structure** (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	**MEP**				
	3.1	Mechanical (Lifts, ventilation, etc.)	NIL	710.78 Lakhs	99.50%
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	NIL	1208.96 Lakhs	99.50%
	4.2	External (Plaster, painting, facade, etc.)			

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Soil Excavation for basement		100%	
2.	Laying of foundation					
	(i)	Raft	Raft		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	1		100%	
	(ii)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		NIL			
	Super-Structure Status					
5.	Total floors in the tower/ building		13		100%	
6.	Total area on each floor		7983		100%	
7.	Stilt floor/ ground floor		1573		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower ..... laid by end of quarter		14		100%	
9.	Status of construction					
	(i)	Walls on floors	Masonry		100%	
	(ii)	Staircase	RCC		100%	
	(iii)	Lift wells along with water proofing	Masonry		100%	
	(iv)	Lift lobbies /common areas floor wise	Masonry		100%	
10.	Fixing of door and window frames in flats/ units		Wooden & UPVC		100%	
11.	Status of MEP		Internal (within Flat)	External works	Internal (within Flat)	External works
	(i)	Mechanical works			100%	100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External	Cement Plaster		100%	
	(ii)	Internal	Gypsum Plaster		100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In Kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/flats			100%	

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	NA	100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Arcop Associates Pvt. Ltd. Gurgaon

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower B2**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	1407.30Lakhs	100%
2.	**Super structure** (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	**MEP**		NIL	677.79 Lakhs	99.90%
	3.1	Mechanical (Lifts, ventilation, etc.)			
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**		NIL	1204.07 Lakhs	99.50%
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (Plaster, painting, facade, etc.)			

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Soil Excavation for basement		100%	
2.	Laying of foundation					
	(i)	Raft	Raft		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	1		100%	
	(ii)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		NIL			
	Super-Structure Status					
5.	Total floors in the tower/ building		13		100%	
6.	Total area on each floor		7983		100%	
7.	Stilt floor/ ground floor		1573		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower B2 laid by end of quarter		14		100%	
9.	Status of construction					
	(i)	Walls on floors	Masonry		100 %	
	(ii)	Staircase	RCC		100%	
	(iii)	Lift wells along with water proofing	Masonry		100%	
	(iv)	Lift lobbies/ common areas floor wise	Masonry		100%	
10.	Fixing of door and window frames in flats/ units		Wooden & UPVC		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	

ArcopAssociates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100 %
	(ii)	External walls		100 %
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Note: (*) extend rows as per requirement.

Arcop Associates Pvt. Ltd. Gurgaon

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower B3**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	1425.72 Lakhs	100%
2.	**Super structure** (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	**MEP**		NIL	662.93 Lakhs	99.80%
	3.1	Mechanical (Lifts, ventilation, etc.)			
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**		NIL	1202.57 Lakhs	99.60%
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (Plaster, painting, facade, etc.)			

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Soil Excavation for basement		100%	
2.	Laying of foundation					
	(i)	Raft	Raft		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	1		100%	
	(ii)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		NIL			
	Super-Structure Status					
5.	Total floors in the tower/ building		13		100%	
6.	Total area on each floor		7983		100%	
7.	Stilt floor/ ground floor		1714		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower B3 laid by end of quarter		14		100%	
9.	Status of construction					
	(i)	Walls on floors	Masonry		100%	
	(ii)	Staircase	RCC		100%	
	(iii)	Lift wells along with water proofing	Masonry		100%	
	(iv)	Lift lobbies/ common areas floor wise	Masonry		100%	
10.	Fixing of door and window frames in flats/ units		Wooden & UPVC		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Cement Plaster		100%	
	(ii)	Internal plaster	Gypsum Plaster		100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100 %
	(ii)	External walls		100 %
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Note: (*) extend rows as per requirement.

Arcop Associates Pvt. Ltd. Gurgaon

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower B4**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	1401.50Lakhs	100%
2.	**Super structure** (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	**MEP**		NIL	675.73 Lakhs	100.00%
	3.1	Mechanical (Lifts, ventilation, etc.)			
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**		NIL	1210.94 Lakhs	99.50%
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (Plaster, painting, facade, etc.)			

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Soil Excavation for basement		100%	
2.	Laying of foundation					
	(i)	Raft	Raft		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	1		100%	
	(ii)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		NIL			
	Super-Structure Status					
5.	Total floors in the tower/ building		13		100%	
6.	Total area on each floor		7983		100%	
7.	Stilt floor/ ground floor		1714		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower B4 laid by end of quarter		14		100%	
9.	Status of construction					
	(i)	Walls on floors	Masonry		100%	
	(ii)	Staircase	RCC		100%	
	(iii)	Lift wells along with water proofing	Masonry		100%	
	(iv)	Lift lobbies/ common areas floor wise	Masonry		100%	
10.	Fixing of door and window frames in flats/ units		Wooden & UPVC		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Note: (*) extend rows as per requirement.

Arcop Associates Pvt. Ltd. Gurgaon

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower B5**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		NIL	1408.48Lakhs	100%
2.	**Super structure** (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	**MEP**		NIL	678.95Lakhs	99.80%
	3.1	Mechanical (Lifts, ventilation, etc.)			
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**		NIL	1199.94 Lakhs	99.50%
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (Plaster, painting, facade, etc.)			

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Soil Excavation for basement		100%	
2.	Laying of foundation					
	(i)	Raft	Raft		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	1		100%	
	(ii)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		NIL			
	Super-Structure Status					
5.	Total floors in the tower/ building		13		100%	
6.	Total area on each floor		7983		100%	
7.	Stilt floor/ ground floor		1714		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower B5 laid by end of quarter		14		100%	
9.	Status of construction					
	(i)	Walls on floors	Masonry		100%	
	(ii)	Staircase	RCC		100%	
	(iii)	Lift wells along with water proofing	Masonry		100%	
	(iv)	Lift lobbies/ common areas floor wise	Masonry		100%	
10.	Fixing of door and window frames in flats/ units		Wooden & UPVC		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	

Arcop Associates Pvt. Ltd. Gurgaon

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		0%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Note: (*) extend rows as per requirement.

Arcop Associates Pvt. Ltd. Gurgaon

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	**Services**			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes	100%	
	Covered no.	Yes	100%	
	Open no.	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
8.	Shopping area	Yes	0%	In Phase 2
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	0%	In Phase 2
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)			
B-2	**Community building to be transferred to RWA**			
17.	Community center			
18.	Others			
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools			
20.	Dispensary			
21.	Club	Yes	100%	
22.	Others			
B-4	**Services/ facilities to be transferred to competent authority**			
23.	*			

Note: (*) extend as per requirement

Arcop Associates Pvt. Ltd. Gurgaon