Pinnacle Architects Pvt. Ltd.

938, First Floor Sec-14
Gurgaon-122001 Haryana
P: +91 124 4089711
M: +91 9810406729
pinnacle938@gmail.com

Annexure A

Architect's Certificate

Report for the period ending	30TH September, 2026
Subject	Certificate of Progress of Construction work.

1. I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans

Sr. No.	Particulars	Information
1.	Project/Phase of the project	Avani Signature Floors
2.	Location	Sector -2, Sohna, Gurugram, Haryana
3.	Licensed area in acres	11.95 Acres
4.	Area for registration in acres	1.1158 Acres
5.	HARERA registration no.	74 of 2025
6.	Name of licensee	Anoop Arora, Surjeet Arora
7.	Name of collaborator	N.S. Buildtech Pvt. Ltd.
8.	Name of developer	N.S. Buildtech Pvt. Ltd.

2. Details related to inspection are as under

1.	Date of certifying of percentage of construction work/ site inspection	30.09.2026
2.	Name of Architect/ Architect's firm	Pinnacle Architect Pvt. Ltd.
3.	Date of site inspection	30.09.2026

VIMAL BAJAJ
Architect CA/96/19791
938, Sector-14, Gurgaon

Scanned with OKEN Scanner

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Ashok Sharma
	2.	Structural consultant	Keen Associates Pvt. Ltd.
	3.	Proof consultant	NA
	4.	MEP consultant	Behra Associates Pvt. Ltd.
	5.	Site in charge	Ashok Sharma
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date	: 30.09.26	Yours faithfully, VIMAL BAJAJ Architect CA/96/19791 938, Sector-14, Gurgaon Signature & name
Place	: Gurugram	
Council of architects (CoA) registration no.	: CA/96/19791	
Council of architects (CoA) registration valid till (date)	: 31.12.2030	

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				80%
2.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				35%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			20%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (plaster, painting, facade, etc.)			

VIMAL BAJAJ
Architect CA/96/19791
938, Sector-14, Gurgaon

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Excavation for basement		100%	
2.	Laying of foundation				100%	
	(i)	Raft				
	(ii)	Pile				
3.	Number of basement(s)				1	
	(i)	Basement Level 1				
	(ii)	Basement level 2*				
4.	Waterproofing of the above sub-structure (wherever applicable)					
	Super-Structure Status					
5.	Total floors in the tower/ building				4	
6.	Total area on each floor				803.85 SQM	
7.	Stilt floor/ ground floor				757.1 SQM	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower ..... laid by end of quarter					
9.	Status of construction					
	(i)	Walls on floors				
	(ii)	Staircase				
	(iii)	Lift wells along with water proofing				
	(iv)	Lift lobbies/ common areas floor wise				
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works				
	(ii)	Electrical works including wiring				
	(iii)	Plumbing works				
12.	Status of wall plastering					
	(i)	External plaster				
	(ii)	Internal plaster				

VIMAL BAJAJ
Architect CA/96/19791
938, Sector-14, Gurgaon

13.	Status of wall tiling			
	(i)	In bathroom		
	(ii)	In kitchen		
14.	Status of flooring			
	(i)	Common areas		
	(ii)	Units/ flats		
15.	Status of white washing			
	(i)	Internal walls		
	(ii)	External walls		
16.	Status of finishing			
	(i)	Staircase with railing		
	(ii)	Lift wells		
	(iii)	Lift lobbies/ common areas floor wise		
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		
	(ii)	Sanitary fixtures		
	(iii)	Modular kitchen		
	(iv)	Electrical fittings/ lighting		
	(v)	Gas piping (if any)		
	(other than flat/units)			
	(vi)	Lifts installation		
	(vii)	Overhead tanks		
	(viii)	Underground water tank		
	(ix)	Firefighting fitting and equipment's as per CFO NOC		
	(x)	Electrical fittings in common areas		
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces			
19.	Entrance lobby finishing			
20.	Status of construction of compound wall			

VIMAL BAJAJ
Architect CA/96/19791
938, Sector-14, Gurgaon

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	**Services**			
1.	Internal roads & pavements	Yes	70%	
2.	Parking	No	0	
	Covered no.	No		
	Open no.	No	NO	
3.	Water supply	Yes	NA	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	NA	
5.	Storm water drains	Yes	NA	
6.	Landscaping & tree plantation	Yes	NA	
7.	Parks and playgrounds	Yes	NA	
	Fixing of children play equipment's		NA	
	Benches		NA	
8.	Shopping area		NA	
9.	Street lighting/ electrification	Yes	NA	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	NA	
11.	Solid waste management & disposal	Yes	NA	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	NA	
13.	Energy management (solar)	No	NA	
14.	Fire protection and fire safety requirements	No	NA	
15.	Electrical meter room, sub-station, receiving station	Yes	NA	
16.	Underground Water Tank	Yes	NA	
B-2	**Community building to be transferred to RWA**			
17.	Community centre	No	NA	
18.	Others		NA	
	1 School	NA	NA	
	2 Dispensary and Nursing Home	NA	NA	
B-3	**Community buildings not to be transferred to RWA/competent authority**			
B-4	**Services/ facilities to be transferred to competent authority**			

VIMAL BAJAJ
Architect CA/96/19791
938, Sector-14, Gurgaon