Architect's Certificate			
Report for quarter ending			June,2026
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	The Melia Project
	2.	Location	Sector-35, Sohna, District-Gurugram
	3.	Licensed area in acres	17.41875 Acre
	4.	Area for registration in acres	17.41875 Acre
	5.	HARERA registration No.	288 of 2017 dt 10/10/2017
	6.	Name of licensee	DSS Buildtech Private Limited
	7.	Name of collaborator	NIL
	8.	Name of developer	DSS Buildtech Private Limited
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	30/06/2026
	2.	Name of Architect/Architect's firm	Arcop Associates Pvt. Ltd
	3.	Date of site inspection	30/06/2026
3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Khemchand Mittal
	2.	Structural consultant	Rajesh Kumar
	3.	Proof consultant	R.K. Bhola
	4.	MEP consultant	ARK Consultants &Envirotech Design Pvt. Ltd.
	5.	Site supervisor/in charge	Praveen Pratap Singh



4.	I certify that the work has been executed as per approved drawings, statutory /mandatory approvals, Haryana Building Code, 2017 /National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project /phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date : Yours faithfully,

Place :

Signature & name (in block letters) with stamp of architect

Council of architects(CoA) registration No. :

Council of architects(CoA) registration valid till(date) :



Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**A**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		0	13,889,598	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	129,111,322	100%
3.	**MEP**				
	3.1	Mechanical (Lifts, ventilation, etc.)	0	6,478,205	100%
	3.2	Electrical (Conducting, wiring, fixtures, etc.)	90,000	19,963,346	100%
	3.3	Plumbing &Firefighting (piping, pumps and pump room, fixtures, etc.)	0	17,855,294	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	26,168,852	100%
	4.2	External (plaster, painting, facade, etc.)	0	10,666,223	100%
	4.3	External Development Work	0	7,845,951	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**126719.84 sqft**			
7.	Stilt floor/ ground floor		Grade Slab DONE		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **A** laid by end of quarter		15		100%	
9.	Status of construction					
	(i)	Walls on floors	DONE		100%	
	(ii)	Staircase	DONE		100%	
	(iii)	Lift wells along with water proofing	DONE		100%	
	(iv)	Lift lobbies/ common areas floor wise	DONE		100%	
10.	Fixing of door and window frames in flats/ units		DONE		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	**100%**	100%
	(iii)	Plumbing works	Done	Done	**100%**	100%
12.	Status of wall plastering					
	(i)	External plaster	Plaster		**100%**	
	(ii)	Internal plaster	Plaster		**100%**	
13.	Status of wall tiling					
	(i)	In bathroom	Done		**100%**	
	(ii)	In kitchen	Done		**100%**	
14.	Status of flooring					
	(i)	Common areas	Done		**100%**	
	(ii)	Units/ flats	Done		**100%**	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	



	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lifts installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**B**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	11,714,803	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	102,448,011	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	4,670,407	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	11,402,637	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	8,641,224	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	20,055,412	100%
	4.2	External (plaster, painting, facade, etc.)	88,050	11,320,853	100%
	4.3	External Development Work	0	6,560,610	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		**100%**	
6.	Total area on each floor		**98946.46sqft**			
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **B** laid by end of quarter		15		100%	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		Done		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	DONE	DONE	100%	Done
	(iii)	Plumbing works	DONE	DONE	100 %	Done
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	DONE	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	DONE	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefightingfittingandequipment'sasper CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*)extendrowsasperrequirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			C		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		2,320,150	32,813,412	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		1,011,225	169,547,696	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	75,000	16,813,681	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	10,000	20,935,538	100%
	3.3	Plumbing & Firefighting(piping, pumps and pump room, fixtures, etc.)	12,000	16,197,151	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	14,000	51,984,397	100%
	4.2	External (plaster, painting, facade, etc.)	0	20,674,357	100%
	4.3	External Development Work	18,000	8,651,933	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	Completed	100%
	(ii)	Basement level 2*	Completed	100%

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**126719.84 sqft**			
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **C** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		Done		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	100%
	(iii)	Plumbing works	Done	Done	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	DONE		100 %	
	(ii)	External walls	DONE		100 %	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**D**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	11,129,486	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	113,651,785	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	4,823,559	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	95,000	14,009,235	100%
	3.3	Plumbing &Firefighting(piping, pumps and pump room, fixtures, etc.)	0	12,796,110	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	17,810,004	100%
	4.2	External (plaster, painting, facade, etc.)	13,500	9,824,092	100%
	4.3	External Development Work	0	5,685,367	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**98946.46sqft**			
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **D** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		**100%**	
	(ii)	Staircase	Done		**100%**	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		Done		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	Done
	(iii)	Plumbing works	Done	Done	100%	Done
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**E**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		6,023,620	39,398,273	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		48,453,361	185,547,128	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	4,562	18,772,244	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	15,000	29,993,469	100%
	3.3	Plumbing &Firefighting (piping, pumps and pump room, fixtures, etc.)	5,000	17,945,204	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	52,139,106	100%
	4.2	External (Plaster, painting, facade, etc.)	1,512,786	22,373,624	100%
	4.3	External Development Work	0	11,553,502	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	Completed	100%
	(ii)	Basement level 2*	Completed	100%

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**126719.84 sqft**			
7.	Stilt floor/ ground floor		Grade Slab DONE		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **E** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	Done
	(iii)	Plumbing works	Done	Done	100%	Done
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			100%
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	100%
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**F**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	12,711,443	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	101,756,568	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	77,564	5,030,583	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	13,846,549	100%
	3.3	Plumbing &Firefighting(piping, pumps and pump room, fixtures, etc.)	0	12,491,933	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	25,971,954	100%
	4.2	External (plaster, painting, facade, etc.)	0	13,905,091	100%
	4.3	External Development Work	0	9,911,651	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**98946.46sqft**			
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **F** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		Done			
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	Done
	(iii)	Plumbing works	Done	Done	100%	Done
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	100%
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			G		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		3,576	14,470,727	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	97,754,692	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	4,893,586	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	8,009,152	100%
	3.3	Plumbing &Firefighting(piping, pumps and pump room, fixtures, etc.)	0	8,311,489	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	6,444,039	100%
	4.2	External (plaster, painting, facade, etc.)	0	6,938,600	100%
	4.3	External Development Work	0	2,213,166	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A



4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**98946.46sqft**			
7.	Stilt floor/ ground floor		DONE		97%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **G** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		**100%**	
	(ii)	Staircase	Done		**100%**	
	(iii)	Lift wells along with water proofing	Done		**100%**	
	(iv)	Lift lobbies/ common areas floor wise	Done		**100%**	
10.	Fixing of door and window frames in flats/ units		DONE		**96%**	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	**100%**	DONE
	(iii)	Plumbing works	Done	Done	**100%**	DONE
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**H**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	11,129,486	85%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	6,278,497	80%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	0	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	443,474	18%
	3.3	Plumbing &Firefighting(piping, pumps and pump room, fixtures, etc.)	0	0	
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	
	4.2	External (plaster, painting, facade, etc.)	0	0	
	4.3	External Development Work	0	178,482	

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		**80%**	
6.	Total area on each floor		**98946.46sqft**			
7.	Stilt floor/ ground floor		Grade Slab DONE		**75%**	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **H** laid by end of quarter		15		12.5	
9.	Status of construction					
	(i)	Walls on floors	DONE		70%	
	(ii)	Staircase	DONE		45%	
	(iii)	Lift wells along with water proofing	DONE		0%	
	(iv)	Lift lobbies/ common areas floor wise	DONE		0%	
10.	Fixing of door and window frames in flats/ units		DONE		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	DONE	DONE	0%	0%
	(iii)	Plumbing works	DONE	DONE	0%	0%
12.	Status of wall plastering					
	(i)	External plaster	DONE		0%	
	(ii)	Internal plaster	DONE		0%	
13.	Status of wall tiling					
	(i)	In bathroom	DONE		0%	
	(ii)	In kitchen	DONE		0%	
14.	Status of flooring					
	(i)	Common areas	DONE		0%	
	(ii)	Units/ flats	DONE		0%	
15.	Status of white washing					
	(i)	Internal walls	DONE		0%	
	(ii)	External walls	DONE		0%	
16.	Status of finishing					
	(i)	Staircase with railing	DONE		0%	



	(ii)	Lift wells	DONE	0%
	(iii)	Lift lobbies/ common areas floor wise	DONE	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	DONE	0%
	(ii)	Sanitary fixtures	DONE	0%
	(iii)	Modular kitchen	DONE	0%
	(iv)	Electrical fittings/ lighting	DONE	0%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	DONE	0%
	(vii)	Overhead tanks	DONE	0%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	DONE	0%
	(x)	Electrical fittings in common areas	DONE	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		DONE	0%
19.	Entrance lobby finishing		DONE	0%
20.	Status of construction of compound wall		DONE	0%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			I		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	14,683,199	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	20,350,281	90 %
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	0	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	0	40%
	3.3	Plumbing &Firefighting(piping, pumps and pump room, fixtures, etc.)	0	0	40%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	37 %
	4.2	External (plaster, painting, facade, etc.)	0	0	16%
	4.3	External Development Work	0	209,603	1%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	DONE	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A



4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**114421.86sqft**			
7.	Stilt floor/ ground floor		DONE		50%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **I** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Progress		85 %	
	(ii)	Staircase	Progress		80%	
	(iii)	Lift wells along with water proofing	Progress		60%	
	(iv)	Lift lobbies/ common areas floor wise	Progress		0%	
10.	Fixing of door and window frames in flats/ units		Progress		4%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	DONE	DONE	30%	0%
	(iii)	Plumbing works	DONE	DONE	30%	0%
12.	Status of wall plastering					
	(i)	External plaster	DONE		16%	
	(ii)	Internal plaster	DONE		80%	
13.	Status of wall tiling					
	(i)	In bathroom	DONE		6%	
	(ii)	In kitchen	DONE		6%	
14.	Status of flooring					
	(i)	Common areas	DONE		0%	
	(ii)	Units/ flats	DONE		4%	
15.	Status of white washing					
	(i)	Internal walls	DONE		2%	
	(ii)	External walls	DONE		0%	
16.	Status of finishing					
	(i)	Staircase with railing	DONE		0%	

	(ii)	Lift wells	DONE	0%
	(iii)	Lift lobbies/ common areas floor wise	DONE	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	DONE	4%
	(ii)	Sanitary fixtures	DONE	0%
	(iii)	Modular kitchen	DONE	0%
	(iv)	Electrical fittings/ lighting	DONE	0%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	DONE	0%
	(vii)	Overhead tanks	DONE	4%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefightingfittingandequipment'sasper CFONOC	DONE	0%
	(x)	Electrical fittings in common areas	DONE	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		DONE	0%
19.	Entrance lobby finishing		DONE	0%
20.	Status of construction of compound wall		DONE	0%

Note: (*)extendrowsasperrequirement

Table – A					
Building/ Tower no. **Building/ Tower no.** (to be prepared separately for each building/ tower in the project/phase of the project)			**S1**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	19,735,604	100%
2.	**Super structure** (slabs,brickwork,blockwork,staircase, liftwells,machinerooms,watertank,etc.)		0	95,044,179	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	5,953,685	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	2,000	12,576,181	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	12,947,410	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	18,636,772	100%
	4.2	External (plaster, painting, facade, etc.)	18,000	19,582,719	100%
	4.3	External Development Work	0	3,430,337	100%

Sr. No.	**Tasks/ Activity** **Sub-Structure Status**		**Description of work done**	**Percentage of total proposed work**
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+13		100%	
6.	Total area on each floor		**71408.59sqft**			
7.	Stilt floor/ ground floor		WORK DONE		99%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **S1** laidbyendofquarter		14		14	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		**100%**	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		DONE		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	100%	100%	100%
	(iii)	Plumbing works	Done	100%	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		80%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	



	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefightingfittingandequipment'sasper CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**S2**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		10,005,061	25,281,061	100%
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		5,000,000	74,935,959	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	5,110,628	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	3,200	8,231,477	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	3,896	11,157,672	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	18,795,430	100%
	4.2	External (plaster, painting, facade, etc.)	300,475	12,205,621	100%
	4.3	External Development Work	0	2,783,832	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	Completed	100%
	(ii)	Basement level 2*	Completed	100%

4.	Waterproofing of the above sub-structure (wherever applicable)		DONE			
	Super-Structure Status					
5.	Total floors in the tower/ building		G+13		100%	
6.	Total area on each floor		**90966.88sqft**			
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **S2** laidbyendofquarter		14		14	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixingofdoorandwindowframesinflats/ units		Done		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	Done
	(iii)	Plumbing works	Done	Done	100%	Done
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Fire fighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	100%
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*)extendrowsasperrequirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**J**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (Inclusive of excavation, foundation, basements, water proofing, etc.)		0	5,010,000	93 %
2.	**Super structure** (Slabs, brickwork, blockwork, staircase, lift wells, machine rooms, water tank, etc.)		0	0	84%
3.	**MEP**				
	3.1	Mechanical (Lifts, ventilation, etc.)	0	0	0 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	0	24 %
	3.3	Plumbing &Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	12 %
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	45 %
	4.2	External (Plaster, painting, facade, etc.)	0	0	3 %
	4.3	External Development Work	0	98,468	0%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Done	100%
2.	Laying of foundation			
	(i)	Raft	Done	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+9		100%	
6.	Total area on each floor		**53088sqft**			
7.	Stilt floor/ ground floor		DONE		35%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		10		100	
9.	Status of construction					
	(i)	Walls on floors	DONE		72%	
	(ii)	Staircase	DONE		50%	
	(iii)	Lift wells along with water proofing	DONE		0%	
	(iv)	Lift lobbies/ common areas floor wise	DONE		0%	
10.	Fixing of door and window frames in flats/ units		DONE		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	DONE	DONE	34%	DONE
	(iii)	Plumbing works	DONE	DONE	29%	DONE
12.	Status of wall plastering					
	(i)	External plaster	DONE		4%	
	(ii)	Internal plaster	DONE		50%	
13.	Status of wall tiling					
	(i)	In bathroom	DONE		6%	
	(ii)	In kitchen	DONE		6%	
14.	Status of flooring					
	(i)	Common areas	DONE		0%	
	(ii)	Units/ flats	DONE		0%	
15.	Status of white washing					
	(i)	Internal walls	DONE		0%	
	(ii)	External walls	DONE		0%	
16.	Status of finishing					
	(i)	Staircase with railing	DONE		0%	

	(ii)	Lift wells	DONE	0%
	(iii)	Lift lobbies/ common areas floor wise	DONE	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	DONE	0%
	(ii)	Sanitary fixtures	DONE	0%
	(iii)	Modular kitchen	DONE	0%
	(iv)	Electrical fittings/ lighting	DONE	0%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	DONE	0%
	(vii)	Overhead tanks	DONE	4%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Fire fighting fitting and equipment's as per CFONOC	DONE	0%
	(x)	Electrical fittings in common areas	DONE	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Waterproofing of terraces		DONE	0%
19.	Entrance lobby finishing		DONE	0%
20.	Status of construction of compound wall		DONE	0%

Note: (*) extend rows as per requirement.



Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**EWS**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	5,894,823	100%
2.	**Super structure** (slabs, brick work, block work, staircase, lightwell's, machine rooms, water tank, etc.)		0	33,727,100	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	3,771,056	95%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1,200	3,321,125	95%
	3.3	Plumbing & Fire fighting (piping, pumps and pump room, fixtures, etc.)	0	3,513,598	95%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	7,454,108	95%
	4.2	External (plaster, painting, facade, etc.)	0	6,151,976	98%
	4.3	External Development Work	0	3,159,323	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+14		100%	
6.	Total area on each floor		**43962.43sqft**			
7.	Stilt floor/ ground floor		Done		95%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **EWS** laid by end of quarter		15		15	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	DONE	DONE	90%	90%
	(iii)	Plumbing works	DONE	DONE	90%	90%
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	



	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	100%
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project)			**Club**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	0	100%
2.	**Super structure** (slabs, brick work, block work, staircase, lightwell's, machine rooms, water tank, etc.)		0	26,881,587	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	2,735,000	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	6,739,264	100%
	3.3	Plumbing & Fire fighting (piping, pumps and pump room, fixtures, etc.)	0	5,582,678	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	7,913,001	100%
	4.2	External (plaster, painting, facade, etc.)	0	5,683,728	100%
	4.3	External Development Work	0	2,697,258	100%

Sr. No.	**Tasks/ Activity**		**Description of work done**	**Percentage of total proposed work**
	Sub-Structure Status			
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	N/A	N/A
3.	Number of basement(s)			
	(i)	Basement Level 1	N/A	N/A
	(ii)	Basement level 2*	N/A	N/A

4.	Waterproofing of the above sub-structure (wherever applicable)		N/A		N/A	
	Super-Structure Status					
5.	Total floors in the tower/ building		G+1		100%	
6.	Total area on each floor					
7.	Stilt floor/ ground floor		Done		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower **CLub** laid by end of quarter				100%	
9.	Status of construction					
	(i)	Walls on floors	Done		100%	
	(ii)	Staircase	Done		100%	
	(iii)	Lift wells along with water proofing	Done		100%	
	(iv)	Lift lobbies/ common areas floor wise	Done		100%	
10.	Fixing of door and window frames in flats/ units		Done			
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	N/A	N/A	N/A	N/A
	(ii)	Electrical works including wiring	Done	Done	100%	100%
	(iii)	Plumbing works	Done	Done	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Done		100%	
	(ii)	Internal plaster	Done		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Done		100%	
	(ii)	In kitchen	Done		100%	
14.	Status of flooring					
	(i)	Common areas	Done		100%	
	(ii)	Units/ flats	Done		100%	
15.	Status of white washing					
	(i)	Internal walls	Done		100%	
	(ii)	External walls	Done		100%	
16.	Status of finishing					
	(i)	Staircase with railing	Done		100%	

	(ii)	Lift wells	Done	100%
	(iii)	Lift lobbies/ common areas floor wise	Done	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Done	100%
	(ii)	Sanitary fixtures	Done	100%
	(iii)	Modular kitchen	Done	100%
	(iv)	Electrical fittings/ lighting	Done	100%
	(v)	Gas piping (if any)	N/A	N/A
	(other than flat/units)			
	(vi)	Lift's installation	Done	100%
	(vii)	Overhead tanks	Done	100%
	(viii)	Underground water tank	N/A	N/A
	(ix)	Firefighting fitting and equipment's as per CFONOC	Done	100%
	(x)	Electrical fittings in common areas	Done	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Done	100%
18.	Waterproofing of terraces		Done	100%
19.	Entrance lobby finishing		Done	100%
20.	Status of construction of compound wall		Done	100%

Note: (*) extend rows as per requirement.

Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	**Services**			
1.	Internal roads & pavements	yes	99%	Done
2.	Parking			Overall Project Parking status
	Covered no. . . . . 1368. . . .	yes	96%	
	Open no. . . . . 390.	yes	96%	
3.	Water supply	yes	95%	Done
4.	Sewerage (chamber, lines, septic tanks, STP)	yes	95%	Done
5.	Storm water drains	yes	95%	Done
6.	Landscaping & tree plantation	yes	95%	Done
7.	Parks and playgrounds	yes	100%	Done
	Fixing of children play equipment's	yes	100%	Done
	Benches	yes	90%	Done
8.	Shopping area	yes	20%	Done
9.	Street lighting/ electrification	yes	100%	Done
10.	Treatment and disposal of sewage and sullage water/STP	yes	98%	Done
11.	Solid waste management & disposal	N/A	N/A	N/A
12.	Water conservation ,rainwater ,harvesting, percolating well/pit	yes	100%	Done
13.	Energy management (solar)	yes	100%	Done
14.	Fire protection and fire safety requirements	yes	100%	Done
15.	Electrical meter room, sub-station, receiving station	yes	90%	Done
16.	Other (option to add more)			
B-2	**Community building to be transferred to RWA**			
17.	Community center	yes	100%	Done
18.	Others			
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools	Provision only	0%	Done
20.	Dispensary	N/A	N/A	N/A
21.	Club	N/A	N/A	N/A
22.	Others			
B-4	**Services/ facilities to be transferred to competent authority**			
23.	Commercial Block	yes	1%	Done

Note: (*) extend as per requirement

