INDIVALUE ADVISORS PRIVATE LIMITED
Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044
Email : Indivalueadvisors@gmail.com Mobile +91-7044091174
CIN : U74999DL2021PTC381050

IVAPL/03/09/2026/ Elan Miracle

Architect's Certificate*			
Report for quarter ending			'July to September' 2026
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	Elan Miracle
	2.	Location	Sector 84, Gurugram
	3.	Licensed area in acres	5.91875 Acres
	4.	Area for registration in acres	5.91875 Acres
	5.	HARERA registration No.	190 of 2017 Dated 14-09-2017
	6.	Name of licensee	Elan Buildcon Private Limited
	7.	Name of collaborator	NA
	8.	Name of developer	Elan Buildcon Private Limited
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	07.10.2026
	2.	Name of Architect/ Architect"s firm	Ar. Ashish Sawe
	3.	Date of site inspection	30.09.2026
3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Vikram Singh
	2.	Structural consultant	Perceptive Idea
	3.	Proof consultant	Isha Consultant (P) Ltd.
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pvt. Ltd.,Ampower Consultancy Services.
	5.	Site supervisor/in-charge	NA

Ar. ASHISH SAWE CA/2001/28463

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 07.10.2026

Yours faithfully,
Name: - **Ar. ASHISH SAWE**

Stamp :



Place : Gurugram

Council of Architecture (CoA)
Registration no. :.CA/2001/28463
(CoA) Registration valid till (date) : 31.12-2033

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			ELAN MIRACLE (Entire project is one building)		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter (Sqmt)**	**Cumulative work done value till date (Sqmt)**	**Percentage of work done to the total proposed work (Approx)**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		-	As per Commercial Colony Plan	100%
2.	**Super structure** (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)		-	9189.059	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	-	9189.059	100%
	3.2	Electrical (conducting, wiring, fixtures, etc.)	-	9189.059	100%
	3.3	Plumbing & Fire fighting (piping, pumps and pump room, fixtures, etc.)	-	9189.059	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	9189.059	100%
	4.2	External (plaster, painting, facade, etc.)	-	9329.61	100%

Sr. No.	**Tasks/ Activity** **Sub-Structure Status**		**Description of work done**	**Percentage of total proposed work**
1.	Excavation		Completed	100%
2.	Laying of foundation			
	(i)	Raft	Completed	100%
	(ii)	Pile	NA	NA

3.	Number of basement(s)			
	(i)	Basement Level 1	Completed	100%
	(ii)	Basement level 2 & 3	Completed	100%
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%
	Super-Structure Status			
5.	Total floors in the tower/ building		Completed	100%
6.	Total area on each floor		Completed	100%
7.	Stilt floor/ ground floor		Completed	100%
8.	Status of laying of slabs floor wise		Completed	100%
	Cumulative number of slabs in the building/ tower laid by end of quarter		08 Floors	08 Floors
9.	Status of construction			
	(i)	Walls on floors	Completed	100%
	(ii)	Staircase	Completed	100%
	(iii)	Lift wells along with water proofing	Completed	100%
	(iv)	Lift lobbies/ common areas floor wise	NA	NIL
10.	Fixing of door and window frames in flats/ units		NA	NIL
11.	Status of MEP		Internal (within flat) / External works	Internal (within flat) / External works
	(i)	Mechanical works	Completed	100%
	(ii)	Electrical works including wiring	Conducting	100% Conducting
	(iii)	Plumbing works	All Piping	100% Piping
12.	Status of wall plastering			
	(i)	External plaster	Completed	100%
	(ii)	Internal plaster	Completed	100%
13.	Status of wall tiling			
	(i)	In bathroom	Completed	100%
	(ii)	In kitchen	NA	NA
14.	Status of flooring			
	(i)	Common areas	Completed	100%
	(ii)	Units/ flats	N.A	NIL
15.	Status of white washing			
	(i)	Internal walls	Completed	100%

AR. ASHISH SAWH CA/2008/28453

	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	Completed	100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment"s as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

.Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	**Services**			
1.	Internal roads & pavements	YES	100%	Completed
2.	Parking			
	Covered no. 1340	YES	100%	Completed
	Open no. . . . 108	YES	NIL	
3.	Water supply	YES	100%	Completed
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	100%	Completed
5.	Storm water drains	YES	100%	Completed

Ar. ASHISH SAWE CA/2001/28463 Registered Architect

6.	Landscaping & tree plantation	YES	100%	Completed
7.	Parks and playgrounds	YES	NIL	
	Fixing of children play equipment"s	YES	NIL	
	Benches	YES	NIL	
8.	Shopping area	YES	100%	Completed
9.	Street lighting/ electrification	YES	100%	Completed
10.	Treatment and disposal of sewage and sullage water/ STP	YES	100%	Completed
11.	Solid waste management & disposal	YES	100%	Completed
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	100%	Completed
13.	Energy management (solar)	YES	100%	Completed
14.	Fire protection and fire safety requirements	YES	100%	Completed
15.	Electrical meter room, sub-station, receiving station	YES	100%	Completed
16.	Other (option to add more)	--	NIL	
B-2	**Community building to be transferred to RWA**			
17.	Community centre	NO	NO	
18.	Others	--	--	

B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
21.	Club	YES	100%	Completed
22.	Others	YES	--	
B-4	**Services/ facilities to be transferred to competent authority**	--	--	
23.	*	NA	NA	

----------End of Report----------

