Arcop Associates Private Limited

Architecture
Planning
Urban Design
Interiors

Annexure A

Architect's Certificate*			
Report for quarter ending			*DEC-* 23
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	***PALM HEIGHTS (PART OF PALM HILLS) B16-01, B16-02 & B-17 (Tower -C, D, & E)***
	2.	Location	PALM HEIGHTS (PALM HILLS), SECTOR-77, GURUGRAM
	3.	Licensed area in acres	29.34675 ACRES
	4.	Area for registration in acres	5.50 Acres
	5.	HARERA registration no.	RC/REP/HARERA/GGM/2018/29 dated 28.11.2018
	6.	Name of licensee	56 of 2009 dated 31-08-09 & License No. 62 of 2013 dated 05-08-2013
	7.	Name of collaborator	ROBIN SOFTWARE LLP and OTHERS
	8.	Name of developer	M/S EMAAR INDIA LTD (Formerly known as M/s Emaar MGF Land Limited)
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	01-JAN- 24
	2.	Name of Architect/ Architect's firm	Mr. Pankaj Sanon / Ms ARCOP
	3.	Date of site inspection	31-DEC- 23

PANKAJ SANON
Council of Architecture
Registration No. CA/2001/28681
REGISTERED ARCHITECT

Regd. Office A – 15, Pamposh Enclave, G.K. -1, Outer Ring Road, New Delhi-110 048, India
CIN/LLPIN – U45201DL1985 PT C021337 Tel.: +91-11-2644 2050, Fax: +91-11-2644 2035
email: info@arcop.co.in, web: www.arcop.co.in

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Vikas Kalra
	2.	Structural consultant	AJAY GUPTA (M/s Perceptive Ideas Consulting Engineering Pvt Ltd.)
	3.	Proof consultant	
	4.	MEP consultant	PARADISE CONSULTANT KANWAR KISHEN
	5.	Site supervisor/incharge	Manoj Soni
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and tableB.		


Date : 09-1-2024	Yours faithfully,
Place:	Signature & name (in block letters) with stamp of architect
Council of Architect (CoA): Registration No.	CA/2001-28681
Council of Architect (CoA): Registration valid till (Date)	31-12-2032

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower C**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		-	398.67	0%
2	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		40.68	1,907.38	2%
3	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	6.81	263.99	3%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	11.08	508.69	2%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	15.23	593.05	3%
4	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	36.96	1,375.42	3%
	4.2	External (plaster, painting, facade, etc.)	7.79	301.92	3%

PANKAJ SANGVI
Council of Architecture
Registration No. CA/2001/28681
REGISTERED ARCHITECT

TOWER – C

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	NIL		NIL	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		25 Floors		100%	
6.	Total area on each floor		Completed		100%	
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower..... laid by end of quarter		25 floor		100%	
9.	Status of construction					
	(i)	Walls on floors	25 floor		100%	
	(ii)	Staircase	25 floor		100%	
	(iii)	Lift wells along with water proofing	25 floor		100%	
	(iv)	Lift lobbies/ common areas floor wise	25 floor		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Complete	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	Complete	100%
	(iv)	Electrical fittings/ lighting	Completed	100%
	(v)	Gas piping (if any)		
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZNOC	NA	NA
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.





Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower D**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		-	398.67	0%
2	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		37.78	1,823.08	2%
3	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	6.90	266.58	3%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	10.28	485.22	2%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	14.88	574.89	3%
4	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	34.32	1,206.34	3%
	4.2	External (plaster, painting, facade, etc.)	7.23	279.47	3%

PANKAJ SANON
Council of Architecture
Registration No. CA/2001/28681
REGISTERED ARCHITECT

TOWER – D

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	NIL		NIL	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		25 Floors		100%	
6.	Total area on each floor		Completed		100%	
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower..... laid by end ofquarter		25 floors		100%	
9.	Status of construction					
	(i)	Walls on floors	25 floors		100%	
	(ii)	Staircase	25 floors		100%	
	(iii)	Lift wells along with water proofing	25 floors		100%	
	(iv)	Lift lobbies/ common areas floor wise	25 floors		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	Completed	100%
	(iv)	Electrical fittings/ lighting	Completed	100%
	(v)	Gas piping (if any)		
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZNOC	NA	NA
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.





Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Tower E**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		-	401.06	0%
2	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	1,097.47	0%
3	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	-	146.32	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	281.76	0%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	310.38	0%
4	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	95.70	1,049.29	9%
	4.2	External (plaster, painting, facade, etc.)	30.35	184.08	16%

PANKAJ GANVIR
Council of Architecture
Registration No.
CA/2001/28681
REGISTERED ARCHITECT

TOWER – E

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA			
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2*	NIL		NIL	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		25 Floors		100%	
6.	Total area on each floor		Completed		100%	
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower..... laid by end of quarter		24 floors		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units		Completed		100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Completed	Completed	100%	100%
	(ii)	Electrical works including wiring	Completed	Completed	100%	100%
	(iii)	Plumbing works	Completed	Completed	100%	100%
12.	Status of wall plastering					
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Completed		100%	
	(ii)	In kitchen	Completed		100%	
14.	Status of flooring					
	(i)	Common areas	Completed		100%	
	(ii)	Units/ flats	Completed		100%	



Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work
15.	Status of white washing			
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Status of finishing			
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	Completed	100%
	(iv)	Electrical fittings/ lighting	Completed	100%
	(v)	Gas piping (if any)		
	(other than flat/units)			
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZNOC	NA	NA
18.	Waterproofing of terraces		Completed	100%
19.	Entrance lobby finishing		Completed	100%
20.	Status of construction of compound wall		Completed	100%

Note: (*) extend rows as per requirement.




Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of workdone	remarks
B-1	**Services**			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no.	Yes	100%	
	Open no.	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	0%	
8.	Shopping area	Yes	NA	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)	No	NA	
B-2	**Community building to be transferred to RWA**			
17.	Community centre	No	NA	
18.	Others	No	NA	
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools	No	NA	
20.	Dispensary	No	NA	
21.	Club	No	NA	
22.	Others	No	NA	
B-4	**Services/ facilities to be transferred to competent authority**			
23.	*			

Note: (*) extend as per requirement

PANKAJ SANON
Council of Architecture
Registration No.
CA/2001/28681
REGISTERED ARCHITECT