Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : +91 9811130867

Annexure A

Architect's Certificate			
Report for quarter ending			**30th September 2026**
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	Infinity
	2.	Location	Village Badshahpur, Sector-70, Badshahpur St, Gurugram, Haryana"
	3.	Licensed area in acres	4.3375 (Acre)
	4.	Area for registration in acres	4.3375 (Acre)
	5.	HARERA registration no.	04 of 2021 Dated 18.01.2021
	6.	Name of licensee	Pyramid Dream Homes LLP
	7.	Name of collaborator	NA
	8.	Name of developer	Pyramid Dream Homes LLP
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	12th October, 2026
	2.	Name of Architect/ Architect's firm	RAO & Associate (Vivek Singh Rao)
	3.	Date of site inspection	11th October, 2026

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Mr. Rahul Singh
	2.	Structural consultant	M/S NNC Design International
	3.	Proof consultant	NA
	4.	MEP consultant	M/S V Consulting
	5.	Site supervisor/Incharge	Mr. Jagdish Prasad
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date : 12.10.2026

Yours faithfully,

Place: Gurugram

Signature & name (in block letters) with stamp of architect

VIVEK SINGH RAO
B. Arch, F.I.V., F.I.I.A.
C.O.A. Reg. No. CA/99/25040
RAO AND ASSOCIATE
374, U.V., Ph-4, Gurgaon-15
Ph:- 4569374, 9811130867

Council of architects (CoA) : registration no. CA/99/25040

Council of architects (CoA) : registration valid till (31.12.2033)

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.

RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

Table – A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)	

A1 **Cumulative progress of the project/phase at the end of the quarter.**

Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)	0%	100%	100%
2.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0%	100%	100%
3.	**MEP**			
	3.1 Mechanical (lifts, ventilation, etc.)	0%	100%	100%
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	0%	100%	100%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	100%	100%
4.	**Finishing**			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	02%	100%	100%
	4.2 External (plaster, painting, facade, etc.)	0%	100%	100%

RAO AND ASSOCIATE * Architects, Engineers, Planners & Regd. Valuers * 374, Udyog Vihar, Ph-IV, Gurgaon

Ar. GAJRAJ SINGH RAO
G.D. Arch., F.I.I.A, F.I.V.

Ar. VIVEK SINGH RAO
B. Arch., P.G. (CMID), F.I.I.A., F.I.V.



RAO AND ASSOCIATE
374, Udyog Vihar, Rao Gajraj Singh Marg,
Phase-4, Gurugram-122015 Haryana, INDIA
E : raoarchitects@gmail.com W : www.raoarchitects.com
Landline : 0124 4569374, Mobile : **+91 9811130867**

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation				100%	
2.	Laying of foundation					
	(i)	Raft			100%	
	(ii)	Pile				
3.	Number of basement(s)					
	(i)	Basement Level 1	Not Applicable			
	(ii)	Basement level 2*	Not Applicable			
4.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
5	Total floors in the tower/ building		Nos of floors Residential Tower =87			
6.	Total area on each floor		39865.482 sq.m.			
7.	Stilt floor/ ground floor				100%	
8.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower ..... laid by end of quarter		0			
9.	Status of construction					
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with water proofing			100%	
	(iv)	Lift lobbies/ common areas floor wise			100%	
10.	Fixing of door and window frames in flats/ units				100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works				100%
	(ii)	Electrical works including wiring			100%	100%
	(iii)	Plumbing works			100%	100%
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			100%	
	(ii)	In kitchen			100%	
14.	Status of flooring					
	(i)	Common areas			100%	
	(ii)	Units/ flats			100%	

RAO AND ASSOCIATE Architects, Engineers, Planners & Valuers 374, Udyog Vihar, Ph-IV, Gurgaon

ARCHITECTS | ENGINEERS | INDUSTRIAL CONSULTANTS
INTERIOR DESIGNERS | VAASTU CONSULTANTS
TURNKEY PROJECTS | REGD. & APPROVED VALUERS
GOVT. OF INDIA - HSVP, MCG & HSIIDC EMPANELLED