Architect's Certificate[1]

Report for quarter ending	Q2 till Sep 2026
Subject	Certificate of progress of construction work

1. I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans

Sr. No.	Particulars	Information
1.	Project/Phase of the project	Godrej Aria & 101
2.	Location	Sector 79, Gurgaon, Haryana
3.	Licensed area in acres	13.60625
4.	Area for registration in acres	
5.	HARERA registration no.	HRERA(Reg.) 168/2017/313 (Regd. No. 61 of 2017 dated 17.08.2017)
6.	Name of licensee	Sterling Infrastructure Private Limited & KJS Colonisers Private Limited
7.	Name of collaborator	Wonder City Buildcon Pvt. Ltd.
8.	Name of developer	Wonder City Buildcon Pvt. Ltd.

2. Details related to inspection are as under

1.	Date of certifying of percentage of construction work/ site inspection	30th June 2026
2.	Name of Architect/ Architect's firm	Ar. Abhishek Verma
3.	Date of site inspection	30th June 2026

[1] On the letter head of the architect firm

<table>
<tr><td rowspan="7">3.</td><td colspan="3">Following technical professionals are appointed by promoter: - (as applicable)</td></tr>
<tr><td>Sr. No.</td><td>Consultants</td><td>Name</td></tr>
<tr><td>1.</td><td>Site engineer</td><td>GPL</td></tr>
<tr><td>2.</td><td>Structural consultant</td><td>Optimisation Consultants</td></tr>
<tr><td>3.</td><td>Proof consultant</td><td>---------</td></tr>
<tr><td>4.</td><td>MEP consultant</td><td>DCCE Pvt Limited</td></tr>
<tr><td>5.</td><td>Site supervisor/in-charge</td><td>GPL</td></tr>
<tr><td>4.</td><td colspan="3">I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.</td></tr>
<tr><td>5.</td><td colspan="3">I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.</td></tr>
</table>

The overall complete work done up to FY 26-27 Q2, is 100%

Yours Faithfully,

Abhishek Verma

Signature & Name with stamp of Architect : **ABHISHEK VERMA**

Council of Architects (CoA) Registration No. **CA/2004/33902**

Council of Architects (CoA) Registration valid till (Date) _____

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**EWS**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
2.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
1.	Excavation				100%	
2.	Laying of foundation					
	(i)	Raft			100%	
	(ii)	Pile			NA	
3.	Number of basement(s)					
	(i)	Basement Level 1			NA	
4.	Waterproofing of the above sub-structure (wherever applicable)				NA	
	Super-Structure Status					
5.	Total floors in the tower/ building		8		100%	
6.	Total area on each floor					
7.	Stilt floor/ ground floor		1		100%	
8.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower G+8=9 slabs laid by end of quarter					
9.	Status of construction					
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with water proofing			100%	
	(iv)	Lift lobbies/ common areas floor wise			100%	
10.	Fixing of door and window frames in flats/ units				100%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			100%	
	(ii)	Electrical works including wiring			100%	
	(iii)	Plumbing works			100%	
12.	Status of wall plastering					
	(i)	External plaster			100%	
	(ii)	Internal plaster			100%	
13.	Status of wall tiling					
	(i)	In bathroom			NA	
	(ii)	In kitchen			NA	

14.	Status of flooring			
	(i)	Common areas		100%
	(ii)	Units/ flats		100%
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Status of finishing			
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels		100%
	(ii)	Sanitary fixtures		100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting		100%
	(v)	Gas piping (if any)	NA	NA
	(other than flat/units)			
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		100%
18.	Waterproofing of terraces			100%
19.	Entrance lobby finishing			100%
20.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower A**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
5.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
6.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
7.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
8.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
21.	Excavation				100%	
22.	Laying of foundation					
	(iii)	Raft			100%	
	(iv)	Pile			NA	
23.	Number of basement(s) – 1 Nos					
	(ii)	Basement Level 1			100%	
24.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
25.	Total floors in the tower/ building		14		100%	
26.	Total area on each floor					
27.	Stilt floor/ ground floor		1		100%	
28.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower B+G+14=16 slabs laid by end of quarter				100%	
29.	Status of construction					
	(v)	Walls on floors			100%	
	(vi)	Staircase			100%	
	(vii)	Lift wells along with water proofing			100%	
	(viii)	Lift lobbies/ common areas floor wise			100%	
30.	Fixing of door and window frames in flats/ units				100%	
31.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(iv)	Mechanical works			100%	100%
	(v)	Electrical works including wiring			100%	100%
	(vi)	Plumbing works			100%	100%
32.	Status of wall plastering					
	(iii)	External plaster			100%	
	(iv)	Internal plaster			100%	
33.	Status of wall tiling					
	(iii)	In bathroom			100%	
	(iv)	In kitchen			100%	

34.	Status of flooring			
	(iii)	Common areas		100%
	(iv)	Units/ flats		100%
35.	Status of white washing			
	(iii)	Internal walls		100%
	(iv)	External walls		100%
36.	Status of finishing			
	(iv)	Staircase with railing		100%
	(v)	Lift wells		100%
	(vi)	Lift lobbies/ common areas floor wise		100%
37.	Status of installation			
	(within flat/unit)			
	(xii)	Doors and windows panels		100%
	(xiii)	Sanitary fixtures		100%
	(xiv)	Modular kitchen	NA	
	(xv)	Electrical fittings/ lighting		100%
	(xvi)	Gas piping (if any)	NA	
	(other than flat/units)			
	(xvii	Lifts installation		100%
	(xvii	Overhead tanks		100%
	(xix)	Underground water tank		100%
	(xx)	Firefighting fitting and equipment's as per CFO NOC		100%
	(xxi)	Electrical fittings in common areas		100%
	(xxii	Compliance to conditions of environment/ CRZ NOC		100%
38.	Waterproofing of terraces			100%
39.	Entrance lobby finishing			100%
40.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower B**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
9.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
10.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
11.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
12.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
41.	Excavation				100%	
42.	Laying of foundation					
	(v)	Raft			100%	
	(vi)	Pile			NA	
43.	Number of basement(s) -1 Nos					
	(iii)	Basement Level 1			100%	
44.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
45.	Total floors in the tower/ building		14		100%	
46.	Total area on each floor					
47.	Stilt floor/ ground floor		1		100%	
48.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower B+G+14=16 slabs laid by end of quarter				100%	
49.	Status of construction					
	(ix)	Walls on floors			100%	
	(x)	Staircase			100%	
	(xi)	Lift wells along with water proofing			100%	
	(xii)	Lift lobbies/ common areas floor wise			100%	
50.	Fixing of door and window frames in flats/ units				100%	
51.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(vii)	Mechanical works			100%	100%
	(viii)	Electrical works including wiring			100%	100%
	(ix)	Plumbing works			100%	100%
52.	Status of wall plastering					
	(v)	External plaster			100%	
	(vi)	Internal plaster			100%	
53.	Status of wall tiling					
	(v)	In bathroom			100%	
	(vi)	In kitchen			100%	

54.	Status of flooring			
	(v)	Common areas		100%
	(vi)	Units/ flats		100%
55.	Status of white washing			
	(v)	Internal walls		100%
	(vi)	External walls		100%
56.	Status of finishing			
	(vii)	Staircase with railing		100%
	(viii)	Lift wells		100%
	(ix)	Lift lobbies/ common areas floor wise		100%
57.	Status of installation			
	(within flat/unit)			
	(xxiii	Doors and windows panels		100%
	(xxiv	Sanitary fixtures		100%
	(xxv)	Modular kitchen	NA	
	(xxvi	Electrical fittings/ lighting		100%
	(xxvi	Gas piping (if any)	NA	
	(other than flat/units)			
	(xxvi	Lifts installation		100%
	(xxix	Overhead tanks		100%
	(xxx)	Underground water tank		100%
	(xxxi	Firefighting fitting and equipment's as per CFO NOC		100%
	(xxxi	Electrical fittings in common areas		100%
	(xxxi	Compliance to conditions of environment/ CRZ NOC		100%
58.	Waterproofing of terraces			100%
59.	Entrance lobby finishing			100%
60.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower C**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
13.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
14.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
15.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
16.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
61.	Excavation				100%	
62.	Laying of foundation					
	(vii)	Raft			100%	
	(viii)	Pile			NA	
63.	Number of basement(s) – 1 Nos					
	(iv)	Basement Level 1			100%	
64.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
65.	Total floors in the tower/ building		14		100%	
66.	Total area on each floor					
67.	Stilt floor/ ground floor		1		100%	
68.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower B+G+14=16 slabs laid by end of quarter				100%	
69.	Status of construction					
	(xiii)	Walls on floors			100%	
	(xiv)	Staircase			100%	
	(xv)	Lift wells along with water proofing			100%	
	(xvi)	Lift lobbies/ common areas floor wise			100%	
70.	Fixing of door and window frames in flats/ units				100%	
71.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(x)	Mechanical works			100%	100%
	(xi)	Electrical works including wiring			100%	100%
	(xii)	Plumbing works			100%	100%
72.	Status of wall plastering					
	(vii)	External plaster			100%	
	(viii)	Internal plaster			100%	
73.	Status of wall tiling					
	(vii)	In bathroom			100%	
	(viii)	In kitchen			100%	

74.	Status of flooring			
	(vii)	Common areas		100%
	(viii)	Units/ flats		100%
75.	Status of white washing			
	(vii)	Internal walls		100%
	(viii)	External walls		100%
76.	Status of finishing			
	(x)	Staircase with railing		100%
	(xi)	Lift wells		100%
	(xii)	Lift lobbies/ common areas floor wise		100%
77.	Status of installation			
	(within flat/unit)			
	(xxxi	Doors and windows panels		100%
	(xxx	Sanitary fixtures		100%
	(xxx	Modular kitchen	NA	
	(xxx	Electrical fittings/ lighting		100%
	(xxx	Gas piping (if any)	NA	
	(other than flat/units)			
	(xxxi	Lifts installation		100%
	(xl)	Overhead tanks		100%
	(xli)	Underground water tank		100%
	(xlii)	Firefighting fitting and equipment's as per CFO NOC		100%
	(xliii	Electrical fittings in common areas		100%
	(xliv	Compliance to conditions of environment/ CRZ NOC		100%
78.	Waterproofing of terraces			100%
79.	Entrance lobby finishing			100%
80.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower D**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
17.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
18.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
19.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
20.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
81.	Excavation				100%	
82.	Laying of foundation					
	(ix)	Raft			100%	
	(x)	Pile			NA	
83.	Number of basement(s) – 1 Nos					
	(v)	Basement Level 1			100%	
84.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
85.	Total floors in the tower/ building		13		100%	
86.	Total area on each floor					
87.	Stilt floor/ ground floor		1		100%	
88.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/ tower B+G+13=15 slabs laid by end of quarter				100%	
89.	Status of construction					
	(xvii	Walls on floors			100%	
	(xvii	Staircase			100%	
	(xix)	Lift wells along with water proofing			100%	
	(xx)	Lift lobbies/ common areas floor wise			100%	
90.	Fixing of door and window frames in flats/ units				100%	
91.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xiii)	Mechanical works			100%	100%
	(xiv)	Electrical works including wiring			100%	100%
	(xv)	Plumbing works			100%	100%
92.	Status of wall plastering					
	(ix)	External plaster			100%	
	(x)	Internal plaster			100%	
93.	Status of wall tiling					
	(ix)	In bathroom			100%	
	(x)	In kitchen			100%	

94.	Status of flooring			
	(ix)	Common areas		100%
	(x)	Units/ flats		100%
95.	Status of white washing			
	(ix)	Internal walls		100%
	(x)	External walls		100%
96.	Status of finishing			
	(xiii)	Staircase with railing		100%
	(xiv)	Lift wells		100%
	(xv)	Lift lobbies/ common areas floor wise		100%
97.	Status of installation			
	(within flat/unit)			
	(xlv)	Doors and windows panels		100%
	(xlvi	Sanitary fixtures		100%
	(xlvii	Modular kitchen	NA	
	(xlvii	Electrical fittings/ lighting		100%
	(xlix	Gas piping (if any)	NA	
	(other than flat/units)			
	(l)	Lifts installation		100%
	(li)	Overhead tanks		100%
	(lii)	Underground water tank		100%
	(liii)	Firefighting fitting and equipment's as per CFO NOC		100%
	(liv)	Electrical fittings in common areas		100%
	(lv)	Compliance to conditions of environment/ CRZ NOC		100%
98.	Waterproofing of terraces			100%
99.	Entrance lobby finishing			100%
100.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower E**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
21.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
22.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
23.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
24.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
101.	Excavation				100%	
102.	Laying of foundation					
	(xi)	Raft			100%	
	(xii)	Pile			NA	
103.	Number of basement(s) – 1 Nos					
	(vi)	Basement Level 1			100%	
104.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
105.	Total floors in the tower/ building		10		100%	
106.	Total area on each floor					
107.	Stilt floor/ ground floor		1		100%	
108.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/tower…B+G+10=12.Slabs (Including Basement) laid by end of quarter				100%	
109.	Status of construction					
	(xxi)	Walls on floors			100%	
	(xxii	Staircase			100%	
	(xxii	Lift wells along with water proofing			100%	
	(xxiv	Lift lobbies/ common areas floor wise			100%	
110.	Fixing of door and window frames in flats/ units				100%	
111.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xvi)	Mechanical works			100%	100%
	(xvii	Electrical works including wiring			100%	100%
	(xvii	Plumbing works			100%	100%
112.	Status of wall plastering					
	(xi)	External plaster			100%	
	(xii)	Internal plaster			100%	
113.	Status of wall tiling					
	(xi)	In bathroom			100%	

	(xii)	In kitchen		100%
114.	Status of flooring			
	(xi)	Common areas		100%
	(xii)	Units/ flats		100%
115.	Status of white washing			
	(xi)	Internal walls		100%
	(xii)	External walls		100%
116.	Status of finishing			
	(xvi)	Staircase with railing		100%
	(xvii	Lift wells		100%
	(xvii	Lift lobbies/ common areas floor wise		100%
117.	Status of installation			
	(within flat/unit)			
	(lvi)	Doors and windows panels		100%
	(lvii)	Sanitary fixtures		100%
	(lviii	Modular kitchen	NA	
	(lix)	Electrical fittings/ lighting		100%
	(lx)	Gas piping (if any)	NA	
	(other than flat/units)			
	(lxi)	Lifts installation		100%
	(lxii)	Overhead tanks		100%
	(lxiii	Underground water tank		100%
	(lxiv	Firefighting fitting and equipment's as per CFO NOC		100%
	(lxv)	Electrical fittings in common areas		100%
	(lxvi	Compliance to conditions of environment/ CRZ NOC		100%
118.	Waterproofing of terraces			100%
119.	Entrance lobby finishing			100%
120.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej Aria – Tower F**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
25.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
26.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
27.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
28.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status	done		proposed work	
121.	Excavation			100%	
122.	Laying of foundation				
	(xiii) Raft			100%	
	(xiv) Pile			NA	
123.	Number of basement(s)-1 Nos				
	(vii) Basement Level 1			100%	
124.	Waterproofing of the above sub-structure (wherever applicable)			100%	
	Super-Structure Status				
125.	Total floors in the tower/ building	10		100%	
126.	Total area on each floor				
127.	Stilt floor/ ground floor	1		100%	
128.	Status of laying of slabs floor wise			100%	
	Cumulative number of slabs in the building/tower…B+G+10=12. Slabs (Including Basement) laid by end of quarter			100%	
129.	Status of construction				
	(xxv Walls on floors			100%	
	(xxvi Staircase			100%	
	(xxvi Lift wells along with water proofing			100%	
	(xxvi Lift lobbies/ common areas floor wise			100%	
130.	Fixing of door and window frames in flats/ units			100%	
131.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xix) Mechanical works			100%	100%
	(xx) Electrical works including wiring			100%	100%
	(xxi) Plumbing works			100%	100%
132.	Status of wall plastering				
	(xiii) External plaster			100%	
	(xiv) Internal plaster			100%	
133.	Status of wall tiling				
	(xiii) In bathroom			100%	

	(xiv)	In kitchen		100%
134.	Status of flooring			
	(xiii)	Common areas		100%
	(xiv)	Units/ flats		100%
135.	Status of white washing			
	(xiii)	Internal walls		100%
	(xiv)	External walls		100%
136.	Status of finishing			
	(xix)	Staircase with railing		100%
	(xx)	Lift wells		100%
	(xxi)	Lift lobbies/ common areas floor wise		100%
137.	Status of installation			
	(within flat/unit)			
	(lxvi	Doors and windows panels		100%
	(lxvi	Sanitary fixtures		100%
	(lxix	Modular kitchen	NA	
	(lxx)	Electrical fittings/ lighting		100%
	(lxxi	Gas piping (if any)	NA	
	(other than flat/units)			
	(lxxii	Lifts installation		100%
	(lxxii	Overhead tanks		100%
	(lxxi	Underground water tank		100%
	(lxxv	Firefighting fitting and equipment's as per CFO NOC		100%
	(lxxv	Electrical fittings in common areas		100%
	(lxxv	Compliance to conditions of environment/ CRZ NOC		100%
138.	Waterproofing of terraces			100%
139.	Entrance lobby finishing			100%
140.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower A**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
29.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
30.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
31.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
32.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status	done	proposed work
141.	Excavation		100%
142.	Laying of foundation		
	(xv) Raft		100%
	(xvi) Pile		NA
143.	Number of basement(s) – 1 Nos		
	(viii) Basement Level 1		100%
144.	Waterproofing of the above sub-structure (wherever applicable)		100%
	Super-Structure Status		
145.	Total floors in the tower/ building	14	100%
146.	Total area on each floor		
147.	Stilt floor/ ground floor	1	100%
148.	Status of laying of slabs floor wise		100%
	Cumulative number of slabs in the building/tower…B+G+14=16. Slabs (Including Basement)laid by end of quarter		100%
149.	Status of construction		
	(xxix Walls on floors		100%
	(xxx Staircase		100%
	(xxxi Lift wells along with water proofing		100%
	(xxxi Lift lobbies/ common areas floor wise		100%
150.	Fixing of door and window frames in flats/ units		100%

151.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xxii Mechanical works			100%	100%
	(xxii Electrical works including wiring			100%	100%
	(xxiv Plumbing works			100%	100%

152.	Status of wall plastering		
	(xv) External plaster		100%
	(xvi) Internal plaster		100%
153.	Status of wall tiling		
	(xv) In bathroom		100%

	(xvi)	In kitchen		100%
154.	Status of flooring			
	(xv)	Common areas		100%
	(xvi)	Units/ flats		100%
155.	Status of white washing			
	(xv)	Internal walls		100%
	(xvi)	External walls		100%
156.	Status of finishing			
	(xxii	Staircase with railing		100%
	(xxii	Lift wells		100%
	(xxiv	Lift lobbies/ common areas floor wise		100%
157.	Status of installation			
	(within flat/unit)			
	(lxxv	Doors and windows panels		100%
	(lxxi	Sanitary fixtures		100%
	(lxxx	Modular kitchen	NA	
	(lxxx	Electrical fittings/ lighting		100%
	(lxxx	Gas piping (if any)	NA	
	(other than flat/units)			
	(lxxx	Lifts installation		100%
	(lxxx	Overhead tanks		100%
	(lxxx	Underground water tank		100%
	(lxxx	Firefighting fitting and equipment's as per CFO NOC		100%
	(lxxx	Electrical fittings in common areas		100%
	(lxxx	Compliance to conditions of environment/ CRZ NOC		100%
158.	Waterproofing of terraces			100%
159.	Entrance lobby finishing			100%
160.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower B**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
33.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
34.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
35.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
36.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status	done	proposed work
161.	Excavation		100%
162.	Laying of foundation		
	(xvii Raft		100%
	(xvii Pile		NA
163.	Number of basement(s) – 1 Nos		
	(ix) Basement Level 1		100%
164.	Waterproofing of the above sub-structure (wherever applicable)		100%
	Super-Structure Status		
165.	Total floors in the tower/ building	14	100%
166.	Total area on each floor		
167.	Stilt floor/ ground floor	1	100%
168.	Status of laying of slabs floor wise		100%
	Cumulative number of slabs in the building/tower…B+G+14=16. Slabs (Including Basement) laid by end of quarter		100%
169.	Status of construction		
	(xxxi Walls on floors		100%
	(xxxi Staircase		100%
	(xxx Lift wells along with water proofing		100%
	(xxx Lift lobbies/ common areas floor wise		100%
170.	Fixing of door and window frames in flats/ units		100%

171.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xxv Mechanical works			100%	100%
	(xxvi Electrical works including wiring			100%	100%
	(xxvi Plumbing works			100%	100%

172.	Status of wall plastering		
	(xvii External plaster		100%
	(xvii Internal plaster		100%
173.	Status of wall tiling		
	(xvii In bathroom		100%

	(xviii	In kitchen		100%
174.	Status of flooring			
	(xvii	Common areas		100%
	(xviii	Units/ flats		100%
175.	Status of white washing			
	(xvii	Internal walls		100%
	(xviii	External walls		100%
176.	Status of finishing			
	(xxv	Staircase with railing		100%
	(xxvi	Lift wells		100%
	(xxvi	Lift lobbies/ common areas floor wise		100%
177.	Status of installation			
	(within flat/unit)			
	(lxxx	Doors and windows panels		100%
	(xc)	Sanitary fixtures		100%
	(xci)	Modular kitchen	NA	
	(xcii	Electrical fittings/ lighting		100%
	(xciii	Gas piping (if any)	NA	
	(other than flat/units)			
	(xciv	Lifts installation		100%
	(xcv	Overhead tanks		100%
	(xcvi	Underground water tank		100%
	(xcvi	Firefighting fitting and equipment's as per CFO NOC		100%
	(xcvi	Electrical fittings in common areas		100%
	(xcix	Compliance to conditions of environment/ CRZ NOC		100%
178.	Waterproofing of terraces			100%
179.	Entrance lobby finishing			100%
180.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower C**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
37.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
38.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
39.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
40.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
181.	Excavation				100%	
182.	Laying of foundation					
	(xix)	Raft			100%	
	(xx)	Pile			NA	
183.	Number of basement(s) – 1 Nos					
	(x)	Basement Level 1			100%	
184.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
185.	Total floors in the tower/ building		14		100%	
186.	Total area on each floor					
187.	Stilt floor/ ground floor		1		100%	
188.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/tower…B+G+14=16. Slabs (Including Basement) laid by end of quarter				100%	
189.	Status of construction					
	(xxx	Walls on floors			100%	
	(xxx	Staircase			100%	
	(xxxi	Lift wells along with water proofing			100%	
	(xl)	Lift lobbies/ common areas floor wise			100%	
190.	Fixing of door and window frames in flats/ units				100%	
191.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xxvi	Mechanical works			100%	100%
	(xxix	Electrical works including wiring			100%	100%
	(xxx	Plumbing works			100%	100%
192.	Status of wall plastering					
	(xix)	External plaster			100%	
	(xx)	Internal plaster			100%	
193.	Status of wall tiling					
	(xix)	In bathroom			100%	

	(xx)	In kitchen		100%
194.	Status of flooring			
	(xix)	Common areas		100%
	(xx)	Units/ flats		100%
195.	Status of white washing			
	(xix)	Internal walls		100%
	(xx)	External walls		100%
196.	Status of finishing			
	(xxvi	Staircase with railing		100%
	(xxix	Lift wells		100%
	(xxx)	Lift lobbies/ common areas floor wise		100%
197.	Status of installation			
	(within flat/unit)			
	(c)	Doors and windows panels		100%
	(ci)	Sanitary fixtures		100%
	(cii)	Modular kitchen	NA	
	(ciii)	Electrical fittings/ lighting		100%
	(civ)	Gas piping (if any)	NA	
	(other than flat/units)			
	(cv)	Lifts installation		100%
	(cvi)	Overhead tanks		100%
	(cvii	Underground water tank		100%
	(cviii	Firefighting fitting and equipment's as per CFO NOC		100%
	(cix)	Electrical fittings in common areas		100%
	(cx)	Compliance to conditions of environment/ CRZ NOC		100%
198.	Waterproofing of terraces			100%
199.	Entrance lobby finishing			100%
200.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower D**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
41.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
42.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
43.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
44.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status		done		proposed work	
201.	Excavation				100%	
202.	Laying of foundation					
	(xxi)	Raft			100%	
	(xxii	Pile			NA	
203.	Number of basement(s) – 1 Nos					
	(xi)	Basement Level 1			100%	
204.	Waterproofing of the above sub-structure (wherever applicable)				100%	
	Super-Structure Status					
205.	Total floors in the tower/ building		14		100%	
206.	Total area on each floor					
207.	Stilt floor/ ground floor		1		100%	
208.	Status of laying of slabs floor wise				100%	
	Cumulative number of slabs in the building/tower B+G+14=16. Slabs (Including Basement) laid by end of quarter				100%	
209.	Status of construction					
	(xli)	Walls on floors			100%	
	(xlii)	Staircase			100%	
	(xliii	Lift wells along with water proofing			100%	
	(xliv	Lift lobbies/ common areas floor wise			100%	
210.	Fixing of door and window frames in flats/ units				100%	
211.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xxxi	Mechanical works			100%	100%
	(xxxi	Electrical works including wiring			100%	100%
	(xxxi	Plumbing works			100%	100%
212.	Status of wall plastering					
	(xxi)	External plaster			100%	
	(xxii	Internal plaster			100%	
213.	Status of wall tiling					
	(xxi)	In bathroom			100%	

	(xxii	In kitchen		100%
214.	Status of flooring			
	(xxi)	Common areas		100%
	(xxii	Units/ flats		100%
215.	Status of white washing			
	(xxi)	Internal walls		100%
	(xxii	External walls		100%
216.	Status of finishing			
	(xxxi	Staircase with railing		100%
	(xxxi	Lift wells		100%
	(xxxi	Lift lobbies/ common areas floor wise		100%
217.	Status of installation			
	(within flat/unit)			
	(cxi)	Doors and windows panels		100%
	(cxii	Sanitary fixtures		100%
	(cxiii	Modular kitchen	NA	
	(cxiv	Electrical fittings/ lighting		100%
	(cxv)	Gas piping (if any)	NA	
	(other than flat/units)			
	(cxvi	Lifts installation		100%
	(cxvi	Overhead tanks		100%
	(cxvi	Underground water tank		100%
	(cxix	Firefighting fitting and equipment's as per CFO NOC		100%
	(cxx)	Electrical fittings in common areas		100%
	(cxxi	Compliance to conditions of environment/ CRZ NOC		100%
218.	Waterproofing of terraces			100%
219.	Entrance lobby finishing			100%
220.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower E**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
45.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
46.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
47.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
48.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status	done		proposed work	
221.	Excavation			100%	
222.	Laying of foundation				
	(xxii Raft			100%	
	(xxiv Pile			NA	
223.	Number of basement(s) – 0 Nos				
	(xii) Basement Level 1			NA	
224.	Waterproofing of the above sub-structure (wherever applicable)			100%	
	Super-Structure Status				
225.	Total floors in the tower/ building	7		100%	
226.	Total area on each floor				
227.	Stilt floor/ ground floor	1		100%	
228.	Status of laying of slabs floor wise			100%	
	Cumulative number of slabs in the building/tower…G+7=8…Slabs laid by end of quarter			100%	
229.	Status of construction				
	(xlv) Walls on floors			100%	
	(xlvi Staircase			100%	
	(xlvi Lift wells along with water proofing			100%	
	(xlvi Lift lobbies/ common areas floor wise			100%	
230.	Fixing of door and window frames in flats/ units			100%	
231.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xxxi Mechanical works			100%	100%
	(xxx Electrical works including wiring			100%	100%
	(xxx Plumbing works			100%	100%
232.	Status of wall plastering				
	(xxii External plaster			100%	
	(xxiv Internal plaster			100%	
233.	Status of wall tiling				
	(xxii In bathroom			100%	
	(xxiv In kitchen			100%	

234.	Status of flooring			
	(xxiii	Common areas		100%
	(xxiv	Units/ flats		100%
235.	Status of white washing			
	(xxiii	Internal walls		100%
	(xxiv	External walls		100%
236.	Status of finishing			
	(xxxi	Staircase with railing		100%
	(xxx	Lift wells		100%
	(xxx	Lift lobbies/ common areas floor wise		100%
237.	Status of installation			
	(within flat/unit)			
	(cxxi	Doors and windows panels		100%
	(cxxi	Sanitary fixtures		100%
	(cxxi	Modular kitchen	NA	
	(cxxv	Electrical fittings/ lighting		100%
	(cxxv	Gas piping (if any)	NA	
	(other than flat/units)			
	(cxxv	Lifts installation		100%
	(cxxv	Overhead tanks		100%
	(cxxi	Underground water tank		100%
	(cxxx	Firefighting fitting and equipment's as per CFO NOC		100%
	(cxxx	Electrical fittings in common areas		100%
	(cxxx	Compliance to conditions of environment/ CRZ NOC		100%
238.	Waterproofing of terraces			100%
239.	Entrance lobby finishing			100%
240.	Status of construction of compound wall			100%

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**Godrej 101 – Tower F**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
49.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)				100%
50.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				100%
51.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)			100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			100%
52.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			100%
	4.2	External (plaster, painting, facade, etc.)			100%

Sr.	**Tasks/ Activity**	**Description of work**	**Percentage of total**

No.	Sub-Structure Status	done	proposed work
241.	Excavation		100%
242.	Laying of foundation		
	(xxv) Raft		100%
	(xxvi Pile		NA
243.	Number of basement(s) – 1 Nos		
	(xiii) Basement Level 1		100%
244.	Waterproofing of the above sub-structure (wherever applicable)		100%
	Super-Structure Status		
245.	Total floors in the tower/ building	6	100%
246.	Total area on each floor		
247.	Stilt floor/ ground floor	1	100%
248.	Status of laying of slabs floor wise		100%
	Cumulative number of slabs in the building/tower…B+G+6=8…Slabs. (Including Basement) laid by end of quarter		100%
249.	Status of construction		
	(xlix Walls on floors		100%
	(l) Staircase		100%
	(li) Lift wells along with water proofing		100%
	(lii) Lift lobbies/ common areas floor wise		100%
250.	Fixing of door and window frames in flats/ units		100%

251.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xxx Mechanical works			100%	100%
	(xxx Electrical works including wiring			100%	100%
	(xxxi Plumbing works			100%	100%

252.	Status of wall plastering		
	(xxv) External plaster		100%
	(xxvi Internal plaster		100%
253.	Status of wall tiling		
	(xxv) In bathroom		100%

	(xxvi	In kitchen		100%
254.	Status of flooring			
	(xxv)	Common areas		100%
	(xxvi	Units/ flats		100%
255.	Status of white washing			
	(xxv)	Internal walls		100%
	(xxvi	External walls		100%
256.	Status of finishing			
	(xxx	Staircase with railing		100%
	(xxx	Lift wells		100%
	(xxxi	Lift lobbies/ common areas floor wise		100%
257.	Status of installation			
	(within flat/unit)			
	(cxxx	Doors and windows panels		100%
	(cxxx	Sanitary fixtures		100%
	(cxxx	Modular kitchen	NA	
	(cxxx	Electrical fittings/ lighting		100%
	(cxxx	Gas piping (if any)	NA	
	(other than flat/units)			
	(cxxx	Lifts installation		100%
	(cxxx	Overhead tanks		100%
	(cxl)	Underground water tank		100%
	(cxli)	Firefighting fitting and equipment's as per CFO NOC		100%
	(cxlii	Electrical fittings in common areas		100%
	(cxlii	Compliance to conditions of environment/ CRZ NOC		100%
258.	Waterproofing of terraces			100%
259.	Entrance lobby finishing			100%
260.	Status of construction of compound wall			100%

Table – B (Godrej Aria & 101)

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	**Services**			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered Nos=1110.Nos (Godrej Aria - 434.Nos) Godrej 101 – 623 Nos) (EWS – 52 Nos)	Yes	100%	
	Open Nos=357 Nos (Godrej Aria - 145 Nos) (Godrej 101 - 208 Nos) (EWS – 16 Nos)	Yes	100%	
3.	Water supply		100%	
4.	Sewerage (chamber, lines, septic tanks, STP)		100%	
5.	Storm water drains		100%	
6.	Landscaping & tree plantation		100%	
7.	Parks and playgrounds		100%	
	Fixing of children play equipment's		100%	
	Benches		100%	
8.	Shopping area		100%	
9.	Street lighting/ electrification		100%	
10.	Treatment and disposal of sewage and sullage water/ STP		100%	
11.	Solid waste management & disposal		100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit		100%	
13.	Energy management (solar)		100%	
14.	Fire protection and fire safety requirements		100%	
15.	Electrical meter room, sub-station, receiving station		100%	
16.	Other (option to add more)			
B-2	**Community building to be transferred to RWA**			
17.	Community centre		100%	
18.	others			
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools			
20.	Dispensary			
21.	Club			
22.	Others			

B-4	**Services/ facilities to be transferred to competent authority**			
23.	Percentage of completion of construction work		100%	