

ACPL Design Ltd

E.24, South Extension I, New Delhi, 110049, India T: +91 11 4823 4444 +91 11 2462 2195 +91 11 2464 6709 F: +91 11 2463 4059

www.acplonline.com

			Annexure-A		
		Architect	's Certificate*		
Repor	t for quar	ter ending	31 <sup>st</sup> Dec 2020		
Subjec	et		Certificate of progress of construction work		
1.	I, KULMEET SHANGARI has undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Elan EPIC		
	2.	Location	Sector 70, Gurugram		
	3.	Licensed area in acres	4 Acres		
	4.	Area for registration in acres	3.525 Acres		
	5.	HARERA registration No.	RC/REP/HARERA/GGM/2018/30		
	6.	Name of licensee	Elan Limited		
	7.	Name of collaborator	NA		
	8.	Name of developer	Elan Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	06 <sup>th</sup> Jan 2021		
	2.	Name of Architect/Architect*sfirm	KULMEET SHANGARI (ACPL Design Ltd.)		
	3.	Date of site inspection	31st Dec 2020		
3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. Parvinder Singh		
	2.	Structural consultant	Perceptive Idea		
	3.	Proof consultant	Isha Consultant (P) Ltd.		
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pvt. Ltd., Ampower Consultancy Services.		
	5.	Site supervisor/incharge	Mr. Ankit Khandelwal		

CIN No.: U74999DL2009PLC188149



4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	Ialsocertifythatasonthedate, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and table B.

Date

: 06-01-2021

Place

: New Delhi

Council of architects (CoA) registration No.

: CA/97/21741

: 31.12.2024

Councilofarchitects(CoA) registration valid till (date)

Yours faithfully,

			Table – A			
(to be p	orepared s	ower no. separately for each building/ tower in the fthe project)	ELAN EPIC (Entire project is one	building)		
A1	Cum	ulative progress of the project/phase	at the end of the qu	arter.		
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		1922	4426	65%	
2.	(slabs	r structure ,brick work,block work,staircase, lift wells, ne rooms, water tank, etc.)	478	532	NA	
3.	MEP					
	3.1	Mechanical (lifts, ventilation, etc.)	NIL	NIL	NA	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	NIL	NIL	NA	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	NIL	NIL	NA	
4.	Finishing					
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)		NIL	NIL	NIL	
	4.2 External (plaster, painting, facade, etc.)		NIL	NIL	NIL	
Sr.	1	Trades/ Angle sys				
No.	Tasks/ Activity		Description doi		Percentage of total proposed work	
1.	Exc	Sub-Structure Status  Excavation In program		orace	100%	
2.		ing of foundation	III pros	51000	10076	
A20078V	(i) Raft *		In progress		100%	
	(ii) Pile		In prog		100%	
3	Number of basement(s)			73		
	(i) Basement Level 1		In prog	gress	80%	
	(ii) Basement level 2 & 3		In prog	In progress		



4.	Waterproofing of the above sub-structure (wherever applicable)		NIL		NIL		
		Super-Structure Status					
5.	Total	floors in the tower/ building	NIL		NIL		
6.	Total	area on each floor	N	IL	NII		
7.	Stilt f	loor/ ground floor	In progress		10%		
8.	Status of laying of slabs floor wise		In progress		10%		
		lative number of slabs in the building/ tower laid of quarter	N	NIL		NIL	
9.	Status	s of construction					
	(i) Walls on floors		N	TL	NIL		
	(ii)	Staircase	N	IL	NIL		
	(iii)	Lift wells along with water proofing	N	IL	NII	3	
	(iv)	Lift lobbies/ common areas floor wise	N	IL	NIL		
10.	Fixing	gofdoorand window frames in flats/ units	N	IL	NIL		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	N	IL	NIL	2	
	(ii)	Electrical works including wiring	NIL		NIL		
	(iii)	Plumbing works	NIL		NIL		
12.	Status	of wall plastering					
	(i) External plaster		NIL		NIL		
	(ii)	Internal plaster	NIL		NIL		
13.	Status	s of wall tiling					
	(i) In bathroom		N	NIL		NIL	
	(ii)	In kitchen	NIL		NIL		
14.	Status	s of flooring					
	(i)	Common areas	NIL		NIL		
	(ii)	Units/ flats	NIL		NIL		
15.	Status	of white washing					
	(i)	Internal walls	NIL		NIL		
•	(ii)	External walls	N	IL	NIL		
16.	Status	of finishing					
	(i) Staircase with railing		NIL		NIL		



	(ii)	Lift wells	NIL	NIL
	(iii)	Lift lobbies/ common areas floor wise	NIL	NIL
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	NIL	NIL
	(ii)	Sanitary fixtures	NIL	NIL
	(iii)	Modular kitchen	NIL	NIL
	(iv)	Electrical fittings/ lighting	NIL	NIL
	(v)	Gas piping (if any)	NIL	NIL
	(other	than flat/units)		
	(vi)	Lifts installation	NIL	· NIL
	(vii)	Overhead tanks	NIL	NIL
	(viii)	Underground water tank	NIL	NIL
	(ix)	Firefighting fitting and equipment"sas per CFO NOC	NIL	NIL
	(x)	Electrical fittings in common areas	NIL	NIL
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL
18.	Water	proofing of terraces	NIL	NIL
19.	Entran	ce lobby finishing	NIL	NIL
20.	Status	of construction of compound wall	NIL	NIL

Note: (\*) extend rows as per requirement.



Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services	ilina a sa	-	
Ι.	Internal roads & pavements	YES	NIL	
2.	Parking			
	Covered no572	YES	NIL	
	Open no Nil	YES	NIL	
3.	Water supply	YES	NIL	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	NIL	
5.	Storm water drains	YES	NIL	
6.	Landscaping & tree plantation	YES	NIL	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment"s	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	YES	NIL	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	NIL	
11.	Solid waste management & disposal	YES	NIL	
12.	Waterconservation, rain water, harvesting, percolating well/pit +	YES	NIL	
13.	Energy management (solar)	YES	NIL	
14.	Fire protection and fire safety requirements	YES	NIL	
15.	Electrical meter room, sub-station, receiving station	YES	NIL	
16.	Other (option to add more)	( <del>4</del>	NIL	
B-2	Community building t	o be transferre	ed to RWA	
17.	Community centre	NO	NO	
18.	Others		22	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
- 21.	Club	NO	NO	
22.	Others		120	
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

ARCHITECT CA/97/21741