		Architect	's Certificate [*]			
Repo	rt for qu	arter ending	30-June-19			
Subje	ect		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. Particulars No.		Information			
	li,	Project/Phase of the project	Sunrise premium floor			
	2.	Location	Sector-35, Karnal			
	3.	Licensed area in acres	6.5104 acre			
	4.	Area for registration in acres	6.5104 acre			
	5.	HARERA registration no.	269 of 2017 dated 09-Oct-2017			
	6.	Name of licensee	M/s Rose Building Solutions Pvt. Ltd.			
	7,.	Name of collaborator	NA			
	8.	Name of developer	M/s Rose Building Solutions Pvt. Ltd.			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	30-June-19			
	2.	Name of Architect/ Architect's firm	M/s Design Cosmos			
	3.	Date of site inspection	30-June-19			

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	_15	Site engineer	M/s NDCC Projects (opc) Pvt.Ltd.		
	2.	Structural consultant	M/s NNC design International		
	3.	Proof consultant	NA		
	4.	MEP consultant	M/s PKV Consulting Engineers		

Add.-A 609, Sushant Lok-1, Gurgaon 122002 ; Tel.- 0124 4203676; e-studio.designcosmos@gmail.com

APOORV SINGH CA/2008/42704

	5.	Site supervisor/incharge	M/s NDCC Projects (opc) Pvt.Ltd.		
4.	I certify that the work has been executed as per approved drawings, statutory/ manda approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and material used in the construction, infrastructure works and internal development works are per the projected standard as envisaged in the registration and brochure, publication material other documents shared with the buyers in this regard.				
5.	buildir and tal	ng/ tower of the real estate project	ercentage of work done in the project for each of the /phase of the project under HARERA is as per table A sentage of the work executed with respect to each of the ailed in table A and table B.		

Yours faithfully,

Signature & name (in block letters) with stamp of architect

Date: 30 · 05 · 17

Place: GURGAON (HARYANA)

Council of architects (COA): CA/2008/42704

Council of architects (COA): Dec 2017

registration valid till(date)

			Table – A		
(to b	e prep	Fower no. ared separately for each building/ e project/ phase of the project)	116 Nos. of Reside	ntial + 1 Commerci	al Building
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(incl foun	structure usive of excavation, dation, basements, water fing, etc.)	05%	45%	60%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		05%	10%	25%
3.	MEI				
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	10%	15%	20%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	05%	10%	20%
4.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	5%	10%

Add.-A 609, Sushant Lok-1, Gurgaon 122002 ; Tel.- 0124 4203676; e-studio.designcosmos@gmail.com



	4.2	External (plaster, painting, facade, etc.)	0%	5%		10%
Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed	
	-	Sub-Structure Status	Evaporation in	a andinom.	work 95%	
1,	Exc	avation		Excavation in ordinary Soil		93%
2.	Lay	ing of foundation				
	(i)	Raft	RCC of Build	ling Raft		70%
	(ii)	Pile	NA			NA
3.	Nun	nber of basement(s)				
	(i)	Basement Level 1	NA			NA
	(ii)	Basement level 2*	NA			NA
4,	Waterproofing of the above sub-structure (wherever applicable)		Applying Water Proofing Compound			10%
		Super-Structure Status				
5.	Total floors in the tower/ building		348N	os		42%
6.	Total area on each floor		42% of RCC works completed on total area			42%
7.	Stilt	floor/ ground floor	Work in progress			47%
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		(45% to 55%)			60%
9.	Status of construction					
	(i)	Walls on floors	RCC work in	progress		42%
	(ii)	Staircase	RCC work in	progress		35%
	(iii)	Lift wells along with water proofing	NA			NA

Add.-A 609, Sushant Lok-1, Gurgaon 122002 ; Tel.- 0124 4203676; e-studio.designcosmos@gmail.com



	(iv)	Lift lobbies/ common areas floor wise		NA		NA	
10.	Fixir flats/	ng of door and window frames in units	Work in progress		10%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	NA	Pumps & Electrical Panels	5%	0%	
	(ii)	Electrical works including wiring	Work in progress	Work in progress	30%	90%	
	(iii)	Plumbing works	Work in progress	Work in progress	25%	90%	
12.	Status of wall plastering						
	(i)	External plaster	Work in progress		0%		
	(ii)	Internal plaster	Work i	Work in progress		0%	
13,	Statu	s of wall tiling					
	(i)	In bathroom	Work i	Work in progress		5%	
	(ii)	In kitchen	Work i	Work in progress		10%	
14.	Statu	s of flooring					
	(i)	Common areas	Work in progress		5%		
	(ii)	Units/ flats	Work in progress		10%		
Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed		
	Sub-Structure Status				work		
15.	Status of white washing						
	(i)	Internal walls	Work in progress		5%		
	(ii)	External walls	Work in progress		5%		
16.	Status	s of finishing					

Add.-A 609, Sushant Lok-1, Gurgaon 122002; Tel.- 0124 4203676; e-studio.designcosmos@gmail.com



	(i)	Staircase with railing	Work in progress	12%
	(ii)	Lift wells	NA	NA
	(iii)	Lift lobbies/ common areas floor wise	NA	NA
17.	Statu	s of installation		
	(with	in flat/unit)		
	(i)	Doors and windows panels	Work in progress	10%
	(ii)	Sanitary fixtures	Yet to be start	0%
	(iii)	Modular kitchen		NA
	(iv)	Electrical fittings/ lighting	Yet to be start	0%
	(v)	Gas piping (if any)		NA
	(other	r than flat/units)		
	(vi)	Lifts installation	NA	NA
	(vii)	Overhead tanks	Yet to be start	0%
	(viii)	Underground water tank	Yet to be start	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be start	0%
	(x)	Electrical fittings in common areas	Yet to be start	0%
	(xi)	Compliance to conditions of environment/ CRZNOC	Yet to be start	0%
18.	Water	proofing of terraces	Works in Progress	10%
19.	Entrance lobby finishing		Yet to be start	0%
20.	Status	s of construction of compound wall	Works in Progress	100%

Add.-A 609, Sushant Lok-1, Gurgaon 122002 ; Tel.- 0124 4203676; e-studio.designcosmos@gmail.com

