LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-i, GURGAON, HARYANA EMAIL : $\underline{lofarchitectsgurgaon@gmail.com}$

Annexure A

	0.7	Architec	t's Certificate*			
Repor	t for qua	rter ending	30.06.2022			
Subjec	:t		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	SS100			
	2.	Location	Sector-49, Gurugram (Haryana)			
	3.	Licensed area in acres	160.60			
	4.	Area for registration in acres	1.334			
	5.	HARERA registration No.	21 of 2020			
	6.	Name of licensee	M/s SS Group Pvt. Ltd.			
	7.	Name of collaborator	M/s Uppal Housing Pvt. Ltd.			
	8.	Name of developer	M/s SS Group Pvt. Ltd.			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	30.06.2022			
	2.	Name of Architect/ Architect's firm				
	3.	Date of site inspection	30.06.2022			
3.	Follow	ing technical professionals are appoi	nted by promoter: - (as applicable)			
	Sr. No.	Consultants	Name			
	1.	Site engineer	Mr. Dheerender Kumar			
	2.	Structural consultant	DESMAN			
	3.	Proof consultant	Arvind Gupta			
	4.	MEP consultant	AEON			
	5.	Site supervisor/in charge	Mr.Rajesh Bhartonia			

LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-1, GURGAON, HARYANA EMAIL : $\underbrace{lofarchitectsgurgaon@gmail.com}$

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5	Lalco contify that as on the data the manager of small days in the minute of the latter of the latte

I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Ar KAPIL SINGH

Yours Faithfully

B. Arch.

Regn. No with Council of Architecture CA/2003/31608

Signature & Name (in block letters)
With stamp of Architect

Date

Place

Council of Architects (CoA): CA/2003/31608

Registration No.

Council of Architects (CoA) :31 Dec 2031

Registration valid till (Date)

			TABLE-A							
Buildi	ng No/	Tower No.	SS100							
A1	Cumulative Progress of the Project/Phase at the end of the Quarter									
Sr.No	Project Components		Work done value during the Quarter (In Lakh)	Cumulative Work done value till Date (In Lakh)	Percentage of work done to the total proposed work					
1	Sub St	tructure	NIL	1010	52.59%					
2	Super	Structure	367.06	716	32.3370					
3	MEP									
	3.1 Mechanical Work									
	3.2	Electrical Work								
11-23	3.3	Plumbing & Fire Fighting Work								
4	FINISH	HING								
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)								
	4.2	External (Plaster, Painting, Façade etc.)	N. T. C.							
Sr.No.		Tasks/ Activity		Description of Work Done	Percentage of total proposed work					
		Sub-Structure Statu	S							
1	Excav	Excavation		Complete	100%					
2	Laying	of Foundation		Complete	100%					
	(i)	Raft	Complete	100%						
3		er of Basements								
	(i)	Basement Level-1		In Progress	80%					
	(ii)	Basement Level-2	In Progress	80%						
		Basement Level-3	In Progress	80%						
4	1	/ater Proofing of the Above Sub-Structure (wherever oplicable)		In Progress	70%					
		Super-Structure State	6:45							
5		Total Floors in the Tower/ Building		G+15						
6 7	_	Area on each floor (Sq.Mtr.) Ground Floor		30423 2443.137						
/		s of Laying of slabs floor wise	2443.137							
8	Cumu	Cumulative number of the slabs in the Building/TowerI by end of the quarter		In Progress	0%					
9	Status	s of Construction	Nil	0%						
	(i) Walls on floors			Nil	0%					
	(ii) Staircase			Nil	0%					
	(iii)	Liftwells along with water proofing	Nil	0%						
	(iv)	Lift Lobbies/Common areas floor	Nil	0%						

10	Fixing	xing of Door & window frames in the Flats/Units		Nil		0%	
11	Status of MEP		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	5-2-304000-SSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSS	Internal (Externa	
			(with in	Work	with in	Work	
			Flat)		Flat)		
		(i) Walls on floors		Nil		0%	
	(ii)	Staircase	Nil		0%		
	(iii) Liftwells along with water proofing		Nil		0%		
12	Status of Wall Plastering						
	(i)	External Plaster	N	lil		0%	
	(ii) Internal Plaster		N	Nil		0%	
13	Status of Wall Tiling				× .		
	(i)	In Bath Rooms	N	Nil		0%	
	(ii)	In Kitchen	N	lil	0%		
14	Status	of Flooring					
	(i) Common Areas		N	Nil		0%	
.545	(ii)	Units/Flats	N	Nil		0%	
15	Status of White Washing		1 210				
	(i)	Internal Walls	N	lil	0	0%	
	(ii)	(ii) External Walls		Nil		0%	
16	Status of Finishing						
	(i)	Staircase with Railing	Nil		0%		
	(ii)	Lift Wells	N	lil	0	0%	
	(iii)	Lift Lobbies/Common areas floor wise	Nil		0%		
17	Status	Status of installation					
	(with	in Flats/ Units)					
The least	(i)	Doors & Windows Panels	Nil		0%		
	(ii)	Sanitary Fixtures	Nil		0%		
	(iii)	Modular Kitchen		Nil		0%	
	(iv)	Electrical Fittings/ Lightings		Nil		0%	
	(v)	Gas Piping (if any) Nil		Jil	0%		
	(other than Flats/ Units)						
	(vi)	Lift Installations	Nil		0%		
	(vii)	Over Head Tanks	N	Jil	0	%	
	(viii)	Under Ground Water Tanks		Nil		0%	
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC		Nil		0%	
	(x)	Electrical Fittings in Common Areas	Nil		0%		
	(xi)	Compliance to condition of environment/CRZ NOC		Nil		0%	
18	Water	Proofing of Terraces	Nil		0%		
19		Entrance Lobby Finishing		Nil		0%	
20	Status of Construction of Compound wall			Nil		0%	