

Architect's Certificate*																												
Report for quarter ending	30-Jun-22																											
Subject	Certificate of progress of construction work																											
1. I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans																												
<table border="1"> <tr> <th>Sr. No.</th> <th>Particulars</th> <th>Information</th> </tr> <tr> <td>1.</td> <td>Project/Phase of the project</td> <td>Signature Global Aspire</td> </tr> <tr> <td>2.</td> <td>Location</td> <td>Sector-95</td> </tr> <tr> <td>3.</td> <td>Licensed area in acres</td> <td>5.1125 Acre</td> </tr> <tr> <td>4.</td> <td>Area for registration in acres</td> <td>5.1125 Acre</td> </tr> <tr> <td>5.</td> <td>HARERA registration no.</td> <td>69 of 2019 Dated 14-11-2019</td> </tr> <tr> <td>6.</td> <td>Name of licensee</td> <td>M/s Signature Infrabuild India Pvt. Ltd</td> </tr> <tr> <td>7.</td> <td>Name of collaborator</td> <td>NA</td> </tr> <tr> <td>8.</td> <td>Name of developer</td> <td>M/s Signature Infrabuild India Pvt. Ltd</td> </tr> </table>	Sr. No.	Particulars	Information	1.	Project/Phase of the project	Signature Global Aspire	2.	Location	Sector-95	3.	Licensed area in acres	5.1125 Acre	4.	Area for registration in acres	5.1125 Acre	5.	HARERA registration no.	69 of 2019 Dated 14-11-2019	6.	Name of licensee	M/s Signature Infrabuild India Pvt. Ltd	7.	Name of collaborator	NA	8.	Name of developer	M/s Signature Infrabuild India Pvt. Ltd	
Sr. No.	Particulars	Information																										
1.	Project/Phase of the project	Signature Global Aspire																										
2.	Location	Sector-95																										
3.	Licensed area in acres	5.1125 Acre																										
4.	Area for registration in acres	5.1125 Acre																										
5.	HARERA registration no.	69 of 2019 Dated 14-11-2019																										
6.	Name of licensee	M/s Signature Infrabuild India Pvt. Ltd																										
7.	Name of collaborator	NA																										
8.	Name of developer	M/s Signature Infrabuild India Pvt. Ltd																										
2. Details related to inspection are as under																												
<table border="1"> <tr> <td>1.</td> <td>Date of certifying of percentage of construction work/ site inspection</td> <td>30-Jun-22</td> </tr> <tr> <td>2.</td> <td>Name of Architect/ Architect's firm</td> <td>ASM Architects</td> </tr> <tr> <td>3.</td> <td>Date of site inspection</td> <td>30-Jun-22</td> </tr> </table>	1.	Date of certifying of percentage of construction work/ site inspection	30-Jun-22	2.	Name of Architect/ Architect's firm	ASM Architects	3.	Date of site inspection	30-Jun-22																			
1.	Date of certifying of percentage of construction work/ site inspection	30-Jun-22																										
2.	Name of Architect/ Architect's firm	ASM Architects																										
3.	Date of site inspection	30-Jun-22																										



2022

3. Following technical professionals are appointed by promoter:- (as applicable)

Sr. No.	Consultants	Name
1.	Site engineer	Mr. Anurag aggarwal
2.	Structural consultant	NNC Design International
3.	Proof consultant	M/s Optimum Design Pvt. Ltd.
4.	MEP consultant	M/s CESPL
5.	Site supervisor/incharge	Mr. Anurag aggarwal

4. I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.

5. I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARRERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

DATE: **30-06-2022**

PLACE: **GHAZIABAD**

COA REGISTRATION NUMBER: **CA/2011/52543**

REGISTRATION VALID DATE: **31-12-2022**

Yours's Faithfully



Table - A

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		5+1 nos (Towers)		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	5%	100%	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	10%	52%	52%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)	0%	0%	0%
	3.2 Electrical (conducting, wiring, fixtures, etc.)	10%	30%	30%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	10%	20%	20%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%
	4.2 External (plaster, painting, facade, etc.)	0%	0%	0%



Ar. Ankur Goel

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Excavation in ordinary Soil		100%	
2.	Laying of foundation					
	(i)	Raft	RCC of Building Raft		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s)					
	(i)	Basement Level 1	NA		NA	
	(ii)	Basement level 2*	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Applying Water Proofing Compound		0%	
Super-Structure Status						
5.	Total floors in the tower/ building		100 Nos.		70%	
6.	Total area on each floor		55%of RCC works completed on total area		55%	
7.	Silt floor/ ground floor		Work in progress		75%	
8.	Status of laying of slabs floor wise		(55% to 65%)		62%	
9.	Cumulative number of slabs in the building/ towerlaid by end of quarter					
	Status of construction					
	(i)	Walls on floors	Work in progress		52%	
	(ii)	Staircase	Work in progress		52%	
	(iii)	Lift wells along with water proofing	Yet to be started		0%	
10.	(iv)	Lift lobbies/ common areas floor wise	Work in progress		52%	
	Fixing of door and window frames in flats/ units		Yet to be started		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%
	(ii)	Electrical works including wiring	Work in Progress	Yet to be started	18%	0%
	(iii)	Plumbing works	Yet to be started	Yet to be started	10%	0%
	Status of wall plastering					
12.	(i)	External plaster	Yet to be started		0%	
	(ii)	Internal plaster ..	Yet to be started		0%	
13.	Status of wall tiling					



ASM ARCHITECTS

ARCHITECTS # INTERIORS # PLANNING

14.	(i)	In bathroom	Yet to be started	0%
	(ii)	In kitchen	Yet to be started	0%
	Status of flooring			
	(i)	Common areas	Yet to be started	0%
	(ii)	Units/ Flats	Yet to be started	0%



Ver

Sr. No.	Tasks/ Activity	Description of work done	Percentage of total proposed work
	Sub-Structure Status		
15.	Status of white washing		
	(i) Internal walls	Yet to be started	0%
	(ii) External walls	Yet to be started	0%
16.	Status of finishing		
	(i) Staircase with railing	Yet to be started	0%
	(ii) Lift wells	Yet to be started	0%
17.	(iii) Lift lobbies/ common areas floor wise	Yet to be started	0%
	Status of installation		
	(within flat/unit)		
	(i) Doors and windows panels	Yet to be started	0%
	(ii) Sanitary fixtures	Yet to be started	0%
	(iii) Modular kitchen	NA	NA
	(iv) Electrical fittings/ lighting	Yet to be started	0%
	(v) Gas piping (if any)	NA	NA
	(other than flat/units)		
	(vi) Lifts installation	Yet to be started	0%
	(vii) Overhead tanks	Yet to be started	0%
	(viii) Underground water tank	Yet to be started	0%
	(ix) Firefighting fitting and equipment's as per CFO NOC	Yet to be started	0%
	(x) Electrical fittings in common areas	Yet to be started	0%
	(xi) Compliance to conditions of environment/ CRZ NOC	Yet to be started	0%
18.	Waterproofing of terraces	Yet to be started	0%
19.	Entrance lobby finishing	Yet to be started	0%
20.	Status of construction of compound wall(Fencing Work)	Completed	100%



Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage work done	of remarks
B-1	Services			
1.	Internal roads & pavements(Temporary)	Yes	100%	
2.	Parking	NA		
	Covered no.....	NA		
	Open no.....	NA		
3.	Water supply	Yes	30%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	20%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation(Temporary)	Yes	100%	
7.	Parks and playgrounds	Yes	50%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	40%	
9.	Street lighting/ electrification	Yes	10%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Site Office(Temporary)	Yes	100%	
B-2	Community building to be transferred to RWA			
17.	Community centre	Yes	0%	
18.	others	-	-	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			



20/5