

INDIVALUE ADVISORS PRIVATE LIMITED

Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044 Email: Indivalueadvisors@gmail.com Mobile +91-7044091174

CIN: U74999DL2021PTC381050

IVAPL/01/102022/M3M 84 Market

		Architect	's Certificate*		
Report fo	r quarter e	ending	July – Sept 2022		
Subject	-		Certificate of Percentage of completion of construction work of the project at the end of the quarter		
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr.No.	Particulars	Information		
	1.	Project/Phase of the project	M3M 84 Market (COMMERCIAL PLOTTED COLONY)		
	2.	Location	Sector 84 Gurugram Haryana		
	3.	Licensed area in acres	5.9407 Acres		
	4.	Area for registration in acres	5.9407 Acres		
	5.	HARERA registration no.	RC/REP/HARERA/GGM/366/87/2019/60 dated -15.10.201 (60 OF 2019 dated 15.10.2019)		
	6.	Name of licensee	122 of 2019 dated 17.09.2019 granted to M3M India Private Limited & (Smt. Pushpa Dhanuka, Sh. Manish Dhanuka, Sh Arun Kumar Dhanuka, Smt. Mamta Dhanuka (Mamta Devi)		
	7.	Name of collaborator	M3M India Private Limited,		
	8.	Name of developer	M3M India Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	03.10.2022		
	2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe		
	3.	Date of site inspection	03.10.2022		

	Following technical professionals are appointed by promoter: - (as applicable)				
3.	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. Lalit Tyagi		
	2.	Structural consultant	Optimum Design Pvt. Ltd.		
	3.	Proof consultant	Proof Consultancy IIT Roorki		
	4.	MEP consultant	Kanwar Krishen Associates Pvt. Ltd		
	5.	Site supervisor/in charge	Mr. Lalit Tyagi		

1 | Page rera@indivalue.org I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 03.10.2022

Issued without prejudice,

Name:-Ar. ASHISH SAWE

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:.CA/2001/28463

(CoA)

Registration valid till (date)

: 31-12-2023

Table - A

(to b	e p	repar	wer no. red separately for each building/ project/ phase of the project)	M3M 84 Market	is a commercial plo	otted colony.	
A1	C	Cumulative progress of the project/phase at the end of the quarter.					
Sr. No.	P	Project components		Work done value during the quarter (Sq.mt.)	Cumulative work done value till date (sq.mt.)	Percentage of work done to the total proposed work (%)	
1.	(I	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)		N.A.	N.A.	N.A.	
2.	(S	labs,	structure brick work, block work, stair ft wells, machine rooms, water tc.)	N.A.	N.A.	N.A.	
3.	M	MEP					
	3.		Mechanical (Lifts, ventilation, etc.)	N.A.	N.A.	N.A.	
	3.	1	Electrical (conduiting, wiring, fixtures, etc.)	N.A.	N.A.	N.A.	
	3.	pı	Plumbing &Fire fighting (piping, pumps and pump room, fixtures, etc.)		N.A.	N.A.	
4.	Fi	inishing					
4.		F	nternal(plaster, tilling, flooring, painting, etc. within units and common areas)	N.A.	N.A.	N.A.	
	4.2	4.2 External (Plaster, painting, facade, etc.)		N.A.	N.A.	N.A.	
C			T-1-/6-11				
Sr. No.			Tasks/ Activity Sub-Structure Status		ription of ork done	(%) of total proposed work	
1.			ivation		N.A.	N.A.	
2.		Laying of foundation			N. A.		
		(i)	Raft	N.A.		N.A.	
		(ii)	Pile		N.A.	N.A.	
3.		Num	nber of basement(s) (4)				
		(i) Basement Level 1		icu a	N.A.	N.A.	

	(ii)	Basement level 2*		N.A.	P	J.A.
	(iii)	Basement level 3		N.A.	ı	I.A.
	(iv)	Basement level 4		N.A.		I.A.
4.	1	erproofing of the above sub-structure erever applicable)				
		Super-Structure Status				
5.	Tota	l floors in the tower/ building		N.A.	N.A.	
6.	Tota	l area on each floor		N.A.	N	I.A.
7.	Stilt	floor/ ground floor	N.A.		N	I.A.
8.	Statu	us of laying of slabs floor wise		N.A.	N	I.A.
A-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		ulative number of slabs in the ling/ tower (6) laid by end of quarter		N.A.	N	I.A.
9.	Status of construction					
	(i)	Walls on floors	N.A.		N.A.	
	(ii)	Staircase	N.A.		N.A.	
	(iii)	Lift wells along with water proofing	N.A.		N.A.	
	(iv)	Lift lobbies/ common areas floor wise		N.A.	N	.A.
10.	Fixing units	g of door and window frames in flats/				
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	Exter nal work
	(i)	Mechanical works	F	V.A.	N	.A.
	(ii)	Electrical works including wiring	N.A.		N.A.	
	(iii)	Plumbing works	N.A.		N.A.	
12.	Statu	s of wall plastering	-			
	(i)	External plaster	N.A.		N.A.	
	(ii)	Internal plaster	N.A.		N.A.	
13.	Status of wall tiling					
	(i)	In bathroom	N.A.		N.A.	
	(ii)	In kitchen	N	v.A.	N.	Α.
14.	Status	s of flooring				
			N			



	(ii)	Units/ flats	N.A.		N.A.	
Sr. No.		Tasks/Activity Sub-Structure Status	Description of w done		6)of total proposed work	
15.	Statu	us of white washing				
	(i)	Internal walls	N.A.		N.A.	
	(ii)	External walls	N.A.		N.A.	
16.	Status of finishing					
	(i)	Staircase with railing	N.A.		N.A.	
	(ii)	Lift wells	N.A.		N.A.	
	(iii)	Lift lobbies/ common areas floor wise	N.A.		N.A.	
17.	Statu	s of installation				
	(with	in flat/unit)			A	
	(i)	Doors and windows panels	N.A.		N.A.	
	(ii)	Sanitary fixtures	N.A.		N.A.	
	(iii)	Modular kitchen	N.A.		N.A.	
	(iv)	Electrical fittings/ lighting	N.A.		N.A.	
	(v)	Gas piping (if any)	N.A.		N.A.	
	(othe	er than flat/units)				
	(vi)	Lifts installation	N.A.		N.A.	
	(vii)	Overhead tanks	N.A.		N.A.	
	(viii)	Underground water tank	N.A.		N.A.	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N.A.		N.A.	
	(x)	Electrical fittings in common areas	N.A.		N.A.	
	(xi) Compliance to conditions of environment/ CRZNOC		N.A.		N.A.	
18.	Wate	rproofing of terraces	N.A.		N.A.	
19.	Entrance lobby finishing		N.A.		N.A.	
20.	Statu	s of construction of compound wall	N.A.		N.A.	
Sr. No	. Co	mmon areas and facilities amenities	Proposed (Yes/ No)	(%)of work done	Remarks	
B-1		rvices	The second secon		-	
1.	Int	ernal roads & pavements	Yes	100%	Complete	

CA/2901/28463 +

2.	Parking				
	Covered no. Not Started	No	N.A.	N.A.	
	Open	Yes	100%	Complete	
3.	Water supply	Yes	100%	Complete	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	Complete	
5.	Storm water drains	Yes	100%	Complete	
6.	Landscaping & tree plantation	Yes	100%	Complete	
7.	Parks and playgrounds	No	N.A.	N.A.	
	Fixing of children play equipment's	No	N.A.	N.A.	
	Benches	No	N.A.	N.A.	
8.	Shopping area	No	N.A.	N.A.	
9.	Street lighting/ electrification	Yes	100%	Complete	
10.	Treatment and disposal of sewage and Sullage water/ STP	Yes	100%	Complete	
11.	Solid waste management & disposal	Yes	100%	Complete	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	Complete	
13.	Energy management (solar)	No	NA	NA	
14.	Fire protection and fire safety requirements	Yes	100%	Complete	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	Complete	
16.	Other (option to add more)	No	N.A.	N.A.	
B-2	Community building to be transferred to RWA				
17.	Community Centre	No	N.A.	N.A.	
18.	Others	No	N.A.	N.A.	
B-3	Community buildings not to be transferred to RWA/competent authority				
19.	Schools	No	N.A.	N.A.	
20.	Dispensary	No	N.A.	N.A.	
21.	Club	No	N.A.	N.A.	
22.	Others	No	N.A.	N.A.	
B-4	Services/ facilities to be transferred to competer	nt authority			
23.	*	No	N.A.	N.A.	

----End of Report----

03-10-2022 M3M SCO 84









ARCHI