INDIVALUE ADVISORS PRIVATE LIMITED



Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044 Email: <u>Indivalueadvisors@gmail.com</u> Mobile +91-7044091174

CIN: U74999DL2021PTC381050

IVAPL01//0102022/ M3M 113 Market

Subject			July - Sept 2022 Certificate of Percentage of completion of construction work of the project at the end of the quarter			
						1.
	Sr.No.	Particulars	Information			
	1.	Project/Phase of the project	M3M 113 Market (COMMERCIAL PLOTTED COLONY)			
	2.	Location	Sector 113, Gurugram Haryana			
	3.	Licensed area in acres	8.526 Acres			
	4.	Area for registration in acres	8.526 Acres			
	5.	HARERA registration no.	RC/REP/HARERA/GGM/365/86/2019/59 DATED- 15.10.2019 (59 OF 2019 dated 15.10.2019)			
	6.	Name of licensee	Licence No. 123 of 2019 dated 17.09.2019 granted to Le Buildtech Private Limited			
	7.	Name of collaborator	N.A.			
	8.	Name of developer	Lekh Buildtech Private Limited			
2.	Details 1	Date of certifying of percentage of construction work/ site inspection	03.10.2022			
	2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe			
	3.	Date of site inspection	03.10.2022			
3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer	Mr. Lalit Tyagi			
	.2.	Structural consultant	Engineering Design & Research Pvt. Ltd			
	3.	Proof consultant	N.A.			
	4.	MEP consultant	Aeon Integrated Building Design Consultants LLP			
	5.	Site supervisor/in charge	Mr. Lalit Tyagi			
4.	Haryana the cons	Building Code, 2017/ National B struction, infrastructure works a I as envisaged in the registration	as per approved drawings, statutory/ mandatory approvals, uilding Code (wherever applicable) and the material used in internal development works are as per the projected and brochure, publication material and other documents			
	snared v	vith the buyers in this regard.	KSHISA			

I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 03.10.2022

Issued without prejudice,

Name:- Ar. ASHISH SAWE

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

: CA/2001/28463

(CoA)

Registration valid till (date)

: 31-12-2023

		T	able – A			
(to b	e pre	Tower no. pared separately for each building/ the project/ phase of the project)	SCO 113 (Shop Cur development colon		ercial plotted	
A1	Cur	ulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total	
	10		(Sq.mt.)	(sq.mt.)	proposed work (%)	
1.	(Inc	o structure clusive of excavation, foundation, sements, water proofing, etc.)	N.A.	N.A.	N.A.	
2.	(Sla	per structure abs, brick work, block work, stair case, wells, machine rooms, water tank, etc.)	N.A.	N.A.	N.A.	
3.	MEP					
3.	3.1	Mechanical (Lifts, ventilation, etc.)	N.A.	N.A.	N.A.	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	N.A.	N.A.	N.A.	
	3.3	Plumbing &Fire fighting (piping, pumps and pump room, fixtures, etc.)	N.A.	N.A.	N.A.	
4.	Finis	hing				
	4.1	Internal(plaster, tilling, flooring, painting, etc. within units and common areas)	N.A.	N.A.	N.A.	
	4.2	External (Plaster, painting, facade, etc.)	N.A.	N.A.	N.A.	
Sr.		Tasks/ Activity	Description o	of work	(%) of total	
No.		Sub-Structure Status	done	I	proposed work	
1.	E	Excavation	N.A.		N.A.	
2.		aying of foundation	N.A.		N.A.	
	- 2	(i) Raft	N.A.		N.A.	
	((ii) Pile	N.A.		N.A.	
3.		Number of basement(s) (4)		an escape	N.A.	
	((i) Basement Level 1	N.A.	R. ASHISH	N.A.	

No.		Sub-Structure Status	done		proposed work	
Sr.	Tasks/Activity		Description of work		(%)of total	
	(ii)	Units/ flats	N.A.		N.A.	
	(i)	Common areas	N.A.		N.A.	
14.	Status of flooring					
	(ii)	In kitchen	N.A.		N.A.	
10.	(i)	In bathroom	N.A.		N.A.	
13.	Status of wall tiling					
	(ii)	Internal plaster	N.A.		N.A.	
	(i) External plaster		N.A.		N.A.	
12.	Status of wall plastering					
	(iii)	Plumbing works	N.A.		N.A.	
	(ii)	Electrical works including wiring	N.A.		N.A.	
	(i)	Mechanical works	N.A.		iidt)	N.A.
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
10.	Fixing units	g of door and window frames in flats/	N.A.		N.A.	
	(iv)	Lift lobbies/ common areas floor wise	N.A.		N.A.	
	(iii)	Lift wells along with water proofing	N.A.		N.A.	
	(ii)	Staircase	N.A.		N.A.	
	(i)	Walls on floors	oors N.A.		N.A.	
9.		s of construction				
	8 ST0-20	ulative number of slabs in the ing/ tower (6) laid by end of quarter	N.A.		N.A.	
8.	Statu	s of laying of slabs floor wise	N.A.		N.A.	
7.	Stilt f	loor/ ground floor	N.A.		N.A.	
6.	Total	area on each floor	N.A.		N.A.	
5.	Total	floors in the tower/ building	N.A.		N.A.	
	_	-Structure Status				
4.	Wate	erproofing of the above sub-structure rever applicable)	N.A.		N.A.	
	(ii)	Basement level 2*	N.A.			N.A.

15.	Status of white washing							
	(i)	Internal walls	N.A.		N.A.			
	(ii)	External walls	N.A.		N.A.			
16.	Status of finishing							
	(i)	Staircase with railing	N.A.		N.A.			
	(ii)	Lift wells	N.A.		N.A.			
	(iii)	Lift lobbies/ common areas floor wise	N.A.		N.A.			
17.	Status of installation							
	(within flat/unit)							
	(i)	Doors and windows panels	N.A.		N.A.			
	(ii)	Sanitary fixtures	N.A.		N.A.			
	(iii)	Modular kitchen	N.A.		N.A.			
	(iv)	Electrical fittings/ lighting	N.A.		N.A.			
	(v)	Gas piping (if any)	N.A.		N.A.			
	(othe	(other than flat/units)						
	(vi)	Lifts installation	N.A.		N.A.			
	(vii)	Overhead tanks	N.A.		N.A.			
	(viii)	Underground water tank	N.A.		N.A.			
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N.A.		N.A.			
	(x)	Electrical fittings in common areas	N.A.		N.A.			
60	(xi)	Compliance to conditions of environment/ CRZNOC	N.A.		N.A.			
18.	Wat	erproofing of terraces	N.A.	N.A.				
19.	Entr	ance lobby finishing	N.A.		N.A.			
20.	Stati	Status of construction of compound wall N.A.			N.A.			
Sr. No.		Common areas and facilities amenities	Proposed (Yes/ No)	(%) of work done	Remarks			
B-1		Services			T			
1.		Internal roads & pavements	Yes	100%	Completed			
2.		Parking						
		Covered no.	N.A.	N.A.	N.A.			
		Open no.	Yes	100%	Completed			
3		Water supply	Yes	100%	Completed			

23.	*	No	N.A.	N.A.	
B-4	Services/ facilities to be transferred to competent authority				
22.	Others	No	N.A.	N.A.	
21.	Club	No	N.A.	N.A.	
20.	Dispensary	No	N.A.	N.A.	
19.	Schools	No	N.A.	N.A.	
B-3	Community buildings not to be transferre	d to RWA/compe	tent authority		
18.	Others	No	N.A.	N.A.	
17.	Community Centre	No	N.A.	N.A.	
B-2	Community building to be transferred to			_	
16.	Other (option to add more)	No	N.A.	N.A.	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	Completed	
14.	Fire protection and fire safety requirements	No	N.A.	N.A.	
13.	Energy management (solar)	No	N.A.	N.A.	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	Completed	
11.	Solid waste management & disposal	Yes	100%	Completed	
10.	Treatment and disposal of sewage and Sullage water/ STP	Yes	100%	Completed	
9.	Street lighting/ electrification	Yes	100%	Completed	
8.	Shopping area	No	N.A.	N.A.	
	Benches	No	N.A.	N.A.	
	Fixing of children play equipment's	No	N.A.	N.A.	
7.	Parks and playgrounds	No	N.A.	N.A.	
6.	Landscaping & tree plantation	Yes	100%	Completed	
5.	Storm water drains	Yes	100%	Completed	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	Completed	

-----End of Report-----

03-10-2022 M3M SCO 113

