

• ARCHITECTURE • URBAN DESIGN • TOWN PLANNING •

## ANNEXURE 6-A ARCHITECT'S CERTIFICATE

To whom so ever it may concern

REPORT FOR QUARTER ENDING

1st July 2022 - 30th Sep 2022

Subject: Certificate of progress of construction work:

Sr. Particulars No.		Information		
i.	Project/Phase of the project	Vijaylaxmi Greens-II		
ii.	Location	Village Jaundi, Sector-29, Jhajjar, Haryana		
iii.	Area in acres	13.356 ACRES		
vi.	HARERA Registration No.	HRERA-PKL-JJR-266-2021 Dated 12.10.2021		
v.	Name of Licensee	Vijaylaxmi Infrabuild Pvt. Ltd.		
vi.	Name of Collaborator	-NA-		
vii.	Name of Developer	Vijaylaxmi Infrabuild Pvt. Ltd.		

Sir,

1. If We have undertaken assignment as architect for certifying progress of construction work in the above mentioned project as per the approvedplans.

i.	Date of certifying of percentage of construction work/ site inspection	07/10/2022
ii.	Name of Architect/Architect's firm	DESIGN FORUM INTERNATIONAL
iii.	Date of site inspection	04/10/2022

2. Following technical professionals are appointed by Promoter: - (asapplicable)

Sr.No.	Consultants	Name	
i.	Site Engineer	VINEET RATHOR	
ii.	Structural Consultant	SAYED TAJUDDIN ASHRAF	
iii.	Proof Consultant	-NA-	
vi.	i. MEP Consultant BIKRAMJII		
v.	Site supervisor/incharge	VIKASH	

3. I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B.

ANOJ TEVATIA B. Arch. (Hons.) PW CA/95/18739



Yours Faithfully,



Signature & Name (IN BLOCK LETTERS) with stamp of Architect Council of Architects (CoA) RegistrationNo.CA/ 95 / 10739

Council of Architects (CoA) Registration validtill(Date) 31 · 12 · 2030

## Table – A

Building/Towerno. \_\_NA-\_\_\_(to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks/Activity	Description done	of work	Percentag proposed	
A1	SUB- STRUCTURE STATUS	-NA-			
1.	Excavation	1			
2.	Laying of foundation				
	i. Raft				
	ii. Pile				
3.	Number of basement(s)				
	i. Basement level1				
	ii. Basement level2*				
4.	Waterproofing of the above sub- structure (wherever applicable)				
A2	SUPER- STRUCTURE STATUS				
5.	Total floors in the tower/building				
6.	Total area on each floor				
7.	Stilt Floor/ Ground Floor				
8.	Status of laying of slabs floor wise				
	Cumulative number of slabs in the building/towerlaid byend of quarter				
9.	Status of construction				
	i. Walls onfloors				
	ii. Staircase				
	iii. Lift wells along with waterproofing				
	iv. Lift lobbies /common areas floorwise				
10.	Fixing of door and window frames in flats/units				
11.	Status of MEP	Internal (within Flat)	External works	Internal (within Flat)	External works
	i. Mechanicalworks	-NA-			
	ii. Electrical works including wiring	-NA-			
	iii. Plumbing works	-NA-			

ANOJ TEVATIA

B. Arch. (Hous.)

CA/95/18739

12.	Status of wall finishing ( plaster/paint/ whitewashing/coating)	-NA-	
	i. External		
	ii. Internal		
13.	Status of wall tiling		
	i. Inbathroom		
	ii. InKitchen		
14.	Status of flooring		
	i. Commonareas		
	ii. Units/flats		
15.	Status of other civil works		
	i. Staircase with railing		7
	ii. Liftwells		
	iii. Lift lobbies /common areas floorwise		
16.	Status of Installation		
	(Within flat/unit)		
	i. Doors and windowspanels		
	ii. SanitaryFixtures		
	iii. Modular Kitchen		
	iv. Electricalfittings/Lighting		
	v. Gas piping (ifany)		
	(Other than flat/units)		
	vi. Liftsinstallation		
	vii. Overhead tanks		
	viii. Underground water tank		
	ix. Firefighting fittings and equipment's as per CFONOC		
	x. Electrical fittings in commonareas		
	xi. Compliance to conditions of environment /CRZNOC		
17.	Waterproofing of terraces	-NA-	
18.	Entrance lobby finishing	-NA-	
19.	Status of construction of Compound wall	-NA-	

Table – B

Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of WorkDone	Remarks		
<b>3</b>	B-1 Services					
1.	Internal roads & pavements	YES	100%			
2.	Parking	NO	-NA-			
	Coveredno	NO	-NA-			
	Openno	NO	-NA-			
3.	Water supply	YES	100%			
4.	Sewerage (Chamber, Lines, Septic Tank, STP)	YES	100%			
5.	Storm water drains	YES	100%			
6.	Landscaping & tree plantation	YES	100%			
7.	Parks and playgrounds	YES	100%			
	Fixing of children play equipment's	YES	100%			
	Benches	YES	100%			
8.	Shopping Area	NO	NA			
9.	Street Lighting	YES	100%			
10.	Treatment and disposal of sewage and sullage water/STP	YES	100%			
11.	Solid Waste Management & disposal	NO				
12.	Water Conservation, Rain Water Harvesting, Percolating Well/Pit	YES	100%			
13.	Energy management (Solar)	NO				
14.	Fire Protection and Fire Safety Requirements	NO				
15.	Electrical meter room, Sub-Station, Receiving station	YES	100%			
16.	Boundary wall	YES	100%			
17.	Hard Landscape	YES	100%			
18.	Security system	YES	100%	011		
19.	DWC	YES	100%	Ano		

B. Arch. (Hons.)

B-2	Community building to be transferred to RWA		
20.	Community centre	NO	
21.	Others	NO	

B-3	Community buildings not to be transferred to RWA/Competent Authority		
22.	Schools	NO	
23.	Dispensary	NO	
24.	Club	NO	
25.	Others	NO	
B-4	Services /facilities to be transferred to the Competent Authority	NO	
26.	*		

Note.— (\*) Extend as per requirement

ANOJ TE VATIA
B. Arch. (Hous.)
PW CA/95/18739