Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect	's Certificate <sup>1</sup>
Repo	Report for quarter ended Subject		30 <sup>th</sup> Sep 22
Subje			Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress construction work in the below mentioned project as per the approved plans		
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Elevate Phase – I
	2.	Location	Village Behrampur, Sector-59, Gurugram
	3.	Licensed area in acres	8.91875
	4.	Area for registration in acres	5.95
	5.	HARERA registration no.	19 of 2019



	6.	Name of licensee	License no. 16 of 2008 :
		Name of ficensee	1) BTVS Buildwell Pvt. Ltd. 2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008:  1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011:  1) Commander Realtors Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd.
			7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd.
	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2.	Detail	s related to inspection are	as under

	1.	Date of certifying of percentage of construction work/ site inspection	30 <sup>th</sup> Sep 2022				
	2.	Name of Architect/ Architect's firm	Arcop associates Private Limited				
	3.	Date of site inspection	30 <sup>th</sup> Sep 2022				
3.	Follo	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name				
	1.	Site engineer	Gopal Gairola				
	2. Structural consultant Vintech Consultant (Mr. Vinod Jain)						
	3.	Proof consultant	Mehro Consultants				
	4.	MEP consultant	Sanelac Consultants Pvt Ltd				
	5.	Site supervisor/incharge	Avinash Nagpal				
4.	manda applic develo	atory approvals, Haryana Buildin able) and the material used in the opment works are as per the procedure, publication material an	xecuted as per approved drawings, statutory/ ng Code, 2017/ National Building Code (wherever ne construction, infrastructure works and internal ojected standard as envisaged in the registration d other documents shared with the buyers in this				
5.			ercentage of work done in the project for each of project/phase of the project under HARERA is as				

Labib Alam, Architect

Council of Architecture Page 3 of 25
Registration No.: CA/2001/27447

per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table

Date

: 14-10-2022

Yours faithfully,

Place

: N. DBCHI

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : CA 200127447

registration no.

Labib Alam, Architect Council of Architecture Registration No.: CA/2001/27447

Council of architects (CoA) : 31.12-2027

registration valid till (date)

			Table - A		
(to buil	be p	/ <b>Tower no.</b> orepared separately for each tower in the project/ phase of ct)			
A1	Cur	nulative progress of the projec	ct/phase at the e	nd of the quarte	er.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure  (inclusive of excavation, foundation, basements, water proofing, etc.)		0.5	34	97%
2.	Super structure  (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		3	45.75	82%
3.	МЕГ				
	3.1	Mechanical (lifts, ventilation, etc.)	2	5	25 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.5	3.25	27 %

				The state of the s			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.5	5	3.5		27%
4.	Finis	shing					
	4.1	Internal	1		5.75		27%
	70	(plaster, tilling, flooring, painting, etc. within units and common areas)					
	4.2	External	1	17	3.25		22%
		(plaster, painting, facade, etc.)					
Sr. No.		Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					_	
1.	Exc	avation		Complete		100 %	
2.	Lay	ing of foundation					
	(i)	Raft		Complete	À	100 %	ò
	(ii)	Pile		0		0	V272
3.	Nun	nber of basement(s)			-		
	(i)	Basement Level 1		Structure Tower I Complete	under Footprint	100%	
	(ii)	Basement level 2*		Structure Tower I Complete	under Footprint	100%	
4.		cerproofing of the above so cture (wherever applicable)	ub-	Above waterproofin	deck	50%	Afam, Architect

		Super-Structure Status		
5.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Total area on each floor 785 Sqm		785 Sqm	100%
7.	Stilt floor/ ground floor  Structure Tower Entrance		100%	
8.	Statı	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
9.	Status of construction			
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.	1	g of door and window frames in / units		
11.	Statu	us of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	3% Completed	1%
	(iii)	UPVC/ RWP Piping	100% Completed	97%
12.	Statu	s of wall plastering		100

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Stat	us of wall tiling		
	(i)	Bathroom Tiles	68% Completed	
	(ii)	Kitchen Wall Tile	42% Completed	
14.	Stat	us of flooring		
	(i)	Lift Lobby Flooring	7% Completed	
-	(ii)	Apt Stone Flooring	58% Completed	
15.	Stati	us of white washing		
	(i)	Apartment Prefinal Paint	7% Completed	
	(ii)	Putty+1stCoat+2nd Coat	58% Completed	
16.	Statı	us of finishing		
	(i)	MS Railing	2% Completed in Apartments	95% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	60% Completed	73%
7	(iii)	Lobby Wall Tiling	6% Completed	2%
17.	Statı	us of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	39% Completed	29%
	(ii)	Bathroom Chinaware	3% Completed	3%
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	1% Completed	
	(iv)	Switch & Sockets	3% Completed	lalle?

	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi) Guide Rail+ Floor Door+ Car Installation		14%	
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	90% Completed	0
	(x)	Staircase & Lobby Lights	0% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	rproofing of terraces	PU Waterproofing	0% Completed
19.	Entra	nce lobby finishing	Gypsum False ceiling	0% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	0% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	0	
2.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
3.	Water supply	Yes	0	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
5.	Storm water drains	Yes	0	
6.	Landscaping & tree plantation	Yes	0	
7.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
8.	Shopping area	Yes	0	
9.	Street lighting/ electrification	Yes	0	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	
11.	Solid waste management & disposal	Yes	0	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	185
13.	Energy management (solar)	Yes	0	
14.	Fire protection and fire safety requirements	Yes	0	
15.	Electrical meter room, sub-station, receiving station	Yes	0 (2)	2

16.	Other (option to add more)	NA	0	
B-2	Community building to be transferred to RWA			
17.	Community centre	Yes	0	
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	0	
22.	Others	NA		·
B-4	Services/ facilities to be transferred to competent authority	NA		-
23.	*	2		

Note: (\*) extend as per requirement

			Table – A		
(to buil	Building/Tower no.  (to be prepared separately for each building/ tower in the project/ phase of the project)				
A1	Cun	nulative progress of the proje	ct/phase at the e	nd of the quarte	er.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	(incl	structure lusive of excavation, idation, basements, water ofing, etc.)	0	34	97%
6.	Super structure  (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		3	45.25	75%
7.	MEP	)			
	3.1	Mechanical (lifts, ventilation, etc.)	2	5.04	25%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.5	3.5	28%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.5	3.25	24%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1	5.5	25%
	4.2	External (plaster, painting, facade, etc.)	1	3.25	22%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status		proposed work	
21.	Exca	vation	Complete	100 %	
22.	Layii	ng of foundation			
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Num	ber of basement(s)			
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	1	erproofing of the above sub- eture (wherever applicable)	Deck Water Proofing	50%	
		Super-Structure Status		Labib Alam, Architect	

25.	Tota	al floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
28.	Stat	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	buile	ulative number of slabs in the ding/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Stati	us of construction		
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room	-	100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.	1	g of door and window frames in units	Door Frame	51% Completed
31.	Statu	s of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	0% Completed	
	(vi)	UPVC/ RWP Piping	91% Completed	
32.	Statu	s of wall plastering		1 18
	(iii)	RCC External Wall	NA	Labib Alam, Architect

Registration No.: CA/2001/27447

	(iv)	Gypsum Plaster	70%	
33.	Stati	us of wall tiling		
	(iii)	Bathroom Tiles	49% Completed	
	(iv)	Kitchen Wall Tile	49% Completed	
34.	Statı	us of flooring		
	(iii)	Lift Lobby Flooring	0% Completed	
	(iv)	Apt Stone Flooring	24% Completed	
35.	Statu	us of white washing	,	
	(iii)	Apartment Prefinal Paint	0% Completed	
	(iv)	Putty+1stCoat+2nd Coat	3% Completed	
36.	Statu	s of finishing		
	(iv)	MS Railing	89% Completed	
	(v)	Lift Well HO for Lift Installation	60% Completed	
	(vi)	Lobby Wall Tiling	0% Completed	
37.	Statu	s of installation		
	(with	in flat/unit)		
	(xii)	UPVC Windows	13% Completed	
	(xiii)	Bathroom Chinaware	0% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	0% Completed	
	(xv)	Switch & Sockets	0% Completed	
	(xvi)	NA	NA	
	(othe	r than flat/units)		Labib Alam, Architect

	(xvii Guide Rail+ Floor Door+ Car Installation		0	
	(xvii	RCC Work	97% Completed	
	(xix) RCC Work		100% Completed	
	(xx)	Fire Pump Installation	30% Completed	
	(xxi)	Staircase & Lobby Lights	0% Completed	
	(xxii)	Six Monthly Compliance	100% Compliance	
38.	Wate	rproofing of terraces	PU Waterproofing	0% Completed
39.	Entra	nce lobby finishing	Gypsum False ceiling	0% Completed
40.	Status of construction of compound wall		Boundary Wall RCC and Brick Work	0% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services			
24.	Internal roads & pavements	Yes	0	
25.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
26.	Water supply	Yes	0	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
28.	Storm water drains	Yes	0	
29.	Landscaping & tree plantation	Yes	0	
30.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
,	Benches	Yes	0	
31.	Shopping area	Yes	0	
32.	Street lighting/ electrification	Yes	0	
33.	Treatment and disposal of sewage and sullage water/STP	Yes	0	
34.	Solid waste management & disposal	Yes	0	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
36.	Energy management (solar)	Yes	0	
37.	Fire protection and fire safety requirements	Yes	0	
38.	Electrical meter room, sub-station, receiving station	Yes	0	am, Archite

41.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
42.	Schools	NA		
43.	Dispensary	NA		
44.	Club	Yes	0	
45.	Others	NA		
	Services/ facilities to be transferred	NA		

Note: (\*) extend as per requirement

			Table – A			
(to buil	be p	Tower no.  repared separately for each tower in the project/ phase of t)			u	
A1	Cun	nulative progress of the projec	ct/phase at the e	nd of the quarte	r.	
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
9.	(incl	structure usive of excavation, dation, basements, water ofing, etc.)	0 23.9		93%	
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		2	33	83%	
11.	MEF	,				
	3.1	Mechanical (lifts, ventilation, etc.)	1.5	3.26	33%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.1	3.1	39%	

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.5		5		63%
12.	Finis	hing					
	4.1 Internal 1.5  (plaster, tilling, flooring, painting, etc. within units and common areas)		1.5		6		63%
	4.2	External (plaster, painting, facade, etc.)	1		3.25	0	65%
Sr. No.		Tasks/ Activity		Description of work done		Percentage of total proposed work	
NO.		Sub-Structure Status					
41.	Exca	avation	Comp	Complete		100 %	
42.	Layi	ng of foundation					
	(v)	Complete		*		100%	
	(vi)	(vi) NA		NA		0	
43.	Nun	nber of basement(s)					
	(v)	Structure under Tower Footpri Complete	nt			100%	
	(vi)	Structure under Tower Footpri Complete	nt			100%	
44.		erproofing of the above sul cture (wherever applicable)	Deck V	Vater Pr	oofing	40%	Sup
		Super-Structure Status					bib Alam, Architect uncil of Architecture

45.	Tota	al floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Tota	al area on each floor	549 Sqm	100%
47.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
48.	Stati	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Statı	us of construction		
	(ix)	Blockwork	95% Completed	30%
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(xi)	Lift Well including Machine room	98% Completed	100%
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	100%
50.		g of door and window frames in units	Door Frame	60% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	1% Completed	
	(ix) UPVC/ RWP Piping		100% Completed	
52.	Statu	s of wall plastering		
	(v)	RCC External Wall	NA	Labib Alam, Architectu

	(vi)	Gypsum Plaster	100%	
53.	Statı	us of wall tiling		
	(v)	Bathroom Tiles	23% Completed	200
	(vi)	Kitchen Wall Tile	23% Completed	
54.	Statu	as of flooring		
	(v)	Lift Lobby Flooring	0% Completed	
	(vi)	Apt Stone Flooring	57% Completed	
55.	Statu	is of white washing		
	(v)	Apartment Prefinal Paint	0% Completed	
	(vi)	Putty+1stCoat+2nd Coat	17% Completed	
56.	Statu	s of finishing		
	(vii)	MS Railing	66% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	10 10 10 10 10 10 10 10 10 10 10 10 10 1
	(ix)	Lobby Wall Tiling	0% Completed	
57.	Statu	s of installation		
	(with	in flat/unit)		
	(xxiii	UPVC Windows	35% Completed	
	(xxiv	Bathroom Chinaware	0%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	0%	
	(xxvi	Switch & Sockets	0% Completed	
	(xxvi	NA	NA	
	(othe	r than flat/units)		Labib Alam, Architec

	(xxvi Guide Installa	Rail+ Floor Door+ ation	Car	14%	
	(xxix RCC W	ork		100% Completed	
	(xxx) RCC Work			100% Completed	
	(xxxi Fire Pu	mp Installation		90% Completed	
	(xxxi Stairca	se & Lobby Lights		0% Completed	
	(xxxi Six Mo	nthly Compliance		100% Compliance	
58.	Waterproofi	ng of terraces		PU Waterproofing	0% Completed
59.	Entrance lob	by finishing		Gypsum False ceiling	0% Completed
60.	Status of construction of compound wall		und	Boundary Wall RCC and Brick Work	0% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services	_l		
47.	Internal roads & pavements	Yes	0	
48.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
49.	Water supply	Yes	0	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
51.	Storm water drains	Yes	0	
52.	Landscaping & tree plantation	Yes	0	
53.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
54.	Shopping area	Yes	0	
55.	Street lighting/ electrification	Yes	0	
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	
57.	Solid waste management & disposal	Yes	0	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
59.	Energy management (solar)	Yes	0	
60.	Fire protection and fire safety requirements	Yes	0	
61.	Electrical meter room, sub-station, receiving station	Yes	0	

Labib Alam, Architect

Council of Architecture
Registration No.: CA/200 ABE 24 of 25

62.	Other (option to add more)	NA		
B-2	Community building to be transferred to RWA			
63.	Community centre	Yes	0	
64.	others	NA		
В-3	Community buildings not to be transferred to RWA/competent authority			
65.	Schools	NA		
66.	Dispensary	NA		
67.	Club	Yes	0	
68.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
69.	*			

Note: (\*) extend as per requirement