

		Architect's	s Certificate			
Repo	ort for qu	uarter ending	30-Sept-22			
Subje	Subject		Certificate of progress of construction work			
1.	I/We work	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Signature Global City-1			
	2.	Location	Sector-28, Karnal			
	3.	Licensed area in acres	15 acre			
	4.	Area for registration in acres	15 acre			
	5.	HARERA registration no.	HRERA-PKL-KNL-27-2018 Dated 20-July-2018			
	6.	Name of licensee	M/s Maa Vaishno Net-Tech Pvt. Ltd.			
	7.	Name of collaborator	NA			
	8.	Name of developer	M/s Maa Vaishno Net-Tech Pvt. Ltd.			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	30-Sept-22			
	2.	Name of Architect/ Architect's firm	M/s Gian P. Mathur & Associates			
	3.	Date of site inspection	30-Sept-22			



C-28, East Of Kailash, New Delhi-110065

T: 46599599 | F: 46599512

El info@gpmindia.com | W: www.gpmindia.com

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1. Site engineer M/s RDC India Proje		M/s RDC India Projects			
	2.	Structural consultant	M/s Gian P. Mathur & Associates			
	3. Proof consultant NA					
	4.	MEP consultant	M/s Gian P. Mathur & Associates			
	5.	Site supervisor/incharge	M/s RDC India Projects			
4.	I certify that the work has been executed as per approved drawings, statutory mandatory approvals, Haryana Building Code, 2017/ National Building Code (whereve applicable) and the material used in the construction, infrastructure works and internatevelopment works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.					
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is a per table A and table B given herein below. The percentage of the work executed wit respect to each of the activity of the entire project/ phase is detailed in table A and table B.					

Date

: 30/09/2022

Place

GIAN_P. MAIN Signature & name (in block letters) with stamp of

architect

Council of architects (CoA) :

registration no.

Council of architects (CoA):

registration no.

Table – A	109.
270 Nos	

A1 Cumulative progress of the project/phase at the end of the quarter.

Sr. No.		Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		7%	74%	74%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		5%	49%	49%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	8%	24%	24%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	0%	0%
4.	Finishing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%

B. Arch M.C.A. I.I.A CA No. 80/5769

Sr.	Tasks/ Activity		Description of work		Percentage of total		
No.	No. Sub-Structure Status			done		proposed work	
1.	Exca	vation	Excavation i	n ordinary Soil		95%	
2.	Layir	ng of foundation					
	(i) Raft		RCC of Building Raft		90%		
	(ii)	Pile		NA		NA	
3.	Num	ber of basement(s)					
	(i)	Basement Level 1	NA		NA		
	(ii)	Basement level 2*	NA		NA		
4.		erproofing of the above sub-structure		ater Proofing		40%	
	(whe	rever applicable)	Com	pound			
		Super-Structure Status					
5.	Total	floors in the tower/ building	810) Nos		65%	
6.	Total	area on each floor	59%of R0	CC works in		65%	
7	Carte	Slaan/ann LCI		gress			
7.		floor/ ground floor	Work in	progress		65% 	
8.	Status of laying of slabs floor wise						
	Cumulative number of slabs in the building/ towerlaid by end of quarter		(30% to 40%)		45%		
9.	Status of construction						
	(i)	Walls on floors	RCC work in progress		55%		
	(ii)	Staircase	RCC work in progress		55%		
	(iii)	Lift wells along with water proofing	NA		NA		
	(iv)	Lift lobbies/ common areas floor wise	NA		NA		
10.	Fixing units	g of door and window frames in flats/	Work in progress		35%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%	
	(ii)	Electrical works including wiring	Work in progress	Work in progress	15%	5%	
	(iii)	Plumbing works	Work in progress	Yet to be started	12%	0%	
12.	Statu	s of wall plastering		•			
	(i)	External plaster	Yet to be started		0%		
	(ii)	Internal plaster	Yet to be started		0%		
L3.		s of wall tiling					
MA I	THEC	In bathroom	Work in progress		20%		
1.C.A		In kitchen	Work in	progress	15%		
BO/5	75€a tu	s of flooring					
	(i)	Common areas	Yet to b	e started		0%	
	(ii)	Units/ flats	Work in	progress		32%	

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of	Percentage of total proposed work	
			work done		
15.	Statu	is of white washing			
	(i)	Internal walls	Work is under progress	25%	
	(ii)	External walls	Yet to be started	0%	
16.	Status of finishing				
	(i)	Staircase with railing	Yet to be started	0%	
	(ii)	Lift wells	NA	NA	
	(iii)	Lift lobbies/ common areas floor wise	NA	NA	
17.	Statu	s of installation			
	(with	in flat/unit)			
	(i)	Doors and windows panels	Work in progress	22%	
	(ii)	Sanitary fixtures	Yet to be start	0%	
	(iii)	Modular kitchen		NA	
	(iv)	Electrical fittings/ lighting	Yet to be start	0%	
	(v)	Gas piping (if any)		NA	
	(othe	er than flat/units)			
,	(vi)	Lifts installation	NA	NA	
	(vii)	Overhead tanks	Yet to be start	0%	
	(viii)	Underground water tank	Yet to be start	0%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be start	0%	
	(x)	Electrical fittings in common areas	Yet to be start	0%	
	(xi)	Compliance to conditions of environment/	Yet to be start	0%	
18.	Wate	rproofing of terraces	Yet to be started	0%	
L9.	Entra	nce lobby finishing	Yet to be start	0%	
20.	Status of construction of compound wall		Yet to be start	0%	

Note: (*) extend rows as per requirement.



Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services		-0	
1.	Internal roads & pavements	Yes	100%	
2.	Parking	NA		
	Covered no	NA		
	Open no	NA		
3.	Water supply	Yes	95%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	97%	
5.	Storm water drains	Yes	95%	
6.	Landscaping & tree plantation	Yes	16%	
7.	Parks and playgrounds	Yes	50%	
	Fixing of children play equipment's	Yes	50%	
	Benches	Yes	30%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	80%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Other (option to add more)	NA		
B-2	Community building to be transferred to	RWA		
17.	Community centre	Yes	0%	
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			

B. ArNote (*) extend as per requirement CA No. 80/5769