

		Architect	's Certificate				
Repo	ort for qu	uarter ending	30-Sept-22				
Subje	ect		Certificate of progress of construction work				
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans						
	Sr. Particulars No.		Information				
	1.	Project/Phase of the project	Golf Greens-79				
	2.	Location	Sector-79				
	3.	Licensed area in acres	5.9125 Acre				
	4.	Area for registration in acres	5.9125 Acre				
	5.	HARERA registration no.	15 of 2020 Dated 23-06-2020				
	6.	Name of licensee	M/s Signature Global (India) Ltd.				
	7.	Name of collaborator	NA				
	8.	Name of developer	M/s Signature Global (India) Ltd.				
2.	Detail	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	30-Sept-22				
	2.	Name of Architect/ Architect's firm	M/s Gian P Mathur & Associates				
	3.	Date of site inspection	30-Sept-22				



C-28, East Of Kailash, New Delhi-110065

T: 46599599 | F: 46599512

E: info@gpmindia.com | W: www.gpmindia.com

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. Consultants No.		Name			
	1. Site engineer Mr. Dinesh Singh					
	2. Structural consultant M/s Optimum Design Pvt.		M/s Optimum Design Pvt. Ltd.			
1. Site eng 2. Structur 3. Proof co 4. MEP cor 5. Site supe 4. I certify that t mandatory approapplicable) and development we	3. Proof consultant RD Consultants					
	MEP consultant	M/s Krim Engineering Services Pvt. Ltd.				
	5.	Site supervisor/incharge	Mr. Dinesh Singh			
4.	applic develo	atory approvals, Haryana Buildin able) and the material used in th opment works are as per the pro ochure, publication material and	Recuted as per approved drawings, statutory/ g Code, 2017/ National Building Code (wherever e construction, infrastructure works and internal ojected standard as envisaged in the registration d other documents shared with the buyers in this			
5.	I also certify that as on the date, the percentage of work done in the project for each the building/ tower of the real estate project/phase of the project under HARERA per table A and table B given herein below. The percentage of the work executed respect to each of the activity of the entire project/ phase is detailed in table A table B.					

Date

: 30/09/2022

GIAYours faithfully,

Place

B. Arch. C.A. III. Signature & Dame (in block letters) with stamp of

architect

Council of architects (CoA) ; registration no.

Council of architects (CoA) : registration valid till (date)

	(* 10K. 51, 1941 BAKA)	109.
	Table – A	
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)	5+1 nos (Towers)	

A1	Cumulative progress of the project/phase at the end of the quarter.							
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work			
1.	(incl	structure Jusive of excavation, Indation, basements, water Ofing, etc.)	0%	100% 100%				
2. Super str (slabs, bri case, lift water tan		er structure os, brick work, block work, stair e, lift wells, machine rooms, er tank, etc.)	12%	51%	51%			
No. 1. 2.	MEF							
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	7%	35%	35%			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	7%	29%	29%			
Sr. No.	Finishing							
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%			
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%			



Sr.	Tasks/ Activity		Description of work		Percentage of total	
No.	Sub-Structure Status Excavation		done Excavation in ordinary Soil		proposed work	
1.						
2.	Layi	ng of foundation				
	(i)	Raft	RCC of B	uilding Raft	1	00%
	(ii)	Pile		NA	NA	
3.	Num	ber of basement(s)				
	(i)	Basement Level 1		NA		NA
	(ii)	Basement level 2*	i	VA	NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Applying Water Proofing Compound			0%
		Super-Structure Status				
5.	Tota	l floors in the tower/ building	126 Nos.		2	25%
6.	Tota	l area on each floor	30% of RCC works completed on total area		3	0%
7.	Stilt	floor/ ground floor	Work in progress		70%	
8.	Statu	is of laying of slabs floor wise				
		ulative number of slabs in the building/ erlaid by end of quarter	(35% to 45%)		45%	
9.	Statu	s of construction				
	(i)	Walls on floors	Work in progress		30%	
	(ii)	Staircase	Work in progress		30%	
	(iii)	Lift wells along with water proofing	Yet to be started		0%	
	(iv)	Lift lobbies/ common areas floor wise	Work in	progress	3	0%
10.	Fixing units	g of door and window frames in flats/	Yet to be started		0%	
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	Externa works
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%
	(ii)	Electrical works including wiring	Work in Progress	Yet to be started	35%	0%
	(iii)	Plumbing works	Work in Progress	Yet to be started	29%	0%
12.		s of wall plastering				
	(i)	External plaster	Yet to be started		0%	
	(ii)	Internal plaster	Yet to be started		0%	
13.	Statu	s of wall tiling				
V P. I	(i) In bathroom		Yet to be started		0%	
A	REVI	n kitchen	Yet to b	e started	C)%
114. M.	satu	s of Nooring				
No. 8	9/15/76	9Common areas	Yet to b	e started	C)%
	(ii)	Units/ flats	Yet to h	e started	٢	1%

Sr. No.	Tasks/ Activity		Description of work	Percentage of total proposed	
140.		Sub-Structure Status	done	work	
15.	Stati	us of white washing			
	(i)	Internal walls	Yet to be started	0%	
	(ii)	External walls	Yet to be started	0%	
16.	Status of finishing				
	(i)	Staircase with railing	Yet to be started	0%	
	(ii)	Lift wells	Yet to be started	0%	
	(iii)	Lift lobbies/ common areas floor wise	Yet to be started	0%	
17.	Statu	us of installation			
	(with	nin flat/unit)			
	(i)	Doors and windows panels	Yet to be started	0%	
	(ii)	Sanitary fixtures	Yet to be started	0%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	Yet to be started	0%	
	(v)	Gas piping (if any)	NA	NA	
	(othe	er than flat/units)			
	(vi)	Lifts installation	Yet to be started	0%	
	(vii)	Overhead tanks	Yet to be started	0%	
	(viii)	Underground water tank	Yet to be started	0%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be started	0%	
	(x)	Electrical fittings in common areas	Yet to be started	0%	
	(xi)	Compliance to conditions of environment/	Yet to be started	0%	
18	Wate	erproofing of terraces	Yet to be started	0%	
19	Entra	nce lobby finishing	Yet to be started	0%	
20	Status of construction of compound wall(Fencing Work)		Completed	100%	

Note: (*) extend rows as per requirement.



Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remark
B-1	Services			
1.	Internal roads & pavements(Temporary)	Yes	100%	
2.	Parking	NA		
	Covered no	NA		
	Open no	NA		
3.	Water supply	Yes	28%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	20%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation(Temporary)	Yes	100%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Site Office(Temporary)	Yes	100%	
B-2	Community building to be transferred to	RWA		
17.	Community centre	Yes	0%	
18.	others	_	_	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			

B. Arc Note: (*) extend as per requirement CA No. 80/5769