



ARCHITECTS & ENGINEER'S

Annexure A

		Architect'	s Certificate*			
Report for quarter ending Subject			30 SEP 2022 Certificate of progress of construction work			
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 28384.54 sq mtr , Commercial Cum Residential Colony, SCO Phase 1			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	2.09 acres & 8.571 acres			
busba di diiw	4.	Area for registration in acres	7.01 acres			
	5.	HARERA registration no.	129 of 2017			
	6.	Name of licensee	Omaxe World Street Pvt. Ltd			
	7.	Name of collaborator	phase is doubled as table A and table B;			
	8.	Name of developer	Omaxe World Street Pvt. Ltd			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	15.10.2022			
	2.	Name of Architect/ Architect's firm	ABMS Design Associates			
	3.	Date of site inspection	11.10.2022			

Apurba Borah

FLAT NO 3A, HIMGIRI APARTMENTS, POCKET-14, KALKAJI EXTENSION, NEW DELHI-110017



ARCHITECTS & ENGINEER'S

3.	Follow	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name				
	1.	Site engineer	Mr. D.C Pant				
	2.	Structural consultant	Mr. Aavinash Pratap Singh Sisodia				
	3.	Proof consultant					
i Con	4.	MEP consultant	Mr, Digambar Singh				
	5.	Site incharge	Mr. D.C Pant				
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approved Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in construction, infrastructure works and internal development works are as per the projected standard envisaged in the registration and brochure, publication material and other documents shared with buyers in this regard.						
5.	I also certify that as on the date, the percentage of work done in the project for each of the building of the real estate project/phase of the project under HARERA is as per table A and table B given below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in table A and table B.						


Date	:	rations as a	Yours faithfully, Borah
Place	10,303.2	estings of inspection	Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date)



ARCHITECTS & ENGINEER'S

		points bonds	Table – A					
(to be	prepar	ed separately for each building/ tower // phase of the project)		smoots vaid				
A1	Cum	ulative progress of the project/phase	e project/phase at the end of the quarter.					
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.) Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work 100%			
1.				15 CR 30.80				
2.								
3.	MEP		gmEnid of propic to b	i in edale eo esclaturi e e volutel	A Caldones Live Toward			
	3.1	Mechanical (lifts, ventilation, etc.)	no l	minorens Esseñ de si	Status of Status			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.10	4.44 CR	90%			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.10	2.44 CR	90%			
4.	Finishing		<i>u</i>)					
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	and the state of	15.9 CR	100%			
	4.2	External (plaster, painting, facade, etc.)	tio)	8.5 CR	100%			





Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work		
		Sub-Structure Status	Completed		100%		
1.	Excav		Completed		10070		
2.	- 1	g of foundation	Commisted		100%	E partition	
	(i)	Raft	Completed N/A		100%	second and on	
	(ii)	Pile	N/A			-	
3.	Number of basement(s) 1		this and the applications and the sa		es (190/ey serise) is	ingle-yordelights) - (7	
	(i) Basement Level 1		Completed		100%	100%	
	(ii)	Basement level 2*	N/A		GF GF		
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%		
		Super-Structure Status			and toward		
5.	Total	floors in the tower/ building	3	(tutetas a)	a in passiv sinte	c in	
6.	Total	area on each floor	113550 SFT				
7.	Stilt f	loor/ ground floor	113550 SFT	als Spen 12			
8.	Status	s of laying of slabs floor wise	Completed		100%		
		lative number of slabs in the building/				estar .	
9.	Status of construction				Service Market		
	(i) Walls on floors		Completed		100%		
	(ii)	Staircase	Completed		100%		
	(iii)	Lift wells along with water proofing	Today wanted action		- tears -		
	(iv)	Lift lobbies/ common areas floor wise					
10.	Fixin units	g of door and window frames in flats/	Completed		100%		
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works					
	(ii)	Electrical works including wiring					
	(iii)	Plumbing works	(ESSUE O	escent Links	recentation one		
12.	Statu	Status of wall plastering					
	(i)	External plaster	Completed		100%		
	(ii)	Internal plaster	Completed		100%		
13.	Statu	s of wall tiling					
	(i)	In bathroom	-			leur Boli	
	(ii)	In kitchen	-		(/	Regazolate Propagatoria	
14.	Statu	s of flooring	1	To a	A	209/2013/	
	(i)	Common areas	WIP	9/1/9/2 30/2	98%	Ch	
	(ii)	Units/ flats	-	OLE - CO	90 1		



ARCHITECTS & ENGINEER'S

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total proposed work	
No.			done		
15.	Status of white washing		er Esterilla visig so	Hillian Me roller	
	(i)	Internal walls	Completed	100%	
	(ii)	External walls	Completed	100%	
16.	Status of finishing			elgene rootii.	
	(i)	Staircase with railing	Completed	100%	
	(ii)	Lift wells	N/A	Additional to a	
	(iii)	Lift lobbies/ common areas floor wise	N/A	rela bas exas?	
17.	Status	of installation	nen plas requisiegntis	dida lo gazia	
	(within flat/unit)			(Rengt)	
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	N/A	The same Association of the sa	
	(iii)	Modular kitchen	N/A	BT2 Yearing	
	(iv)	Electrical fittings/ lighting	N/A managan	on stanu bibo? ! !	
	(v)	Gas piping (if any)	N/A	Assert consens	
	(other	than flat/units)	(neloc) month	esaum varedii 14	
	(vi)	Lifts installation	N/A	rolloplang out 4 i ·	
	(vii)	Overhead tanks	N/A mana a	100%	
	(viii)	Underground water tank	N/A	, MACHINE	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	90%	
	(x)	Electrical fittings in common areas	N/A	90%	
	(xi)	Compliance to conditions of environment/ CRZ NOC	N/A	8-3 Community In EVVA/compe	
18.	Waterproofing of terraces		Completed	100%	
19.	Entra	nce lobby finishing	N/A	.20. Dispensary	
20.	Status	s of construction of compound wall		dul9 L. L.	

Note: (*) extend rows as per requirement.



FLAT NO. 3A, HIMGIRI APARTMENTS, POCKET-14, KALKAJI EXTENSION, NEW DELHI-110017



ARCHITECTS & ENGINEER'S

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			TO THE REP
1.	Internal roads & pavements	YES	97%	
2.	Parking			
	Covered no	YES	97%	(A)
	Open no	YES	97%	Cilca
3.	Water supply	YES	97%	6. 135.00
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	97%	
5.	Storm water drains	YES	97%	
6.	Landscaping & tree plantation	YES	97%	
7.	Parks and playgrounds	N/A		1000
	Fixing of children play equipment's	N/A	menalisadica e	0.12
	Benches	N/A	esina tsibusi	lin)
8.	Shopping area	YES	97%	1
9.	Street lighting/ electrification	YES	97%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	97%	
11.	Solid waste management & disposal	N/A	Electrical fattigus 1-	4/32
12.	Water conservation, rain water, harvesting, percolating well/ pit	N/A	95%	
13.	Energy management (solar)	N/A	· VERBRIEG BK	de la
14.	Fire protection and fire safety requirements	N/A	95%	NAME OF
15.	Electrical meter room, sub-station, receiving station	N/A	95%	(riv)
16.	Other (option to add more)	N/A		1
B-2	Community building to be transferred to RWA	Acont huge by	is the service of the service of	10001
17.	Community centre	N/A		
18.	others	N/A	the agreement recommendance	
B-3	Community buildings not to be transferred to RWA/competent authority	arossbesso 30	Companie 1) en-morganie CB Car	(02)
19.	Schools	N/A	arasmei le salteose	- NW 1
20.	Dispensary	N/A	Acceptable Made a	e see 3 · O
21.	Club	N/A		
22.	Others	N/A		
B-4	Services/ facilities to be transferred to competent authority	Ja	cat Ausper tog en awar	Litalia (*)
23.	*			

Note: (*) extend as per requirement

