Ar. R. W. Kirala

(Architect) C1, RZ - 440A/1, 19th Street, Sadh Nagar, Palam Colony, New Delhi - 110045

ARCHITECT'S CERTIFICATE

To,

Date- 30TH Sep. 2022

The Manager, L & T Finance Ltd., 6th Floor, DCM Building, Barakhamba Road, Connaught Place, New Delhi - 110001

Borrower: RPS Infrastructure Ltd., 1117-1120, 11th Floor, DLF Towers, Tower-B, New Delhi - 110025.

Subject: Certificate of Percentage of Completion of Construction Work of RPS Infinia, IT Park Project, Three No. of Building (Three Towers in First, Second and Third Phase of the Project) [bearing RERA Registration No. 204 of 2017,203 of 2017 and 198 of 2017] project situated at 12/6 Milestone, Main Mathura Road, Sector-27 A, Faridabad, demarcated by its boundaries (latitude and longitude of the end points) 28°28'21.32"N 77°18'14.71"E" to the North 28°28'17.78"N 77°18'15.34" to the South 28°28'19.63"N 77°18'19.61"E to the East 28°28'20.47" 77°18'8.17"E to the West of Division Faridabad, village Sarai Khawaja, taluka & District Faridabad PIN 121003 admeasuring 4.50 Acres (18211 sq.mts.) area being developed by RPS Infrastructure Ltd.

I, R P Nirala have undertaken assignment as Architect certifying Percentage of Completion of Construction Work of the Tower 3 (Three Towers) of the Project RPS - Infinia, situated at 12/6 Milestone, Main Mathura Road, Sector-27 A, Faridabad taluka and District Faridabad PIN 121003 admeasuring 4.50 Acres (18211 sq.mts.) area being developed by RPS Infrastructure Ltd.

1. Following technical professionals are appointed by Owner / Borrower :-- (i) M/s/Vastunidhi as Architect; (ii) M/s Cecon as Structural Consultant (iii) M/s VS Kukreja Associates as MEP Consultant (iv) Shri Padma Lochan Dash as Site Supervisor Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid IT Park Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the IT Park Project bearing RERA Registration No. 204 of 2017, 203 of 2017 and 198 of 2017 under Haryana RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Page 1 | 3

TABLE-A

Tower No. 3, 4 and 5, RPS Infinia, IT Park Project.

| S. No | Tasks/ Activity | Percentage of Work Done 100% | |
|-------|---|--|--|
| 1. | Excavation | | |
| 2. | Three numbers of Basement(s) and Plinth | Structure 100% | |
| 3. | Number of Podiums | NA | |
| 4. | Stilt Floor (part stilt) | NA | |
| 5. | Tower-3 = G+S+12 number of Slabs of Super Structure | 100% | |
| | Tower-4 = G+7 number of Slabs of Super Structure | 100% | |
| | Tower-5 = G+11 number of Slabs of Super Structure | 100% | |
| 6. | Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the offices/Premises. | 60% | |
| 7. | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises. | 40% | |
| 8. | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks. | Structure done 100% Staircase Finishing 70% | |
| 9. | The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing | 30% | |
| 10. | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation/ Completion Certificate. | Lift Installation in progress. Finishing of entrance lobby 60% | |

R.P. NIRALA

TABLE-B
Internal and External Development Works in respect of the entire Registered Phase

| S. No. | Common Areas and Facilities | Proposed | Percentage of Work | Details |
|--------|--|----------|-----------------------|---------------------------------------|
| | 55 | (Yes/No) | Done | |
| 1. | Internal Roads & Footpaths. | Yes | In progress | |
| 2. | Water Supply | Yes | 35% | OHT and UGT Structure completed |
| 3. | Sewerage (chamber, lines, Septic Tank, STP). | Yes | 20% | STP Structure completed |
| 4. | Storm Water Drains | Yes | In progress | |
| 5. | Landscaping& Tree Planting. | Yes | Yet to commence | |
| 6. | Street Lighting | Yes | Yet to commence | |
| 7. | Community Buildings | Yes | NA | |
| 8. | Treatment and disposal of sewage and sullage water | Yes | Yet to commence | |
| 9. | Solid Waste management & Disposal. | Yes | Yet to commence | |
| 10. | Water conservation, Rainwater harvesting. | Yes | In Progress | |
| 11. | Energy management | Yes | In progress | Electrical Conducting started |
| 12. | Fire protection and fire safety requirements. | Yes | In progress | |
| 13. | Electrical meter room, sub-station, receiving station. | Yes | Yet to commence | |
| 14. | Others (Commercial). | Yes | NA | |

Yours Faithfully,

R.P. NIRALA CA/2002/29507

Ar. RP Nirala (CA/2002/29507)