14		Architect's	s Certificate ¹		
Repo	Report for quarter ending 30-09-19				
Subje	ct		Certificate of progress of construction work		
1.	I/We const	have undertaken assignme	ent as architect for certifying progress of entioned project as per the approved plans		
	Sr. Particulars No.		Information		
	1.	Project/Phase of the project	Conscient One		
	2.	Location	Sector-109, Gurugram, Haryana		
	3.	Licensed area in acres	8.393 Acres		
	4.	Area for registration in acres	3.138 Acres		
	5.	HARERA registration no.	RC/REP/HARERA/GGM/308/40/2019/02 /Dated-16-01-2019		
	6.	Name of licensee	M/S Shrimaya Buildcon Pvt. Ltd. And Others		
	7.	Name of collaborator	M/S Shrimaya Buildcon Pvt. Ltd.		
	8.	Name of developer	Conscient Infrastructure Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	30.09.19		
9	2.	Name of Architect/ Architect's firm	Ashwin Alva Associates		
	3.	Date of site inspection	30.09.19		

ALVA ASSOCIATES

SHOBHNA BATRA CA/2005/35496

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

ASHWIN

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. Consultants No.		Name		
	1.	Site engineer	Sharad Chandra		
	2. Structural consultant Civtech Consultant Pvt. Ltd.				
	3.	Proof consultant	Mehro Consultants		
	4.	MEP consultant	Plumbing & Fire Fighting- Soni Consultants, Electrical Consultant-Kanwa Krishen Associates Pvt Ltd		
	5.	Site supervisor/incharge	Ashwini Arora		
4.	I certify that the work has been executed as per approved drawings, statutory mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internate development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in the regard. I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is a per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.				
5.					

Date

Yours faithfully,

Place

Signature & name (in block letters) with stamp of architect

Council of architects (CoA): registration no.

ASHWIN

SHOBHNA BATRA

CA/2005/35496

SOCIATES

Council of architects (CoA) : 31/12/2026 registration valid till (date)

N-93, South Avenue Sainik Farm, New Delhi-62, Ph./Fax.011 29555054, 011 29555098 email: admin@alva.co.in

		T	able – A				
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	(Cos	st Break up Exc Developme	1 Nos luding Internal ent Work Cost).		
A1	Cum	ulative progress of the project	/phase at the end	l of the quarter	•		
Sr. No.	Proj	ect components	Work done value during the quarter (In Lacs) Cumulative work done work done the quarter (in Lacs)				
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.0	1621.8	100%		
2.	(slat	er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	158.6	2745.8	90%		
3.	MEP			£			
	3.1	Mechanical (lifts, ventilation, etc.)	56.9	765.8	70%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	75.3	810.9	70%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	118.9	781.9	75%		
4.	Finishing				1. 1		
4. 35	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	285.0	1042.6	75%		
	4.2	External (plaster, painting, facade, etc.)	137.1	1073.4	66%		

ASHWIN ASSOCIATES

N-93, South Accide Sainik Farm, New Delhi-62, Ph./Fax of 200555054,011 29555098 email: admin@alva.co.in

Sr.	Tasks/ Activity		Description of work		Percentage of total		
No.		Sub-Structure Status	do	done		proposed work	
1.	Exca	vation	Completed		1009		
2.	Layir	ng of foundation					
	(i)	Raft	ft Completed			100%	
	(ii)	Pile			-		
3.	Num	ber of basement(s) 3					
	(i)	Basement Level 1	(Completed	100%		
	(ii)	Basement level 2	1	Completed		100%	
	(iii)	Basement level 3		Completed		100%	
4.		erproofing of the above sub- cture (wherever applicable)	I	n Progress		95%	
		Super-Structure Status					
5.	Tota	l floors in the tower/ building		G+10			
6.	Total area on each floor			mmercial			
				79.602 to .212 Sqm.			
				Apartment			
			ı	41.907 to			
_			1072.663 Sqm				
7.	+	floor/ ground floor	Completed		100%		
8.	\vdash	is of laying of slabs floor wise	1	Completed	eted		
	build	ulative number of slabs in the ling/tower11 laid by of quarter					
9.	Statu	is of construction		X		,	
	(i)	Walls on floors	I	n-progress	709		
	(ii)	Staircase		Completed	1009		
	(iii)	Lift wells along with water proofing	Completed		100%		
	(iv)	Lift lobbies/ common areas floor wise	In Progress			70%	
10.		ng of door and window frames in / units	In Progress			68%	
11.	Statı	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
13	(i)	Mechanical works	I	n Progress		70%	
	(ii)	Electrical works including wiring	I	n Progress	70%		

ASHWIN - ASSOCIATES

N-93, South Sainik Farm, New Delhi-62,Ph/Fax 35555054,011 29555098 email: admin@alva.co.in

Annexure C

	(iii)	Plumbing works	In Progress	75%
12.	Statu Glazi	1 0, ,		
	(i)	External plaster/Façade Glazing	In Progress	65%
	(ii)	Internal plaster	In Progress	75%
13.	Status of wall tiling			
	(i)	In bathroom	In Progress	65%
	(ii)	In kitchen	NA	
14.	Statu	is of flooring		
	(i)	Common areas	In Progress	80%
	(ii)	Units/ flats	NA	
15.	Statu	is of white washing		
	(i)	Internal walls	In Progress	75%
	(ii)	External walls	NA	19
16.	Statu	is of finishing		
	(i)	Staircase with railing	In Progress	75%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	In Progress	75%
17.	Statu	is of installation		
	(with	nin flat/unit)		
	(i)	Doors and windows panels	In Progress	65%
	(ii)	Sanitary fixtures	In Progress	90%
	(iii)	Modular kitchen	To be Started	
	(iv)	Electrical fittings/ lighting	In Progress	65%
	(v)	Gas piping (if any)	In Progress	80%
	(othe	er than flat/units)		
	(vi)	Lifts installation	In Progress	70%
	(vii)	Overhead tanks	In Progress	40%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	In Progress	80%
	(x)	Electrical fittings in common areas	In Progress	70%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.		erproofing of terraces	In Progress	80%
19.	Entra	ance lobby finishing	In Progress	80%

N-93, South See Sainik Farm, New Delhi-62,Phira 25555054,011 29555098 email: admin@alva.co.in

20.	Status of construction of compound	In Progress	90%
	wall	12	

Note: (*) extend rows as per requirement.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			-
	Covered no 513	Yes	100%	
	Open no	No		
3.	Water supply	Yes	70%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	90%	
5.	Storm water drains	Yes	90%	
6.	Landscaping & tree plantation	Yes	75%	
7.	Parks and playgrounds	No		
	Fixing of children play equipment's	No	,	
	Benches	Yes	10%	
8.	Shopping area	No		
9.	Street lighting/ electrification	Yes	75%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	90%	
11.	Solid waste management & disposal	Yes	80%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	90%	
13.	Energy management (solar)	Yes	50%	
14.	Fire protection and fire safety requirements	Yes	80%	
15.	Electrical meter room, sub-station, receiving station	Yes	80%	ia
16.	Other (option to add more)	NA	NA	
B-2	Community building to be transferred to	RWA		
17.	Community centre	NA		
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority		-	
19.	Schools	NA		

N-93, South Sainik Farm, New Delhi-62, Ph./Har S555054,011 29555098 email: admin@alva.co.in

20.	Dispensary	NA	
21.	Club	NA	
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority		
23.	*		

Note: (*) extend as per requirement

SHOBHNA BATRA CA/2005/35496

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in