Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

	Architect's Certificate ¹					
Repo	Report for quarter ended Subject		31st Dec 22			
Subje			Certificate of progress of construction work			
			ent as architect for certifying progress of ntioned project as per the approved plans			
	Sr. No.	Particulars	Information			
,	1.	Project/Phase of the project	Elevate Phase – I			
	2.	Location	Village Behrampur, Sector-59, Gurugram			
	3.	Licensed area in acres	8.91875			
	4.	Area for registration in acres	5.95			
	5.	HARERA registration no.	19 of 2019			
	6.	Name of licensee	License no. 16 of 2008 : 1) BTVS Buildwell Pvt. Ltd.			

New Delhi-48

	T		
			2) Adson Software Pvt. Ltd.
			3) Bulls Realtors Pvt. Ltd.
			4) Commander Realtors Pvt. Ltd.
			5) Fiverivers Developers Pvt. Ltd.
4			6) Fiverivers Townships Pvt. Ltd.
			7) Ornamental Realtors Pvt. Ltd.
			8) Aspirant Builders Pvt. Ltd.
			of hispitalite ballacis i vi. Bia.
			License no. 28 of 2008 :
			1) BTVS Buildwell Pvt. Ltd.
1			2) Golden View Builders Pvt. Ltd.
			3) Hi Energy Realtors Pvt. Ltd.
			4) Base Exports Pvt. Ltd.
		=	5) Adson Software Pvt. Ltd.
			6) Bulls Realtors Pvt. Ltd.
	,		7) Commander Realtors Pvt. Ltd.
			8) Fiverivers Developers Pvt. Ltd.
			9) Ornamental Realtors Pvt. Ltd.
			10) Aspirant Builders Pvt. Ltd.
			License no. 44 of 2011 :
			1) Commander Realtors Pvt. Ltd.
			2) BTVS Buildwell Pvt. Ltd.
			3) Golden View Builders Pvt. Ltd.
			4) Hi Energy Realtors Pvt. Ltd.
			5) Base Exports Pvt. Ltd.
			6) Adson Software Pvt. Ltd.
			7) Bulls Realtors Pvt. Ltd.
			8) Fiverivers Buildcon Pvt. Ltd.
			oj i ivenveis bandeon i vi. Etd.
	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2.	Detai	ls related to inspection are as	under
		T	
	1.	Date of certifying of	31st Dec 2022
		percentage of construction	
		work/site inspection	6
		l state of the sta	
			1 100

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	31st Dec 2022

ıltant n)
tants
iltants Pvt Ltd
al

and brochure, publication material and other documents shared with the buyers in this regard. 5. I also certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table

Date

:

Yours faithfully,

Place

: W. DBLHI

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : $CA/2\infty 1/274447$

Labib Alam, Architect Council of Architecture

registration no.

Registration No.: CA/2001/27447

Council of architects (CoA) :

registration valid till (date)

31,12,2027

			Table – A		
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)					
A1	Cun	nulative progress of the projec	ct/phase at the e	nd of the quarte	r.
Sr. No.	Pro	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(incl	structure lusive of excavation, idation, basements, water ofing, etc.)	0.5	34	97%
2.	(slat	er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	0.5	46.25	83%
3.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	5	10	50 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	2	5.25	44 %

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.5	5	38%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	3	8.75	42%
	4.2	External (plaster, painting, facade, etc.)	1	4.25	28%

Sr. No.		Tasks/ Activity Sub-Structure Status	Description of work done	Percentage of total proposed work
1.	Exca	vation	Complete	100 %
2.	Layi	ng of foundation		
	(i)	Raft	Complete	100 %
	(ii)	Pile	0	0
3.	Num	ber of basement(s)		
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%
4.	1	erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	50%

		Super-Structure Status		
5.	Total floors in the tower/ building		1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Tota	ıl area on each floor	785 Sqm	100%
7.	Stilt	floor/ ground floor	Structure Tower Entrance	100%
8.	Status of laying of slabs floor wise		Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
9.	Status of construction			
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		ng of door and window frames in / units		
11.	Statu	s of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	15% Completed	15%
	(iii)	UPVC/ RWP Piping	100% Completed	97%
12.	Statu	s of wall plastering		abib Alam, Architect

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statu	is of wall tiling		~
	(i)	Bathroom Tiles	70% Completed	
	(ii)	Kitchen Wall Tile	45% Completed	
14.	Statu	as of flooring		
	(i)	Lift Lobby Flooring	10% Completed	
	(ii)	Apt Stone Flooring	60% Completed	
15.	Statu	as of white washing		- 100
	(i)	Apartment Prefinal Paint	10% Completed	
	(ii)	Putty+1stCoat+2nd Coat	60% Completed	
16.	Statu	as of finishing		
	(i)	MS Railing		95% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	65% Completed	
	(iii)	Lobby Wall Tiling	6% Completed	
17.	Statu	as of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	40% Completed	
	(ii)	Bathroom Chinaware	5% Completed	
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	1% Completed	
	(iv)	Switch & Sockets	5% Completed	ahih Alam, Architect

	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	14%	-
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	90% Completed	0
	(x)	Staircase & Lobby Lights	0% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	rproofing of terraces	PU Waterproofing	0% Completed
19.	Entra	ance lobby finishing	Gypsum False ceiling	0% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	0% Completed

Note: (*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remark
B-1	Services			<u> </u>
1.	Internal roads & pavements	Yes	0	
2.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
3.	Water supply	Yes	0	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
5.	Storm water drains	Yes	0	-
6.	Landscaping & tree plantation	Yes	0	
7.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	_
	Benches	Yes	0	
8.	Shopping area	Yes	0	
9.	Street lighting/ electrification	Yes	0	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	
11.	Solid waste management & disposal	Yes	0	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
13.	Energy management (solar)	Yes	0	
14.	Fire protection and fire safety requirements	Yes	0	
15.	Electrical meter room, sub-station, receiving station	Yes	0	2

16.	Other (option to add more)	NA	0
B-2	Community building to be transferred	to RWA	
17.	Community centre	Yes	0
18.	others	NA	
B-3	Community buildings not to be transferred to RWA/competent authority		
19.	Schools	NA	
20.	Dispensary	NA	
21.	Club	Yes	0
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority	NA	
23.	*		Care I

Note: (*) extend as per requirement

		•	Гable – A		
(to buile	Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower-B		
A1	Cun	nulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.			o 34	34	
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		2	47.25	79%
7.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	4	9.04	45%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	2	5.5	44%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	2.5	5.75	43%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.5	8	36%
	4.2	External (plaster, painting, facade, etc.)	.5	3.75	25%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
		Sub-Structure Status		
21.	Exca	vation	Complete	100 %
22.	Layi	ng of foundation		7
	(iii)	Complete	100 %	100 %
	(iv)	NA	NA	0
23.	Number of basement(s)			
	(iii)	Structure under Tower Footprint Complete	Complete	100%
	(iv)	Structure under Tower Footprint Complete	Complete	100%
24.	4. Waterproofing of the above sul structure (wherever applicable)		Deck Water Proofing	50%
		Super-Structure Status		abib Alam, Architect

25.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Tota	l area on each floor	772 Sqm	100%
27.	Stilt	floor/ground floor	Structure Tower Entrance	100% Completed
28.			Upto terrace Level Completed	100%
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Statu	s of construction		8
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room		100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.	1	g of door and window frames in units	Door Frame	55% Completed
31.	Statu	s of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	0% Completed	
	(vi)	UPVC/ RWP Piping	91% Completed	
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	ahih Alam, Architect

	(iv)	Gypsum Plaster	70%	
33.	Statu	as of wall tiling		
	(iii)	Bathroom Tiles	50% Completed	
	(iv)	Kitchen Wall Tile	50% Completed	
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	0% Completed	
	(iv)	Apt Stone Flooring	28% Completed	
35.	Statu	s of white washing		
	(iii)	Apartment Prefinal Paint	0% Completed	
	(iv)	Putty+1stCoat+2nd Coat	5% Completed	
36.	Status of finishing			
	(iv)	MS Railing	90% Completed	
	(v)	Lift Well HO for Lift Installation	65% Completed	
	(vi)	Lobby Wall Tiling	0% Completed	
37.	Statu	s of installation	1100	
	(with	in flat/unit)		
	(xii)	UPVC Windows	20% Completed	
	(xiii)	Bathroom Chinaware	0% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	0% Completed	
	(xv)	Switch & Sockets	5% Completed	
	(xvi)	NA	NA	
	(othe	r than flat/units)		Sie

	(xvii	Guide Rail+ Floor Door+ Car Installation	0	
	(xvii	RCC Work	97% Completed	
	(xix)	RCC Work	100% Completed	
	(xx)	Fire Pump Installation	60% Completed	
	(xxi)	Staircase & Lobby Lights	0% Completed	
	(xxii]	Six Monthly Compliance	100% Compliance	
38.	Wate	rproofing of terraces	PU Waterproofing	0% Completed
39.	Entra	ance lobby finishing	Gypsum False ceiling	0% Completed
40.	Status of construction of compound wall		Boundary Wall RCC and Brick Work	5% Completed

Note: (*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services		<u> </u>	L
24.	Internal roads & pavements	Yes	0	
25.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
26.	Water supply	Yes	0	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
28.	Storm water drains	Yes	0	
29.	Landscaping & tree plantation	Yes	0	
30.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
31.	Shopping area	Yes	0	
32.	Street lighting/ electrification	Yes	0	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	
34.	Solid waste management & disposal	Yes	0	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
36.	Energy management (solar)	Yes	0	
37.	Fire protection and fire safety requirements	Yes	0	
38.	Electrical meter room, sub-station, receiving station	Yes	0	e de

46.	*		College Colleg
B-4	Services/ facilities to be transferred to competent authority	NA	
45.	Others	NA	
44.	Club	Yes	0
43.	Dispensary	NA	
42.	Schools	NA	
B-3	Community buildings not to be transferred to RWA/competent authority		
41.	others	NA	
40.	Community centre	Yes	0
B-2	Community building to be transferred	to RWA	
39.	Other (option to add more)	NA	

Note: (*) extend as per requirement

			Table - A		
(to buile	Building/Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)				
A1	Cun	nulative progress of the projec	ct/phase at the e	nd of the quarte	er.
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		b structure aclusive of excavation, and ation, basements, water	Cumulative work done value till date	Percentage of work done to the total proposed work
9.				23.46	
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0.5	33.5	84%
11.	MEP	•			
	3.1	Mechanical (lifts, ventilation, etc.)	3	6.26	63%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1	4.1	51%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	.5	5.5	69%
12.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2	8	50%
	4.2	External (plaster, painting, facade, etc.)	0.5	3.75	75%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
		Sub-Structure Status		
41.	Exca	vation	Complete	100 %
42.	Layii	ng of foundation		
	(v)	Complete		100%
	(vi)	NA	NA	0
43.	Number of basement(s)			
	(v)	Structure under Tower Footprint Complete		100%
	(vi)	Structure under Tower Footprint Complete		100%
44.	1	erproofing of the above sub- eture (wherever applicable)	Deck Water Proofing	40%
		Super-Structure Status		Labib Alam, Architect

45.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Tota	ll area on each floor	549 Sqm	100%
47.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
48.	Status of laying of slabs floor wise		Upto terrace Level Completed	100%
	build	ulative number of slabs in the ding/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Statı	us of construction		
	(ix)	Blockwork	95% Completed	
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	
	(xi)	Lift Well including Machine room	100% Completed	
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	8
50.	1	g of door and window frames in units	Door Frame	70% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	5% Completed	5% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	-
52.	Statu	s of wall plastering		
	(v)	RCC External Wall	NA	Labib Alam, Architec

Registration No.: CA/2001/27447

	(vi)	Gypsum Plaster	100%	
53.	Status of wall tiling			
	(v)	Bathroom Tiles	25% Completed	
	(vi)	Kitchen Wall Tile	25% Completed	
54.	Status of flooring			
	(v)	Lift Lobby Flooring	0% Completed	2/11
	(vi)	Apt Stone Flooring	60% Completed	
55.	Status of white washing			
	(v)	Apartment Prefinal Paint	0% Completed	
	(vi)	Putty+1stCoat+2nd Coat	20% Completed	
56.	Status of finishing			
	(vii)	MS Railing		70% Completed
	(viii)	Lift Well HO for Lift Installation		100% Completed
	(ix)	Lobby Wall Tiling		0% Completed
57.	Statu	s of installation		
	(with	in flat/unit)		
	(xxii	UPVC Windows	40% Completed	
	(xxiv	Bathroom Chinaware	0%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	0%	
	(xxvi	Switch & Sockets	0% Completed	
	(xxvi	NA	NA	
	(othe	r than flat/units)		ship Alam Ambian

	(xxvi	Guide Rail+ Floor Door+ Car Installation	20%	
	(xxix	RCC Work	100% Completed	
	(xxx)	RCC Work	100% Completed	
	(xxxi	Fire Pump Installation	90% Completed	
	(xxxi	Staircase & Lobby Lights	0% Completed	
	(xxxi	Six Monthly Compliance	100% Compliance	
58.	Wate	rproofing of terraces	PU Waterproofing	0% Completed
59.	Entra	nce lobby finishing	Gypsum False ceiling	0% Completed
60.	Status of construction of compound wall		Boundary Wall RCC and Brick Work	0% Completed

Note: (*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remark
B-1	Services			
47.	Internal roads & pavements	Yes	0	
48.	Parking	Yes	0	
	Covered no	Yes	0	<u> </u>
	Open no	Yes	0	
49.	Water supply	Yes	0	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
51.	Storm water drains	Yes	0	
52.	Landscaping & tree plantation	Yes	0	
53.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
54.	Shopping area	Yes	0	
55.	Street lighting/ electrification	Yes	0	
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	
57.	Solid waste management & disposal	Yes	0	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
59.	Energy management (solar)	Yes	0	2-10-1
60.	Fire protection and fire safety requirements	Yes	0	
61.	Electrical meter room, sub-station, receiving station	Yes	0	ND_

62.	Other (option to add more)	NA	
B-2	Community building to be transferred to RWA		
63.	Community centre	Yes	0
64.	others	NA	
B-3	Community buildings not to be transferred to RWA/competent authority		
65.	Schools	NA	
66.	Dispensary	NA	
67.	Club	Yes	0
68.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority	NA	
69.	*		0.00

Note: (*) extend as per requirement

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page **25** of **25**