

R K & ASSOCIATES, Architects

E 31, Green Park Main, New Delhi 110016 INDIA

T 91 11 26862540

E rka.architects@gmail.com; contact@rkaindia.net; rohit.rkaindia@gmail.comW www.rkaindia.net

Annexure C			
Architect's Certificate1			
Report for quarter ending		01-01-2023	
Subject		Certificate of percentage of completion of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
	Sr. No	Particulars	Information
	1.	Project/Phase of the project	Habitat Residences
	2.	Location	Village Faridpur, Sector-78, Faridabad, Haryana
	3.	Licensed area in acres	5.08125 Acre
	4.	Area for registration in acres	5.08125 Acre
	5.	HARERA registration no.	HRERA-PKL-FBD-170-2019, dated – 24/10/2019
	6.	Name of licensee	BCC Edutech Pvt. Ltd.
	7.	Name of collaborator	Conscient Infrastructure Pvt. Ltd.
	8.	Name of developer	Conscient Infrastructure Pvt. Ltd.
2.	Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection	01-01-2023
	2.	Name of Architect/ Architect's firm	R.K. & ASSOCIATES
	3.	Date of site inspection	31-12-2022
3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Sharad Chandra
	2.	Structural consultant	NNC DESIGN INTERNATIONAL
	3.	Proof consultant	BMSF Design Consultants Pvt. Ltd.
	4.	MEP consultant	V CONSULTING
4	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
	5		
I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B			

Date 01-01-2023

Place : New Delhi

Yours faithfully



Signature & name (in block letters) with stamp of architect

Local authority license no.

Local authority license no. valid till (date)

Council of architects (CoA) registration no. CA/94/17868

Council of architects (CoA) registration valid till (date) 31 12 2025

Project Details:

- ☐ Plot Area: 5.08125 Acre
- ☐ Residential Towers: 8 nos - D1,D2,D3,D4,D5,D6,D7,D8,E
- ☐ Commercial Component
- ☐ Community Center
- ☐ Anganwadi Cum Crèche

Total No of Units: 732 Nos.

Table-A

Building/Tower no. **Tower-D-3**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	9 Floors
	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%
	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	90%
	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	95%
	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	98%
	ii. In Kitchen	Kitchen Wall Tile	98%
	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	98%
	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	

10/5/24



vi. Lifts installation	Rail + Floor Door	0%
vii. Overhead tanks	RCC Work	100%
viii. Underground water tank	NA	NA
ix. Firefighting fittings and equipment's as per	Fire Pump	

lob-f



	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-7**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	98%
11.	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	90%
12.	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	89%
13.	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	95%
	ii. In Kitchen	Kitchen Wall Tile	95%
14.	Status of flooring		
	i. Common areas	Lift Lobby Flooring	90%
	ii. Units/flats	Apt Stone Flooring	95%
15.	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
	Status of Installation		
	(Within flat/unit)		

i. Doors and windows panels	Windows	98%
ii. Sanitary Fixtures	Chinaware	0%
iii. Modular Kitchen	NA	
iv. Electrical fittings/Lighting	Switch & Socket	0%

lob-f



16	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	99%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-8**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	99%
	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	100%
	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	95%
	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	99%
	Status of flooring		
	i. Common areas	Lift Lobby Flooring	0%
	ii. Units/flats	Apt Stone Flooring	99%
	Status of finishing		

lob-f



i. Staircase with railing	MS Railing	100%
---------------------------	------------	------

lob-t



15	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
	Status of Installation (Within flat/unit)		
16	i. Doors and windows panels	Windows	99%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-4**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	99%
11	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	91%
12	Status of wall Finishing		
	i. External	External Paint	100%



	ii. Internal	Int. Paint. 1st Coat	99%
	Status of wall tiling		
13	i. In bathroom	Bathroom Tiles	95%
	ii. In Kitchen	Kitchen Wall Tile	95%

lob-f



14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	90%
	ii. Units/flats	Apt Stone Flooring	95%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	99%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	44%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-5**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	96%
	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA

11	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	91%
	Status of wall Finishing		



12	i. External	External Paint	98%
	ii. Internal	Int. Paint. 1st Coat	97%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	99%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	90%
	ii. Units/flats	Apt Stone Flooring	99%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	96%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	81%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-6**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+13)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	14 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%



	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA

lob-t



11	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	93%
12	Status of wall Finishing		
	i. External	External Paint	98%
	ii. Internal	Int. Paint. 1st Coat	98%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	98%
	ii. In Kitchen	Kitchen Wall Tile	98%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	98%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	97%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-E**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	573.7 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	9 Floors
	Status of construction		

lob-f



9.	i. Walls on floors	RCC Wall	90%
	ii. Staircase	Rcc Structure	90%
	iii. Lift wells along with water proofing	Rcc Structure	90%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	90%




10.	Fixing of door and window frames in flats/units	Door Frame	94%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	95%
12	Status of wall Finishing		
	i. External	External Paint	20%
	ii. Internal	Int. Paint. 1st Coat	94%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	86%
	ii. In Kitchen	Kitchen Wall Tile	46%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	0%
	ii. Units/flats	Apt Stone Flooring	86%
15	Status of finishing		
	i. Staircase with railing	MS Railing	90%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	94%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	0%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	90%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-1**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	



6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	8 Floors

lob-f



9.	Status of construction		
	i. Walls on floors	RCC Wall	80%
	ii. Staircase	Rcc Structure	80%
	iii. Lift wells along with water proofing	Rcc Structure	80%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	80%
10.	Fixing of door and window frames in flats/units	Door Frame	68%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	89%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	89%
12	Status of wall Finishing		
	i. External	External Paint	0%
	ii. Internal	Int. Paint. 1st Coat	57%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	0%
	ii. In Kitchen	Kitchen Wall Tile	0%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	0%
	ii. Units/flats	Apt Stone Flooring	0%
15	Status of finishing		
	i. Staircase with railing	MS Railing	0%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	0%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	0%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	0%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-2**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-



	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
<u>A2</u>	SUPER- STRUCTURE STATUS		

lob-f



5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	9 Floors
	Status of construction		
9.	i. Walls on floors	RCC Wall	90%
	ii. Staircase	Rcc Structure	90%
	iii. Lift wells along with water proofing	Rcc Structure	90%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	90%
10.	Fixing of door and window frames in flats/units	Door Frame	83%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	94%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	89%
12	Status of wall Finishing		
	i. External	External Paint	0%
	ii. Internal	Int. Paint. 1st Coat	92%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	77%
	ii. In Kitchen	Kitchen Wall Tile	38%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	0%
	ii. Units/flats	Apt Stone Flooring	0%
15	Status of finishing		
	i. Staircase with railing	MS Railing	0%
	ii. Lift wells	Handover of Lift Well to Lift Agency	0%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	0%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	0%
	vii. Overhead tanks	RCC Work	0%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	0%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		