# **BEE BEE ARCHITECTS**

**Architects & Engineers** 

APURBA BORAH Annexure A

		Architect	's Certificate <sup>*</sup>		
Report	t for quar	ter ending	31 DECEMBER 2019		
Subject		-	Certificate of progress of construction work		
1.		ave undertaken assignment as architonent aver the approve	ect for certifying progress of construction work in the ed plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Project Area 8093.7 sq mtr , Commercial Cum Residential Colony		
	2.	Location	Village Bhatola, Sector-79, Faridabad		
	3.	Licensed area in acres	11.49375 acres		
	4.	Area for registration in acres	1.99 acres		
	5.	HARERA registration no.	111 of 2017		
	6.	Name of licensee	Robust Buildwell Private Limited		
-	7.	Name of collaborator			
	8.	Name of developer	Robust Buildwell Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	6 gr 24N 5050		
	2.	Name of Architect/ Architect's firm	BEE BEE Architects.		
	3.	Date of site inspection	4th JAN, 2020		

**Architects & Engineers** 

### **APURBA BORAH**

3.	Following technical professionals are appointed by promoter: - (as applicable)			
	Sr. No.	Consultants	Name	
	1.	Site engineer	Mr. D.C Pant	
	2.	Structural consultant	Mr. Pankaj Varshney	
	3.	Proof consultant		
	4.	MEP consultant	Mr, Dharmendra Singh	
			Mr. D.C Pant	
	5.	Site incharge		
4.	Haryan constru envisag	a Building Code, 2017/ National Build ction, infrastructure works and intern	s per approved drawings, statutory/ mandatory approvals, ling Code (wherever applicable) and the material used in the al development works are as per the projected standard as publication material and other documents shared with the	
5.	of the r	real estate project/phase of the project	ge of work done in the project for each of the building/ tower under HARERA is as per table A and table B given herein d with respect to each of the activity of the entire project/	

Date

: 6 TAN, 20 JOHNSON BORAH]

Yours faithfully,

Place

: New Delti.

Signature & name (in block letters) with

Apurba Boreh

Regd. Architect CA/2013/61618

Council of architects (CoA) : registration no.

Council of architects registration valid till (date)

(CoA) :

## **BEE BEE ARCHITECTS**

Architects & Engineers
APURBA BORAH

			Table – A		
(to be	e prepar	ed separately for each building/ tower t/phase of the project)			
A1	Cum	ulative progress of the project/phase a	at the end of the qua	rter.	9
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(inclu	structure usive of excavation, foundation, nents, water proofing, etc.)	.80 CR	9.40 CR	12.53%
	ouser	nones, water proofing, etc.)			
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)			-	
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	<u>-</u>	<u>.</u>	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)		-	
4.	Finis	hing			9
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	
	4.2	External (plaster, painting, facade, etc.)	* .		

# BEE BEE ARCHITECTS Architects & Engineers

1694

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		APURBA BORA Percentage of total	
No.						proposed work
1.	Excav	ration	Completed		100%	
2.	Layin	g of foundation				
	(i)	Raft	Comp	leted	100	%
	(ii)	Pile	N/A		N/A	
3.	Numb	per of basement(s)				
	(i) Basement Level 1		Completed		100	9%
	(ii)	Basement level 2*	Completed		100%	
	(iii)	Basement Level 3	WIP		45%	
	(iv)	Basement Level 4	WIP			
4.		rproofing of the above sub-structure rever applicable)				
		Super-Structure Status				
5.	Total	floors in the tower/ building	- 4		-	
6.	Total	area on each floor	12000		-	
7.	Stilt f	loor/ ground floor	636	600		
8.	Status	s of laying of slabs floor wise	-	0	:-	
		ulative number of slabs in the building/				
9.	Status	s of construction		8		
	(i)	Walls on floors	12			
	(ii)	Staircase				
	(iii)	Lift wells along with water proofing	-		-	
	(iv)	Lift lobbies/ common areas floor wise	-			-
10.	Fixin units	g of door and window frames in flats/		(9.)		
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works				
	(ii)	Electrical works including wiring				
	(iii)	Plumbing works		-		
12.	Statu	s of wall plastering				
	(i)	External plaster		-		
	(ii)	Internal plaster		-		-
13.	Statu	s of wall tiling				
	(i)	In bathroom		-		
	(ii)	In kitchen		-		
14.	Statu	as of flooring				
9	Brag	gatioRatbi,aMathura Nagar, Dispu	Guwahati	Kamrup, A	Assam-78100	6
	(ii)	Units/ flats		-		

## **BEE BEE ARCHITECTS**

Architects & Engineers

				1695
Sr. No.		Tasks/ Activity	Description of work done	APURBA BORA Percentage of total proposed work
NO.	Sub-Structure Status		done	proposea work
15.	Status of white washing			
	(i)	Internal walls	* .	14
	(ii)	External walls	-	
16.	Status of finishing			
	(i)	Staircase with railing		
	(ii)	Lift wells	-	
	(iii)	Lift lobbies/ common areas floor wise	œ	
17.	Status of installation			11 8
	(within flat/unit)			
	(i)	Doors and windows panels	-	
	(ii)	Sanitary fixtures	-	
	(iii)	Modular kitchen	-	
	(iv)	Electrical fittings/ lighting	-	
	(v)	Gas piping (if any)	-	
	(other	than flat/units)		
	(vi)	Lifts installation	3	
	(vii)	Overhead tanks	. <del>.</del> .	
	(viii)	Underground water tank	H.S	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	T .
	(x)	Electrical fittings in common areas		
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	
18.	Water	rproofing of terraces		
19.	Entra	nce lobby finishing	-	
20.	Status	s of construction of compound wall	-	

Note: (\*) extend rows as per requirement.

## **APURBA BORAH**

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements		0%	
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	,
7.	Parks and playgrounds	-		
- Major	Fixing of children play equipment's			
	Benches			-
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	-		
12.	Water conservation, rain water, harvesting, percolating well/ pit	8, 10	11	
13.	Energy management (solar)	<b>=</b> :		
14.	Fire protection and fire safety requirements			
15.	Electrical meter room, sub-station, receiving station	-		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community centre	-		
18.	others	-		
B-3	Community buildings not to be transferred to RWA/competent authority	-		
19.	Schools	-		
20.	Dispensary	-		
21.	Club	(2)		2
22.	Others	2		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement