BEE BEE ARCHITECTS Architects & Engineers

	1691
APU	RBA BORAH

		Architect	's Certificate [*]
Report	for qua	rter ending	31 DECEMBER 2019
Subject	t		Certificate of progress of construction work
I/We have undertaken assignment as archite below mentioned project as per the approve		ave undertaken assignment as archite mentioned project as per the approve	ect for certifying progress of construction work in the
	Sr. No.	Particulars	Information
		n i mi	Project Area 4105.53 sq mtr , Commercial Cum
	1.	Project/Phase of the project	Residential Colony
	2.	Location	Village Bhatola, Sector-79, Faridabad
	3.	Licensed area in acres	11.49375 acres
7 7	4.	Area for registration in acres	1.01 acres
	5.	HARERA registration no.	76 of 2017
	6.	Name of licensee	Robust Buildwell Private Limited
, ,	7.	Name of collaborator	
	8.	Name of developer	Robust Buildwell Private Limited
2.	2. Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection	6 th JAN, 2020
	2.	Name of Architect/ Architect's firm	BEE BEE Architects.
	3.	Date of site inspection	W dr JAN, 2020.

Architects & Engineers

1692

APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Traine	
	1.	Site engineer	Mr. D.C Pant
	2.	Structural consultant	Mr. Pankaj Varshney
	3.	Proof consultant	
	4.	MEP consultant	Mr, Dharmendra Singh
			Mr. D.C Pant
	5.	Site incharge	
4.	Haryana construc envisag	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.	
5.	of the rebelow.	eal estate project/phase of the project	e of work done in the project for each of the building/ tower under HARERA is as per table A and table B given herein with respect to each of the activity of the entire project/

Date

: 6 th JAN, 20

Yours faithfully,

Place

: New Dethe

Apurba Borah
R Signature & name (in block letters) with
CA/2013/stamp of architect

Council of architects (CoA) : registration no.

Council of architects (CoA) : registration valid till (date)

BEE BEE ARCHITECTS

Architects & Engineers
APURBA BORAH

			Table – A			
(to be	prepar	ower no. red separately for each building/ tower t/ phase of the project)				
A1	Cum	ulative progress of the project/phase	at the end of the qua	rter.		
Sr. No.	Proje	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	(inclu	structure usive of excavation, foundation, ments, water proofing, etc.)	0.47 Cr	6.89 Cr	10.42%	
2.	Supe (slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	-	-	-	
3.	MEP)				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-	
4.	Finis	hing			ja ja	
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)		-	-	
	4.2	External (plaster, painting, facade, etc.)		-	-	

BEE BEE ARCHITECTS

Architects & Engineers

1694

Sr.		Tasks/ Activity	Description of work		Percentag	BA BORAI ge of total
No.	Sub-Structure Status		done		proposed work	
1.	Excav	vation	Comp	leted	100)%
2.	Laying of foundation					
	(i)	Raft	Comp	oleted	100%	
	(ii)	Pile	N/	Ά		
3.	Numb	per of basement(s) 2				
	(i)	Basement Level 1	W	IP	60 %	
	(ii)	Basement level 2*	W	IP	-	
4.		rproofing of the above sub-structure rever applicable)		·	-	
		Super-Structure Status				
5.	Total	floors in the tower/ building	G+	-16		
6.	_	area on each floor	12			•
7.		loor/ ground floor		00		-
8.		s of laying of slabs floor wise		-		-)
0.		ulative number of slabs in the building/				-3:
		anative number of stabs in the building.				
9.	Status	s of construction				
	(i)	Walls on floors				-
	(ii)	Staircase		-		-
	(iii)	Lift wells along with water proofing		-		-
	(iv)	Lift lobbies/ common areas floor wise		-		-
10.		g of door and window frames in flats/		-	3	-
	units	0.150				
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works		-	1 10	-
	(ii)	Electrical works including wiring		-		-
	(iii)	Plumbing works		-		-
12.	Statu	s of wall plastering				
	(i)	External plaster		-	-	
	(ii)	Internal plaster		-		-
13.	Statu	s of wall tiling				
	(i)	In bathroom		=		=
	(ii)	In kitchen		.		-
14.	Statu	s of flooring				
	(i)	Common areas		-		-
	(ii)	Units/ flats		-		-

BEE BEE ARCHITECTS

Architects & Engineers

C.,		Translat Astron	D	APURBA BORA	H
Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work	
15.	Status of white washing				
13.	(i)	Internal walls	-	- 0	
	(ii)	External walls	·-	# X	
16.		of finishing			
10.	(i)	Staircase with railing	_	-	
	(ii)	Lift wells			
	(iii)	Lift lobbies/ common areas floor wise			
17.	3 .5	of installation			
17.					
	-	n flat/unit)	_		
	(i)	Doors and windows panels			
	(ii)	Sanitary fixtures	-	-	
	(iii)	Modular kitchen	-	~	
	(iv)	Electrical fittings/ lighting			
	(v)	Gas piping (if any)	*	通	
	(other	than flat/units)	(A)		
	(vi)	Lifts installation	-	-	
	(vii)	Overhead tanks	**	-	
	(viii)	Underground water tank	-	~	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	6	
	(x)	Electrical fittings in common areas	-	-	
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	-	
18.	Water	rproofing of terraces	-	-	
19.	Entra	nce lobby finishing	-	-	
20.	Status	s of construction of compound wall	-	-	

Note: (*) extend rows as per requirement.

Architects & Engineers

APURBA BORAH

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services	N N		
1.	Internal roads & pavements	YES	0%	
2.	Parking	YES	0%	
	Covered no	•,	- 1	
	Open no	=:		
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	YES	0%	
	Fixing of children play equipment's	N/A		
	Benches	YES	0%	
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	N/A		
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	0%	
13.	Energy management (solar)	N/A		
14.	Fire protection and fire safety requirements	YES	0%	
15.	Electrical meter room, sub-station, receiving station	YES	0%	
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community centre			
18.	others	;=		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	-	· ·	
20.	Dispensary	-	Ti di	
21.	Club	=		
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement