

LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTH CITY-1, GURGAON, HARYANA

EMAIL : lofarchitectsgurgaon@gmail.com

Annexure A

Architect's Certificate*		
Report for quarter ending		30.06.2022
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	THE LEAF
2.	Location	Vill- Badha, Sector-85, Tehsil-Manesar, Gurugram
3.	Licensed area in acres	11.093
4.	Area for registration in acres	11.093
5.	HARERA registration No.	23 OF 2019
6.	Name of licensee	Shiva Profins Pvt. Ltd.,
7.	Name of collaborator	NA
8.	Name of developer	SS Group Pvt. Ltd.
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	30.06.2022
2.	Name of Architect/ Architect's firm	
3.	Date of site inspection	30.06.2022
3.	Following technical professionals are appointed by promoter: - (as applicable)	
Sr. No.	Consultants	Name
1.	Site engineer	Mr.Baidhnath Mishra
2.	Structural consultant	DESMAN
3.	Proof consultant	DESMAN
4.	MEP consultant	ASHOK GANGWAR (ARK Consultants)
5.	Site supervisor/in charge	Mr. Mohnis Das

LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTH CITY-1, GURGAON, HARYANA

EMAIL : lofarchitectsgurgaon@gmail.com

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.



Yours Faithfully

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council
of Architecture CA/2003/31608

Signature & Name (in block letters)

With stamp of Architect

Date

Place

Council of Architects (CoA): CA/2003/31608

Registration No.

Council of Architects (CoA) : 31st DEC 2031

Registration valid till (Date)

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T1		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		75	2749.88	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			95%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			96%
	4.2	External (Plaster, Painting, Façade etc.)			93%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+25	100%
6	Total Area on each floor (Sq.Mtr.)			425.192	100%
7	Stilt / Ground Floor			532.506	100%
	Status of Laying of slabs floor wise			Complete	100%

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	Status of Construction		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	Complete	100%
11	Status of MEP	Internal (with in Flat)	External Work
	(i) Mechanical Works	In Progress	65%
	(ii) Electrical work including wiring	In Progress	95%
	(iii) Plumbing work	In Progress	95%
12	Status of Wall Plastering		
	(i) External Plaster	Complete	100%
	(ii) Internal Plaster	Complete	100%
13	Status of Wall Tiling		
	(i) In Bath Rooms	In Progress	96%
	(ii) In Kitchen	In Progress	96%
14	Status of Flooring		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	Status of White Washing		
	(i) Internal Walls	In Progress	96%
	(ii) External Walls	In Progress	96%
16	Status of Finishing		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation		
	(within Flats/ Units)		
	(i) Doors & Windows Panels	Complete	96%
	(ii) Sanitary Fixtures	Complete	96%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping (if any)	NA	NA
	(other than Flats/ Units)		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x) Electrical Fittings in Common Areas	Complete	100%
	(xi) Compliance to condition of environment/CRZ NOC	NA	NA
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T2		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		74	2714.49	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			95%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			88%
	4.2	External (Plaster, Painting, Façade etc.)			93%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+25	100%
6	Total Area on each floor (Sq.Mtr.)			425.192	100%
7	Stilt / Ground Floor			532.506	100%
	Status of Laying of slabs floor wise			Complete	100%

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	Status of Construction		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	Complete	100%
11	Status of MEP	Internal (with in Flat)	External Work
	(i) Mechanical Works	In Progress	65%
	(ii) Electrical work including wiring	In Progress	95%
	(iii) Plumbing work	In Progress	95%
12	Status of Wall Plastering		
	(i) External Plaster	Complete	100%
	(ii) Internal Plaster	Complete	100%
13	Status of Wall Tiling		
	(i) In Bath Rooms	In Progress	88%
	(ii) In Kitchen	In Progress	88%
14	Status of Flooring		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	Status of White Washing		
	(i) Internal Walls	In Progress	93%
	(ii) External Walls	In Progress	93%
16	Status of Finishing		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation		
	(within Flats/ Units)		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	In Progress	80%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping (if any)	NIL	NA
	(other than Flats/ Units)		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x) Electrical Fittings in Common Areas	NA	NA
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T3		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		134	2699.35	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			95%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			87%
	4.2	External (Plaster, Painting, Façade etc.)			90%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+25	100%
6	Total Area on each floor (Sq.Mtr.)			425.192	100%
7	Stilt / Ground Floor			532.506	100%
	Status of Laying of slabs floor wise			Complete	100%

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	Status of Construction		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	Complete	100%
11	Status of MEP	Internal (with in Flat)	External Work
	(i) Mechanical Works	In Progress	65%
	(ii) Electrical work including wiring	In Progress	95%
	(iii) Plumbing work	In Progress	95%
12	Status of Wall Plastering		
	(i) External Plaster	In Progress	90%
	(ii) Internal Plaster	Complete	100%
13	Status of Wall Tiling		
	(i) In Bath Rooms	In Progress	87%
	(ii) In Kitchen	In Progress	87%
14	Status of Flooring		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	Status of White Washing		
	(i) Internal Walls	NIL	NIL
	(ii) External Walls	Complete	100%
16	Status of Finishing		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation		
	(within Flats/ Units)		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	In Progress	70%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping (if any)	NA	NA
	(other than Flats/ Units)		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NA	NA
	(x) Electrical Fittings in Common Areas	Complete	100%
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B1		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1189.33	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			96%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			97%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+14	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85 ,LPH-227.46, UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	96%
	(iii)	Plumbing work	Complete	97%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	Complete	100%
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B2		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1189.33	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			96%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			97%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+14	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85 ,LPH-227.46, UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	96%
	(iii)	Plumbing work	Complete	97%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B3		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1142.37	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete	100%	
	(ii)	Pile	NA	NA	
3	Number of Basements				
	(i)	Basement Level-1	Complete	100%	
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
			Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	95%
	(iii)	Plumbing work	Complete	96%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	97%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B4		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1141.79	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	95%
	(iii)	Plumbing work	Complete	96%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	In Progress	70%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B5		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1141.79	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conducting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	95%
	(iii)	Plumbing work	Complete	96%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	NIL	0%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B6		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	1143.98	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work Internal (with in Flat)
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	96%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		NIL	NIL
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B7		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		34	1301.27	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			93%
	4.2	External (Plaster, Painting, Façade etc.)			92%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete	100%	
	(ii)	Pile	NA	NA	
3	Number of Basements				
	(i)	Basement Level-1	Complete	100%	
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	95%
	(iii)	Plumbing work	Complete	96%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	93%
	(ii)	Units/Flats	Complete	93%
15	Status of White Washing			
	(i)	Internal Walls	Complete	93%
	(ii)	External Walls	Complete	93%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	In Progress	93%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	In Progress	80%
	(ii)	Sanitary Fixtures	In Progress	80%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	65%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		In Progress	93%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B8		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		21	1295.06	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			95%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			95%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			92%
	4.2	External (Plaster, Painting, Façade etc.)			88%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		In Progress	50%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	Complete	65%
	(ii)	Electrical work including wiring	Complete	95%
	(iii)	Plumbing work	Complete	95%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	In Progress	92%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	In Progress	92%
	(ii)	Units/Flats	In Progress	92%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	In Progress	92%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	In Progress	25%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B9		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lac)	Cumulative Work done value till Date (in Cr)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		89	1176.76	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			47%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			70%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			73%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			78%
	4.2	External (Plaster, Painting, Façade etc.)			72%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	In Progress	47%
	(ii)	Electrical work including wiring	In Progress	70%
	(iii)	Plumbing work	In Progress	73%
12	Status of Wall Plastering			
	(i)	External Plaster	In Progress	85%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	In Progress	78%
	(ii)	In Kitchen	In Progress	78%
14	Status of Flooring			
	(i)	Common Areas	In Progress	78%
	(ii)	Units/Flats	In Progress	78%
15	Status of White Washing			
	(i)	Internal Walls	In Progress	72%
	(ii)	External Walls	In Progress	72%
16	Status of Finishing			
	(i)	Staircase with Railing	In Progress	90%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	In Progress	78%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	NIL	80%
	(ii)	Sanitary Fixtures	NIL	70%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B10		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		55	1285.88	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			65%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			88%
	4.2	External (Plaster, Painting, Façade etc.)			89%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor (Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal (with in Flat)	External Work Internal (with in Flat) External Work
	(i)	Mechanical Works	In Progress	65%
	(ii)	Electrical work including wiring	In Progress	100%
	(iii)	Plumbing work	In Progress	96%
12	Status of Wall Plastering			
	(i)	External Plaster	In Progress	89%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	In Progress	88%
	(ii)	In Kitchen	In Progress	88%
14	Status of Flooring			
	(i)	Common Areas	In Progress	88%
	(ii)	Units/Flats	In Progress	88%
15	Status of White Washing			
	(i)	Internal Walls	In Progress	89%
	(ii)	External Walls	In Progress	89%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	In Progress	88%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	In Progress	90%
	(ii)	Sanitary Fixtures	In Progress	70%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER- EWS		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		15	357.76	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			100%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			96%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			97%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of BasementsNA				
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+9	100%
6	Total Area on each floor (Sq.Mtr.)			G.F-266.190,1st to 3rd-322.75,4th to 6th-	100%
7	Stilt / Ground Floor			266.19	100%

8	Status of Laying of slabs floor wise		Complete		100%	
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete		100%	
9	Status of Construction					
	(i)	Walls on floors	Complete		100%	
	(ii)	Staircase	Complete		100%	
	(iii)	Liftwells along with water proofing	Complete		100%	
	(iv)	Lift Lobbies/Common areas floor wise	Complete		100%	
10	Fixing of Door & window frames in the Flats/Units		NIL		NIL	
11	Status of MEP		Internal (with in Flat)	External Work	Internal (with in Flat)	External Work
	(i)	Mechanical Works	NIL		NIL	
	(ii)	Electrical work including wiring	Complete		100%	
	(iii)	Plumbing work	Complete		96%	
12	Status of Wall Plastering					
	(i)	External Plaster	Complete		100%	
	(ii)	Internal Plaster	Complete		100%	
13	Status of Wall Tiling					
	(i)	In Bath Rooms	Complete		100%	
	(ii)	In Kitchen	Complete		100%	
14	Status of Flooring					
	(i)	Common Areas	Complete		100%	
	(ii)	Units/Flats	NIL		NIL	
15	Status of White Washing					
	(i)	Internal Walls	Complete		100%	
	(ii)	External Walls	Complete		100%	
16	Status of Finishing					
	(i)	Staircase with Railing	Complete		100%	
	(ii)	Lift Wells	Complete		100%	
	(iii)	Lift Lobbies/Common areas floor wise	Complete		100%	
17	Status of installation					
	(within Flats/ Units)					
	(i)	Doors & Windows Panels	Complete		100%	
	(ii)	Sanitary Fixtures	Complete		100%	
	(iii)	Modular Kitchen	NA		NA	
	(iv)	Electrical Fittings/ Lightings	NA		NA	
	(v)	Gas Piping (if any)	NA		NA	
	(other than Flats/ Units)					
	(vi)	Lift Installations	Complete		100%	
	(vii)	Over Head Tanks	Complete		100%	
	(viii)	Under Ground Water Tanks	NA		NA	
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	Complete		100%	
	(x)	Electrical Fittings in Common Areas	Complete		100%	
	(xi)	Compliance to condition of environment/CRZ NOC	Complete		100%	
18	Water Proofing of Terraces		Complete		100%	
19	Entrance Lobby Finishing		Complete		100%	
20	Status of Construction of Compound wall		NIL		NIL	

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			COMMUNITY BUILDING		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		1	507.35	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			100%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			100%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			100%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of Basements				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			G+1	100%
6	Total Area on each floor (Sq.Mtr.)			GF=716.26 F.F=198.900	100%
7	Stilt / Ground Floor			716.26	100%

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		NIL	NIL
11	Status of MEP		Internal (with in Flat)	External Work
	(i)	Mechanical Works	In Progress	100%
	(ii)	Electrical work including wiring	In Progress	100%
	(iii)	Plumbing work	In Progress	100%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	Complete	100%
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	NA	NA
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	Complete	100%
	(x)	Electrical Fittings in Common Areas	Complete	100%
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			NURSERY SCHOOL		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	17.57	80%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				80%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			0%
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			0%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			0%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			0%
	4.2	External (Plaster, Painting, Façade etc.)			0%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			NIL	NIL
2	Laying of Foundation			NIL	NIL
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of BasementsNA			NA	NA
4	Water Proofing of the Above Sub-Structure (wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			G+2	80%
6	Total Area on each floor (Sq.Mtr.)			524.54	80%
7	Stilt / Ground Floor			271.27	0%
	Status of Laying of slabs floor wise			NIL	NIL

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	NIL	NIL
9	Status of Construction		
	(i) Walls on floors	NIL	NIL
	(ii) Staircase	NIL	NIL
	(iii) Liftwells along with water proofing	NIL	NIL
	(iv) Lift Lobbies/Common areas floor wise	NIL	NIL
10	Fixing of Door & window frames in the Flats/Units	NIL	NIL
11	Status of MEP	Internal (with in Flat)	External Work
	(i) Mechanical Works	NIL	0%
	(ii) Electrical work including wiring	NIL	0%
	(iii) Plumbing work	NIL	0%
12	Status of Wall Plastering		
	(i) External Plaster	NIL	NIL
	(ii) Internal Plaster	NIL	NIL
13	Status of Wall Tiling		
	(i) In Bath Rooms	NIL	NIL
	(ii) In Kitchen	NIL	NIL
14	Status of Flooring		
	(i) Common Areas	NIL	NIL
	(ii) Units/Flats	NIL	NIL
15	Status of White Washing		
	(i) Internal Walls	NIL	NIL
	(ii) External Walls	NIL	NIL
16	Status of Finishing		
	(i) Staircase with Railing	NIL	NIL
	(ii) Lift Wells	NIL	NIL
	(iii) Lift Lobbies/Common areas floor wise	NIL	NIL
17	Status of installation		
	(within Flats/ Units)		
	(i) Doors & Windows Panels	NIL	NIL
	(ii) Sanitary Fixtures	NIL	NIL
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping (if any)	NA	NA
	(other than Flats/ Units)		
	(vi) Lift Installations	NIL	NIL
	(vii) Over Head Tanks	NIL	NIL
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x) Electrical Fittings in Common Areas	NIL	NIL
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	NIL	NIL
19	Entrance Lobby Finishing	NIL	NIL
20	Status of Construction of Compound wall	NIL	NIL

TABLE-A					
Building No/Tower No. (To be prepared seperately for each buildings/Tower in the project/phase of the project)			CONVENIENT SHOPPING		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date (in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure (inclusive of excavation,Foundation,Basement, Water Proofing etc.)		NIL	33.52	100%
2	Super Structure (Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)				100%
3	MEP				
	3.1	Mechanical (Lifts, Ventilation etc.)			NA
	3.2	Electrical (Conduiting,Wiring,Fixtures etc.)			100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)			100%
4	FINISHING				
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)			100%
	4.2	External (Plaster, Painting, Façade etc.)			100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of BasementsNA				
4	Water Proofing of the Above Sub-Structure (wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			GROUND	100%
6	Total Area on each floor (Sq.Mtr.)			188.57	100%
7	Stilt / Ground Floor			188.57	100%
	Status of Laying of slabs floor wise			NA	NA

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	NA	NA
9	Status of Construction		
	(i) Walls on floors	COMPLETE	100%
	(ii) Staircase	NA	NA
	(iii) Liftwells along with water proofing	NIL	NA
	(iv) Lift Lobbies/Common areas floor wise	NA	NA
10	Fixing of Door & window frames in the Flats/Units	NA	NA
11	Status of MEP	Internal (with in Flat)	External Work
	(i) Mechanical Works	NIL	NA
	(ii) Electrical work including wiring	COMPLETE	100%
	(iii) Plumbing work	COMPLETE	100%
12	Status of Wall Plastering		
	(i) External Plaster	COMPLETE	100%
	(ii) Internal Plaster	COMPLETE	100%
13	Status of Wall Tiling		
	(i) In Bath Rooms	COMPLETE	100%
	(ii) In Kitchen	NA	NA
14	Status of Flooring		
	(i) Common Areas	COMPLETE	100%
	(ii) Units/Flats	COMPLETE	100%
15	Status of White Washing		
	(i) Internal Walls	COMPLETE	100%
	(ii) External Walls	COMPLETE	100%
16	Status of Finishing		
	(i) Staircase with Railing	NA	NA
	(ii) Lift Wells	NA	NA
	(iii) Lift Lobbies/Common areas floor wise	NA	NA
17	Status of installation		
	(within Flats/ Units)		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	COMPLETE	100%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping (if any)	NA	NA
	(other than Flats/ Units)		
	(vi) Lift Installations	NA	NA
	(vii) Over Head Tanks	NA	NA
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	COMPLETE	100%
	(x) Electrical Fittings in Common Areas	NA	NA
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	NA	NA
20	Status of Construction of Compound wall	NA	NA

TABLE-B

Sr.No	Common Areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done	Remarks
B-1	Services			
1	Internal Roads & Pavements	Yes	100%	
	Parkings			
2	Covered.....1005 Nos	Yes	100%	
	Open Nos....235	Yes	100%	
3	Water Supply	Yes	100%	
4	Sewarage (Chambers,Lines,STP,Septic Tanks)	Yes	100%	
5	Storm Water Drains	Yes	100%	
6	Landscaping & Tree Plantations	Yes	95%	
	Parks & Playgrounds	Yes	95%	
7	Fixing of Children Play Equipments	Yes	100%	
	Benches	Yes	95%	
8	Shopping Areas	Yes	100%	
9	Street Lighting/Electrification	Yes	95%	
10	Treatment & Disposal of Sewage & Sludge water/STP	Yes	100%	
11	Solid waste Management & Disposal	Yes	100%	
12	Water Conservation,Rain water Harvesting,Percolating Well/Pit	Yes	100%	
13	Energy Management (Solar)	Yes	100%	
14	Fire Protection & Fire safety Equipments	Yes	100%	
15	Electrical Meter Room,Sub-Station,Receiving Station	Yes	95%	
16	Under Ground Water Tank	Yes	100%	
B-2	Community Building to be Transferred to RWA			
17	Community Center	NA	NA	
18	Others.	NA	NA	
B-2	Community Building not to be Transferred to RWA/Competent Authority			
19	School	YES	43%	
20	Dispensary	NA	NA	
21	Club/Community Building	YES	100%	
22	Others.	NA	NA	
B-3	Services/ Facilities to be Transferred to Competent Authority			