F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-1, GURGAON, HARYANA  $EMAIL: \underline{lofarchitectsgurgaon@gmail.com}$ 

#### Annexure A

		Architec	Annexure		
Repor	t for qua	rter ending	30.09.2022		
Subjec	et		Certificate of progress of construction work		
1.	I/We I below	have undertaken assignment as arch mentioned project as per the approv	nitect for certifying progress of construction work in the red plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	SS100		
	2.	Location	Sector-49, Gurugram ( Haryana)		
	3.	Licensed area in acres	160.60		
	4.	Area for registration in acres	1.334		
	5.	HARERA registration No.	21 of 2020		
	6.	Name of licensee	M/s SS Group Pvt. Ltd.		
	7.	Name of collaborator	M/s Uppal Housing Pvt. Ltd.		
	8.	Name of developer	M/s SS Group Pvt. Ltd.		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	01.10.2022		
	2.	Name of Architect/ Architect's firm			
	3.	Date of site inspection	01.10.2022		
3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. Dheerender Kumar		
	2.	Structural consultant	DESMAN		
	3.	Proof consultant	Arvind Gupta		
	4.	MEP consultant	AEON		
	5.	Site supervisor/in charge	Mr.Rajesh Bhartonia		

Ar. KAPIL SINGH

Ar. KATH STNGH

B. Arch. Regn. No wan Council

Re. of Architecture CA/2003/31608 of Arci.

uncil /2.303/31608

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-1, GURGAON, HARYANA EMAIL: lofarchitectsgurgaon@gmail.com

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
----	---

I also certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Yours Faithfully

B. Arch.

Regn. No with Council of Architecture CA/2003/31608
Signature & Name (in block letters)

With stamp of Architect

Date

Place

Council of Architects (CoA):

Registration No. (CA/2003/31608)

Council of Architects (CoA) :

Registration valid till (Date) 31st Dec 2031

			Table – A		
Building/ Tower no.			SS 100		
(to be	e prepar	ed separately for each building/ project/ phase of the project)			
A1	Cum	ulative progress of the project/phase	at the end of the qua	rter.	
Sr. No.	Proje	ect components	Work done value during the quarter ( In Lac)	Cumulative work done value till date (In Lac)	Percentage of work done to the total proposed work
1.	(Inclu	tructure usive of excavation, foundation, nents, water proofing, etc.)	29.01	2154.66 25.34%	
2.	(Slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	NIL	NIL	NIL
3.	MEP				
	3.1	Mechanical (Lifts, ventilation, etc.)	NIL	NIL	NIL
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	NIL	NIL	NIL
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	NIL	NIL	NIL
4.	Finisl	ning	David Control		
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	NIL	NIL	NIL
	4.2	External (Plaster, painting, facade, etc.)	NIL	NIL	NIL
-					
Sr. No.		Tasks/ Activity	Description of work done		Percentage of total proposed work
	-	Sub-Structure Status	Comm	lata	•
1.	-	avation	Comp	iete	100%
2.	-	ing of foundation	Comp	loto	100%
	(i) (ii)	Raft Pile	NA		100% 
3.		aber of basement(s) 03 Nos.	IVA		IVA
٥.	(i)	Basement Level 1	Comp	lete	100%
	(ii)	Basement level 2	Comp		100%
	(iii)	Basement level 3		Complete	
	(111)	Zasement tevel 3		1.7 A.M.	100%

Ar. KAPIL SING

B. Arch.

Regn. No with Council of Architecture CA/2003/31608

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-1, GURGAON, HARYANA EMAIL :  $\underbrace{\text{lofarchitectsgurgaon@gmail.com}}$ 

4.	Waterproofing of the above sub-structure (wherever applicable)		NIL		NIL	
		Super-Structure Status				
5.	Total	floors in the building	G+15		NIL	
6.	Total	area of Floors	30422.569 sq.mtr.		NIL	
7.	Stilt	floor/ ground floor	2443.137	7 Sq.Mtr.	NIL	
8.	Status of laying of slabs floor wise		In Progress		70%	
	Cumulative number of slabs in the building/ towerlaid by end of quarter		8 Nos		70%	
9.	Statu	s of construction				
	(i) Walls on floors		NIL		NIL	
	(ii)	Staircase	N	IIL	NIL	
	(iii)	Lift wells along with water proofing	N	IIL	NIL	
	(iv)	Lift lobbies/ common areas floor wise	NIL		NIL	
10.	Fixin units	g of door and window frames in flats/	N	IIL	N	IL
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External
	(i)	Mechanical works	N	IL	N	IL
	(ii)	Electrical works including wiring	NIL		NIL	
	(iii)	Plumbing works	NIL		NIL	
12.	Statu	s of wall plastering		47		
	(i) External plaster		NIL		NIL	
	(ii)	Internal plaster	NIL		NIL	
13.	Status of wall tiling					
	(i) In bathroom		NIL		NIL	
	(ii)	In kitchen	NIL		NIL	
14.	Status	s of flooring				
	(i)	Common areas	NIL		NIL	
	(ii)	Units/ flats	NIL		NIL	
15.	Status	s of white washing				
	(i)	Internal walls	NIL		NIL	
	(ii)	External walls	NIL		NIL	
16.	Status	s of finishing				
	(i)	(i) Staircase with railing		IL	NI	L

Ar. KAPIL SINGH

B. Aich.

Regn. No. with Council of Architecture CA/2003/31608

HARYANA GOVT. GAZ. (EXTRA.), MAY 10, 2019 (VYSK. 20, 1941 SAKA)

1633

	(ii)	Lift wells	NIL	NIL
	(iii)	Lift lobbies/ common areas floor wise	NIL	NIL
17.	Status	of installation		
	(withi	n flat/unit)	NA	NA
	(i)	Doors and windows panels	NA	NA
	(ii)	Sanitary fixtures	NA	NA
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	NA	NA
	(v)	Gas piping (if any)	NA	NA
	(other	than flat/units)		
	(vi)	Lifts installation	NIL	NIL
	(vii)	Overhead tanks	NIL	NIL
	(viii)	Underground water tank	NIL	NIL
	(ix)	Firefighting fitting and equipment's as per CFO NOC	NIL	NIL
	(x)	Electrical fittings in common areas	NIL	NIL
	(xi)	Compliance to conditions of environment/ CRZ NOC	NA	NA
18.	Water	proofing of terraces	NIL	NIL
9.	Entrar	nce lobby finishing	NIL	NIL
20.	Status of construction of compound wall		NIL	NIL

Note: (\*) extend rows as per requirement.

B. Arch.

Regn. No with Council of Architecture CA/2003/31608

Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services		•	
1.	Internal roads & pavements	YES	NIL	
2.	Parking			
	Covered no 290 Nos.	YES	65%	
	Open no	NIL	NIL	
3.	Water supply	YES	NIL	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	NIL	
5.	Storm water drains	YES	NIL	
6.	Landscaping & tree plantation	YES	NIL	
7.	Parks and playgrounds	NA		
	Fixing of children play equipment's	NA		
	Benches	NA		
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	YES	NIL	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	NIL	
11.	Solid waste management & disposal	NA		
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	NIL	
13.	Energy management (solar)	NA		
14.	Fire protection and fire safety requirements	YES	NIL	
15.	Electrical meter room, sub-station, receiving station	YES	NIL	
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community center	NA	NA	
18.	Others	NA	NA	
B-3	Community buildings not to be transferred to RWA/competent authority	NA	NA	
19.	Schools	NA	NA	
20.	Dispensary	NA	NA	
21.	Club	NA	NA	
22.	Others	NA	NA	
B-4	Services/ facilities to be transferred to competent authority	NA	NA	
23.	*			

Note: (\*) extend as per requirement

Ar. KAPIL SINGH B. Arch.

Regn. No with Council of Architecture CA/2003/31608