	Architect's Certificate ¹					
Repo	Report for quarter ending 31-03-2020					
Subject			Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. Particulars No.		Information			
	1.	Project/Phase of the project	Conscient One			
	2.	Location	Sector-109, Gurugram, Haryana			
	3.	Licensed area in acres	8.393 Acres			
	4.	Area for registration in acres	3.138 Acres			
	5.	HARERA registration no.	RC/REP/HARERA/GGM/308/40/2019/0 /Dated-16-01-2019			
	6.	Name of licensee	M/S Shrimaya Buildcon Pvt. Ltd. And Others			
	7.	Name of collaborator	M/S Shrimaya Buildcon Pvt. Ltd.			
	8.	Name of developer	Conscient Infrastructure Private Limited			
2.	Detai	ls related to inspection are as	under			
	1.	Date of certifying of percentage of construction work/ site inspection	31.03.2020			
	2.	Name of Architect/ Architect's firm	Ashwin Alva Associates			
	3.	Date of site inspection	18.03.2020			

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

3.	Following technical professionals are appointed by promoter: - (as applicable)			
	Sr. No.	Consultants	Name	
	1.	Site engineer	Sharad Chandra	
	2.	Structural consultant	Civtech Consultant Pvt. Ltd.	
	3. Proof consultant Mehro Consultants		Mehro Consultants	
	Consultants, Electrical Co		Plumbing & Fire Fighting- Soni Consultants, Electrical Consultant-Kanwar Krishen Associates Pvt Ltd	
	5.	Site supervisor/incharge	Ashwini Arora	
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.			
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.			

Date : Yours faithfully,

Place Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : SHOBHNA BATRA cA/2005/35496

Council of architects (CoA) : 31-12-2026 registration valid till (date)

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm,
New Delhi-62,Ph./Fax:011 29555054,011 29555098
email: admin@alva.co.in

		T	able – A					
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)			1 Nos			
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.						
Sr. No.	Project components		Work done value during the quarter (In Lacs)	Cumulative work done value till date (in Lacs)	Percentage of work done to the total proposed work			
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.0	1621.8	100%			
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		152.5	3050.9	100%			
3.	MEP							
	3.1	Mechanical (lifts, ventilation, etc.)	54.7	995.6	91%			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	34.8	938.3	81%			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	22.8	836.0	80%			
4.	Finishing							
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	304.3	1388.6	79%			
	4.2	External (plaster, painting, facade, etc.)	38.7	1420.9	87%			

N-93, South Avenue Sainik Farm, New Delhi-62,Ph:/Fax:011 29555054,011 29555098 email: admin@alva.co.in

Sr.	Sub-Structure Status done		Description of work	Percentage of total proposed work		
No.			done			
1.			Completed		100%	
2.	Laying of foundation					
	(i)	Raft	3	Completed		100%
	(ii)	Pile				
3.	Num	ber of basement(s) 3			2	
	(i)	Basement Level 1	3	Completed		100%
	(ii)	Basement level 2		Completed		100%
	(iii)	Basement level 3		Completed		100%
4.		erproofing of the above sub- cture (wherever applicable)		Completed		100%
		Super-Structure Status				
5.	Tota	l floors in the tower/ building		G+10		
6.	Tota	l area on each floor	FAR=2 6260 Service FAR=10	ommercial 279.602 to 2212 Sqm. Apartment 341.907 to 2.663 Sqm		
7.	Stilt	floor/ground floor		Completed	100%	
8.	Stati	us of laying of slabs floor wise		Completed		100%
	build	ulative number of slabs in the ding/tower11 laid by of quarter	STATE OF THE PROPERTY OF THE P			
9.	Statı	us of construction			2	
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase		Completed		100%
	(iii)	Lift wells along with water proofing	8	Completed		100%
	(iv)	Lift lobbies/ common areas floor wise	In Progress		85%	
10.	L + C. S. S. S. A. C.	ng of door and window frames in / units	In Progress			85%
11.	Statu	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works		n Progress		91%
	(ii)	Electrical works including wiring	1	n Progress		81%

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

	(iii)	Plumbing works	In Progress	80%
12.	Statu Glazi	1 0, ,		
	(i)	External plaster/Façade Glazing	In Progress	88%
	(ii)	Internal plaster	In Progress	82%
13.	Status of wall tiling			
	(i)	In bathroom	In Progress	80%
	(ii)	In kitchen	NA	
14.	Statu	s of flooring		
	(i)	Common areas	In Progress	80%
	(ii)	Units/ flats	NA	
15.	Statu	s of white washing		
	(i)	Internal walls	In Progress	85%
	(ii)	External walls	NA	
16.	Statu	s of finishing		
	(i)	Staircase with railing	In Progress	81%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	In Progress	85%
17.	Statu	s of installation		
	(with	nin flat/unit)		
	(i)	Doors and windows panels	In Progress	82%
	(ii)	Sanitary fixtures	In Progress	90%
	(iii)	Modular kitchen	NA	
	(iv)	Electrical fittings/lighting	In Progress	80%
	(v)	Gas piping (if any)	In Progress	85%
	(othe	er than flat/units)		
	(vi)	Lifts installation	In Progress	82%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	In Progress	92%
	(x)	Electrical fittings in common areas	In Progress	90%
	(xi)	Compliance to conditions of environment/ CRZ NOC		
18.	Wate	erproofing of terraces	In Progress	92%
19.	Entra	ance lobby finishing	In Progress	92%

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in

20.	Status of construction of compound wall	Completed	100%
	Wall		

Note: (*) extend rows as per requirement.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking).		
	Covered no 513	Yes	100%	
	Open no	No		
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	98%	
5.	Storm water drains	Yes	97%	
6.	Landscaping & tree plantation	Yes	95%	
7.	Parks and playgrounds	No		
	Fixing of children play equipment's	No		
	Benches	Yes	60%	
8.	Shopping area	No		
9.	Street lighting/ electrification	Yes	95%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	85%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	75%	
14.	Fire protection and fire safety requirements	Yes	85%	
15.	Electrical meter room, sub-station, receiving station	Yes	85%	
16.	Other (option to add more)	NA	NA	
B-2	Community building to be transferred to	RWA		
17.	Community centre	NA		
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in



20.	Dispensary	NA	
21.	Club	NA	
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority		
23.	*		

Note: (*) extend as per requirement

SHOBHNA BATRA CA/2005/35496

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph./Fax:011 29555054,011 29555098 email: admin@alva.co.in