

Annexure C			
Architect's Certificate1			
Report for quarter ending		01-04-2023	
Subject		Certificate of percentage of completion of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
	Sr. No	Particulars	Information
	1.	Project/Phase of the project	Habitat Residences
	2.	Location	Village Faridpur, Sector-78, Faridabad, Haryana
	3.	Licensed area in acres	5.08125 Acre
	4.	Area for registration in acres	5.08125 Acre
	5.	HARERA registration no.	HRERA-PKL-FBD-170-2019, dated – 24/10/2019
	6.	Name of licensee	BCC Edutech Pvt. Ltd.
	7.	Name of collaborator	Conscient Infrastructure Pvt. Ltd.
8.	Name of developer	Conscient Infrastructure Pvt. Ltd.	
2.	Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection	01-04-2023
	2.	Name of Architect/ Architect's firm	R.K. & ASSOCIATES
3.	3.	Date of site inspection	31-03-2023
	Following technical professionals are appointed by promoter:- (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Hemansh Rastogi
	2.	Structural consultant	NNC DESIGN INTERNATIONAL
	3.	Proof consultant	BMSF Design Consultants Pvt. Ltd.
4.	4.	MEP consultant	V CONSULTING
	5.	Site supervisor/incharge	Mr. Manoj Kumar
5.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
6.	I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B		

Date 01-04-2023
Place : New Delhi



Yours faithfully

ROHIT GARG
CA/94/17868

Signature & name (in block letters) with stamp of architect

Local authority license no.

Local authority license no. valid till (date)

Council of architects (CoA) registration no.

CA / 94 / 17868

Council of architects (CoA) registration valid till (date)

31 / 12 / 2025

Project Details:

- ☐ Plot Area: 5.08125 Acre
- ☐ Residential Towers: 8 nos - D1,D2,D3,D4,D5,D6,D7,D8,E
- ☐ Commercial Component
- ☐ Community Center
- ☐ Anganwadi Cum Crèche

Total No of Units: 732 Nos.



Table-A

Building/Tower no. **Tower-D-3**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	9 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%
11.	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	90%
12.	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	95%
13.	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	98%
14.	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	98%
15.	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16.	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	75%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	

	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-7**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
	Laying of foundation		
2.	i. Raft	Completed	100%
	ii. Pile	NA	NA
	Number of basement(s) Nil		-
3.	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
	Status of construction		
	i. Walls on floors	RCC Wall	100%
9.	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	98%
	Status of MEP	Internal Flats / External External	Internal Flats / External External
11	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	90%
	Status of wall Finishing		
12	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	99%
	Status of wall tiling		
13	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	99%
	Status of flooring		
14	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	95%
	Status of finishing		
15	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	93%

16	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-8**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
	Laying of foundation		
2.	i. Raft	Completed	100%
	ii. Pile	NA	NA
	Number of basement(s) Nil		-
3.	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
	Status of construction		
	i. Walls on floors	RCC Wall	100%
9.	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	99%
	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
11	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	100%
	Status of wall Finishing		
12	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	99%
	Status of wall tiling		
13	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	99%
	Status of flooring		
14	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	99%
	Status of finishing		
	i. Staircase with railing	MS Railing	100%

15	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
	Status of Installation (Within flat/unit)		
16	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	63%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-4**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%
11	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	100%
12	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	100%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	100%
	ii. In Kitchen	Kitchen Wall Tile	100%



14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	97%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	95%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-5**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	96%
11	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	91%
	Status of wall Finishing		

12	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	99%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	100%
	ii. In Kitchen	Kitchen Wall Tile	100%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	100%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16	Status of Installation		
	(Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	95%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-6**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+13)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	14 Floors
9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%
	Status of MEP	Internal Flats / External	Internal Flats / External
	i. Mechanical works	NA	NA

11	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	93%
12	Status of wall Finishing		
	i. External	External Paint	100%
13	ii. Internal	Int. Paint. 1st Coat	98%
	Status of wall tiling		
14	i. In bathroom	Bathroom Tiles	98%
	ii. In Kitchen	Kitchen Wall Tile	98%
15	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
16	ii. Units/flats	Apt Stone Flooring	98%
	Status of finishing		
17	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
18	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
	Status of Installation (Within flat/unit)		
19	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
20	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	97%
21	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
22	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
23	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
24	xi. Compliance to conditions of environment	At Final Stage	
	17	Waterproofing of terraces	WP in Toilet
25	18	Entrance lobby finishing	
	19	Status of construction of Compound wall	

Building/Tower no. **Tower-E**, (to be prepared separately for each building/tower in the project/phase of the project)

Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
3.	ii. Pile	NA	NA
	Number of basement(s) Nil		-
4.	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
5.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
6.	Total floors in the tower/building	(G+9)	
7.	Total area on each floor	573.7 Sqm	
8.	Stilt Floor/ Ground Floor		
9.	Status of laying of slabs floor wise		
10.	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
	Status of construction		
11.	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
12.	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%

10.	Fixing of door and window frames in flats/units	Door Frame	99%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	95%
12	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	100%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	99%
	ii. In Kitchen	Kitchen Wall Tile	96%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	100%
15	Status of finishing		
	i. Staircase with railing	MS Railing	100%
	ii. Lift wells	Handover of Lift Well to Lift Agency	100%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	100%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	100%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-1**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) <u>Nil</u>		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		
5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors

9.	Status of construction		
	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	100%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	100%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	92%
12	Status of wall Finishing		
	i. External	External Paint	100%
	ii. Internal	Int. Paint. 1st Coat	97%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	94%
	ii. In Kitchen	Kitchen Wall Tile	85%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	80%
	ii. Units/flats	Apt Stone Flooring	60%
15	Status of finishing		
	i. Staircase with railing	MS Railing	97%
	ii. Lift wells	Handover of Lift Well to Lift Agency	80%
	iii. Lift lobbies / common area floor wise	Common Area Painting	0%
16	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	80%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	94%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		

Building/Tower no. **Tower-D-2**, (to be prepared separately for each building/tower in the project/phase of the project)
Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Tasks / Activity	Description of work done	Percentage of total proposed work
A1	SUB- STRUCTURE STATUS		
1.	Excavation	Completed	100%
2.	Laying of foundation		
	i. Raft	Completed	100%
	ii. Pile	NA	NA
3.	Number of basement(s) Nil		-
	i. Basement level 1	NA	-
	ii. Basement level 2*	NA	-
4.	Waterproofing of the above sub- structure (wherever applicable)	NA	-
A2	SUPER- STRUCTURE STATUS		

5.	Total floors in the tower/building	(G+9)	
6.	Total area on each floor	618.6 Sqm	
7.	Stilt Floor/ Ground Floor		
8.	Status of laying of slabs floor wise		
	Cumulative number of slabs in the building/tower	Rcc Structure	10 Floors
	Status of construction		
9.	i. Walls on floors	RCC Wall	100%
	ii. Staircase	Rcc Structure	100%
	iii. Lift wells along with water proofing	Rcc Structure	100%
	iv. Lift lobbies /common areas floor wise	Rcc Structure	100%
10.	Fixing of door and window frames in flats/units	Door Frame	99%
11	Status of MEP	Internal Flats / External External	Internal Flats / External External
	i. Mechanical works	NA	NA
	ii. Electrical works excluding wiring & S.S	Apartment Electrical Wiring / Transformer Installation	94%
	iii. Plumbing Conduiting works	CPVC Work/External Storm Network	97%
12	Status of wall Finishing		
	i. External	External Paint	90%
	ii. Internal	Int. Paint. 1st Coat	100%
13	Status of wall tiling		
	i. In bathroom	Bathroom Tiles	97%
	ii. In Kitchen	Kitchen Wall Tile	94%
14	Status of flooring		
	i. Common areas	Lift Lobby Flooring	100%
	ii. Units/flats	Apt Stone Flooring	90%
15	Status of finishing		
	i. Staircase with railing	MS Railing	0%
	ii. Lift wells	Handover of Lift Well to Lift Agency	80%
	iii. Lift lobbies / common area floor wise	Common Area Painting	100%
16	Status of Installation (Within flat/unit)		
	i. Doors and windows panels	Windows	100%
	ii. Sanitary Fixtures	Chinaware	0%
	iii. Modular Kitchen	NA	
	iv. Electrical fittings/Lighting	Switch & Socket	0%
	v. Gas piping (if any)	NA	
	vi. Lifts installation	Rail + Floor Door	80%
	vii. Overhead tanks	RCC Work	100%
	viii. Underground water tank	NA	NA
	ix. Firefighting fittings and equipment's as per	Fire Pump	
	x. Electrical fittings in common areas	Staircase & Lobby lights	0%
	xi. Compliance to conditions of environment	At Final Stage	
17	Waterproofing of terraces	WP in Toilet	99%
18	Entrance lobby finishing		
19	Status of construction of Compound wall		