#### Annexure A

		Architec	t's Certificate		
Repo	rt for qua	rter ending	Mar'23		
Subject			Certificate of progress of construction work		
1.	I/We have undertaken assignment : construction work in the below men		t as architect for certifying progress of entioned project as per the approved plans		
	Sr.No.	Particulars	Information		
	1.	Project/Phase of the project	New Haven Bahadurgarh/ Ph-1A		
	2.	Location	Bahadurgarh		
	3.	Licensed area in acres	16.431		
	4.	Area for registration in acres	5.252		
	5.	HARERA registration No.	o. 22 of 2017 dated 13th July 2017		
	6.	Name of licensee	HL Promoters Private Limited		
	7.	Name of collaborator	HLT Residency Pvt. Ltd & SAS Realtech LLF		
	8.	Name of developer	HL Promoters Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	11-04-2023		
	2.	Name of Architect/ Architect's firm	C P Kukreja Architects		
	3.	Date of site inspection	30-03-2023		
3.	Followin	ng technical professionals are	e appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name		
	L.	Site engineer	Ashish Ticku		
	2.	Structural consultant	TPC Technical Projects Consultants Pvt. Ltd.		
	3.	Proof consultant	Melior Structure Solution		
	4.	MEP consultant	Paradise Consultants		
	5.	Site supervisor/in charge	Ashish Ticku		



# P Kukreja Architects

Ashirwad Building, D-1, Green Park, New Delhi-110016 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com Phone: 91-11-26863953, 26862449, 41004554, 41759907

9001 : 2015 QMS/016261/0320

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and tableB.

Date

:11/04/2023

Yours faithfully,

Place

: New Delhi

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration No. For C P Kukreja Architects

Council of architects (CoA) registration valid till (date) : 31 Dec. 2028 PAK AGARWAL Council of Architecture

Registration No. CA/17/89820



## C P Kukreja Architects

Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone : 91-11-26863953, 26862449, 41004554, 41759907

E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001 : 2015 QMS/016261/0320

,			Table – A				
Buil	ding/	Tower No5					
Al Cumulative progress of the project/phase at the end of the quarter.							
Sr. No.	Project components		Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining		
1	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)  Super structure (Slabs, brickwork, block work, staircase, lift wells, machine rooms, water tank, etc.)		0%	100%	0%		
2			0%	100%	()%		
	ME	P					
		Mechanical					
	3.1	(Lifts, ventilation, etc.)	0%	100%	0%		
3	3.2	Electrical (Conduit, wiring, fixtures, etc.)	0%	100%	0%		
	3.3	Plumbing & Firefighting (Piping, pumps and pump room, fixtures, Over Head & Under Ground Tank etc.)	0%	99%	1%		
	Fini	shing					
4	4.1	Internal (plaster, tilling, flooring, painting, Door/Window etc. within units and common areas)	0%	100%	0%		
	4.2	External (Plaster, painting, facade, etc.)	0%	100%	0%		



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

Sr.	Ta	isks/ Activity	Descriptio		ntage of to	
No.	S	ub-Structure Status	n of work done	proposed work		
1.	Exca	vation	Completed		100%	
2.	Layin	ng of foundation	Completed			
	(i)	Raft	Completed		1009	%
	(ii)	Pile	Completed			
3.	Num	ber of basement(s)01				
	(i)	Basement Level 1	Completed		100%	6
	(ii)	Basement level 2*	N/A			
4.	sub-s	rproofing of the above tructure(wherever cable)				
		Super-Structure				
5.	Total	Status floors in the tower/	G+14		1009	6
	build	ng	3.11			
6.		area on each floor	6670 SFT		1009	
7.		loor/ ground floor	6670 SFT		1009	6
8.	Status	s of laying of slabs	Completed		100%	0
	Cumu slabs tower	ilative number of in the building/ laid d of quarter	Completed	100%		
9.	Status	of construction				
	(i)	Walls on floors	Completed	100%		0
	(ii)	Staircase	Completed	100%		0
	(iii)	Lift wells along	Completed	100%		0
	(iv)	with water proofing Lift lobbies/ common areas floor wise	Completed	100%		
10.		of door and w frames in flats/				
11.		of MEP	Internal (within flat)	External works	Internal (within flat)	Exter-nal works
	(i)	Mechanical works	Completed	10	00%	1
	(ii)	Electrical works	Completed	10	00%	
	(iii)	including wiring Plumbing works	Completed	16	00%	
2.	10 00	of wall plastering		-		
	(i)	External plaster	Completed	10	00%	
	(ii)	Internal plaster	Completed	100%		
3.		of wall tiling		1,		
400	(i)	In bathroom	Completed	10	00%	
	(ii)	In kitchen	Completed	S)	100%	
	7117	THE MINISTER	Completed	10		
1.4	Statue	of flooring				
14.	Status (i)	of flooring Common areas	Completed	14	100%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907

E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com 9001 : 2015 QMS/016261/0320 ARCHITECTURE URBAN PLANNING INTERIORS ENGINEERING SUSTAINBILITY

Sr.	Tasks/ Activity		Description of	Percentage of total	
No.	Sub-S	tructure Status	work done	proposed work	
15.	Status of white washing				
	(i)	Internal walls	Completed	100%	
	(ii)	External walls	NA	NA	
16.	Statu	s of finishing			
	(i)	Staircase with railing	Completed	100%	
	(ii)	Lift wells	Completed	100%	
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%	
17.	Statu	s of installation			
	(with	in flat/unit)			
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	Completed	100%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	NA	NA	
	(v)	Gas piping (if any)	NA	NA	
	(other	than flat/units)			
	(vi)	Lifts installation	Completed	100%	
	(vii)	Overhead tanks	Completed	100%	
	(viii)	Underground water tank	Completed	100%	
	(ix)	Firefighting fitting and equipment's asper CFO NOC	Completed	100%	
	(x)	Electrical fittings in common areas	Completed	100%	
	(xi)	Compliance to conditions of environment/ CRZ.	Completed	100%	
8.	Water	proofing of terraces	Completed	100%	
9.	Entran	ce lobby finishing	Completed	100%	
20.		of construction of und wall	Completed	100%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001 : 2015 QMS/016261/0320

A1	The state of the s							
Sr. No.	Pro	ject components	Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining			
1	Sub structure  (Inclusive of excavation, foundation, basements, water proofing, etc.)  Super structure  (Slabs, brickwork, block work, staircase, lift wells, machine rooms, water tank, etc.)		0%	100%	0%			
2			0%	100%	0%			
	MEP				1			
	3.1	Mechanical (Lifts, ventilation, etc.)	0%	100%	0%			
3	3.2	Electrical (Conduit, wiring, fixtures, etc.)	0%	100%	0%			
	3.3	Plumbing & Firefighting (Piping, pumps and pump room, fixtures, Over Head & Under Ground Tank etc.)	0%	99%	1%			
	Fini	shing						
4	4.1	Internal (plaster, tilling, flooring, painting, Door/Window etc. within units and common areas)	0%	100%	0%			
	4.2	External (Plaster, painting, facade, etc.)	0%	100%	0%			



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001 : 2015 QMS/016261/0320

Sr.	Tasks/ Activity		Description			entage of
No.	Sub-Str	ructure Status	work done		total proposed work	
1.	Excav	ation	Con	npleted		00%
2.	Laying	g of foundation				
	(i) Raft		Comp	pleted	10	00%
	(ii)	Pile	Comp	pleted		
3.	Numb	er of basement(s)01				
	(i)	Basement Level 1	Comp	pleted	10	0%
	(ii)	Basement level 2*	N/A			
4.		proofing of the above sub- ire(wherever applicable)				
	Supe	er-Structure Status				
5.	Total f	loors in the tower/	G+1	200	100%	
6.	Total a	rea on each floor		70 SFT		100%
7.	Stilt fl	oor/ ground floor	6670	3000		100%
8.	Status wise	of laying of slabs floor		oleted	100%	
	in the	ative number of slabs building/tower laid by quarter	Completed		100%	
9.	Status	of construction				
	(i)	Walls on floors	Completed		10	00%
	(ii)	Staircase	Completed		10	0%
	(iii)	Lift wells along with water proofing	Completed		10	00%
	(iv)	Lift lobbies/ common areas floor wise	Comp	oleted	100%	
10.		of door and window in flats/units				
11.	Status	of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Comp	oleted		00%
	(ii)	Electrical works including wiring	Comp	oleted	100%	
	(iii)	Plumbing works	Comp	oleted	10	10%
12.	Status	of wall plastering				
	(i)	External plaster	Comp	oleted	10	0%
	(ii)	Internal plaster	Completed		10	10%
13.	Status	of wall tiling				
	(i)	In bathroom	Completed		10	0%
	(ii)	In kitchen	Completed		10	0%
14.	Status	of flooring				
	(i)	Common areas	Comp	oleted	10	0%
	(ii)	Units/ flats	Comp	oleted	10	0%



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001 : 2015 QMS/016261/0320

Sr. No.	Tasks/ Activity		Description	Percentage of
		Sub-Structure Status	of work done	totalproposed work
15.	Status	of white washing		
	(i)	Internal walls	Completed	100%
	(ii)	External walls	NA	NA
16.	Status	of finishing		
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status	of installation		
	(withi	n flat/unit)		
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	NA	NA
	(v)	Gas piping (if any)	NA	NA
	(other	than flat/units)		
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's asper CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Water	proofing of terraces	Completed	100%
19.	Entrar	nce lobby finishing	Completed	100%
20.	Status	of construction of compound	Completed	100%



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

	_	Tower No7	2000			
Al	Cur	mulative progress of th	ne project/phase at the end of the quarter.			
Sr. No.	Pro	ject components	Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining	
1	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)		0%	100%	0%	
2	Super structure (Slabs, brickwork, block work, staircase, lift wells, machine rooms, water tank, etc.)		0%	100%	0%	
	MEP					
	3.1	Mechanical (Lifts, ventilation, etc.)	0%	100%	0%	
3	3.2	Electrical (Conduit, wiring, fixtures, etc.)	0%	100%	0%	
	3.3	Plumbing & Firefighting (Piping, pumps and pump room, fixtures, Over Head & Under Ground Tank etc.)	0%	99%	1%	
	Fini	shing				
4	4.1	Internal (plaster, tilling, flooring, painting, Door/Window etc. within units and common areas)	0%	100%	0%	
	4.2	External (Plaster, painting, facade, etc.)	0%	100%	0%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001 : 2015 QMS/016261/0320

Sr.	Tasks	/ Activity	Descript		Percentage of total proposed work	
No.	Sub-S	tructure Status	work d	work done		ork
1.	Exca	vation	Completed		100%	
2.	Layin	ng of foundation				
	(i)	Raft	Con	npleted	100%	
	(ii)	Pile	Con	npleted		
3.	Num	ber of basement(s) . 01				
	(i)	Basement Level 1	Con	npleted	100%	i i
	(ii)	Basement level 2*	N/A			
4.	sub-s	rproofing of the above tructure(wherever cable)				
		Super-Structure Status				
5.	Total build	floors in the tower/	G+	14	100%	
6.		area on each floor	6	670 SFT	10	10%
7.	Stilt	floor/ ground floor	6670	SFT	10	00%
8.	Statu	s of laying of slabs floor	Completed		100%	
	Cumi in the	ulative number of slabs e building/tower laid by f quarter	Completed		100%	
9.	Statu	Status of construction				
	(i)	Walls on floors	Completed		100%	
	(ii)	Stairease	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	ĝ.
	(iv)	Lift lobbies/ common areas floor wise	Con	pleted	100%	
10.		g of door and window es in flats/units				
11.	Statu	s of MEP	Internal (within flat)	Externa works	Internal (within flat)	External works
	(i)	Mechanical works	Соп	pleted	100%	
	(ii)	Electrical works including wiring		pleted	100%	
	(iii)	Plumbing works	Completed		100%	
12.	Status	s of wall plastering				
	(i)	External plaster	Con	pleted	100%	2
	(ii)	Internal plaster	Completed		100%	
13.	Status	s of wall tiling				
	(i)	In bathroom	Com	pleted	100%	
	(ii)	In kitchen	Completed		100%	
14.	Status	of flooring				
	(i)	Common areas	Com	pleted	100%	3
	(ii)	Units/ flats	Com	pleted	100%	3



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

Sr. No.	Tasks/ Activity		Description of	Percentage of tota
		Sub-Structure Status	work done	proposed work
15.	Status	s of white washing		
	(i)	Internal walls	Completed	100%
	(ii)	External walls	NA	NA
16.	Status	of finishing		
	(i)	Staircase with railing	Completed	100%
	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Status	of installation		
	(withi	n flat/unit)		
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	NA	NA
	(v)	Gas piping (if any)	NA	NA
	(other	than flat/units)		
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's asper CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%
18.	Water	proofing of terraces	Completed	100%
19.	Entran	nce lobby finishing	Completed	100%
20.		of construction of ound wall	Completed	100%



Ashirwad Building, D-1, Green Park, New Delhi-110016
Phone: 91-11-26863953, 26862449, 41004554, 41759907
E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

	_	/ Tower No11					
Al	Cumulative progress of the project/phase at the end of the quarter.  Percentage						
Sr. No.	10000	oject components	Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining		
1	(Inc	b structure clusive of excavation, ndation, basements, ter proofing, etc.)	0%	100%	0%		
2	(Sla	ber structure abs, brickwork, block rk, staircase, lift wells, chine rooms, water tank,	0%	100%	0%		
	ME	.P					
		Mechanical					
	3.1	(Lifts, ventilation, etc.)	0%	100%	0%		
3	3.2	Electrical (Conduit, wiring, fixtures, etc.)	0%	100%	0%		
	3.3	Plumbing & Firefighting (Piping, pumps and pump room, fixtures, Over Head & Under Ground Tank etc.)	0%	100%	0%		
	Fini	shing					
4	4.1	Internal (plaster, tilling, flooring, painting, Door/Window etc. within units and common areas)	0%	100%	0%		
	4.2	External (Plaster, painting, facade, etc.)	0%	100%	0%		



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone : 91-11-26863953, 26862449, 41004554, 41759907 E-mail : cpka@cpkukreja.com Website : www.cpkukreja.com

9001 : 2015 QMS/016261/0320

Sr.		Tasks/ Activity	Descriptio		Percenta		
No.		Sub-Structure Status	workdone		totalproposed work		
1.	Excav	vation	Com	pleted	1	00%	
2.	Layin	g of foundation					
	(i)	Raft	Completed		1	00%	
	(ii)	Pile	Comp	oleted			
3.	Number of basement(s) . 01						
	(i)	(i) Basement Level 1		oleted	100%		
	(ii)	Basement level 2*	N/A				
4.	Waterproofing of the above sub- structure(wherever applicable)						
		Super-Structure Status					
5.	Total	floors in the tower/	G+1	4	100%		
6.	Total	area on each floor	7412	SFT	I	00%	
7.	Stilt f	loor/ ground floor	7412	SFT	1	00%	
8.	wisc	s of laying of slabs floor		oleted	100%		
	Cumulative number of slabs in the building/tower laid by end of quarter		Completed		1	00%	
9.		s of construction					
	(i) Walls on floors		Comp	oleted	1	00%	
	(ii)	Staircase	Comp	oleted	1	00%	
	(iii)	(iii) Lift wells along with water proofing		Completed		00%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		1	00%	
10.		g of door and window es in flats/units					
11.	Status	s of MEP	Internal (within flat)	Externa Iworks	Internal (within flat)	Extern al works	
	(i)	Mechanical works	Completed		100%		
	(ii)	Electrical works including wiring	Completed		100%		
	(iii)	Plumbing works	Comp	oleted	1	00%	
12.	Status	s of wall plastering					
	(i)	(i) External plaster		Completed		100%	
	(ii)	Internal plaster	Completed		100%		
13.	Status of wall tiling						
	(i) In bathroom		Completed		- 1	00%	
	(ii)			Completed		100%	
14.	Statu	s of flooring					
	(i)	Common areas	Comp	oleted	100%		
	(ii)	Units/ flats	Com	pleted	1	00%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907

E-mail : cpka@cpkukreja.com Website : www.cpkukreja.com

9001: 2015 QMS/016261/0320

Sr.		Tasks/ Activity	Description	Percentage of	
No.	Sub-Structure Status		of work done	totalproposed work	
15.	Status	s of white washing			
	(i)	Internal walls	Completed	100%	
	(ii)	External walls	NA	NA	
16.	Status of finishing				
	(i)	Staircase with railing	Completed	109%	
	(ii)	Lift wells	Completed	100%	
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%	
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	Completed	100%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	NA	NA	
	(v)	Gas piping (if any)	NA	, NA	
	(other	than flat/units)			
	(vi)	Lifts installation	Completed	100%	
	(vii)	Overhead tanks	Completed	100%	
	(viii)	Underground water tank	Completed	100%	
	(ix)	Firefighting fitting and equipment's asper CFO NOC	Completed	100%	
	(x)	Electrical fittings in common areas	Completed	100%	
	(xi)	Compliance to conditions ofenvironment/ CRZ NOC	Completed	100%	
18.	Water	proofing of terraces	Completed	100%	
19.	Entrar	nce lobby finishing	Completed	100%	
20.	Status	of construction of compound	Completed	100%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

AI	Cu	mulative progress of the pr	ject/phase at the end of the quarter.					
Sr. No.	Pro	ject components	Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining			
1	(Inc	clusive of excavation, indation, basements, water ofing, etc.)	0%	100%	0%			
2	(Sla	ber structure bs, brickwork, block work, rease, lift wells, machine ns, water tank, etc.)	0%	100%	0%			
	ME	P						
	3.1	Mechanical (Lifts, ventilation, etc.)	0%	100%	0%			
3	3.2	Electrical (Conduit, wiring, fixtures, etc.)	0%	99%	1%			
	3.3	Plumbing & Firefighting (Piping, pumps and pump room, fixtures, Over Head & Under Ground Tank etc.)	0%	100%	0%			
	Finishing							
4	4.1	Internal (plaster, tilling, flooring, painting, Door/Window etc. within units and common areas)	0%	100%	0%			
	4.2	External (Plaster, painting, facade, etc.)	0%	100%	0%			



## C P Kukreja Architects Ashirwad Bullding. D-1, Green Park, New Delhi-110016

ARCHITECTURE URBAN PLANNING INTERIORS ENGINEERING SUSTAINBILITY

E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com ISO 9001: 2015 QMS/016261/0320

Phone: 91-11-26863953, 26862449, 41004554, 41759907

Sr.	7	Tasks/ Activity	Descrip		Percentage of tota		
No.	Sub-Structure Status		of work done		proposed work		
1.	Exca	avation	C	ompleted	100	0%	
2.	Layi	ng of foundation					
	(i)	(i) Raft		Completed		)%	
	(ii)	(ii) Pile		Completed			
3.	Number of basement(s) . 01						
	(i) Basement Level 1		Cor	npleted	100%		
	(ii)	Basement level 2*	N/A	\ <u></u>			
4.	Waterproofing of the above sub- structure(wherever applicable)						
	Super	-Structure Status					
5.	Tota	floors in the tower/building	G-	-14	100%		
6.	Tota	area on each floor	7412	SFT	- 1	00%	
7.	Stilt	floor/ ground floor	7412	SFT	1	00%	
8.	Statu	s of laying of slabs floor wise					
	the b	ulative number of slabs in building/towerlaid by of quarter	Completed		100%		
9.	Status of construction						
	(i)	(i) Walls on floors		npleted	100%		
	(ii)	Staircase	Con	pleted	100%		
	(iii)	Lift wells along with water proofing	Completed		100	%	
	(iv)	Lift lobbies/ common areas floor wise	Con	pleted	100	%	
10.		g of door and window es in flats/units					
11.	Statu	s of MEP	Internal (within flat)	Exter nal works	Internal (within flat)	Exter nal works	
	(i)	Mechanical works	Completed		100%		
	(ii)	Electrical works including wiring	Completed		100%		
	(iii)	Plumbing works	Com	pleted	100	%	
12.	Status	s of wall plastering					
	(i)	(i) External plaster		Completed		100%	
	(ii)	(ii) Internal plaster		Completed		%	
13.	Status	Status of wall tiling					
	(i)	(i) In bathroom		Completed		%	
	(ii)	(ii) In kitchen		Completed		%	
4.	Status	of flooring					
	(i)	Common areas	Com	pleted	1009	%	
	(ii)	Units/ flats	Com	pleted	1009	%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907 E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

Sr.	Tasks/ Activity		Description	Percentage of total	
No.	Sub-S	Structure Status	of work done	proposed work	
15.	Stati	us of white washing			
	(i)	Internal walls	Completed	100%	
	(ii)	External walls	NA	NA	
16.	Statu	is of finishing			
	(i)	Staircase with railing	Completed	100%	
	(ii)	Lift wells	Completed	100%	
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%	
17.	Statu	s of installation			
	(with	in flat/unit)			
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	Completed	100%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	NA	NA	
	(v)	Gas piping (if any)	NA	NA	
	(other	than flat/units)			
	(vi)	Lifts installation	Completed	100%	
	(vii)	Overhead tanks	Completed	100%	
	(viii)	Underground water tank	Completed	100%	
	(ix)	Firefighting fitting and equipment's asper CFO NOC	Completed	100%	
	(x)	Electrical fittings in common areas	Completed	100%	
	(xi)	Compliance to conditions of environment/ CRZ NOC	Completed	100%	
18.	Water	proofing of terraces	Completed	100%	
9.	Entran	ce lobby finishing	Completed	100%	
20.	Status wall	of construction of compound	Completed	100%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone: 91-11-26863953, 26862449, 41004554, 41759907

E-mail: cpka@cpkukreja.com Website: www.cpkukreja.com

9001: 2015 QMS/016261/0320

			Table-B			
Sr No		Proposed (Yes/ No)	Percentage of Work done during the quarter	Percentage of Cumulative work done value till date	Percentage of work Remaining	Remark
B-1	Services					
1	Internal roads & pavements	Yes	0%	100%	0%	
2	Parking Covered no	Yes	0%	100%	0%	
	Open no	Yes	0%	100%	0%	
3	Water supply	Yes	0%	100%	0%	
4	Sewerage (chamber, lines, septic tanks, STP)	Yes	0%	100%	0%	
5	Storm water drains	Yes	0%	100%	0%	
6	Landscaping & tree plantation	Yes	0%	100%	0%	
	Parks and playgrounds	Yes	0%	100%	0%	
7	Fixing of children play equipment's	Yes	0%	100%	0%	
	Benches	Yes	0%	100%	0%	
8	Shopping area	Yes	0%	100%	0%	
9	Street lighting/ electrification	Yes	0%	100%	0%	
10	Treatment and disposal of sewage and slug water/ STP	Yes	0%	100%	0%	
1	Solid waste management & disposal	Yes	1%	99%	1%	
2	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	100%	0%	
3	Energy management (solar)	Yes	0%	100%	0%	
1	Fire protection and fire safety requirements	Yes	0%	100%	0%	
5	Electrical meter room, sub-station,	Yes	0%	100%	0%	



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone : 91-11-26863953, 26862449, 41004554, 41759907 E-mail : cpka@cpkukreja.com Website : www.cpkukreja.com

9001: 2015 QMS/016261/0320

	receiving station				
16	Other- NTA - Basement	Yes	0%	100%	0%
B-2	Community buil	lding to be t	ransferred to	RWA	
17	Community center	Yes	0%	100%	0%
18	Club House	Yes	0%	100%	0%
B-3	Community buil	dings not to	be transferr	ed to RWA/con	100000000
19	Schools	No			-percir autabrity
20	Dispensary	No			
B-4	Services/ facilitie	s to be tran	sferred to cor	nnotont outh-	14



Ashirwad Building, D-1, Green Park, New Delhi-110016 Phone : 91-11-26863953, 26862449, 41004554, 41759907 E-mail : cpka@cpkukreja.com Website : www.cpkukreja.com

9001 : 2015 QMS/016261/0320