

ARCH. KUMUD KANCHAN

Architecture & Valuation

Planning, Interior & Exterior Designer,

Project Consultant



Annexure - A

Office Address:-

Office No. 425, 4th Floor

Shree Ram Plaza, Bank More,

Dhantadi - 826001 (Jharkhand)

34

Mob No: 7633959700 | Email id: vaastushreth@gmail.com

Architect's Certificate¹

Report for quarter ending		30 th June 2023	
Subject		Certificate of progress of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans		
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Hero Homes
	2.	Location	Village Dhanwapor and Gurgaon, Sector 104, Dwarka Expressway, Gurugram, Haryana
	3.	Licensed area in acres	Total licenced area is 34.0229 Acres, out of which project land is 9.053 Acres
	4.	Area for registration in acres	9.053 acres (includes area of Residential Tower 8, which shall be developed in future as a separate phase)
	5.	HARERA registration no.	RC/REP/HARERA/GGM/2018/24
	6.	Name of licensee	Juventus Estates Ltd. Mahon Properties Ltd. Mariana Infrastructure Ltd.
	7.	Name of collaborator	Vikas Parks Private Limited
	8.	Name of developer	Vikas Parks Private Limited
2.	Details related to inspection are as under		
	1.	Date of certifying of percentage of construction work/ site inspection.	06.07.2023




Kumud Kanchan
KUMUD KANCHAN
B. Arch
J.A. No. 06/2023/11/23

35

2.	Name of Architect/ Architect's firm	Mrs. Kumad Kachhan
3.	Date of site inspection	Site inspection date 03.07.2023

3.	Following technical professionals are appointed by promoter: - (as applicable)	
	Sr. No.	Consultants
		Name
	1.	Site engineer
		Mr. Prem Sukh
	2.	Structural consultant
		M/s Optimization Consultants
	3.	Proof consultant
		IIT - Bombay
	4.	MEP consultant
		M/s Serene Designs
	5.	Site supervisor/incharge
		Mr. Mukul Kansal
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.	
5.	I also certify that as 30 th June 2022, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.	

Date	06.07.2023
Place	Haryana

Yours faithfully,

 Signature & name (in Block letters) with stamp of architect



Council of architects (CoA) registration no.	CA/2006/37532	
Council of architects (CoA) registration valid till (date)	31/12/2025	

Table - A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-01		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Cumulative Work done value till last quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	306	306	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	1540	1540.4	99%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	87	87	24%
3.2	Electrical (conduiting, wiring, fixtures, etc.)	86	244	25%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	101	109	45%
4.	Finishing			
4.1	Internal	459	577	66%



Kundrich

KUND RICHAN

24/07/2024

24/07/2024

		(plaster, tiling, flooring, painting, etc. within rooms and common areas)			
	4.2	External (plaster, painting, facade, etc.)	2	3	38%
Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work
	Sub-Structure Status				
1.	Excavation		Excavation Completed		100%
2.	Laying of foundation				
	(i)	Raft	Yes, Completed		100%
	(ii)	Pile	NA		
3.	Number of basement(s)		2 Nos. of Basement		
	(i)	Basement Level 1	Yes, Completed		100%
	(ii)	Basement level 2*	Yes, Completed		100%
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%
	Super-Structure Status				
5.	Total floors in the tower/ building		38 Floors including Ground Floor		
6.	Total area on each floor (Carpet Area of complete tower)		141057.06 Sqft		
7.	Stilt floor/ ground floor		GF Completed		100%
8.	Status of laying of slabs floor wise				
	Cumulative number of slabs in the building/ tower <u>37</u> laid by end of quarter		37 Slabs Completed		100%
9.	Status of construction				
	(i)	Walls on floors	38 Floors, Completed	38	100%
	(ii)	Staircase	38 Floors, Completed	38	100%
	(iii)	Lift wells along with water proofing	38 Floors, Completed	38	100%

	(ii) Sanitary fixtures	China ware's & CP Fittings	0%
	(iii) Modular kitchen	Yes	0%
	(iv) Electrical fittings/ lighting	Switch Sockets	0%
	(v) Gas piping (if any)	NA	
	(other than Hat/units)		
	(vi) Lifts installation	3 Nos. Lift including Services Lift	60%
	(vii) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(viii) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(ix) Firefighting fitting and equipment's as per CPO NOC	Sprinklers, Fire Hose & Fire Extinguishers	28%
	(x) Electrical fittings in common areas	LED Lights	0%
	(xi) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Cuba	100%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	-

Note: (*) extend rows as per requirement.

Kund...
KUNDAN CHAN
B. No.
B. No. 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100

40

Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-02		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	293	293	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank etc.)	1380	1381	99%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	70	70	20%
3.2	Electrical (conducting, wiring, fixtures, etc.)	67	31	25%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	78	79	46%
4.	Finishing			
4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	300	324	66%
4.2	External (plaster, painting, facade, etc.)	1.7	1.74	44%



[Signature]
ABHINAV KANCHAN
 S. No.

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
1.	Excavation		Excavation Completed	100%
2.	Laying of foundation			
	(iii)	Raft	Completed	100%
	(iv)	Pile	NA	
3.	Number of basement(s)		2 Nos. of Basement	
	(iii)	Basement Level 1	Yes, Completed	100%
	(iv)	Basement level 2 nd	Yes, Completed	100%
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing	100%
	Super-Structure Status			
5.	Total floors in the tower/ building		28 Floors including Ground Floor	
6.	Total area on each floor (Carpet Area of complete tower)		120244.79 Sqft	
7.	Slab floor/ ground floor		Ground Floor Completed	100%
8.	Status of laying of slabs floor wise			
	Cumulative number of slabs in the building/ tower 28 laid by end of quarter		28 Slabs Completed	100%
9.	Status of construction			
	(v)	Walls on floors	28 Floors, Completed	100%
	(vi)	Staircase	28 Floors, Completed	100%
	(vii)	Lift wells along with water proofing	28 Floors, Completed	100%
	(viii)	Lift, lobbies/ common areas floor wise	28 Floors, Completed	100%
10.	Fixing of door and window frames in flats/ units		Wooden Door Frames	85%
11.	Status of MEP		Internal (within flat) External works	Internal (within flat) External works



Kundlakes
KUNDLAKES
 B. Arch.

	(iv)	Mechanical works	Yes	Yes	34%	17%
	(v)	Electrical works including wiring	Yes	Yes	41%	20%
	(vi)	Plumbing works	Yes	Yes	51%	30%
12.	Status of wall plastering					
	(iii)	External plaster	Rendering and Minor Cement Based Plaster		50%	
	(iv)	Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.	Status of wall tiling					
	(iii)	In bathroom	Ceramic Tiles		100%	
	(iv)	In kitchen	Ceramic Tiles		100%	
14.	Status of flooring					
	(iii)	Common areas	Tiling Works		43%	
	(iv)	Units/ flats	Tiling Works		100%	
15.	Status of white washing					
	(iii)	Internal walls	Not yet started		0%	
	(iv)	External walls	Not yet started		0%	
16.	Status of finishing					
	(iv)	Staircase with railing	Kota Stone Floor with MS Railing		80%	
	(v)	Lift wells	Shaft Plaster & Waterproofing		100%	
	(vi)	Lift lobbies/ common areas floor wise	Tiling Works Flooring, OBD		100%	
17.	Status of installation					
	(within flat/unit)					
	(xi)	Doors and windows panels	UPVC Windows		75%	
	(xiii)	Sanitary fixtures	Chinaware & CP Fittings		0%	
	(xiv)	Modular kitchen	Yes		0%	
	(xv)	Electrical fittings/ lighting	Switch Sockets		0%	
	(xvi)	Gas piping (if any)	NA			
	(other than flat/units)					
	(xvii)	Lifts installation	3 Nos. Lift including Services Lift		60%	



KUMBHAR PAVAR
Private Limited
B. And

93

	(xviii) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(xix) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(xx) Firefighting fitting and equipment's as per CFO NOC	Sprinklers, Fire Hose & Fire Extinguishers	0%
	(xxi) Electrical fittings in common areas	LED Lights	0%
	(xxii) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for entire phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	100%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

Kundanchan
KUNDANCHAN
 B. Arch.
 Reg. No. 12/1984/11/12



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-03		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	280	280	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	1354	1355	100%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	70	70	20%
3.2	Electrical (conducting, wiring, fixtures, etc.)	63	97	75%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	82	82.4	45%
4.	Finishing			
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	262	300	64%
4.2	External (plaster, painting, facade, etc.)	1.24	1.76	38%

K. M. Chandra
K. M. CHANDRA



Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Excavation Completed		100%	
2.	Laying of foundation					
	(v)	Raft	Completed		100%	
	(vi)	Pile	NA			
3.	Number of basement(s)		2 Nos. of Basement			
	(v)	Basement level 1	Yes, Completed		100%	
	(vi)	Basement level 2*	Yes, Completed		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		28 Floors including Ground Floor			
6.	Total area on each floor (Carpet Area of complete tower)		120244.79 Sq.ft			
7.	Strike floor/ ground floor		GF Completed		100%	
8.	Status of laying n° slabs floor wise					
	Cumulative number of slabs in the building/ tower 27 laid by end of quarter		27 Slabs Completed		100%	
9.	Status of construction					
	(ix)	Walls on floors	28 Floors, Completed	28	100%	
	(x)	Staircase	28 Floors, Completed	28	100%	
	(xi)	Lift wells along with water proofing	23 Floors total,		100%	
	(xii)	Lift lobbies/ common areas floor wise	28 Floors, Completed	28	100%	
10.	Fixing of door and window frames in flats/ units		Wooden Door Frames		75%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(vii)	Mechanical works	Yes	Yes	24%	



K. R. M. M.
K. R. M. M. Private Limited
B. A. S.

	(viii)	Electrical works including wiring	Yes	Yes	44%	20%
	(ix)	Plumbing works	Yes	Yes	51%	30%
12.		Status of wall plastering				
	(v)	External plaster	Rendering and Minor Cement Based Plaster		50%	
	(vi)	Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.		Status of wall tiling				
	(v)	in bathroom	Ceramic Tiles		100%	
	(vi)	In kitchen	Ceramic Tiles		100%	
14.		Status of flooring				
	(v)	Common areas	Tiling Works		89%	
	(vi)	Units/ flats	Tiling Works		100%	
15.		Status of white washing				
	(v)	Internal walls	ORB/ Emulsion Acrylic		0%	
	(vi)	External walls	External Texture Paint		0%	
16.		Status of finishing				
	(vii)	Staircase with railing	Rota Stone Floor with MS Railing		50%	
	(viii)	Lift wells	Shaft Plaster & Waterproofing		100%	
	(ix)	Lift lobbies/ common areas floor wise	Tiling Works Flooring ORB		0%	
17.		Status of installation (within flat/unit)				
	(xxiii)	Doors and windows panels	UPVC Windows		75%	
	(xxiv)	Sanitary fixtures	Chinawarels & CP Fittings		0%	
	(xxv)	Modular kitchen	Yes		0%	
	(xxvi)	Electrical fittings/ lighting	Switch Sockets		0%	
	(xxvii)	Gas piping (if any)	NA			
		(other than flat/units)				
	(xxviii)	Lifts installation	3 Nos. Lift including Services Lift		60%	



K. S. Chandra
K. S. CHANDRA
& A/P

	(xxix) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(xxx) Underground water tank	Not Applicable for Building, combined for entire Phase	-
	(xxx) Firefighting fitting and equipment's as per CFO NOC	Sprinklers, Fire Hose & Fire Extinguishers	22%
	(xxx) Electrical fittings in common areas	LED Lights	0%
	(xxx) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	100%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

Kund Karch
KUND KARCHAN
 S. Arch.
 JDA Reg No-CA/2004/1742



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-04		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	292	292	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	1518	1523	99%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	86	86	18%
3.2	Electrical (conducting, wiring, fixtures, etc.)	76	91	25%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	85	90	45%
4.	Finishing			
4.1	Internal (plaster, dilling, flooring, painting, etc. within units and common areas)	286	340	62%
4.2	External (plaster, painting, facade, etc.)	1.24	1.55	26%

K. S. Dhanu
K. S. Dhanu
G. Archt.



Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Excavation Completed		100%	
2.	Laying of foundation					
	(vii)	Raft	Completed		100%	
	(viii)	Pile	NA			
3.	Number of basement(s)		2 Nos. of Basement			
	(vii)	Basement Level 1	Yes, Completed		100%	
	(viii)	Basement level 2 nd	Yes, Completed		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		37 Floors including Ground floor			
6.	Total area on each floor (Carpet Area of complete tower)		137168.72 Sqft			
7.	Stilt floor/ ground floor		Ground Floor		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 37 laid by end of quarter		37 Slabs Completed		100%	
9.	Status of construction					
	(xii)	Walls on floors	37 Floors, Completed	37	100%	
	(xiv)	Staircase	37 Floors, Completed	37	100%	
	(xv)	Lift wells along with water proofing	37 Floors Total, Completed,	37	100%	
	(xvi)	Lift lobbies/ common areas floor wise	37 Floors, Completed	37	100%	
10.	Fixing of door and window frames in flats/ units		Wooden door Frames		73%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(x)	Mechanical works	Yes	Yes	20%	17%

Kundanchan
KUNDANCHAN
S. Arch



	(xi)	Electrical works including wiring	Yes	Yes	100%	20%
	(xii)	Plumbing works	Yes	Yes	51%	30%
12.	Status of wall plastering					
	(vi)	External plaster	Rendering and Minor Cement Based Plaster		50%	
	(viii)	Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.	Status of wall tiling					
	(vii)	In bathroom	Ceramic Tiles		100%	
	(viii)	In kitchen	Ceramic Tiles		100%	
14.	Status of flooring					
	(vii)	Common areas	Tiling Works		5%	
	(viii)	Units/ flats	Tiling Works		100%	
15.	Status of white washing					
	(vii)	Internal walls	OBD/ Emulsion	Acrylic	0%	
	(viii)	External walls	External Paint	Texture	0%	
16.	Status of finishing					
	(x)	Staircase with railing	Kota Stone Floor with MS Railing		50%	
	(xi)	Lift wells	Shaft Plaster & Waterproofing		100%	
	(xii)	Lift lobbies/ common areas floor wise	Tiling Works Flooring, OBD		0%	
17.	Status of installation					
	(within flat/unit)					
	(xxx)	Doors and windows panels	UPVC Windows		47%	
	(xxxi)	Sanitary fixtures	China wares & CP Fittings		0%	
	(xxxv)	Modular kitchen	Yes		0%	
	(xxxv)	Electrical fittings/ lighting	Switch Sockets		0%	
	(xxxv)	Gas piping (if any)	NA			
	(other than flat/units)					
	(xxxvi)	Lifts installation	3 Nos. Lift including Services etc.		60%	

	(xi) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(xii) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(xiii) Firefighting fitting and equipment's as per CPO NOC	Sprinklers, Fire Hose & Fire Extinguishers	23%
	(xiv) Electrical fittings in common areas	LED lights	0%
	(xv) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	100%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

K. Kanchan
K. KANCHAN
 B. Arch.
 JIA Reg No-CL/2016/1543



Table - A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-05		
A1 Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	292	292	100%
2.	Super structure (slabs, brick work, blockwork, stair case, lift wells, machine rooms, water tank, etc.)	1390	1410	97%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	6	29	14%
3.2	Electrical (conducting, wiring, fixtures, etc.)	39	40	22%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	15	1%
4.	Finishing			
4.1	Internal (plaster, filling, flooring, painting, etc. within units and common areas)	114	125.4	15%
4.2	External (plaster, painting, facade, etc.)	0	0	15%



K. S. R. P.
KSRP PARKS & RESORTS
BANGALORE

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(ix)	Raft	Yes, Completed		100%	
	(x)	Pile	NA			
3.	Number of basement(s)		2 Nos. of basement			
	(ix)	Basement Level 1	Completed		100%	
	(x)	Basement level 2*	Work in Progress		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%	
	Super-Structure Status					
5.	Total Floors in the tower/ building		37 Floors including Ground Floor		100%	
6.	Total area on each floor (Carpet Area of complete tower)		137168.72 Sqft			
7.	Stilt floor/ ground floor		Ground Floor		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		37 Slabs Completed		100%	
9.	Status of construction					
	(xvii)	Walls on floors	37 Floors, completed	37	100%	
	(xviii)	Staircase	37 Floors, completed	37	100%	
	(xix)	Lift wells along with water proofing	37 Floors, completed.	37	100%	
	(xx)	Lift lobbies/ common areas floor wise	37 Floors, completed	37	100%	
10.	Fixing of door and window frames in flats/ units		Wooden Door Frames		40%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xiii)	Mechanical works	Yes	Yes	3%	



K. Kancha
 K. Kancha
 S. No.

	(xiv)	Electrical works including wiring	Yes	Yes	30%	20%
	(xv)	Plumbing works	Yes	Yes	1%	0%
12.	Status of wall plastering					
	(ix)	External plaster	Rendering and Minor Cement Based Plaster		0%	
	(x)	Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.	Status of wall tiling					
	(ix)	In bathroom	Ceramic Tiles		0%	
	(x)	In kitchen	Ceramic Tiles		0%	
14.	Status of flooring					
	(ix)	Common areas	Tiling Works		0%	
	(x)	Units/ flats	Tiling Works		0%	
15.	Status of white washing					
	(ix)	Internal walls	OBD/ Emulsion	Acrylic	0%	
	(x)	External walls	External Paint	Texture	0%	
16.	Status of finishing					
	(xiii)	Staircase with railing	Kota Stone Floor with MS Railing		0%	
	(xiv)	Lift wells	Shaft Plaster & Waterproofing		0%	
	(xv)	Lift lobbies/ common areas floor wise	Tiling Works Flooring, OBD		0%	
17.	Status of installation					
	[within flat/unit]					
	(xiv)	Doors and windows panels	UPVC Windows		0%	
	(xvi)	Sanitary fixtures	Chinawares & CP Fittings		0%	
	(xvii)	Modular kitchen	Yes		0%	
	(xviii)	Electrical fittings/ lighting	Switch Sockets		0%	
	(xix)	Gas piping (if any)	NA			
	[other than flat/units]					
	(i)	Lifts installation	3 Nos. Lift including Services Lift		7%	

K. K. Kanchan
K. K. KANCHAN
S. Archt.



	(ii) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(iii) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(iii) Firefighting fitting and equipment's as per LFO NOC	Sprinklers, Fire Hose & Fire Extinguishers	0%
	(iv) Electrical fittings in common areas	LED Lights	0%
	(iv) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	100%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

Kund Kanchan
 KUND KANCHAN
 8, 4/2
 84 kg in 12/10/2013



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-06		
A1 Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	251	251	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	1233	1252	95%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	5	23	1%
3.2	Electrical (conduiting, wiring, fixtures, etc.)	48	49.4	22%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	83	104.4	15%
4.2	External (plaster, painting, facade, etc.)	0	0	14%

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(xi)	Raft	Completed		100%	
	(xii)	Pile	NA			
3.	Number of basement(s)		2 Nos. of Basement			
	(xi)	Basement Level 1	Completed		100%	
	(xii)	Basement level 2 nd	Completed		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		28 Floors including Ground Floor, 28 completed		100%	
6.	Total area on each floor (Carpet Area of complete tower)		118475.63 Sqft			
7.	Stilt floor/ ground floor		Ground Floor		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		28 Slabs Completed		100%	
9.	Status of construction					
	(xxi)	Walls on floors	28 Floors, completed	28	100%	
	(xxii)	Staircase	28 Floors, completed	28	100%	
	(xxiii)	Lift wells along with water proofing	28 Floors, completed	28	100%	
	(xxiv)	Lift lobbies/ common areas floor wise	28 Floors, completed	20	100%	
10.	Fixing of door and window frames in flats/ units		Wooden Door Frames		40%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xvi)	Mechanical works	Yes	Yes	34%	


 K. R. RAMESH
 E. Archt

	(xvii) Electrical works including wiring	Yes	Yes	30%	20%
	(xviii) Plumbing works	Yes	Yes	1%	0%
12.	Status of wall plastering				
	(xi) External plaster	Rendering and Minor Cement Based Plaster		50%	
	(xii) Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.	Status of wall tiling				
	(xi) In bathroom	Ceramic Tiles		0%	
	(xii) In kitchen	Ceramic Tiles		0%	
14.	Status of flooring				
	(xi) Common areas	Tiling Works		0%	
	(xii) Units/ flats	Tiling Works		0%	
15.	Status of white washing				
	(xi) Internal walls	OBD/ Emulsion Acrylic		0%	
	(xii) External walls	External Texture Paint		0%	
16.	Status of finishing				
	(xvi) Staircase with railing	Kota Stone floor with MS Railing		0%	
	(xvii) Lift wells	Shaf. Plaster & Waterproofing		0%	
	(xviii) Lift lobbies/ common areas floor wise	Tiling Works Flooring, ORC		0%	
17.	Status of installation (within flat/unit)				
	(ivc) Doors and windows panels	UPVC Windows		0%	
	(ivi) Sanitary fixtures	Chinaware & CP Fittings		0%	
	(lviii) Modular kitchen	Yes		0%	
	(lix) Electrical fittings/ lighting	Switch Sockets		0%	
	(ix) Gas piping (if any)	NA			
	(other than flat/units)				
	(lxi) Lifts installation	3 Nos. Lift including Services L. ft		7%	

Kundane
KUNDANE
S. A. 100-41/100-1150

	(ixii) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	0%
	(ixiii) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(ixiv) Firefighting fitting and equipment's as per CPO NOC	Sprinklers, Fire Huse & Fire Extinguishers	0%
	(ixv) Electrical fittings in common areas	LED Lights	0%
	(ixvi) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	0%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

K. Kanchan
KUMUD KANCHAN
 B. Arch.
 Reg. No. 16723/1992



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		T-07		
A1 Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	285	285	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	1392	1442	95%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	6	29	1%
3.2	Electrical (conduiting, wiring, fixtures, etc.)	52	55	22%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	6	30	2%
4.	Finishing			
4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	103	135.4	15%
4.2	External	0	0	



ASSTD NARAYAN
S. Arer



K. M. M. M.

 K. M. M. M.

11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xix)	Mechanical works	Yes	Yes	3%	0%
	(xx)	Electrical works including wiring	Yes	Yes	30%	20%
	(xxi)	Plumbing works	Yes	Yes	3%	0%
12.	Status of wall plastering					
	(xii)	External plaster	Rendering and Minor Cement Based Plaster		50%	
	(xiv)	Internal plaster	Gypsum Plaster / Cement Based Plaster		100%	
13.	Status of wall tiling					
	(xiii)	In bathroom	Ceramic Tiles		0%	
	(xiv)	In kitchen	Ceramic Tiles		0%	
14.	Status of flooring					
	(xiii)	Common areas	Tiling Works		0%	
	(xiv)	Units/ flats	Tiling Works		0%	
15.	Status of white washing					
	(xiii)	Internal walls	OBD/ Emulsion	Acrylic	0%	
	(xiv)	External walls	External Paint	Texture	0%	
16.	Status of finishing					
	(xix)	Staircase with railing	Kota Stone Floor with MS Railing		0%	
	(xx)	Lift wells	Shaft Plaster & Waterproofing		0%	
	(xxi)	Lift lobbies/ common areas floor wise	Tiling Works Flooring, OBD		0%	
17.	Status of installation (within flat/unit)					
	(lxvii)	Doors and windows panels	UPVC Windows		0%	
	(lxvi)	Sanitary fixtures	Ch. newares & CP Fittings		0%	
	(lxix)	Modular kitchen	Yes		0%	
	(lxx)	Electrical fittings/ lighting	Switch Sockets		0%	
	(lxxi)	Gas piping (if any)	NA			

	(other than flat/units)		
	(lxxii) Lifts installation	3 Nos. Lift including Services Lift	7%
	(lxxiii) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	100%
	(lxxiv) Underground water tank	Not Applicable for Building, combined for entire Phase	.
	(lxxv) Firefigating fitting and equipment's as per CPO NOC	Sprinklers, Fire Hose & Fire Extinguishers	0%
	(lxxvi) Electrical fittings in common areas	LED Lights	0%
	(lxxvii) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	0%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	.

K. Kanchan
KURUD KANCHAN
 S. Archt.
 Reg. No. CA/196/11137



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Convenient Shopping 1		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	100	110	90%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	NA	NA	NA
3.2	Electrical (conduiting, wiring, fixtures, etc.)	0	0	0%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	0	0%
4.2	External (plaster, painting, facade, etc.)	0	0	0%


 K. N. D. S. S. S.
 K. N. D. S. S. S.

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(xv)	Raft	Completed		100%	
	(xvi)	Pile	NA			
3.	Number of basement(s)					
	(xv)	Basement Level 1	Completed		100%	
	(xvi)	Basement level 2*	In Progress		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		1 Floor including Ground Floor			
6.	Total area on each floor (Carpet Area of complete tower)		2669.42 Sqft			
7.	Stilt floor/ ground floor		Ground Floor		0%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		0 Slabs Completed		0%	
9.	Status of construction:					
	(xxix)	Walls on floors	1 Floor, Not Yet Started		0%	
	(xxx)	Staircase	NA			
	(xxxi)	Lift wells along with water proofing	NA			
	(xxxii)	Lift lobbies/ common areas floor wise	1 Floor, Not Yet Started		0%	
10.	Fixing of door and window frames in flats/ units		NA			
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xxxiii)	Mechanical works	NA	NA		


 K. S. Narayan
 Director
 K. S. Narayan & Co. Private Limited
 2A, Top Floor, 7th Floor, 1st Floor

	(xxii) Electrical works including wiring	Yes	Yes	0%	0%
	(xxiii) Plumbing works	Yes	Yes	0%	0%
12.	Status of wall plastering				
	(xv) External plaster	Cement Based Plaster		0%	
	(xvi) Internal plaster	Gypsum Plaster		0%	
13.	Status of wall tiling				
	(xv) In bathroom	Ceramic Tiles		0%	
	(xvi) In kitchen	NA			
14.	Status of flooring				
	(xv) Common areas	Stone Works		0%	
	(xvi) Units/ flats	IPS Works		0%	
15.	Status of white washing				
	(xv) Internal walls	OBD		0%	
	(xvi) External walls	External Texture Paint		0%	
16.	Status of finishing				
	(xxii) Staircase with railing	NA			
	(xxiii) Lift wells	NA			
	(xxiv) Lift lobbies/ common areas floor wise	Stone Flooring, OBD		0%	
17.	Status of installation				
	(within flat/unit)				
	(lxxxv) Doors and windows panels	Rolling Shutters		0%	
	(lxxxvi) Sanitary fixtures	Chinawares & CP Fittings		0%	
	(lxxxvii) Modular kitchen	NA			
	(lxxxviii) Electrical fittings/ lighting	Switch Sockets		0%	
	(lxxxix) Gas piping (if any)	NA			
	(other than flat/units)				
	(lxxx) Lifts installation	NA			
	(lxxx) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing		0%	
	(lxxx) Underground water tank	Not Applicable for Building. combined for entire Phase			



K. S. Sankar
K. S. SANKAR
 8 Apr.
 11:24 AM 11/11

	(lxxx) Firefighting fitting and equipment's as per CFO NOC	Fire Hose & Fire Extinguishers	0%
	(lxxx) Electrical fittings in common areas	LED Lights	0%
	(lxxx) Compliance to conditions of environment/CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	0%
19.	Entrance lobby finishing	NA	
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

KUMAR NACHAN
B. Arch.
Reg No. CA/780/1993



Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Convenient Shopping 2		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)	100	110	90%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	NA	NA	NA
3.2	Electrical (conducting, wiring, fixtures, etc.)	0	0	0%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%



 KSRUD ANSCHAN

 B. Arch

 RA Reg No. 12000/2010

4.	Finishing			
4.1	Internal (plaster, tiling, flooring, painting, etc. within units and common areas)	0	0	0%
4.2	External (plaster, painting, facade, etc.)	0	0	0%
Sr. No.	Tasks/ Activity Sub-Structure Status	Description of work done	Percentage of total proposed work	
1.	Excavation	Completed	100%	
2.	Laying of foundation			
	(xvii) Raft	Completed	100%	
	(xviii) Pile	NA		
3.	Number of basement(s)			
	(xvii) Basement Level 1	Completed	100%	
	(xviii) Basement level 2*	In Progress	100%	
4.	Waterproofing of the above sub- structure (wherever applicable)	Foundation Waterproofing	100%	
	Super-Structure Status			
5.	Total floors in the tower/ building	1 Floor including Ground Floor		
6.	Total area on each floor (Carpet Area of complete tower)	2182.71 Sqft		
7.	Still floor/ ground floor	Ground Floor	0%	
8.	Status of laying of slabs floor wise			
	Cumulative number of slabs in the building/ tower laid by end of quarter	0 Slabs Completed	0%	
9.	Status of construction			
	(xxx) Walls on floors	1 Floor, Not Yet Started	0%	
	(xxx) Staircase	NA		
	(xxx) Lift wells along with water proofing	NA		

	(xxxv) Lift lobbies/ common areas floor wise	1 Floor, Not Started	Yes	0%	
10.	Fixing of door and window frames in flats/ units	NA			
11.	Status of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(xxv) Mechanical works	NA	NA		
	(xxvi) Electrical works including wiring	Yes	Yes	0%	0%
	(xxvi) Plumbing works	Yes	Yes	0%	0%
12.	Status of wall plastering				
	(xvi) External plaster	Cement Based Plaster		0%	
	(xvii) Internal plaster	Gypsum Plaster		0%	
13.	Status of wall tiling				
	(xvii) In bathroom	Ceramic Tiles		0%	
	(xvii) In kitchen	NA			
14.	Status of flooring				
	(xvii) Common areas	Stone Works		0%	
	(xviii) Units/ flats	IPS Works		0%	
15.	Status of white washing				
	(xvii) Internal walls	OBD		0%	
	(xviii) External walls	External Paint	Texture	0%	
16.	Status of finishing				
	(xxv) Staircase with railing	NA			
	(xxvi) Lift wells	NA			
	(xxvi) Lift lobbies/ common areas floor wise	Stone Flooring, OBD		0%	
17.	Status of installation				
	(within flat/unit)				
	(xxx) Doors and windows panels	Rolling Shutters		0%	
	(xc) Sanitary fixtures	Chinawares & CP Fittings		0%	
	(xci) Modular kitchen	NA			
	(xcii) Electrical fittings/ lighting	Switch Sockets		0%	
	(xciii) Gas piping (if any)	NA			

	(other than flat/units)		
(xciv)	Lifts installation	NA	
(xcv)	Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	0%
(xcvi)	Underground water tank	Not Applicable for Building, combined for entire Phase	
(xcvii)	Firefighting fitting and equipment's as per CPO NOC	Fire Hose & Fire Extinguishers	0%
(xcviii)	Electrical fittings in common areas	LED Lights	0%
(xcix)	Compliance to conditions of environment/ CRZ NOC.	Yes	0%
18.	Waterproofing of terraces	Brick Bat Coba	0%
19.	Entrance lobby finishing	NA	
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

Kund Kanchan
 KUND KANCHAN
 B. Arch.
 Reg. No. 16/2004/1153



Table - A

Table - A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Community Building / Club		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter (Lacs)	Cumulative work done value till date (Lacs)	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing etc.)	14	15	8%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	0	0	0%
3.	MEP			
3.1	Mechanical (lifts, ventilation, etc.)	0	0	0%
3.2	Electrical (conducting, wiring, fixtures, etc.)	0	0	0%
3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	0	0%
4.	Finishing			
4.1	Internal (plaster, tilling, flooring, painting, etc within units and common areas)	0	0	0%
4.2	External (plaster, painting, facade, etc.)	0	0	0%


 K. S. Srinivasan
 B.A. (Hons.)

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation:		Work in progress		90%	
2.	Laying of foundation					
	(xix)	Raft	Yes, Not Yet Started		40%	
	(xx)	Pile	NA			
3.	Number of basement(s)					
	(xix)	Basement Level 1	NA			
	(xx)	Basement level 2*	NA			
4.	Waterproofing of the above sub-structure (wherever applicable)		Foundation Waterproofing		0%	
	Super-Structure Status					
5.	Total Floors in the tower/ building		4 Floors including Ground Floor			
6.	Total area on each floor (Carpet Area of complete tower)		18127 Sqft			
7.	Still floor/ ground floor		Ground Floor		0%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		0 Slabs Completed		0%	
9.	Status of construction					
	(xxx)	Walls on floors	4 Floors, Not Yet Started		0%	
	(xxx)	Staircase	4 Floors, Not Yet Started		0%	
	(xxx)	Lift wells along with water proofing	4 Floors, Not Yet Started		0%	
	(xl)	Lift lobbies/ common areas floor wise	4 Floors Not Yet Started		0%	
10.	Fixing of door and window frames in flats/ units		Wooden Frames, Door Frames, Aluminium		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(xxv)	Mechanical works	Yes	Yes		10%



 Signature: *[Handwritten Signature]*

 Project Name: *[Handwritten Project Name]*

	(xxix) Electrical works including wiring	Yes	Yes	0%	0%
	(xxx) Plumbing works	Yes	Yes	0%	0%
12.	Status of wall plastering				
	(xix) External plaster	Cement Based Plaster		0%	
	(xx) Internal plaster	Gypsum Plaster		0%	
13.	Status of wall tiling				
	(xix) In bathroom	Ceramic Tiles		0%	
	(xx) In kitchen	Ceramic Tiles		0%	
14.	Status of flooring				
	(xx) Common areas	Stone and Tiling Works		0%	
	(xx) Units/ flats	NA			
15.	Status of white washing				
	(xix) Internal walls	OBD/ Acrylic Emulsion		0%	
	(xx) External walls	External Texture Paint		0%	
16.	Status of finishing				
	(xxv) Staircase with railing	Stone Floor with Railing		0%	
	(xxix) Lift wells	Shaft Plaster & Waterproofing		0%	
	(xxx) Lift lobbies/ common areas floor wise	Stone/Tile Flooring, OBD/ Acrylic Emulsion.		0%	
17.	Status of installation				
	(within flat/unit)				
	(c) Doors and windows panels	Aluminium Windows / Glass Doors/ Flush Doors		0%	
	(ci) Sanitary fixtures	Chinawares & CP Fittings		0%	
	(cii) Modular kitchen	NA			
	(ciii) Electrical fittings/ lighting	Switch Sockets		0%	
	(civ) Gas piping (if any)	NA			
	(other than flat/units)				
	(cv) Lifts installation	2 Nos. Lift		0%	




	(vi) Overhead tanks	3 Nos. Tank - Domestic, Fire & Flushing	0%
	(vii) Underground water tank	Not Applicable for Building, combined for entire Phase	
	(viii) Firefighting fitting and equipment's as per CFO NOC	Sprinklers, Fire Hose & Fire Extinguishers	0%
	(ix) Electrical fittings in common areas	LED Lights	0%
	(x) Compliance to conditions of environment/ CRZ NOC	Yes, Applicable for Entire Phase	0%
18.	Waterproofing of terraces	Brick Bat Coba	0%
19.	Entrance lobby finishing	Paint, Marble/Granite Flooring	0%
20.	Status of construction of compound wall	Not Applicable for Building, combined for entire Phase	

K. N. Nandhan
 K. N. NANDHAN
 B. Arch.
 RA Reg No: 62/2004/1912



Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
R-1	Services			
1.	Internal roads & pavements	Yes	0%	
2.	Parking			
	Covered no. 1100	Yes	65%	Cumulative spend Rs. 4823 Lacs
	Open no. 18	Yes	0%	
3.	Water supply	Yes	0%	
4.	Sewerage (chamber, lines, septic tanks)	Yes	0%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation	Yes	0%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	NA		
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	Composter is being provided
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	
13.	Energy management (solar)	Yes	0%	Solar Panels provided
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	Panel Room is being provided
16.	Under Ground Water Tank	Yes	0%	
17.	Compound Wall	Yes	0%	
R-2	Community building to be transferred to RWA			
18.	Community centre	No Such Building		
19.	Others			


 MUNICIPAL ENGINEER
 B. And.
 11/11/2018

B-3	Community buildings not to be transferred to RWA/competent authority			
20.	Schools	No Such Building		
21.	Dispensary	No Such Building		
22.	Club	No Such Building		
23.	Nursery School	No Such Building		
B-4	Services/ facilities to be transferred to competent authority			
24.	*			

Note: (*) extend as per requirement

K. M. Nanchan
K. M. NANCHAN
 B. Arch.
 RA Reg No. CA/2006/11137

