

ACPL Design Ltd

E.24, South Extension I. New Dethi, 110049, India T: +91 11 4828 4444 +91 11 2462 2195 +91 11 2464 6709 F: +91 11 2463 4059

www.acplonline.com

Annexure-A

		Architect ³	's Certificate*			
Repor	t for qua	rter ending	30 th June 2023			
Subjec		<u> </u>	Certificate of progress of construction work			
1.	I, KULMEET SHANGARI has undertaken assignment as architect for certifying p construction work in the below mentioned project as per the approved plans					
	Sr. Particulars Information No.					
	1.	Project/Phase of the project	Elan EPIC			
	2. Location Sector 70, C		Sector 70, Gurugram			
	3.	4 Acres				
	4. Area for registration in acres 3.525 Acres					
	5.	HARERA registration No.	RC/REP/HARERA/GGM/2018/30			
	6.	Name of licensee	Elan Limited			
	7.	Name of collaborator	NA			
	8.	Name of developer	Elan Limited			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	11th July 2023			
	2.	Name of Architect/Architect"s firm	KULMEET SHANGARI (ACPL Design Ltd.)			
	3.	Date of site inspection	30 th June 2023			
3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer	Anil Kumar Gautam			
	2.	Structural consultant	Perceptive Idea ARCHITECT			
	3.	Proof consultant	Isha Consultani (P) Ltd.CA/97/21741			
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pvt. Ltd., Ampower Consultancy Services.			
	5.	Site supervisor/in charge	Saurabh Gupta			

I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
 Ialsocertify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect

Date

11th July 2023

to each of the activity of the entire project/ phase is detailed in table A and table B.

Place

: New Delhi

Councilofarchitects(CoA)

registration No.

: CA/97/21741

Councilofarchitects(CoA)

registration valid till (date)


: 31.12.2024

Yours faithfully,

KULMEET SHANGAR ARCHITECT

RULMEET SHANGARI

Table - A ELAN EPIC Building/ Tower no. (Entire project is one building) (to be prepared separately for each building/tower in the project/phase of the project) Cumulative progress of the project/phase at the end of the quarter. (In Lacs) **A1** Sr. **Project components** Work done Cumulative Percentage of work No. value during the work done done to the total quarter value till date proposed work 1. Sub structure (inclusive of excavation, foundation, 0 5061 basements, water proofing, etc.) 2. Super structure (slabs, brick work, block work, staircase, lift wells, 67 4032 machine rooms, water tank, etc.) 3. MEP 3.1 Mechanical 98 981 (lifts, ventilation, etc.) 3.2 Electrical 84 872 (conduiting, wiring, fixtures, etc.) 3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.) 116 1313 4. **Finishing** 4.1 Internal (plaster, tilling, flooring, painting, etc. 227 991 within units and common areas) 4.2 External 887 2890 (plaster, painting, facade, etc.) Sr. Tasks/ Activity Description of work Percentage of total No. done proposed work **Sub-Structure Status** 1. Excavation Completed 100% 2. Laying of foundation



KULMEET SHANGARI WARCHIFECT CA/97/21741

4.	Waterproofing of the above sub-structure (wherever applicable)		In Progress		98%	
		Super-Structure Status				
5.	Total	floors in the tower/ building	6		6	
6.	Total	area on each floor	NA		NA	
7.	Stilt 1	floor/ ground floor	Completed		100%	
8.	Status of laying of slabs floor wise		Completed		100%	
	Cumulative number of slabs in the building/ tower laid by end of quarter		Completed		100%	
9.	Status	s of construction				
	(i) Walls on floors		Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Com	pleted	100%	
	(iv)	Lift lobbies/ common areas floor wise	In progress		89%	
10.	Fixing	gofdoorand window frames in flats/ units	N	TL.	NIL	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	In pro	ogress	90%	
	(ii)	Electrical works including wiring	In pro	ogress	90%	, 0
	(iii)	Plumbing works	In progress		90%	
12.	Status	of wall plastering				
	(i)	External plaster	In pro	ogress	90%	, D
	(ii)	Internal plaster	In progress		90%	
13.	Status	of wall tiling				
	(i)	In bathroom	In progress		95%	
	(ii)	In kitchen	NA		NA	
14.	Status	of flooring				
	(i)	Common areas	In progress		90%	
	(ii)	Units/ flats	NA		NA	
15.	Status	of white washing				
	(i)	Internal walls	In pro	ogress	90%	
	(ii)	External walls	KULMEET	PESHANGAF	95%	•
		Must	WZ CA/9	HITECT 7/21 741		

16.	Status of finishing					
	(i)	Staircase with railing	In progress	90%		
	(ii)	Lift wells	In progress	95%		
	(iii)	Lift lobbies/ common areas floor wise	In progress	85%		
17.	Status of installation					
	(within flat/unit)					
	(i)	Doors and windows panels	NIL	85%		
	(ii)	Sanitary fixtures	NIL	25%		
	(iii)	Modular kitchen	NA	NA		
	(iv)	Electrical fittings/ lighting	NIL	80%		
	(v)	Gas piping (if any)	NA	NA		
	(other than flat/units)					
	(vi)	Lifts installation	NIL	80%		
	(vii)	Overhead tanks	Completed	100%		
	(viii)	Underground water tank	Completed	100%		
	(ix)	Firefighting fitting and equipment"sas per CFO NOC	In progress	85%		
	(x)	Electrical fittings in common areas	In progress	85%		
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL		
18.	Waterproofing of terraces		NIL	60%		
19.	Entran	ce lobby finishing	NIL	85%		
20.	Status	of construction of compound wall	Completed	100%		

Note: (*) extend rows as per requirement.

ARCHITECT CA/97/21741

Table-B

Sr. No.	Common areas and facilities amenities	Proposed	Percentage of	Remark
B-1	Services	(Yes/No)	work done	
Б-1 1.	Internal roads & pavements	YES	050/	
2.	Parking	1 ES	85%	
۷.	Covered no572.	YES	000/	
	Open no Nil		90%	
3.	Water supply	YES	NIL	
4.		YES YES	70%	
4.	Sewerage (chamber, lines, septic tanks, STP)		80%	
5.	Storm water drains	YES	50%	
6.	Landscaping & tree plantation	YES	NIL	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment"s	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	YES	75%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	45%	
11.	Solid waste management & disposal	YES	NIL	
12.	Waterconservation, rain water, harvesting, percolating well/pit	YES	90%	
13.	Energy management (solar)	YES	10%	
14.	Fire protection and fire safety requirements	YES	75%	
15.	Electrical meter room, sub-station, receiving station	YES	70%	
16.	Other (option to add more)		NIL	
B-2	Community building to be transferred to RWA	1		
17.	Community centre	NO	NO	
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
21.	Club	NO	NO	
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*	1	MEET SHANG	

Note: (*) extend as per requirement

ARCHITECT