

| TABLE-A  |   |   |   |   |  |  |
|--|---|---|---|---|--|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-T1                                    |   |  |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) |  | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 51  |  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 1402  |  | 100%   |
| 3  | MEP   |   |   |   |  |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 15  | 260   |  | 86%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 114   |  | 100%   |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 20  | 193   |  | 95%  |
| 4  | FINISHING   |   |   |   |  |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 15  | 642   |  | 99%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 192   |  | 100%   |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        |  | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |  |
| 1  | Excavation  |   |   | Complete  |  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  |  | 100%   |
|  | (i)   | Raft  |   | Complete  |  | 100%   |
|  | (ii)  | Pile  |   | NA  |  | NA   |
| 3  | Number of Basements ....  |   |   |   |  |  |
|  | (i)   | Basement Level-1  |   | Complete  |  | 100%   |
|  | (ii)  | Basement Level-2  |   | Complete  |  | 100%   |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | NIL   |  | NIL  |
|  | Super-Structure Status  |   |   |   |  |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+25  |  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | 425.192   |  | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 532.506   |  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  |  | 100%   |

*K. Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | In Progress             | 86%           |
|    | (ii) Electrical work including wiring   | Complete                | 100%          |
|    | (iii) Plumbing work   | In Progress             | 95%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | In Progress             |               |
|    | (ii) In Kitchen   | In Progress             | 99%           |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | In Progress             | 99%           |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                | 100%          |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | Complete                | 100%          |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | NA                      | NA            |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |
|    |   |                         |               |
|    |   |                         |               |

*Kapil*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-T2                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 51  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 1402  | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 10  | 239   | 79%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 10  | 108   | 95%  |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 8   | 196   | 96%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 15  | 576   | 89%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 7   | 180   | 93%  |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    | 100%  |  |
|  | (ii)  | Pile  | NA  | NA  |  |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    | 100%  |  |
|  | (ii)  | Basement Level-2  | Complete                                    | 100%  |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+25  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | 425.192   | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 532.506   | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

*Kapil*

At. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | In Progress             | 93%           |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | In Progress             | 79%           |
|    | (ii) Electrical work including wiring   | In Progress             | 95%           |
|    | (iii) Plumbing work   | In Progress             | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | In Progress             | 89%           |
|    | (ii) In Kitchen   | In Progress             | 89%           |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | In Progress             | 89%           |
|    | (ii) External Walls   | In Progress             | 89%           |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | In Progress             | 89%           |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NIL                     | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NA                      | NA            |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-T3                                    |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 51  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 1402  | 100%   |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 22  | 196   | 65%  |
|   | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 10  | 108   | 95%  |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 9   | 194   | 95%  |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 5   | 593   | 87%  |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 3   | 183   | 90%  |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   | Description of Work Done                    |   | Percentage of total proposed work                  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   | Complete                                    |   | 100%   |
| 2   | Laying of Foundation  |   | Complete                                    |   | 100%   |
|   | (i)   | Raft  | Complete                                    |   | 100%   |
|   | (ii)  | Pile  | NA  |   | NA   |
| 3   | Number of Basements ....  |   |   |   |  |
|   | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|   | (ii)  | Basement Level-2  | Complete                                    |   | 100%   |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | Complete                                    |   | 100%   |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   | S+25  |   | 100%   |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   | 425.192                                     |   | 100%   |
| 7   | Stilt / Ground Floor  |   | 532.506                                     |   | 100%   |
|   | Status of Laying of slabs floor wise  |   | Complete                                    |   | 100%   |

  
 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                         |   |
|----|---|-------------------------|---|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%  |
| 9  | <b>Status of Construction</b>   |                         |   |
|    | (i) Walls on floors   | Complete                | 100%  |
|    | (ii) Staircase  | Complete                | 100%  |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%  |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%  |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%  |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work Internal (with in Flat) External Work |
|    | (i) Mechanical Works  | In Progress             | 65%   |
|    | (ii) Electrical work including wiring   | In Progress             | 95%   |
|    | (iii) Plumbing work   | In Progress             | 95%   |
| 12 | <b>Status of Wall Plastering</b>  |                         |   |
|    | (i) External Plaster  | In Progress             | 90%   |
|    | (ii) Internal Plaster   | Complete                | 100%  |
| 13 | <b>Status of Wall Tiling</b>  |                         |   |
|    | (i) In Bath Rooms   | In Progress             | 87%   |
|    | (ii) In Kitchen   | In Progress             | 87%   |
| 14 | <b>Status of Flooring</b>   |                         |   |
|    | (i) Common Areas  | Complete                | 100%  |
|    | (ii) Units/Flats  | Complete                | 100%  |
| 15 | <b>Status of White Washing</b>  |                         |   |
|    | (i) Internal Walls  | NIL                     | NIL   |
|    | (ii) External Walls   | Complete                | 100%  |
| 16 | <b>Status of Finishing</b>  |                         |   |
|    | (i) Staircase with Railing  | Complete                | 100%  |
|    | (ii) Lift Wells   | Complete                | 100%  |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%  |
| 17 | <b>Status of installation</b>   |                         |   |
|    | <b>( within Flats/ Units)</b>   |                         |   |
|    | (i) Doors & Windows Panels  | Complete                | 100%  |
|    | (ii) Sanitary Fixtures  | In Progress             | 70%   |
|    | (iii) Modular Kitchen   | NA                      | NA  |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA  |
|    | (v) Gas Piping ( if any)  | NA                      | NA  |
|    | <b>( other than Flats/ Units)</b>   |                         |   |
|    | (vi) Lift Installations   | Complete                | 100%  |
|    | (vii) Over Head Tanks   | Complete                | 100%  |
|    | (viii) Under Ground Water Tanks   | NA                      | NA  |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NA                      | NA  |
|    | (x) Electrical Fittings in Common Areas   | Complete                | 100%  |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%  |
| 18 | Water Proofing of Terraces  | Complete                | 100%  |
| 19 | Entrance Lobby Finishing  | Complete                | 100%  |
| 20 | Status of Construction of Compound wall   | NA                      | NA  |

*Kapil*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B1                                    |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 32  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 15  | 83  | 65%  |
|   | 3.2   | Electrical<br>( Conducting,Wiring,Fixtures etc.)                              | Nil   | 48  | 100%   |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 3   | 83  | 96%  |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 2   | 268   | 97%  |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 82  | 100%   |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   | Description of Work Done                    |   | Percentage of total proposed work                  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   | Complete                                    |   | 100%   |
| 2   | Laying of Foundation  |   | Complete                                    |   | 100%   |
|   | (i)   | Raft  | Complete                                    |   | 100%   |
|   | (ii)  | Pile  | NA  |   | NA   |
| 3   | Number of Basements ....  |   |   |   |  |
|   | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|   | (ii)  | Basement Level-2  | Complete                                    |   | 100%   |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | Complete                                    |   | 100%   |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   | S+14  |   | 100%   |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   | Typ.Floor-302.85 ,LPH-227.46, UPH-214.44    |   | 100%   |
| 7   | Stilt / Ground Floor  |   | 341.73                                      |   | 100%   |
|   | Status of Laying of slabs floor wise  |   | Complete                                    |   | 100%   |

*Kapil*

At. KAPIL SINGH  
B. Arch.

Regn. No with Council  
of Architecture CA/2003/31603

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | In Progress             | 65%           |
|    | (ii) Electrical work including wiring   | Complete                | 100%          |
|    | (iii) Plumbing work   | In Progress             | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | In Progress             | 97%           |
|    | (ii) In Kitchen   | In Progress             | 97%           |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                | 100%          |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | Complete                | 100%          |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*Kapil*

Ar. KAPIL SINGH  
B. Arch.

Regn. No with Council  
of Architecture CA/2003/31600



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B2                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 32  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 20  | 83  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 48  | 100%   |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 5   | 83  | 96%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 3   | 268   | 97%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 82  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    |   | 100%   |
|  | (ii)  | Pile  | NA  |   | NA   |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|  | (ii)  | Basement Level-2  | Complete                                    |   | 100%   |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+14  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | Typ.Floor-302.85 ,LPH-227.46, UPH-214.44        | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 341.73  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

*KAPIL*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | Complete                | 65%           |
|    | (ii) Electrical work including wiring   | Complete                | 100%          |
|    | (iii) Plumbing work   | Complete                | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | Complete                | 100%          |
|    | (ii) In Kitchen   | Complete                | 100%          |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                | 100%          |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |



Ar. KAPIL SINGH  
B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31603



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B3                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 36  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 22  | 80  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 3   | 44  | 95%  |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 5   | 80  | 96%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 3   | 258   | 97%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 79  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    |   | 100%   |
|  | (ii)  | Pile  | NA  |   | NA   |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|  |   |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+12  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | Typ.Floor-340.98 .LPH-310.06., UPH-263.96       | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 375.12  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                          |  |
|----|---|--------------------------|--|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                 | 100%   |
| 9  | <b>Status of Construction</b>   |                          |  |
|    | (i) Walls on floors   | Complete                 | 100%   |
|    | (ii) Staircase  | Complete                 | 100%   |
|    | (iii) Liftwells along with water proofing   | Complete                 | 100%   |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                 | 100%   |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                 | 100%   |
| 11 | <b>Status of MEP</b>  | Internal ( with in Flat) | External Work<br>Internal ( with in Flat)<br>External Work |
|    | (i) Mechanical Works  | Complete                 | 65%  |
|    | (ii) Electrical work including wiring   | Complete                 | 95%  |
|    | (iii) Plumbing work   | Complete                 | 96%  |
| 12 | <b>Status of Wall Plastering</b>  |                          |  |
|    | (i) External Plaster  | Complete                 | 100%   |
|    | (ii) Internal Plaster   | Complete                 | 100%   |
| 13 | <b>Status of Wall Tiling</b>  |                          |  |
|    | (i) In Bath Rooms   | Complete                 | 97%  |
|    | (ii) In Kitchen   | Complete                 | 100%   |
| 14 | <b>Status of Flooring</b>   |                          |  |
|    | (i) Common Areas  | Complete                 | 100%   |
|    | (ii) Units/Flats  | Complete                 | 100%   |
| 15 | <b>Status of White Washing</b>  |                          |  |
|    | (i) Internal Walls  | Complete                 | 100%   |
|    | (ii) External Walls   | Complete                 | 100%   |
| 16 | <b>Status of Finishing</b>  |                          |  |
|    | (i) Staircase with Railing  | Complete                 | 100%   |
|    | (ii) Lift Wells   | Complete                 | 100%   |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                 | 100%   |
| 17 | <b>Status of installation</b>   |                          |  |
|    | <b>( within Flats/ Units)</b>   |                          |  |
|    | (i) Doors & Windows Panels  | Complete                 | 100%   |
|    | (ii) Sanitary Fixtures  | Complete                 | 100%   |
|    | (iii) Modular Kitchen   | NA                       | NA   |
|    | (iv) Electrical Fittings/ Lightings   | NA                       | NA   |
|    | (v) Gas Piping ( if any)  | NA                       | NA   |
|    | <b>( other than Flats/ Units)</b>   |                          |  |
|    | (vi) Lift Installations   | Complete                 | 100%   |
|    | (vii) Over Head Tanks   | Complete                 | 100%   |
|    | (viii) Under Ground Water Tanks   | NA                       | NA   |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                      | NIL  |
|    | (x) Electrical Fittings in Common Areas   | NIL                      | NIL  |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                 | 100%   |
| 18 | Water Proofing of Terraces  | Complete                 | 100%   |
| 19 | Entrance Lobby Finishing  | Complete                 | 100%   |
| 20 | Status of Construction of Compound wall   | NA                       | NA   |

*Kapil*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B4                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 36  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 18  | 80  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 2   | 44  | 95%  |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 2   | 80  | 96%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 2   | 257   | 97%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 3   | 79  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    | 100%  |  |
|  | (ii)  | Pile  | NA  | NA  |  |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    | 100%  |  |
|  |   |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+12  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | Typ.Floor-340.98 .LPH-310.06., UPH-263.96       | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 375.12  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

*Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31648

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | Complete                | 65%           |
|    | (ii) Electrical work including wiring   | Complete                | 95%           |
|    | (iii) Plumbing work   | Complete                | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | Complete                | 100%          |
|    | (ii) In Kitchen   | Complete                | 100%          |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | In Progress             | 70%           |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*Kapil*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B5                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 36  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 20  | 80  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 2   | 44  | 95%  |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 2   | 80  | 96%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | Nil   | 257   | 97%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 2   | 79  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    |   | 100%   |
|  | (ii)  | Pile  | NA  |   | NA   |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|  |   |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+12  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | Typ.Floor-340.98 .LPH-310.06., UPH-263.96       | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 375.12  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

*Kapil Singh*

AR. KAPIL SINGH  
B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | Complete                | 65%           |
|    | (ii) Electrical work including wiring   | Complete                | 95%           |
|    | (iii) Plumbing work   | Complete                | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | Complete                | 100%          |
|    | (ii) In Kitchen   | Complete                | 100%          |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | NIL                     | 0%            |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*Kapil*

Ar. KAPIL SINGH  
B. Arch.

Regn. No with Council  
of Architects CA/2003/31698



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B6                                    |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 36  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 585   | 100%   |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 25  | 80  | 65%  |
|   | 3.2   | Electrical<br>( Conducting,Wiring,Fixtures etc.)                              | Nil   | 46  | 100%   |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 2   | 80  | 96%  |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 2   | 257   | 97%  |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 79  | 100%   |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   | Description of Work Done                    | Percentage of total proposed work               |  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   | Complete                                    |   | 100%   |
| 2   | Laying of Foundation  |   | Complete                                    |   | 100%   |
|   | (i)   | Raft  | Complete                                    |   | 100%   |
|   | (ii)  | Pile  | NA  |   | NA   |
| 3   | Number of Basements ....  |   |   |   |  |
|   | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|   |   |   |   |   |  |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | Complete                                    |   | 100%   |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   | S+12  |   | 100%   |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   | Typ.Floor-340.98 .LPH-310.06, UPH-263.96    |   | 100%   |
| 7   | Stilt / Ground Floor  |   | 375.12                                      |   | 100%   |
|   | Status of Laying of slabs floor wise  |   | Complete                                    |   | 100%   |

*Kapil Singh*

**Ar. KAPIL SINGH**  
B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | Complete                | 65%           |
|    | (ii) Electrical work including wiring   | Complete                | 100%          |
|    | (iii) Plumbing work   | Complete                | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | Complete                | 100%          |
|    | (ii) In Kitchen   | Complete                | 100%          |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                | 100%          |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |
|    |   |                         |               |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



| TABLE-A  |   |   |   |  |
|--|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   | TOWER-B7                                    |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |  |
| Sr.No  | Project Components  | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     | Nil   | 32  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) | Nil   | 657   | 100%   |
| 3  | MEP   |   |   |  |
|  | 3.1 Mechanical<br>( Lifts, Ventilation etc.)  | 12  | 113   | 79%  |
|  | 3.2 Electrical<br>( Conduiting,Wiring,Fixtures etc.)  | 2   | 51  | 95%  |
|  | 3.3 Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)                              | 3   | 93  | 96%  |
| 4  | FINISHING   |   |   |  |
|  | 4.1 Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)                     | Nil   | 284   | 93%  |
|  | 4.2 External ( Plaster, Painting, Façade etc.)  | 2   | 88  | 96%  |
|  |   |   |   |  |
| Sr.No.   | Tasks/ Activity   | Description of Work Done                    | Percentage of total proposed work               |  |
|  | Sub-Structure Status  |   |   |  |
| 1  | Excavation  | Complete                                    |   | 100%   |
| 2  | Laying of Foundation  | Complete                                    |   | 100%   |
|  | (i) Raft  | Complete                                    |   | 100%   |
|  | (ii) Pile   | NA  |   | NA   |
| 3  | Number of Basements ....  |   |   |  |
|  | (i) Basement Level-1  | Complete                                    |   | 100%   |
|  |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      | NIL   |   | NIL  |
|  | Super-Structure Status  |   |   |  |
| 5  | Total Floors in the Tower/ Building   | S+16  |   | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   | Typ.Floor-302.85,LPH-227.46 , UPH-214.44    |   | 100%   |
| 7  | Stilt / Ground Floor  | 341.73                                      |   | 100%   |
|  | Status of Laying of slabs floor wise  | Complete                                    |   | 100%   |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                | 100%          |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | In Progress             | 79%           |
|    | (ii) Electrical work including wiring   | In Progress             | 96%           |
|    | (iii) Plumbing work   | In Progress             | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | In Progress             | 93%           |
|    | (ii) In Kitchen   | In Progress             | 93%           |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | In Progress             | 93%           |
|    | (ii) Units/Flats  | In Progress             | 93%           |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | In Progress             | 93%           |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | In Progress             | 80%           |
|    | (ii) Sanitary Fixtures  | In Progress             | 80%           |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA            |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | Complete                | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*K. Singh*  
**Ar. KAPIL SINGH**  
 B. Arch.

Regn. No with Council  
 of Architecture CA/2003/31608



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B8                                    |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 32  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 657   | 100%   |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 14  | 93  | 65%  |
|   | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 2   | 56  | 95%  |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 2   | 92  | 95%  |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | Nil   | 285   | 93%  |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 3   | 84  | 91%  |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   | Description of Work Done                    | Percentage of total proposed work               |  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   | Complete                                    |   | 100%   |
| 2   | Laying of Foundation  |   | Complete                                    |   | 100%   |
|   | (i)   | Raft  | Complete                                    |   | 100%   |
|   | (ii)  | Pile  | NA  |   | NA   |
| 3   | Number of Basements ....  |   |   |   |  |
|   | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|   |   |   |   |   |  |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | Complete                                    |   | 100%   |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   | S+16  |   | 100%   |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   | Typ.Floor-302.85,LPH-227.46 , UPH-214.44    |   | 100%   |
| 7   | Stilt / Ground Floor  |   | 341.73                                      |   | 100%   |
|   | Status of Laying of slabs floor wise  |   | Complete                                    |   | 100%   |

  
 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

|    |   |                         |   |
|----|---|-------------------------|---|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%  |
| 9  | <b>Status of Construction</b>   |                         |   |
|    | (i) Walls on floors   | Complete                | 100%  |
|    | (ii) Staircase  | Complete                | 100%  |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%  |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%  |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | In Progress             | 91%   |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work Internal (with in Flat) External Work |
|    | (i) Mechanical Works  | In Progress             | 65%   |
|    | (ii) Electrical work including wiring   | In Progress             | 95%   |
|    | (iii) Plumbing work   | In Progress             | 95%   |
| 12 | <b>Status of Wall Plastering</b>  |                         |   |
|    | (i) External Plaster  | Complete                | 100%  |
|    | (ii) Internal Plaster   | Complete                | 100%  |
| 13 | <b>Status of Wall Tiling</b>  |                         |   |
|    | (i) In Bath Rooms   | In Progress             | 93%   |
|    | (ii) In Kitchen   | Complete                | 100%  |
| 14 | <b>Status of Flooring</b>   |                         |   |
|    | (i) Common Areas  | Complete                | 100%  |
|    | (ii) Units/Flats  | Complete                | 100%  |
| 15 | <b>Status of White Washing</b>  |                         |   |
|    | (i) Internal Walls  | Complete                | 100%  |
|    | (ii) External Walls   | Complete                | 100%  |
| 16 | <b>Status of Finishing</b>  |                         |   |
|    | (i) Staircase with Railing  | Complete                | 100%  |
|    | (ii) Lift Wells   | Complete                | 100%  |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%  |
| 17 | <b>Status of installation</b>   |                         |   |
|    | <b>( within Flats/ Units)</b>   |                         |   |
|    | (i) Doors & Windows Panels  | Complete                | 100%  |
|    | (ii) Sanitary Fixtures  | In Progress             | 25%   |
|    | (iii) Modular Kitchen   | NA                      | NA  |
|    | (iv) Electrical Fittings/ Lightings   | NA                      | NA  |
|    | (v) Gas Piping ( if any)  | NA                      | NA  |
|    | <b>( other than Flats/ Units)</b>   |                         |   |
|    | (vi) Lift Installations   | Complete                | 100%  |
|    | (vii) Over Head Tanks   | Complete                | 100%  |
|    | (viii) Under Ground Water Tanks   | NA                      | NA  |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                     | NIL   |
|    | (x) Electrical Fittings in Common Areas   | NIL                     | NIL   |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%  |
| 18 | Water Proofing of Terraces  | Complete                | 100%  |
| 19 | Entrance Lobby Finishing  | Complete                | 100%  |
| 20 | Status of Construction of Compound wall   | NA                      | NA  |

*K. Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |  |   |  |
|--|---|---|--|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B9                                   |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |  |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lac) | Cumulative Work done value till Date ( in Cr) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil  | 32  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil  | 657   | 100%   |
| 3  | MEP   |   |  |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 15   | 93  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | 12   | 51  | 95%  |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 5  | 89  | 91%  |
| 4  | FINISHING   |   |  |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 8  | 284   | 93%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 10   | 87  | 95%  |
|  |   |   |  |   |  |
| Sr.No.   | Tasks/ Activity   |   |  | Description of Work Done                      | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |  |   |  |
| 1  | Excavation  |   |  | Complete                                      | 100%   |
| 2  | Laying of Foundation  |   |  | Complete                                      | 100%   |
|  | (i)   | Raft  | Complete                                   | 100%  |  |
|  | (ii)  | Pile  | NA   | NA  |  |
| 3  | Number of Basements ....  |   |  |   |  |
|  | (i)   | Basement Level-1  | Complete                                   | 100%  |  |
|  |   |   |  |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |  | Complete                                      | 100%   |
|  | Super-Structure Status  |   |  |   |  |
| 5  | Total Floors in the Tower/ Building   |   |  | S+16  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |  | Typ.Floor-302.85,LPH-227.46 , UPH-214.44      | 100%   |
| 7  | Stilt / Ground Floor  |   |  | 341.73  | 100%   |

*K. Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |   |  |                          |  |
|----|---|--|--------------------------|--|
| 8  | <b>Status of Laying of slabs floor wise</b>                                       |  | Complete                 | 100%   |
|    | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter |  | Complete                 | 100%   |
| 9  | <b>Status of Construction</b>   |  |                          |  |
|    | (i)   | Walls on floors                                    | Complete                 | 100%   |
|    | (ii)  | Staircase  | Complete                 | 100%   |
|    | (iii)   | Liftwells along with water proofing                | Complete                 | 100%   |
|    | (iv)  | Lift Lobbies/Common areas floor wise               | Complete                 | 100%   |
| 10 | Fixing of Door & window frames in the Flats/Units                                 |  | Complete                 | 100%   |
| 11 | <b>Status of MEP</b>  |  | Internal ( with in Flat) | External Work<br>Internal ( with in Flat)<br>External Work |
|    | (i)   | Mechanical Works                                   | Complete                 | 65%  |
|    | (ii)  | Electrical work including wiring                   | Complete                 | 95%  |
|    | (iii)   | Plumbing work                                      | Complete                 | 91%  |
| 12 | <b>Status of Wall Plastering</b>  |  |                          |  |
|    | (i)   | External Plaster                                   | Complete                 | 100%   |
|    | (ii)  | Internal Plaster                                   | Complete                 | 100%   |
| 13 | <b>Status of Wall Tiling</b>  |  |                          |  |
|    | (i)   | In Bath Rooms                                      | In Progress              | 93%  |
|    | (ii)  | In Kitchen   | In Progress              | 93%  |
| 14 | <b>Status of Flooring</b>   |  |                          |  |
|    | (i)   | Common Areas                                       | In Progress              | 93%  |
|    | (ii)  | Units/Flats  | In Progress              | 93%  |
| 15 | <b>Status of White Washing</b>  |  |                          |  |
|    | (i)   | Internal Walls                                     | In Progress              | 95%  |
|    | (ii)  | External Walls                                     | In Progress              | 95%  |
| 16 | <b>Status of Finishing</b>  |  |                          |  |
|    | (i)   | Staircase with Railing                             | Complete                 | 100%   |
|    | (ii)  | Lift Wells   | Complete                 | 100%   |
|    | (iii)   | Lift Lobbies/Common areas floor wise               | Complete                 | 100%   |
| 17 | <b>Status of installation</b>   |  |                          |  |
|    | <b>( within Flats/ Units)</b>   |  |                          |  |
|    | (i)   | Doors & Windows Panels                             | Complete                 | 100%   |
|    | (ii)  | Sanitary Fixtures                                  | In Progress              | 70%  |
|    | (iii)   | Modular Kitchen                                    | NA                       | NA   |
|    | (iv)  | Electrical Fittings/ Lightings                     | NA                       | NA   |
|    | (v)   | Gas Piping ( if any)                               | NA                       | NA   |
|    | <b>( other than Flats/ Units)</b>   |  |                          |  |
|    | (vi)  | Lift Installations                                 | Complete                 | 100%   |
|    | (vii)   | Over Head Tanks                                    | Complete                 | 100%   |
|    | (viii)  | Under Ground Water Tanks                           | NA                       | NA   |
|    | (ix)  | Fire Fighting Equipments & Fittings as per CFO NOC | NIL                      | NIL  |
|    | (x)   | Electrical Fittings in Common Areas                | NIL                      | NIL  |
|    | (xi)  | Compliance to condition of environment/CRZ NOC     | Complete                 | 100%   |
| 18 | Water Proofing of Terraces  |  | Complete                 | 100%   |
| 19 | Entrance Lobby Finishing  |  | Complete                 | 100%   |
| 20 | Status of Construction of Compound wall   |  | NA                       | NA   |

*K. Kapil*

**Ar. KAPIL SINGH**

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER-B10                                   |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 32  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 657   | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | 5   | 93  | 65%  |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 54  | 100%   |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 20  | 95  | 98%  |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 10  | 285   | 93%  |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | 10  | 87  | 95%  |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  | Complete                                    |   | 100%   |
|  | (ii)  | Pile  | NA  |   | NA   |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    |   | 100%   |
|  |   |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | NIL   | NIL  |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | S+16  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | Typ.Floor-302.85,LPH-227.46 , UPH-214.44        | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 341.73  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                          |  |
|----|---|--------------------------|--|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                 | 100%   |
| 9  | <b>Status of Construction</b>   |                          |  |
|    | (i) Walls on floors   | Complete                 | 100%   |
|    | (ii) Staircase  | Complete                 | 100%   |
|    | (iii) Liftwells along with water proofing   | Complete                 | 100%   |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                 | 100%   |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | Complete                 | 100%   |
| 11 | <b>Status of MEP</b>  | Internal ( with in Flat) | External Work<br>Internal ( with in Flat)<br>External Work |
|    | (i) Mechanical Works  | Complete                 | 65%  |
|    | (ii) Electrical work including wiring   | Complete                 | 100%   |
|    | (iii) Plumbing work   | Complete                 | 98%  |
| 12 | <b>Status of Wall Plastering</b>  |                          |  |
|    | (i) External Plaster  | Complete                 | 95%  |
|    | (ii) Internal Plaster   | Complete                 | 100%   |
| 13 | <b>Status of Wall Tiling</b>  |                          |  |
|    | (i) In Bath Rooms   | In Progress              | 93%  |
|    | (ii) In Kitchen   | In Progress              | 93%  |
| 14 | <b>Status of Flooring</b>   |                          |  |
|    | (i) Common Areas  | In Progress              | 93%  |
|    | (ii) Units/Flats  | In Progress              | 93%  |
| 15 | <b>Status of White Washing</b>  |                          |  |
|    | (i) Internal Walls  | Complete                 | 95%  |
|    | (ii) External Walls   | Complete                 | 95%  |
| 16 | <b>Status of Finishing</b>  |                          |  |
|    | (i) Staircase with Railing  | Complete                 | 100%   |
|    | (ii) Lift Wells   | Complete                 | 100%   |
|    | (iii) Lift Lobbies/Common areas floor wise  | In Progress              | 93%  |
| 17 | <b>Status of installation</b>   |                          |  |
|    | <b>( within Flats/ Units)</b>   |                          |  |
|    | (i) Doors & Windows Panels  | In Progress              | 90%  |
|    | (ii) Sanitary Fixtures  | In Progress              | 70%  |
|    | (iii) Modular Kitchen   | NA                       | NA   |
|    | (iv) Electrical Fittings/ Lightings   | NA                       | NA   |
|    | (v) Gas Piping ( if any)  | NA                       | NA   |
|    | <b>( other than Flats/ Units)</b>   |                          |  |
|    | (vi) Lift Installations   | Complete                 | 100%   |
|    | (vii) Over Head Tanks   | Complete                 | 100%   |
|    | (viii) Under Ground Water Tanks   | NA                       | NA   |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                      | NIL  |
|    | (x) Electrical Fittings in Common Areas   | NIL                      | NIL  |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                 | 100%   |
| 18 | Water Proofing of Terraces  | Complete                 | 100%   |
| 19 | Entrance Lobby Finishing  | Complete                 | 100%   |
| 20 | Status of Construction of Compound wall   | NA                       | NA   |

*Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | TOWER- EWS                                  |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 40  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 155   | 100%   |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | Nil   | 8   | 100%   |
|   | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 15  | 100%   |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | 8   | 27  | 96%  |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | 7   | 87  | 97%  |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 26  | 100%   |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   |   | Complete  | 100%   |
| 2   | Laying of Foundation  |   |   | Complete  | 100%   |
|   | (i)   | Raft  |   | NA  | NA   |
|   | (ii)  | Pile  |   | NA  | NA   |
| 3   | Number of Basements ....NA  |   |   |   |  |
|   |   |   |   |   |  |
|   |   |   |   |   |  |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | NIL   | NIL  |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   |   | S+9   | 100%   |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   |   | G.F-266.190,1st to 3rd- 322.75,4th to 6th-      | 100%   |
| 7   | Stilt / Ground Floor  |   |   | 266.19  | 100%   |
|   | Status of Laying of slabs floor wise  |   |   | Complete  | 100%   |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                          |               |
|----|---|--------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                 | 100%          |
| 9  | <b>Status of Construction</b>   |                          |               |
|    | (i) Walls on floors   | Complete                 | 100%          |
|    | (ii) Staircase  | Complete                 | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                 | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                 | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | NIL                      | NIL           |
| 11 | <b>Status of MEP</b>  | Internal ( with in Flat) | External Work |
|    | (i) Mechanical Works  | NIL                      | NIL           |
|    | (ii) Electrical work including wiring   | Complete                 | 100%          |
|    | (iii) Plumbing work   | Complete                 | 96%           |
| 12 | <b>Status of Wall Plastering</b>  |                          |               |
|    | (i) External Plaster  | Complete                 | 100%          |
|    | (ii) Internal Plaster   | Complete                 | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                          |               |
|    | (i) In Bath Rooms   | Complete                 | 100%          |
|    | (ii) In Kitchen   | Complete                 | 100%          |
| 14 | <b>Status of Flooring</b>   |                          |               |
|    | (i) Common Areas  | Complete                 | 100%          |
|    | (ii) Units/Flats  | NIL                      | NIL           |
| 15 | <b>Status of White Washing</b>  |                          |               |
|    | (i) Internal Walls  | Complete                 | 100%          |
|    | (ii) External Walls   | Complete                 | 100%          |
| 16 | <b>Status of Finishing</b>  |                          |               |
|    | (i) Staircase with Railing  | Complete                 | 100%          |
|    | (ii) Lift Wells   | Complete                 | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                 | 100%          |
| 17 | <b>Status of installation</b>   |                          |               |
|    | <b>( within Flats/ Units)</b>   |                          |               |
|    | (i) Doors & Windows Panels  | Complete                 | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                 | 100%          |
|    | (iii) Modular Kitchen   | NA                       | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                       | NA            |
|    | (v) Gas Piping ( if any)  | NA                       | NA            |
|    | <b>( other than Flats/ Units)</b>   |                          |               |
|    | (vi) Lift Installations   | Complete                 | 100%          |
|    | (vii) Over Head Tanks   | Complete                 | 100%          |
|    | (viii) Under Ground Water Tanks   | NA                       | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | Complete                 | 100%          |
|    | (x) Electrical Fittings in Common Areas   | Complete                 | 100%          |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                 | 100%          |
| 18 | Water Proofing of Terraces  | Complete                 | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                 | 100%          |
| 20 | Status of Construction of Compound wall   | NIL                      | NIL           |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | COMMUNITY BUILDING                          |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 21  | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | Nil   | 66  | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | Nil   | 19  | 100%   |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 7   | 100%   |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | Nil   | 12  | 100%   |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | Nil   | 34  | 100%   |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 12  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   | Description of Work Done                    | Percentage of total proposed work               |  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   | Complete                                    | 100%  |  |
| 2  | Laying of Foundation  |   | Complete                                    | 100%  |  |
|  | (i)   | Raft  | NA  | NA  |  |
|  | (ii)  | Pile  | NA  | NA  |  |
| 3  | Number of Basements ....  |   |   |   |  |
|  | (i)   | Basement Level-1  | Complete                                    | 100%  |  |
|  | (ii)  | Basement Level-2  | Complete                                    | 100%  |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | NIL   | NIL   |  |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   | G+1   | 100%  |  |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   | GF=716.26<br>F.F=198.900                    | 100%  |  |
| 7  | Stilt / Ground Floor  |   | 716.26                                      | 100%  |  |
|  | Status of Laying of slabs floor wise  |   | Complete                                    | 100%  |  |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

|    |   |                         |               |
|----|---|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | Complete                | 100%          |
| 9  | <b>Status of Construction</b>   |                         |               |
|    | (i) Walls on floors   | Complete                | 100%          |
|    | (ii) Staircase  | Complete                | 100%          |
|    | (iii) Liftwells along with water proofing   | Complete                | 100%          |
|    | (iv) Lift Lobbies/Common areas floor wise   | Complete                | 100%          |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | NIL                     | NIL           |
| 11 | <b>Status of MEP</b>  | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works  | Complete                | 100%          |
|    | (ii) Electrical work including wiring   | Complete                | 100%          |
|    | (iii) Plumbing work   | Complete                | 100%          |
| 12 | <b>Status of Wall Plastering</b>  |                         |               |
|    | (i) External Plaster  | Complete                | 100%          |
|    | (ii) Internal Plaster   | Complete                | 100%          |
| 13 | <b>Status of Wall Tiling</b>  |                         |               |
|    | (i) In Bath Rooms   | Complete                | 100%          |
|    | (ii) In Kitchen   | Complete                | 100%          |
| 14 | <b>Status of Flooring</b>   |                         |               |
|    | (i) Common Areas  | Complete                | 100%          |
|    | (ii) Units/Flats  | Complete                | 100%          |
| 15 | <b>Status of White Washing</b>  |                         |               |
|    | (i) Internal Walls  | Complete                | 100%          |
|    | (ii) External Walls   | Complete                | 100%          |
| 16 | <b>Status of Finishing</b>  |                         |               |
|    | (i) Staircase with Railing  | Complete                | 100%          |
|    | (ii) Lift Wells   | Complete                | 100%          |
|    | (iii) Lift Lobbies/Common areas floor wise  | Complete                | 100%          |
| 17 | <b>Status of installation</b>   |                         |               |
|    | <b>( within Flats/ Units)</b>   |                         |               |
|    | (i) Doors & Windows Panels  | Complete                | 100%          |
|    | (ii) Sanitary Fixtures  | Complete                | 100%          |
|    | (iii) Modular Kitchen   | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings   | Complete                | 100%          |
|    | (v) Gas Piping ( if any)  | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>   |                         |               |
|    | (vi) Lift Installations   | Complete                | 100%          |
|    | (vii) Over Head Tanks   | NA                      | NA            |
|    | (viii) Under Ground Water Tanks   | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | Complete                | 100%          |
|    | (x) Electrical Fittings in Common Areas   | Complete                | 100%          |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                | 100%          |
| 18 | Water Proofing of Terraces  | Complete                | 100%          |
| 19 | Entrance Lobby Finishing  | Complete                | 100%          |
| 20 | Status of Construction of Compound wall   | NA                      | NA            |

*Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



| TABLE-A  |   |   |   |   |  |
|--|---|---|---|---|--|
| Building No/Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | CONVENIENT SHOPPING                         |   |  |
| A1   | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No  | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1  | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | Nil   | 6   | 100%   |
| 2  | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   |   | 12  | 100%   |
| 3  | MEP   |   |   |   |  |
|  | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | Nil   | 2   | NA   |
|  | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   | 1   | 100%   |
|  | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | Nil   | 3   | 100%   |
| 4  | FINISHING   |   |   |   |  |
|  | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | Nil   | 0.70  | 100%   |
|  | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   | 0.18  | 100%   |
|  |   |   |   |   |  |
| Sr.No.   | Tasks/ Activity   |   |   | Description of Work Done                        | Percentage of total proposed work                  |
|  | Sub-Structure Status  |   |   |   |  |
| 1  | Excavation  |   |   | Complete  | 100%   |
| 2  | Laying of Foundation  |   |   | Complete  | 100%   |
|  | (i)   | Raft  |   | NA  | NA   |
|  | (ii)  | Pile  |   | NA  | NA   |
| 3  | Number of Basements ....NA  |   |   |   |  |
|  |   |   |   |   |  |
|  |   |   |   |   |  |
| 4  | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   |   | Complete  | 100%   |
|  | Super-Structure Status  |   |   |   |  |
| 5  | Total Floors in the Tower/ Building   |   |   | GROUND  | 100%   |
| 6  | Total Area on each floor ( Sq.Mtr.)   |   |   | 188.57  | 100%   |
| 7  | Stilt / Ground Floor  |   |   | 188.57  | 100%   |
|  | Status of Laying of slabs floor wise  |   |   | NA  | NA   |

*Kapil*

**Ar. KAPIL SINGH**

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

|    |  |                         |               |
|----|--|-------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower....Laid by end of the quarter | NA                      | NA            |
| 9  | <b>Status of Construction</b>  |                         |               |
|    | (i) Walls on floors  | COMPLETE                | 100%          |
|    | (ii) Staircase   | NA                      | NA            |
|    | (iii) Liftwells along with water proofing  | NIL                     | NA            |
|    | (iv) Lift Lobbies/Common areas floor wise  | NA                      | NA            |
| 10 | Fixing of Door & window frames in the Flats/Units                                  | NA                      | NA            |
| 11 | <b>Status of MEP</b>   | Internal (with in Flat) | External Work |
|    | (i) Mechanical Works   | NIL                     | NA            |
|    | (ii) Electrical work including wiring  | COMPLETE                | 100%          |
|    | (iii) Plumbing work  | COMPLETE                | 100%          |
| 12 | <b>Status of Wall Plastering</b>   |                         |               |
|    | (i) External Plaster   | COMPLETE                | 100%          |
|    | (ii) Internal Plaster  | COMPLETE                | 100%          |
| 13 | <b>Status of Wall Tiling</b>   |                         |               |
|    | (i) In Bath Rooms  | COMPLETE                | 100%          |
|    | (ii) In Kitchen  | NA                      | NA            |
| 14 | <b>Status of Flooring</b>  |                         |               |
|    | (i) Common Areas   | COMPLETE                | 100%          |
|    | (ii) Units/Flats   | COMPLETE                | 100%          |
| 15 | <b>Status of White Washing</b>   |                         |               |
|    | (i) Internal Walls   | COMPLETE                | 100%          |
|    | (ii) External Walls  | COMPLETE                | 100%          |
| 16 | <b>Status of Finishing</b>   |                         |               |
|    | (i) Staircase with Railing   | NA                      | NA            |
|    | (ii) Lift Wells  | NA                      | NA            |
|    | (iii) Lift Lobbies/Common areas floor wise   | NA                      | NA            |
| 17 | <b>Status of installation</b>  |                         |               |
|    | <b>( within Flats/ Units)</b>  |                         |               |
|    | (i) Doors & Windows Panels   | Complete                | 100%          |
|    | (ii) Sanitary Fixtures   | COMPLETE                | 100%          |
|    | (iii) Modular Kitchen  | NA                      | NA            |
|    | (iv) Electrical Fittings/ Lightings  | NA                      | NA            |
|    | (v) Gas Piping ( if any)   | NA                      | NA            |
|    | <b>( other than Flats/ Units)</b>  |                         |               |
|    | (vi) Lift Installations  | NA                      | NA            |
|    | (vii) Over Head Tanks  | NA                      | NA            |
|    | (viii) Under Ground Water Tanks  | NA                      | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                            | COMPLETE                | 100%          |
|    | (x) Electrical Fittings in Common Areas  | NA                      | NA            |
|    | (xi) Compliance to condition of environment/CRZ NOC                                | Complete                | 100%          |
| 18 | Water Proofing of Terraces   | Complete                | 100%          |
| 19 | Entrance Lobby Finishing   | NA                      | NA            |
| 20 | Status of Construction of Compound wall  | NA                      | NA            |
|    |  |                         |               |
|    |  |                         |               |

*K. Kapil Singh*  
**Ar. KAPIL SINGH**  
 B. Arch.

Regn No with Council  
 of Architecture CA/2003/31608



| TABLE-A   |   |   |   |   |  |
|---|---|---|---|---|--|
| Building No./Tower No.<br>( To be prepared seperately for each buildings/Tower in the project/phase of the project) |   |   | NURSERY SCHOOL                              |   |  |
| A1  | Cumulative Progress of the Project/Phase at the end of the Quarter                                    |   |   |   |  |
| Sr.No   | Project Components  |   | Work done value during the Quarter(In Lakh) | Cumulative Work done value till Date ( in Lakh) | Percentage of work done to the total proposed work |
| 1   | Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)                     |   | 8   | 25  | 100%   |
| 2   | Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.) |   | 7   | 24  | 60%  |
| 3   | MEP   |   |   |   |  |
|   | 3.1   | Mechanical<br>( Lifts, Ventilation etc.)                                      | Nil   |   | 0%   |
|   | 3.2   | Electrical<br>( Conduiting,Wiring,Fixtures etc.)                              | Nil   |   | 0%   |
|   | 3.3   | Plumbing & Fire Fighting<br>(Piping,Pumps & Pump Room Fixtures etc.)          | Nil   |   | 0%   |
| 4   | FINISHING   |   |   |   |  |
|   | 4.1   | Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas) | Nil   |   | 0%   |
|   | 4.2   | External ( Plaster, Painting, Façade etc.)                                    | Nil   |   | 0%   |
|   |   |   |   |   |  |
| Sr.No.  | Tasks/ Activity   |   | Description of Work Done                    | Percentage of total proposed work               |  |
|   | Sub-Structure Status  |   |   |   |  |
| 1   | Excavation  |   | NIL   | NIL   |  |
| 2   | Laying of Foundation  |   | NIL   | NIL   |  |
|   | (i)   | Raft  | NA  | NA  |  |
|   | (ii)  | Pile  | NA  | NA  |  |
| 3   | Number of Basements ....NA  |   | NA  | NA  |  |
|   |   |   |   |   |  |
|   |   |   |   |   |  |
| 4   | Water Proofing of the Above Sub-Structure ( wherever applicable)                                      |   | NIL   | NIL   |  |
|   | Super-Structure Status  |   |   |   |  |
| 5   | Total Floors in the Tower/ Building   |   | G+2   | 60%   |  |
| 6   | Total Area on each floor ( Sq.Mtr.)   |   | 524.54                                      | 60%   |  |
| 7   | Stilt / Ground Floor  |   | 271.27                                      | 0%  |  |
|   | Status of Laying of slabs floor wise  |   | NIL   | NIL   |  |

*K. Kapil Singh*

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608

|    |   |                          |               |
|----|---|--------------------------|---------------|
| 8  | Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter | NIL                      | NIL           |
| 9  | <b>Status of Construction</b>   |                          |               |
|    | (i) Walls on floors   | NIL                      | NIL           |
|    | (ii) Staircase  | NIL                      | NIL           |
|    | (iii) Liftwells along with water proofing   | NIL                      | NIL           |
|    | (iv) Lift Lobbies/Common areas floor wise   | NIL                      | NIL           |
| 10 | Fixing of Door & window frames in the Flats/Units                                 | NIL                      | NIL           |
| 11 | <b>Status of MEP</b>  | Internal ( with in Flat) | External Work |
|    | (i) Mechanical Works  | NIL                      | 0%            |
|    | (ii) Electrical work including wiring   | NIL                      | 0%            |
|    | (iii) Plumbing work   | NIL                      | 0%            |
| 12 | <b>Status of Wall Plastering</b>  |                          |               |
|    | (i) External Plaster  | NIL                      | NIL           |
|    | (ii) Internal Plaster   | NIL                      | NIL           |
| 13 | <b>Status of Wall Tiling</b>  |                          |               |
|    | (i) In Bath Rooms   | NIL                      | NIL           |
|    | (ii) In Kitchen   | NIL                      | NIL           |
| 14 | <b>Status of Flooring</b>   |                          |               |
|    | (i) Common Areas  | NIL                      | NIL           |
|    | (ii) Units/Flats  | NIL                      | NIL           |
| 15 | <b>Status of White Washing</b>  |                          |               |
|    | (i) Internal Walls  | NIL                      | NIL           |
|    | (ii) External Walls   | NIL                      | NIL           |
| 16 | <b>Status of Finishing</b>  |                          |               |
|    | (i) Staircase with Railing  | NIL                      | NIL           |
|    | (ii) Lift Wells   | NIL                      | NIL           |
|    | (iii) Lift Lobbies/Common areas floor wise  | NIL                      | NIL           |
| 17 | <b>Status of installation</b>   |                          |               |
|    | <b>( within Flats/ Units)</b>   |                          |               |
|    | (i) Doors & Windows Panels  | NIL                      | NIL           |
|    | (ii) Sanitary Fixtures  | NIL                      | NIL           |
|    | (iii) Modular Kitchen   | NA                       | NA            |
|    | (iv) Electrical Fittings/ Lightings   | NA                       | NA            |
|    | (v) Gas Piping ( if any)  | NA                       | NA            |
|    | <b>( other than Flats/ Units)</b>   |                          |               |
|    | (vi) Lift Installations   | NIL                      | NIL           |
|    | (vii) Over Head Tanks   | NIL                      | NIL           |
|    | (viii) Under Ground Water Tanks   | NA                       | NA            |
|    | (ix) Fire Fighting Equipments & Fittings as per CFO NOC                           | NIL                      | NIL           |
|    | (x) Electrical Fittings in Common Areas   | NIL                      | NIL           |
|    | (xi) Compliance to condition of environment/CRZ NOC                               | Complete                 | 100%          |
| 18 | Water Proofing of Terraces  | NIL                      | NIL           |
| 19 | Entrance Lobby Finishing  | NIL                      | NIL           |
| 20 | Status of Construction of Compound wall   | NIL                      | NIL           |

  
**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



HARYANA GOVT. GAZ. ( EXTRA), MAY 10, 2019 ( VYSK. 20 ,1941 SAKA )

| TABLE-B    |  |                       |                            |         |
|------------|--|-----------------------|----------------------------|---------|
| Sr.No      | Common Areas and Facilities Amenities                                      | Proposed<br>( Yes/No) | Percentage of<br>work done | Remarks |
| <b>B-1</b> | <b>Services</b>  |                       |                            |         |
| 1          | Internal Roads & Pavements   | Yes                   | 100%                       |         |
|            | Parkings   |                       |                            |         |
| 2          | Covered.....1005 Nos   | Yes                   | 100%                       |         |
|            | Open Nos....235  | Yes                   | 100%                       |         |
| 3          | Water Supply   | Yes                   | 100%                       |         |
| 4          | Sewarage ( Chambers,Lines,STP,Septic Tanks)                                | Yes                   | 100%                       |         |
| 5          | Storm Water Drains   | Yes                   | 100%                       |         |
| 6          | Landscaping & Tree Plantations   | Yes                   | 100%                       |         |
|            | Parks & Playgrounds  | Yes                   | 100%                       |         |
| 7          | Fixing of Children Play Equipments   | Yes                   | 100%                       |         |
|            | Benches  | Yes                   | 100%                       |         |
| 8          | Shopping Areas   | Yes                   | 100%                       |         |
| 9          | Street Lighting/Electrification  | Yes                   | 100%                       |         |
| 10         | Treatment & Disposal of Sewage & Sludge<br>water/STP                       | Yes                   | 100%                       |         |
| 11         | Solid waste Management & Disposal  | Yes                   | 100%                       |         |
| 12         | Water Conservation,Rain water<br>Harvesting,Percolating Well/Pit           | Yes                   | 100%                       |         |
| 13         | Energy Management ( Solar)   | Yes                   | 100%                       |         |
| 14         | Fire Protection & Fire safety Equipments                                   | Yes                   | 100%                       |         |
| 15         | Electrical Meter Room,Sub-Station,Receiving Station                        | Yes                   | 96%                        |         |
| 16         | Under Ground Water Tank  | Yes                   | 100%                       |         |
| <b>B-2</b> | <b>Community Building to be Transferred to RWA</b>                         |                       |                            |         |
| 17         | Community Center   | NA                    | NA                         |         |
| 18         | Others.  | NA                    | NA                         |         |
| <b>B-2</b> | <b>Community Building not to be Transferred to RWA/Competent Authority</b> |                       |                            |         |
| 19         | School   | YES                   | 47%                        |         |
| 20         | Dispensary   | NA                    | NA                         |         |
| 21         | Club/Community Building  | YES                   | 100%                       |         |
| 22         | Others.  | NA                    | NA                         |         |
| <b>B-3</b> | <b>Services/ Facilities to be Transferred to Competent Authority</b>       |                       |                            |         |

  
Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608