Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect'	s Certificate ¹
Repo	ort for q	uarter ended	30th September 2023
Subject			Certificate of progress of construction work
1.	50.00	[ent as architect for certifying progress of ontioned project as per the approved plans
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Elevate Phase – I
	2.	Location	Village Behrampur, Sector-59, Gurugram
	3.	Licensed area in acres	8.91875
	4.	Area for registration in acres	5.95
	5.	HARERA registration no.	19 of 2019

onles Pur

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page 1 of 25

6.	Name of licensee	License no. 16 of 2008 :
6.	Name of licensee	License no. 16 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011: 1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd.
7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
8.	Name of developer	Heritage Max Realtech Pvt. Ltd.

1.	Date of certifying of percentage of construction work/ site inspection	30 th September 2023
2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	30th September 2023

3.	Follo	wing technical professionals a	re appointed by promoter: - (as applicable)
	Sr. No.	Consultants	Name
	1.	Site engineer	Vijayant Singh
	2.	Structural consultant	Vintech Consultant (Mr. Vinod Jain)
	3.	Proof consultant	Mehro Consultants
	4.	MEP consultant	Sanelac Consultants Pvt Ltd
*	5.	Site supervisor/incharge	Avinash Nagpal
4.	mand applic develo	atory approvals, Haryana Buildir cable) and the material used in th opment works are as per the pro rochure, publication material and	Recuted as per approved drawings, statutory/ ng Code, 2017 / National Building Code (wherever e construction, infrastructure works and internal ojected standard as envisaged in the registration d other documents shared with the buyers in this
5.	The state of the s		ercentage of work done in the project for each of project/phase of the project under HARERA is as

per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table

Date

: 10-10-23

Labib Alam, Architect

Place

: N. DECHI

Council of Architecture Registration No.: CA/2001/27447

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : CA/2001/27447

registration no.

Council of architects (CoA) : 31 - 12 - 2027 registration valid till (date)

		,	Table - A			
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)				
A1	Cun	nulative progress of the projec	gress of the project/phase at the end of the quarter.			
Sr. No.	Proj	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	(incl	structure lusive of excavation, idation, basements, water ofing, etc.)	0.30	35.00	100%	
2.	(slal	er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	6.05	56.00	100%	
3.	MEF)				
	3.1	Mechanical (lifts, ventilation, etc.)	0.09	15.51	78 %	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.06	6.81	57 %	

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.04	8.64	66%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.09	10.84	52%
	4.2	External (plaster, painting, facade, etc.)	0.09	6.92	46%

Sr. No.		Tasks/ Activity Sub-Structure Status	Description of work done	Percentage of total proposed work
1.	Exca	vation	Complete	100 %
2.	Layi	ng of foundation	11 47 4	
	(i)	Raft	Complete	100 %
	(ii)	Pile	0	0
3.	Num	ber of basement(s)		
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%
4.		erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%

		Super-Structure Status		
5.	Total floors in the tower/ building		1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Tota	l area on each floor	785 Sqm	100%
7.	Stilt floor/ ground floor		Structure Tower Entrance	100%
8.	Stati	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
9.	Status of construction			
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		g of door and window frames in / units		
11.	Statu	s of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statu	s of wall plastering		Sup 1

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Stati	us of wall tiling		
	(i)	Bathroom Tiles	100% Completed	
	(ii)	Kitchen Wall Tile	68% Completed	
14.	Statı	us of flooring	× 200 - 100	
	(i)	Lift Lobby Flooring	99% Completed	
	(ii)	Apt Stone Flooring	99% Completed	
15.	Statı	us of white washing		
	(i)	Apartment Prefinal Paint	9% Completed	
	(ii)	Putty+1slCoat+2nd Coat	80% Completed	
16.	Statu	as of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	
	(iii)	Lobby Wall Tiling	74% Completed	
17.	Statu	as of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	95% Completed	
	(ii)	Bathroom Chinaware	3% Completed	
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	4% Completed	abib Alam Architect

	(iv)	Switch & Sockets	59% Completed	
	(v)	NA	NA	0
	(othe	r than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	80%	
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	100% Completed	0
	(x)	Staircase & Lobby Wiring	100% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	rproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	nce lobby finishing	Gypsum False ceiling	77% Completed
20.	Statu	s of construction of compound	Boundary Wall RCC and Brick Work	0% Completed

Note: (*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services	1		
1.	Internal roads & pavements	Yes	0	
2.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
3.	Water supply	Yes	0	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
5.	Storm water drains	Yes	0	
6.	Landscaping & tree plantation	Yes	0	
7.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
8.	Shopping area	Yes	0	
9.	Street lighting/ electrification	Yes	0	9
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	(1
11.	Solid waste management & disposal	Yes	0	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
13.	Energy management (solar)	Yes	0	
14.	Fire protection and fire safety requirements	Yes	0	
15.	Electrical meter room, sub-station, receiving station	Yes	0 m	-

16.	Other (option to add more)	NA	0
B-2	Community building to be transferred	to RWA	
17.	Community centre	Yes	0
18.	others	NA	
B-3	Community buildings not to be transferred to RWA/competent authority		
19.	Schools	NA	
20.	Dispensary	NA	
21.	Club	Yes	0
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority	NA	
23.	*		

Note: (*) extend as per requirement

		1	Table – A		
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower-B			
A1	A1 Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.			usive of excavation, dation, basements, water		100%
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		10.40	60.05	100%
7.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.05	13.49	67%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.05	7.65	61%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.05	8.50	63%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.05	10.95	50%
	4.2	External (plaster, painting, facade, etc.)	0.05	6.90	46%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
		Sub-Structure Status		
21.	Exca	vation	Complete	100 %
22.	Layir	ng of foundation		
	(iii)	Complete	100 %	100 %
	(iv)	NA	NA	0
23.	Num	ber of basement(s)		
	(iii)	Structure under Tower Footprint Complete	Complete	100%
	(iv)	Structure under Tower Footprint Complete	Complete	100%
24.	1	erproofing of the above sub- eture (wherever applicable)	Deck Water Proofing	100%
		Super-Structure Status	Lai	bib Alam, Architect

25.	Total	l floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
28.	Statu	is of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/ tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Statu	s of construction		
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room		100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.	COST DO NOT YOUR	g of door and window frames in units	Door Frame	100% Completed
31.	Statu	s of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	81% Completed	88% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	Come

	(iv)	Gypsum Plaster	100%	
33.	Statu	as of wall tiling		
	(iii)	Bathroom Tiles	95% Completed	
	(iv)	Kitchen Wall Tile	65% Completed	
34.	Statu	as of flooring		
	(iii)	Lift Lobby Flooring	97% Completed	
	(iv)	Apt Stone Flooring	98% Completed	
35.	Statu	s of white washing		
	(iii)	Apartment Prefinal Paint	30% Completed	
	(iv)	Putty+1stCoat+2nd Coat	30% Completed	
36.	Status of finishing			
	(iv)	MS Railing	100% Completed	
	(v)	Lift Well HO for Lift Installation	100% Completed	
	(vi)	Lobby Wall Tiling	70% Completed	
37.	Statu	s of installation		
	(with	in flat/unit)		
	(xii)	UPVC Windows	95% Completed	
	(xiii)	Bathroom Chinaware	0% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	3% Completed	
	(xv)	Switch & Sockets	17% Completed	
	(xvi)	NA	NA	
	(othe	r than flat/units)		26)

(xvii)	Guide Rail+ Floor Door+ Car Installation	82 % Complete	
(xviii	RCC Work	100% Completed	
(xix) RCC Work		100% Completed	
(xx)	Fire Pump Installation	100% Completed	
(xxi)	Staircase & Lobby Wiring	100% Completed	
(xxii)	Six Monthly Compliance	100% Compliance	
Wate	rproofing of terraces	PU Waterproofing	100% Completed
Entra	nce lobby finishing	Gypsum False ceiling	70% Completed
Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	5% Completed
	(xviii (xix) (xx) (xxi) (xxii) Wate	Installation (xviii RCC Work (xix) RCC Work (xx) Fire Pump Installation (xxi) Staircase & Lobby Wiring (xxii Six Monthly Compliance Waterproofing of terraces Entrance lobby finishing Status of construction of compound	Installation (xviii RCC Work 100% Completed (xix) RCC Work 100% Completed (xx) Fire Pump Installation 100% Completed (xxi) Staircase & Lobby Wiring 100% Completed (xxii Six Monthly Compliance 100% Compliance Waterproofing of terraces PU Waterproofing Entrance lobby finishing Gypsum False ceiling Status of construction of compound Boundary Wall RCC and

Note: (*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remark
B-1	Services	<u> </u>		
24.	Internal roads & pavements	Yes	0	
25.	Parking	Yes	0	
	Covered no	Yes	0	
	Open no	Yes	0	
26.	Water supply	Yes	0	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0	
28.	Storm water drains	Yes	0	
29.	Landscaping & tree plantation	Yes	0	******
30.	Parks and playgrounds	Yes	0	
	Fixing of children play equipment's	Yes	0	
	Benches	Yes	0	
31.	Shopping area	Yes	0	
32.	Street lighting/ electrification	Yes	0	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	0	191313
34.	Solid waste management & disposal	Yes	0	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0	
36.	Energy management (solar)	Yes	0	11
37.	Fire protection and fire safety requirements	Yes	0	
38.	Electrical meter room, sub-station, receiving station	Yes	0	4

Dags 17 of 20

39.	Other (option to add more)	NA	
B-2	Community building to be transferred	to RWA	
40.	Community centre	Yes	0
41.	others	NA	×
B-3	Community buildings not to be transferred to RWA/competent authority		
42.	Schools	NA	
43.	Dispensary	NA	
44.	Club	Yes	0
45.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority	NA	
46.	*		

Note: (*) extend as per requirement

		1	Table – A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	. I		
A1	Cun	nulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	24.96	100%
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		2.70	40.02	100%
11.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.01	8.77	88%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.01	6.31	79%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.0	01	6.94		87%	
12.	Finis	shing		ħ				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.0)1	10.76		67%	
	4.2	External (plaster, painting, facade, etc.)	0.0	01 4.41			88%	
Sr. No.		Tasks/ Activity		Description		100000000000000000000000000000000000000	entage of total	
140.		Sub-Structure Status		don		Pr	oposcu work	
41.	Exc	avation		Complete		100 %)	
42.	Lay	Laying of foundation					-	
	(v)	(v) Complete				100%	i ,	
	(vi)	(vi) NA		NA		0		
43.	Nur	nber of basement(s)						

Structure under Tower Footprint

Structure under Tower Footprint

Waterproofing of the above sub-

Super-Structure Status

structure (wherever applicable)

(v)

(vi)

44.

Complete

Complete

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

100%

100%

100%

Deck Water Proofing

45.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
48.	Statu	is of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	
	(xi)	Lift Well including Machine room	100% Completed	
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	
50.	1	g of door and window frames in units	Door Frame	100% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	
52.	Statu	s of wall plastering		
	(v)	RCC External Wall	NA	1 00.

	(vi)	Gypsum Plaster	100%	
53.	Statu	s of wall tiling		
	(v)	Bathroom Tiles	100% Completed	
	(vi)	Kitchen Wall Tile	70% Completed	
54.	Statu	s of flooring		
	(v)	Lift Lobby Flooring	100% Completed	
	(vi)	Apt Stone Flooring	100% Completed	
55.	Statu	s of white washing		
	(v)	Apartment Prefinal Paint	100% Completed	
	(vi)	Putty+1stCoat+2nd Coat	32% Completed	
56.	Statu	s of finishing		
	(vii)	MS Railing	100% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	
	(ix)	Lobby Wall Tiling	100% Completed	
57.	Statu	s of installation		
	(with	in flat/unit)		
	(xxiii	UPVC Windows	100% Completed	
	(xxiv	Bathroom Chinaware	0%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	3%	
	(xxvi	Switch & Sockets	47% Completed	
	(xxvi	NA	NA	
	(othe	r than flat/units)		abib Alam, Architect

	(xxvi Guide Rail+ Floor Door+ Ca Installation	ar 100% Complete		
	(xxix RCC Work	100% Completed		
	(xxx) RCC Work	100% Completed		
	(xxxi Fire Pump Installation	100% Completed		
	(xxxi Staircase & Lobby Wiring	100% Completed		
	(xxxi Six Monthly Compliance	100% Compliance		
58.	Waterproofing of terraces	PU Waterproofing	100% Completed	
59.	Entrance lobby finishing	Gypsum False ceiling	81% Completed	
60.	Status of construction of compoun wall	d Boundary Wall RCC and Brick Work	0% Completed	
			all	

Note: (*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remark	
B-1	1 Services				
47.	Internal roads & pavements	Yes	0		
48.	Parking	Yes	0		
	Covered no	Yes	0		
	Open no	Yes	0		
49.	Water supply	Yes	0		
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0		
51.	Storm water drains	Yes	0		
52.	Landscaping & tree plantation	Yes	0		
53.	Parks and playgrounds	Yes	0		
	Fixing of children play equipment's	Yes	0		
	Benches	Yes	0		
54.	Shopping area	Yes	0		
55,	Street lighting/ electrification	Yes	0		
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	0		
57.	Solid waste management & disposal	Yes	0		
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0		
59.	Energy management (solar)	Yes	0		
60.	Fire protection and fire safety requirements	Yes	0		
61.	Electrical meter room, sub-station, receiving station	Yes	0		

62.	Other (option to add more)	NA			
B-2	Community building to be transferred to RWA				
63.	Community centre	Yes	0		
64.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
65.	Schools	NA			
66.	Dispensary	NA			
67.	Club	Yes	0		
68.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
69.	*				

Note: (*) extend as per requirement