Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect's	s Certificate*		
Repo	Report for quarter ending September 2023				
Subje	ect		Certificate of progress of construction work		
1.			ent as architect for certifying progress of ntioned project as per the approved plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Birla Navya (Amoda I & II)		
	2.	Location	Sector – 63 A, Gurugram , Haryana		
	3.	Licensed area in acres	110.20575		
	4.	Area for registration in acres	3.79 acres		
	5.	HARERA registration no.	RC/REP/HARERA/GGM/390/122/2020/06		
	6.	Name of licensee	M/s Anant Raj Limited & Others		
	7.	Name of collaborator	N/a		
	8.	Name of developer	M/s Avarna Projects LLP		
2.	Details related to inspection are as under				

^{*} On the letter head of the architect firm

Associates Private Limited

Architecture Planning Urban Design Interiors

1.	Date of certifying of percentage of construction work/ site inspection	30 th September 2023
2.	Name of Architect/ Architect's firm	Arcop Associates Pvt. Ltd.
3.	Date of site inspection	30 th September 2023

Sr. No.	Consultants	Name
1.	Site engineer	Avarna Projects LLP
2.	Structural consultant	Vintech Consultants
3.	Proof consultant	Buro Happold/WWP Consulting Engineers Pv Ltd.
4.	MEP consultant	Sunil Nayyar Consulting Engineers LLP
5.	Site supervisor/incharge	CBRE South Asia Pvt. Ltd.
I certify that the work has been executed as per approved drawings, statutory mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internate development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in the regard.		

Associates Private Limited

Architecture Planning Urban Design Interiors

Annexure A

I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date : 09-10-2023 Yours faithfully,

Place : Gurugram

Mark

Ashu, Architect
Council of Architecture
Registration No.: CA/2007/40332

Signature & name (in block letters) with stamp of architect

Council of architects (CoA): CA/2007/40332

registration no.

Council of architects (CoA) : 31/12/2028

registration valid till (date)

Associates Private Limited

Architecture Planning Urban Design Interiors

					Annexure A
		1	Table - A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	H-(P01-12,12A,14-16,19-45);D- (01-12,12A,14)		
A1	Cum	ulative progress of the projec	t/phase at the en	d of the quarter	•
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		7,86,47,952	28,10,22,059	74.12%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		8,17,76,812	72,26,28,152	66.97%
3.	МЕР	,			
	3.1	Mechanical (lifts, ventilation, etc.)	58%	58%	58%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	20.13%	54.39%	54.39%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	9.36%	33.33%	33.33%

Associates Private Limited

Architecture Planning Urban Design Interiors

4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	14.97%	45.02%	45.02%
	4.2	External (plaster, painting, facade, etc.)	13.16%	42.54%	42.54%

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed
NO.			uone	completed work
1.	Exca	vation	By Mechanical Means	100%
2.	Layi	ng of foundation		
	(i)	Raft	Combined Footing	100%
	(ii)	Pile	N/a	
3.	Num	ber of basement(s)		
	(i)	Basement Level 1	57*1=57	100%
	(ii)	Basement level 2*	N/a	
4.	Waterproofing of the above substructure (wherever applicable)			Nil
	Super-Structure Status			
5.	Tota	l floors in the tower/building	57*4=228	100%
6.	Tota	l area on each floor		
7.	Stilt floor/ ground floor		57*1 =57	100%
8.	Status of laying of slabs floor wise			
	Cumulative number of slabs in the building/ tower laid by end of quarter		57*6=342	100%

Associates Private Limited

Architecture Planning Urban Design Interiors

(i) Mechanical works 57*4=228 58% (ii) Electrical works including wiring 57*7=399 51.38% (iii) Plumbing works including wiring 57*7=399 30.53% 12. Status of wall plastering 57*4=228 84.21% (ii) Internal plaster 57*7=399 75.39% 13. Status of wall tiling 73.68% (ii) In bathroom 57*4=228 73.68% (ii) In kitchen 57*4=228 73.68% 14. Status of flooring 57*4=228 63.16% 15. Status of white washing 57*4=228 63.16% 15. Status of white washing 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%		1		I		Г	Annexure A
(ii) Staircase 57*1= 57 100% (iii) Lift wells along with water proofing 57*1= 57 100% (iv) Lift lobbies/ common areas floor wise 57*7= 399 100% 10. Fixing of door and window frames in flats/ units 57*4 = 228 53% 11. Status of MEP Internal (within flat) Internal (within flat) External (within flat) (i) Mechanical works 57*4=228 58% (ii) Electrical works including wiring 57*7=399 51.38% (iii) Plumbing works 57*7=399 30.53% 12. Status of wall plastering (i) External plaster 57*4=228 84.21% (ii) Internal plaster 57*4=228 73.68% 13. Status of wall tiling (ii) In bathroom 57*4=228 73.68% 14. Status of flooring (ii) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal w	9.	Statu	is of construction				
(iii) Lift wells along with water proofing 57*1=57 100% (iv) Lift lobbies/ common areas floor wise 57*7=399 100% 10. Fixing of door and window frames in flats/ units 57*4=228 53% 11. Status of MEP Internal (within flat) External (within flat) Internal (within flat) External (within flat) External (within flat) External (within flat) 57*4=228 58% (ii) Electrical works including works including wiring (iii) F7*7=399 51.38% 57*7=399 30.53% 12. Status of wall plastering (i) External plaster (ii) 57*4=228 84.21% (ii) Internal plaster (ii) 57*4=228 73.68% 13. Status of wall tiling (ii) In bathroom (57*4=228) 73.68% 14. Status of flooring (ii) Common areas (57*7=399) 35.96% (iii) (ii) Units/ flats (57*4=228) 63.16% 15. Status of white washing (iii) Internal walls (57*4=228) 19.12% 16. Status of finishing (iii) Status of finishing (iii) Status of finishing (iii) <td></td> <td>(i)</td> <td>Walls on floors</td> <td>57*4=228</td> <td></td> <td>98.25%</td> <td></td>		(i)	Walls on floors	57*4=228		98.25%	
The proofing		(ii)	Staircase	57*1= 57		100%	
10. Fixing of door and window frames in flats/ units 57*4 = 228 53% 11. Status of MEP		(iii)	_	57*1= 57		100%	
flats units		(iv)		57*7= 399		100%	
(i) Mechanical works 57*4=228 58% (ii) Electrical works including wiring 57*4=228 58% (iii) Plumbing works including wiring 57*7=399 51.38% 12. Status of wall plastering 57*4=228 84.21% (ii) Internal plaster 57*4=228 84.21% (ii) In bathroom 57*4=228 73.68% 13. Status of wall tiling 73.68% (ii) In bathroom 57*4=228 73.68% 14. Status of flooring 57*4=228 63.16% 15. Status of white washing 57*4=228 63.16% 15. Status of white washing 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%	10.		_	57*4 = 228	3	53%	
(ii) Electrical works including wiring 57*7=399 51.38% (iii) Plumbing works 57*7=399 30.53% 12. Status of wall plastering (i) External plaster 57*4=228 84.21% (ii) Internal plaster 57*7=399 75.39% 13. Status of wall tiling (i) In bathroom 57*4=228 73.68% (ii) In kitchen 57*4=228 73.68% 14. Status of flooring (i) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%	11.	Statı	us of MEP	(within		(within	External works
wiring		(i)	Mechanical works	57*4=228		58%	
12. Status of wall plastering (i) External plaster 57*4=228 84.21% (ii) Internal plaster 57*7=399 75.39% 13. Status of wall tiling 73.68% (i) In bathroom 57*4=228 73.68% (ii) In kitchen 57*4=228 73.68% 14. Status of flooring 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing 57*6=342 24.74% (ii) Internal walls 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%		(ii)	9	57*7=399		51.38%	
(i) External plaster 57*4=228 84.21% (ii) Internal plaster 57*7=399 75.39% 13. Status of wall tiling 73.68% (i) In bathroom 57*4=228 73.68% (ii) In kitchen 57*4=228 73.68% 14. Status of flooring 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%		(iii)	Plumbing works	57*7=399		30.53%	
(ii) Internal plaster 57*7=399 75.39% 13. Status of wall tiling 57*4=228 73.68% (i) In bathroom 57*4=228 73.68% 14. Status of flooring 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing 57*4=228 19.12%	12.	Status of wall plastering					
13. Status of wall tiling		(i)	External plaster	57*4=228		84.21%	
(i) In bathroom 57*4=228 73.68% (ii) In kitchen 57*4=228 73.68% 14. Status of flooring (i) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing		(ii)	Internal plaster	57*7=399		75.39%	
(ii) In kitchen 57*4=228 73.68% 14. Status of flooring (i) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing (ii) Internal walls (iii) External walls (iiiiiiiiiiiiiiiiiiiiiiiiiiiii	13.	Statu	ıs of wall tiling				
14. Status of flooring (i) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing		(i)	In bathroom	57*4=228		73.68%	
(i) Common areas 57*7=399 35.96% (ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing		(ii)	In kitchen	57*4=228		73.68%	
(ii) Units/ flats 57*4=228 63.16% 15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing	14.	Statu	is of flooring				
15. Status of white washing (i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing		(i)	Common areas	57*7=399		35.96%	
(i) Internal walls 57*6=342 24.74% (ii) External walls 57*4=228 19.12% 16. Status of finishing		(ii)	Units/ flats	57*4=228		63.16%	
(ii) External walls 57*4=228 19.12% 16. Status of finishing	15.	Statı	is of white washing				
16. Status of finishing		(i)	Internal walls	57*6=342		24.74%	
		(ii)	External walls	57*4=228		19.12%	
(i) Staircase with railing 57*6=342 53.68%	16.	Statu	us of finishing				
(1) Staticase with raning 37 0-342 33.0070		(i)	Staircase with railing	57*6=342		53.68%	

Associates Private Limited

Architecture Planning Urban Design Interiors

Annexure A

	(ii)	Lift wells	57*4=228	28.07%
	(iii)	Lift lobbies/ common areas floor wise	57*7=399	35.96%
17.	Statu	s of installation		
	(with	nin flat/unit)		
	(i)	Doors and windows panels	57*4=228	35.09%
	(ii)	Sanitary fixtures	Nil	Nil
	(iii)	Modular kitchen	Nil	Nil
	(iv)	Electrical fittings/ lighting	Nil	Nil
	(v)	Gas piping (if any)	N/a	
	(othe	er than flat/units)		
	(vi)	Lifts installation	Nil	Nil
	(vii)	Overhead tanks	Nil	Nil
	(viii)	Underground water tank	Nil	Nil
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Nil	Nil
	(x)	Electrical fittings in common areas	Nil	Nil
	(xi)	Compliance to conditions of environment/ CRZ NOC	Nil	Nil
18.	Waterproofing of terraces		57*1 = 57	28.07%
19.	Entrance lobby finishing		Nil	Nil
20.	Status of construction of compound wall		Nil	Nil

Note: (*) extend rows as per requirement.

Associates Private Limited

Architecture Planning Urban Design Interiors

Annexure A

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks	
B-1	Services				
1.	Internal roads & pavements	Yes	Nil		
2.	Parking				
	Covered no				
	Open no				
3.	Water supply	Yes	Nil		
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	Nil		
5.	Storm water drains	Yes	Nil		
6.	Landscaping & tree plantation	Yes	Nil		
7.	Parks and playgrounds	Yes	Nil		
	Fixing of children play equipment's	Yes	Nil		
	Benches	Yes	Nil		
8.	Shopping area	Yes	Nil		
9.	Street lighting/ electrification	Yes	Nil		
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	Nil		
11.	Solid waste management & disposal	Yes	Nil		
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	Nil		
13.	Energy management (solar)	Yes	Nil		
14.	Fire protection and fire safety requirements	Yes	Nil		
15.	Electrical meter room, sub-station, receiving station	Yes	Nil		
16.	Other (option to add more)				
B-2	Community building to be transferred to RWA				
17.	Community centre		Nil		
18.	Others				

Associates Private Limited

Architecture Planning Urban Design Interiors

Annexure A

B-3	Community buildings not to be transferred to RWA/competent authority	
19.	Schools	
20.	Dispensary	
21.	Club	Nil
22.	Others	
B-4	Services/ facilities to be transferred to competent authority	
23.	*	

Note: (*) extend as per requiremen

Associates Private Limited

Architecture Planning Urban Design Interiors