

ACPL Design Ltd

E.24, South Extension I. T: +91 11 4823 4444 New Delhi, 110049, India

+91 11 2462 2195 +91 11 2464 6709 F: +91 11 2463 4059

www.acplonline.com

Annexure-A

		Architect's Cer	tificate		
Report	Report of quarter ending 30-Jun-23				
Subject			Certificate of progress of construction work		
1	I, KULMEET SHANGARI has undertaken assignment as architect for certifying progress of construwork in the below mentioned project as per the approved plans.				
	Sr.No.		Information		
	1	Project/ Phase of the project	Project Area 1.6577 Acres, Commercial Colony		
	2	Location	Sector-37, Faridabad		
	3	Licensed area in acres	1.6577 Acres		
	4	Area for registration in acres	1.6577 Acres		
	5	HARERA registration no.	226 of 2017 dated 19.09.2017		
	6	Name of Licensee	MPDL LIMITED		
	7	Name of collaborator	N.A.		
	8	Name of developer	MPDL LIMITED		
2	Details related to inspection are as under				
	1	Date of certifying of percentage of construction work/ site inspection	6-Jul-23		
	2	Name of Architect/Architect's firm	Principal Architect:- Mr.Kulmeet Shangari		
			Firm : ACPL Design Ltd.		
	3	Date of site inspection	4-Jul-23		
3	Followin	g technical professional are appointed by pro	pmoter:- (as applicable)		
	Sr.No.	Consultants	Name		
	1	Site Engineer	Sanjay Kumar		
	2	Structural consultant	TPC Technical Projects Consultants Pvt. Ltd.		
	3	Proof consultant			
	4	MEP consultant	C P Vidya & Associates, RAD infra Consulting MEP Engineers, Udayan Choudhary & Associates Pvt. Ltd.		
	5	Site incharge	Santosh Kumar Jha KIII MEET SAANKAA		

4	I certify that the work has been executed as per approved drawings, statutory/mandatory, approvals Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure, works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with tje buyers in this regard.
5	I also certify that as on the date, the percentage of work done in the rpoject for each of the building/tower of the real estate project/phae of the project under HARERA is as per table A and Table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and table B.

Date:

6-Jul-23

Place

Council of architects (CoA) : registration no.

Council of architects (CoA) registration valid till (date)

Yours faithfully

ARCHITECT CA/97/21741

KULMEET SHANGARI

CA/ 97/ 21741

31.12.2024

QUARTERLY REPORT - (APRIL 2023 TO JUNE 2023) Table - A Building / Tower No. M1 TRADE TOWER FARIDABAD HR. **A1** Cumulative progress of the project / phase at the end of the quarter Sr. No. **Project components** Work done value during **Cumulative work** Percentage of done value till date the quarter work done to the total proposed work Sub Structure (Including of excavation, foundation, 350,000.00 basement, water proofing, etc.) 160,978,444.00 99% 2 Super Structure (Slabs, brick work, block work, stair case 1,250,000.00 176,057,793.00 98% , lift wells, machine rooms, water tank. etc.) 3 MEP Mechanical 3.1 6,554,000.00 44,619,000.00 75% (lifts, ventilation, etc.) Electrical 3.2 (conducting, wiring, fixtures, 9,709,000.00 45,231,000.00 70% etc.) Plumbing & Firefighting (piping 3.3 pumps and pump room, fixtures 6,999,000.00 29,314,836.00 71% etc. 4 **Finishing** Internal (Plaster, tilling, flooring, 4.1 2473000.00 4,946,262.00 72% painting etc. within units and common areas) External 4.2 17322000.00 57,405,665.00 67% (Plaster, Painting, façade, etc.)



Sr. No.		Tasks / Activity Sub- Structure Status	Tasks / Activity Description of wor done		Percentage of total proposed work		
1	Excava				<u> </u>		
2		g of foundation	Doi		100%		
~			Done		100%		
	(i)	Raft	Doi		100	1%	
3	(ii)	Pile	N/	A			
3	Number of basement (s)3						
	(i) Basement Level 1		Doi	Done		100%	
	(ii)	Basement Level 2	Doi	Done		100%	
	(iii)	Basement Level 3	Doi	ne	100	%	
4		proofing of the above sub-structure (wherever			0%	6	
	applicable) Super - Structure Status		In pro-	In progress		99%	
5	Total f	loors in the tower / building	14		-		
6	Total a	area on each floor	8589				
7	Stilt flo	oor/ ground floor	1630				
8	Status	of laying of slabs floor wise	1030	1112			
	Cumulative number of slabs in the building / tower						
	18	Blaid by end of quarter	18	3	100%		
9	Status	of Construction					
	(i)	Walls on floor	Dor	Done			
	(ii)	Staircase	Dor	Done			
	(iii)	Lift wells along wit water proofing	Dor	Done			
	(iv)	Lift lobbies / common area floor wise	Done				
10	Fixing	of door and window frames in flats / units					
11	Status of MEP		Internal	External	Internal	Externa	
	(;)	M. J. J. J.	(within flat)	works	(within flat)	works	
	(i)	Mechinal works	In prog				
	(ii)	Electrical works including wiring		In progress			
12	(iii)	Plumbing works	In prog	gress			
12		of wall plastering	<u> </u>				
	(i)	External Plaster	In prog	In progress			
	(ii)	Internal Plaster	In prog	gress			
13	Status of wall tiling			+			
	(i)	in bathroom	Yet to	Yet to Start			
	(ii) in kitchen		Yet to	Yet to Start			
14	Status	of flooring					
	, (i) Common areas		In prog	In progress			
	(ii)	Unit / flats	Yet to	Yet to Start			
			*				

15	Status of white washing				
	* (i)	External Walls	In progress		
	(ii)	Internal Walls	In progress		
16	Status of finishing				
	(i)	Staircase with railing	Done		
	(ii)	Lift wells along wit water proofing	Done		
	(iii)	Lift lobbies / common area floor wise	In progress		
17	Status	of Installation			
	(withir	n flat / unit)			
	(i)	Doors and window panels	In progress		
	(ii)	Sanitary fixtures	Yet to Start		
	(iii)	Modular kitchen	NA		
	(iv)	Electrical fitting / lighting	In progress		
	(v)	Gas piping (if any)	NA		
	(other than flat / units)				
	(vi)	Lift installation	In progress		
	(vii)	overhead tanks	Done		
	(viii)	Underground water tank	Done		
	(ix)	Fire fighting fitting and equipment 's as per CFO NOC	Yet to Start		
	(x)	Electrical fitting in common areas	In progress		
	(xi)	Compliance to conditions of environment / CRZ NOC	In progress		
18	Waterp	proofing of terraces	Done		
19	Entran	ce lobby finishing	In progress		
20	Status	of Construction of compound wall	In progress		

Note (*) extend rows as per requirement

TABLE B

Sr. No.	Common areas and facilities amenities	Proposed (Yes / No)	Percentage of work done	Remarks	
B-1	Services	1.			
1	Internal roads & pavements	Yes		In progress	
2	Parking	Yes		In progress	
3	Covered no.	204		Yet to Start	
4	Open No.	38		Yet to Start	
5	Water supplies	Yes		In progress	
6	Sewerage (chamber, lines, septic tanks, STP)	Yes		In progress	
7	Storm water drains	Yes		In progress	
8	Landscaping & tree plantation	Yes		Yet to Star	
9	Parks and playgrounds	NA		Yet to Star	
10	Fixing of children play equipment's	NA		Yet to Star	
11	Benches	NA		NA	
12	Shopping area	Yes		Yet to stsr	
13	Street lighting / electrification	Yes		Yet to stsr	
14	Treatment and disposal of sewerages and sullage water / STP	Yes		In progres	
15	Electrical meter room , sub - station , receiving station .	Yes		In progres	
16	Other (option to add more)				
B-2	Community building to be transferred to RWA				
17	Community center	NA		NA	
18	others				
B-3	Community building not to be transferred to RWA / competent authority				
19	Schools	NA		NA	
20	Dispensary	Dispensary NA		NA	
21	Club	NA		NA	
22	Others				
B-4	Services / facilities to be transferred to competent authority	7			
23					

